

21st Sept 2019

Quotation No.: Q19-OPS-1329

India International Insurance
64 Cecil St,
Singapore 049711

ComfortDelGro Engineering Pte Ltd
205 Braddell Rd
Singapore 579701

Attn: Claims Department

Dear Sir/Mdm

Estimated Cost of Repair job for SBS6485X Accident on 17/09/2019 @ T4 Way X T4 Link involving SBS6485X & SH8744S

S/N	Description	Qty.	Unit Price	Total Price
1	Supply OSF corner bumper - 10%	1 pc	\$ 2,478.50	\$ 2,478.50
2	Supply RHS Indicator lamp x	1 pc	\$ 70.00	\$ 70.00
3	Supply skilled labour to remove, replace OSF bumper	1 job	\$ 450.00	\$ 450.00 \$ 300
4	Supply skilled painter with paint material to Putty, grinding & spraypaint OSF bumper	1 portion	\$ 880.00	\$ 880.00 \$ 600
5	Supply skilled electrician to replace, check connectivity and functionality of OSF indicator	1 job	\$ 250.00	\$ 250.00 \$ 50
Total				\$ 4,128.50
7% G.S.T.				\$ 289.00
Grand Total				\$ 4,417.50

Terms and Conditions:

Payment Terms : 30 days upon invoice
Quotation Validity : 30 days
Lead-Time : 3 working days
Price quoted subject to 7% GST

Yours faithfully

Acknowledged by
Signature:
Date:

[Signature]



Ka Lin (LKK)
25/9/19
2 Days
L/S
After Repair

Approval by

Shirley Lim

LexBuild International Pte. Ltd.
2 Woodlands Sector 1, #05-12 (Woodlands Spectrum 1), Singapore 738068.
Tel: (65) 6456 3533, Fax: (65) 6456 3353
Website: www.LexBuild.com, Email: sales@LexBuild.com



ROC / CR / GST Reg No: 200004370R