

22/03/2002

ASS. REC. BY:

REF:

99/CT119016744/69f 322

Special Instruction:

Surveyor: GA

ASSIGNMENT (Office)

From (Person): Elaine Chong

of

CT1

Date/Time: 23.9.19 15.01pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SJ2 9196D

Insured:

G8J 5805K

at Workshop m/s

Team Autopro

Tel:

62581955

of

385 sm ming Drive #01-02

Policy No:

DMCVSR3040 1419000

Claim No:

SNM191204328C02

Sum Insured:

Excess:

Make of Veh:

D.O.A. 9.9.2019

(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

23.9.19 3pm

Person Contacted:

Reach

Vehicle IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	SJ2 9196D-X
	G8J 5805K-X
	Dismantle: 25/9/2019
	After repair: 30/9/2019

Surveyor:

air.
PRS

REF:

Cti

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s Teamauto pro
of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.Bal. or Market Value: \$24K

IDAC Accident Rpt: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: 5 days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: ST891960 Yr Regn: 05 Jan 2011Type: M Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /Truck / Trailer or Scirocco 1.4Make: Volkswagen c.c. 1390Colour: Red A/C: Insured / Std / NI / NASp. Reading: 188104 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WVW 888 137 BV 016344Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 245 / 35 2R 19R: 11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Fire N/A

Front

Rear

R/Bal. 5 mm R/Bal. 5 mmL/Bal. 5 mm L/Bal. 5 mmD.O.A. _____ D.O.I. 24-09-19Survey held at w/s 4:30 pm

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame o/s / Body Structure affected due to collision.

Date / Time Action / Instruction

\$2000 - \$3000CoG: 17960

RECEIVED 07 OCT 2019

Date/Time, File Pass to?

☐ : Preli. ReportDays Of Repair: 5

1)

☐ : Final ReportResurvey No. of Trip: 2

Date/Time, File Return to?

Survey Fee:

2)

Transportation:

Add Fee: ☐ : Site Insp (\$) S + RS, SI☐ : Interview (\$) Photos☐ : Tech. Invs (\$) Others☐ : Weekend (\$)Report Format: PRC

Lump Sum / I.B.I.: (\$)

TOTAL

190
190

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	23 Sep 2019		23 Sep 2019 15:01 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	----------

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:			
Main Claimant:	LEE LI MENG, ID: S1200782E		
Vehicle Reg. No.:	SJZ9196D	Date of Loss:	09/09/2019 16:00 - :59
Claim Type:	TP / SNM19D204328C02	Policy/Cover Note No.:	DMCVSN30401419000
Vehicle Reg. No. (Insured):	GBJ5805K	Policy No. (Claimant):	P10033493R01
		Excess:	S\$350.00
Repairer:	Team Autopro Pte Ltd (Sin Ming) 385 Sin Ming Drive, #01-02 Vicom Inspection Centre, 575718 Sin Ming - Tel: 62581955		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Elaine Cheong]		
Claimant's Insurer:	Auto & General Insurance (Singapore) Pte. Limited. (HQ) - Tel: 6540 2180		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 02/10/2019]		

ASSOCIATED MAIL RECEIVED

View All

Compose Case Mail

There are no mail for this case.

ALL ASSOCIATED TASKS

View All

Search Tasks

Create New Task

Complete

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Shiau Chan (LKKAUTO)

From: Chong Boon Sen <boonsen.chong@sg.cntaiping.com>
Sent: Wednesday, 9 October 2019 3:50 PM
To: Shiau Chan (LKKAUTO)
Subject: RE: OUR REF; SNM19D204328-GBJ5805K-CML - Pre Repair Inspection

GBJ5805K

Chong Boon Sen

Claims Executive
Department

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #16-00 Springleaf Tower Singapore 079909
DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

W: www.sg.cntaiping.com | **FB:** www.facebook.com/chinataipingsg/ | **WeChat:** 太平獅城 Taiping SG 3 Anson
Road #16-00 Springleaf Tower Singapore 079909
DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

From: Shiau Chan (LKKAUTO) [mailto:siewsc@lkkauto.com]
Sent: Wednesday, October 9, 2019 2:32 PM
To: Chong Boon Sen <boonsen.chong@sg.cntaiping.com>
Subject: FW: OUR REF; SNM19D204328-GBJ5805K-CML - Pre Repair Inspection

Dear Boon Sen,

Kindly assist to confirm the insured vehicle no. is GBJ 5805K or GBJ 8505K.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Shiau Chan (LKKAUTO) <siewsc@lkkauto.com>
Sent: Monday, 7 October 2019 4:54 PM
To: 'Elaine Cheong' <elaine.cheong@sg.cntaiping.com>; assignments <assignments@lkkauto.com>
Cc: 'Claims Dept of CTI' <claimsdept@sg.cntaiping.com>; 'Alfred Toh' <alfred.toh@sg.cntaiping.com>; 'Chee So Chow' <sochow.chee@sg.cntaiping.com>; SUR <sur@lkkauto.com>
Subject: RE: OUR REF; SNM19D204328-GBJ5805K-CML - Pre Repair Inspection

Dear Elaine,

Kindly confirm the insured vehicle no. is GBJ 5805K or GBJ 8505K.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Owner ID Type:	Singapore NRIC
Owner ID:	782E
Vehicle No.:	SJZ9196D
Vehicle to be Exported:	No
Intended Deregistration Date:	24 Sep 2019
Vehicle Make:	VOLKSWAGEN
Vehicle Model:	SCIROCCO 1.4L AT TSI 1372Q5
Primary Colour:	Red
Manufacturing Year:	2010
Engine No.:	CAV235759
Chassis No.:	WVWZZZ13ZBV016344
Maximum Power Output:	118.0 kW (158 bhp)
Open Market Value:	\$24,948.00
Original Registration Date:	05 Jan 2011
First Registration Date:	05 Jan 2011
Transfer Count:	1
Actual ARF Paid:	\$24,948.00
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	04 Jan 2021
PARF Rebate Amount:	\$13,721.00
COE Expiry Date:	04 Jan 2021
COE Category:	A - Car (1600cc & below)
COE Period(Years):	10
QP Paid:	\$33,132.00
COE Rebate Amount:	\$4,239.00
Total Rebate Amount:	\$17,960.00

The information contained herein is correct as at 24 Sep 2019

OK

► Volkswagen Scirocco Used Vehicle List (13 vehicles)

Car Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Company	Availability
Volkswagen Scirocco 1.4A TSI	\$25,000	\$9,030 /yr	26-Jan-2011	1,390 cc	120,000 km	Absolute Wheels Leasing Pte Ltd	Available
Well Maintained, Excellent Condition, Accident Free, Bank And In House Loan Available, Trade In Are Welcome, Powerful Engine And Smooth Transmission, Buy With Confidence! Call Us Now							
Office No. - - Mike - 92269616 Brandon - 97294488							
Volkswagen Scirocco 1.4A TSI	\$28,888	\$10,640 /yr	11-Apr-2011	1,390 cc	-		Available
Particular Owner, No Repair Required, Maintained By Reputable Workshop, Mechatronic Changed 1 Year Ago, Serviced Every 8000km. Please Call For Viewing Today!							
Office No. - - Sim - 98715624							
Volkswagen Scirocco 1.4A TSI Sunroof	\$28,800	\$9,820 /yr	19-Apr-2011	1,390 cc	160,000 km	Top Drive Automobiles LLP	Available
Forge Intake, R8 Ignition Coils, H&R Lowering Springs, Water Pump, Tensioner, Guides, Mountings, Battery Replaced Recently, Car In Excellent Condition! Well Maintained By Meticulous Owner, All Wear An...							
Office No. - - Loh - 88128988 Chew - 88119797							
Volkswagen Scirocco 1.4A TSI	\$29,500	\$10,400 /yr	03-May-2011	1,390 cc	-	Car Empire Automobiles Pte Ltd	Available
Consignment Unit. All Wear And Tear Parts Replaced, Water Pump, Gearbox, ABS Replaced Recently! Comes With Remus Exhaust (With Certification) And Many More Good Stuff, View To Believe! Owner Takes Very...							
Office No. - 69097310 Sean Tan - 90120468 Ben - 88668682 Lucas - 87506761 Soon - 97379527							
Volkswagen Scirocco 1.4A TSI	\$29,800	\$9,640 /yr	07-Jul-2011	1,390 cc	-	38 Karz Station LLP	Available
Well Maintained By Owner, No Repairs Required. Drive With Peace Of Mind! High Trade In And Flexible 100% Loan Available, Consignment Unit. Please Call/SMS Our Sales Consultant For Viewing Appointment.							
Office No. - 69247738 Costa Yeo - 82662662 Tony Lim - 91700981 Javier Chua - 91692347 Clara Loh - 84314321							
Volkswagen Scirocco 1.4A TSI	\$37,688	\$13,770 /yr	14-Jul-2011	1,390 cc	150,000 km	Cars 88 Pte Ltd	Available
Flexi-Loan Available! High Trade In Available. Rare Aspec Bodykit Scirocco! Fully Legal Unit, Just Passed Inspection! New Galaxy Black Paintwork On Rims, New Engine, Gearbox, Waterpump, MU, ABS Module...							
Office No. - - Alex Poh - 92242194 Barry Lee - 82828788							
Volkswagen Scirocco 1.4A TSI	\$31,500	\$10,070 /yr	08-Aug-2011	1,390 cc	139,555 km	Pramie Automobil Pte Ltd	Available
Twin Charged 1.4 Engine! Comes With Quad Exhaust, Stage 1 Custom Tune, 10H Ceramic Glass Coating, New Road Tax! No Repair Needed! 6 Months Warranty! 100% Accident Free, STA Evaluation Welcome! High Tr...							
Office No. - 65709088 / 65709008 Nic - 93559559 Wilson - 98563669							
Volkswagen Scirocco 1.4A TSI	\$33,588	\$10,420 /yr	28-Sep-2011	1,390 cc	121,000 km	Trillions Auto	Available
Selling Near Export Price. High Paper Value. Don't Miss This Best Deal In Town. Best Conditions Assured. Trade-In Welcome. STA/VICOM, Workshop Inspection Anytime Welcome. Bank Loan, In House Finance L...							
Office No. - - EK - 92297878							
Volkswagen Scirocco 1.4A TSI	\$33,888	\$9,870 /yr	10-Nov-2011	1,390 cc	123,199 km	360 VR Cars	Available
A Beautiful 2 Door Car With A Responsive Engine. Genuine Mileage Done. No Leaks Or Wear And Tear. Pristine Condition Of Paintwork. Interior							

With No Wear And Tear. Whatsapp To View Now! By Appointment ...

Office No. - 69310005

Anson - 83121019 | James Tan - 90700005

Volkswagen Scirocco 1.4A TSI	\$34,800	\$10,280 /yr	11-Nov-2011	1,390 cc	-	Dream Selection Pte Ltd	Available
-------------------------------------	-----------------	---------------------	--------------------	-----------------	----------	--------------------------------	------------------

Beautiful Condition. Comes With Keyless Entry And Keyless Start. Loan Available. Call Now.

Office No. - 62422212

Jaslyn - 98823331 | Vincent - 96335503

Volkswagen Scirocco 1.4A TSI Sunroof	\$32,800	\$9,090 /yr	18-Nov-2011	1,390 cc	108,000 km	D&L Auto Trading	Available
---	-----------------	--------------------	--------------------	-----------------	-------------------	-----------------------------	------------------

100% Guaranteed Accident Free, High COE \$56K, Highest Scrap Value \$28.5K, Beautiful Leather Interior, Extremely Well Maintained, All Wear And Tear Replaced, 90% Loan At 2.28%, Guaranteed Loan For Bad ...

Office No. - 62960188

Darren Low - 96236322

Volkswagen Scirocco 1.4A TSI	\$33,800	\$9,560 /yr	01-Dec-2011	1,390 cc	140,000 km	Dream Selection Pte Ltd	Available
-------------------------------------	-----------------	--------------------	--------------------	-----------------	-------------------	--------------------------------	------------------

Beautiful Condition. Comes With Keyless Entry And Keyless Start. High Loan Possible. Call Now.

Office No. - 62422212

Jaslyn - 98823331 | Vincent - 96335503

Volkswagen Scirocco 1.4A TSI	\$34,800	\$9,950 /yr	16-Dec-2011	1,390 cc	-	360 VR Cars	Available
-------------------------------------	-----------------	--------------------	--------------------	-----------------	----------	--------------------	------------------

1 Year Extended Warranty Available! Passed Warranty Check Underwrite By Reputable Liberty Insurance, Sporty White Exterior With Leather Interior, Low Maintenance And Good Fuel Economy, Well Maintained...

Office No. - 69310005

James Tan - 88703005

sgCarMart is the number one car classifieds for parallel import cars, Toyota, Honda, Nissan, Mitsubishi & BMW. There are plenty of cars for sale, even for COE cars, OPC cars, vans, trucks, hybrid cars, sports cars or stationwagons. You can also buy from a car auction, look up car loans, financial services, low mileage cars, car brands, carpark rates & car insurance. We have new car dealers comprising parallel importers, authorised car dealers, and used car dealers on our site. Find new car price lists, new car launches and new car promotions, and also motoring advice, car reviews & car news on the latest models. Visit our partner sites for job openings for Singapore jobs, real estate properties for sale, mover, car performance parts, car discussion, forum discussion, commercial vehicle leasing & COE results.

© 2004-2019 sgCarMart. All rights reserved.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report 12/09/2019 14:01
 Date Of Accident 09/09/2019 16:40
 Exact Location Of Accident KEAT HONG MSCP- LEVEL 2
 Country/State of Loss SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number SJZ9196D
Insured/Policyholder
 Name Of Registered Owner LEE LI MENG
 NRIC No S1200782E
 Email Address DANIELSIM84@HOTMAIL.COM
 Mobile Phone No (LOCAL) +65-83844984
 Alternative Phone No Office-NOPHONE

Vehicle Particulars

Manufacturer VOLKSWAGEN
 Model SCIROCCO-1.4 (A)

Exact Purpose for which vehicle was being used at time of accident PRIVATE USE

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category PRIVATE CAR

Insurance Company

Name of Insurance Company AUTO & GENERAL INSURANCE (SINGAPORE) PTE. LIMITED.
 Type Of Coverage COMPREHENSIVE
 Fleet Policy NO
 Policy Number P10033493R01
 Cover Note Number 05/01/2019 TO 04/01/2020

Driver

Name of Driver DANIEL SIM ZHI WEI
 NRIC No S8410164H
 Date Of Birth 21/03/1984
 Occupation INDOOR
 Date Of Driving Pass 21/05/2009
 Driving Experience 10 YEARS AND 3 MONTHS
 Gender MALE
 Mobile Number (LOCAL) +65-83844984

Fax Number

Contact Number

EMail Address

DANIELSIM84@HOTMAIL.COM

Address

APT BLK 803C KEAT HONG CLOSE #09-114

Postcode

683803

Was driver an employee of the Insured's Company

NO

If No, Relationship of the Driver with the Insured

CHILDREN

Vehicle Registration Number of Driver's Own Vehicle

-
-
-

Insurance Company of Driver's Own Vehicle

-
-
-**General Information of the Accident**

Type Of Accident

COLLISION - MAJOR/MINOR RD

Weather Conditions

CLEAR

Road Surface

DRY

Other Information

Was any foreign vehicle involved in this accident?

NO

Number of vehicles (including own vehicle) involved in the accident

2

Was any body injured in the Accident?

NO

Was any injured conveyed to hospital by ambulance?

NO

Was any other material or property damaged?

YES

I have been approached by unknown person(s) soliciting/offering accident claims assistance.

NO

Number of Passengers (Including Driver)

0

Details of Police Action

Was the accident reported to the police?

NO

If Yes, Please state which Police Station

Was notice of intended Prosecution given?

NO

If Yes, against whom?

Circumstances of Accident

REFER TO SKETCH PLAN

Attachment(s)

Are accident photos available for attachment?

YES

Was there any video captured by Car Camera?

YES

Remarks/ Reasons:

FOOTAGE IS WITH OWNER'S WORKSHOP

Was there any audio recorded?

NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number

GBJ8505K

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category

COMMERCIAL VEHICLE

Name of Driver

NRIC/Passport Number

Contact Number

Address

10/7/2019

E-FILE

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Sketch Plan

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the Information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

GIA/RAAC Standard Form 1000

Date of accident: 09/01/2019 Time: 16:40hrs Location: Keat close
 My Vehicle A: SJZ 9196D Vehicle B: 6BJ 8505K Vehicle C: /
 SKETCH PLAN


Budget Direct

Vehicle: - SJZ
9196D



V.A) SSZ 9196D
V.B) 61838505K

Keat Hong close
carpark.



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On the stated date and time, my vehicle was parked at my house car park. There was no damage and everything was intact. When I went back to collect my vehicle, I noticed there was a note on my windscreen writing: Please call 84181708. I then noticed my vehicle right portion was damaged. I called the number however it's a wrong number. I then check my video footage and notice the company details. I called and they inform that driver will contact me. I received his call and we tried to do a private settlement however he do not agree on my repair cost, hence I proceed to report to my insurance instead. I wish to state that the reason for late reporting was because I couldn't find the driver, and later we tried to private settle however unable to come to a settlement.

☐ Claim OD/TP at Ah Lim Motor ☒ Claim OD/TP at other workshop ☐ Reporting Only

Remarks: Please forward a copy of my efile accident report to:

My workshop: Team Autopro pte Ltd
Email address: Daniel Sim 84 @ hotmail.com
& myself:
Email address: G1areporting@gmail.com

Note: Please take note that your Insurer have 14 days timeframe for you to submit own damage claim under you own policy. Kindly check with your own Insurer for more information.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Vehicle: SSZ 9196D

Policyholder's Signature

Date & Time:

GIARMC SketchPlanForm_V3

Driver's Signature

(If driver is not the policyholder)

Date & Time:

Reporting Centre Person's Signature

Name:

NRIC/FIN No.:



Driver's Particulars

...CLAIM SUBFOLDER...(Pending for Survey Report)
















































CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	23 Sep 2019		23 Sep 2019 15:01 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured: -, Co. Reg. No.: -									
Main Claimant: LEE LI MENG , ID: S1200782E									
Vehicle Reg. No.: SJZ9196D		Date of Loss: 09/09/2019 16:00 - :59 [104 Months and 4 Days From LTA Reg Date (Man Yr)]							
Claim Type: TP / SNM19D204328C02		Policy/Cover Note No.: DMCVSN30401419000							
Vehicle Reg. No. (Insured): GBJ5805K		Policy No. (Claimant): P10033493R01							
		Excess: S\$350.00							
Repairer: Team Autopro Pte Ltd (Sin Ming) 385 Sin Ming Drive, #01-02 Vicom Inspection Centre, 575718 Sin Ming - Tel: 62581955									
Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Elaine Cheong]									
Claimant's Insurer: Auto & General Insurance (Singapore) Pte. Limited. (HQ) - Tel: 6540 2180									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Final Rpt due 02/10/2019]									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SJZ9196D (SNM19D204328C02)
[GBJ5805K]
TP
LEE LI MENG
Sep 9 2019 4:00PM
[-]
Team Autopro Pte Ltd

Upload Documents		Upload Photos	Compose New Letter	View View in Browser	
Assessment Reports				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Ah Lim Motor Company (Sin Ming)		Thumbnail	Print
1	12/09/19 14:17	Accident Statement		Load HTM	
2	23/09/19 09:33	Addendum Sheet		Load TIF	
3	23/09/19 11:13	Accident Statement Addm. #1		Load HTM	
Photos/Images				3 per page	<input checked="" type="checkbox"/>
No	Finalized On	Ah Lim Motor Company (Sin Ming)		Thumbnail	Print
1	12/09/19 14:13	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>
2	12/09/19 14:13	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>
3	12/09/19 14:13	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>
4	12/09/19 14:13	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>
5	12/09/19 14:13	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>
6	12/09/19 14:13	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>
7	12/09/19 14:13	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>
8	12/09/19 14:13	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>
9	12/09/19 14:13	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>
10	12/09/19 14:13	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>
11	12/09/19 14:13	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	07/10/19 12:44	General View		Load JPG	<input checked="" type="checkbox"/>
2	07/10/19 12:44	General View		Load JPG	<input checked="" type="checkbox"/>
3	07/10/19 12:44	General View		Load JPG	<input checked="" type="checkbox"/>
4	07/10/19 12:44	General View		Load JPG	<input checked="" type="checkbox"/>
5	07/10/19 12:44	General View		Load JPG	<input checked="" type="checkbox"/>
6	07/10/19 12:44	General View		Load JPG	<input checked="" type="checkbox"/>
7	07/10/19 12:44	General View		Load JPG	<input checked="" type="checkbox"/>
8	07/10/19 12:44	General View		Load JPG	<input checked="" type="checkbox"/>
9	07/10/19 12:44	General View		Load JPG	<input checked="" type="checkbox"/>
10	07/10/19 12:44	General View		Load JPG	<input checked="" type="checkbox"/>
11	07/10/19 12:44	General View		Load JPG	<input checked="" type="checkbox"/>
12	07/10/19 12:44	General View		Load JPG	<input checked="" type="checkbox"/>
13	07/10/19 12:44	General View		Load JPG	<input checked="" type="checkbox"/>
14	07/10/19 12:44	General View		Load JPG	<input checked="" type="checkbox"/>
15	07/10/19 12:44	General View		Load JPG	<input checked="" type="checkbox"/>
16	07/10/19 12:44	General View		Load JPG	<input checked="" type="checkbox"/>
17	07/10/19 12:44	General View		Load JPG	<input checked="" type="checkbox"/>
18	07/10/19 12:44	General View		Load JPG	<input checked="" type="checkbox"/>
19	07/10/19 12:44	General View		Load JPG	<input checked="" type="checkbox"/>
20	07/10/19 12:44	General View		Load JPG	<input checked="" type="checkbox"/>
21	07/10/19 12:44	General View		Load JPG	<input checked="" type="checkbox"/>
22	07/10/19 12:44	General View		Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Ah Lim Motor Company (Sin Ming)	Thumbnail	Print
23	07/10/19 12:44	General View	 Load JPG	<input checked="" type="checkbox"/>
24	07/10/19 12:44	General View	 Load JPG	<input checked="" type="checkbox"/>
25	07/10/19 12:44	General View	 Load JPG	<input checked="" type="checkbox"/>
26	07/10/19 12:44	General View	 Load JPG	<input checked="" type="checkbox"/>
27	07/10/19 12:44	General View	 Load JPG	<input checked="" type="checkbox"/>
28	07/10/19 12:44	General View	 Load JPG	<input checked="" type="checkbox"/>
29	07/10/19 12:44	General View	 Load JPG	<input checked="" type="checkbox"/>
30	07/10/19 12:44	General View	 Load JPG	<input checked="" type="checkbox"/>
31	07/10/19 12:44	General View	 Load JPG	<input checked="" type="checkbox"/>
32	07/10/19 12:44	General View	 Load JPG	<input checked="" type="checkbox"/>
33	07/10/19 12:44	General View	 Load JPG	<input checked="" type="checkbox"/>
34	07/10/19 12:44	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
35	07/10/19 12:44	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
36	07/10/19 12:44	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
37	07/10/19 12:44	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
38	07/10/19 12:44	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
39	07/10/19 12:44	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
40	07/10/19 12:44	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
41	07/10/19 12:44	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
42	07/10/19 12:44	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
43	07/10/19 12:44	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
44	07/10/19 12:44	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
45	07/10/19 12:44	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
46	07/10/19 12:44	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
47	07/10/19 12:44	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
48	07/10/19 12:44	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
49	07/10/19 12:44	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
50	07/10/19 12:44	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
51	07/10/19 12:44	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
52	07/10/19 12:44	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
53	07/10/19 12:44	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
54	07/10/19 12:44	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
55	07/10/19 12:44	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
56	07/10/19 12:44	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
57	07/10/19 12:44	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
58	07/10/19 12:44	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
59	07/10/19 12:50	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
60	07/10/19 12:50	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
61	07/10/19 12:50	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
62	07/10/19 12:50	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
63	07/10/19 12:50	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
64	07/10/19 12:50	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
65	07/10/19 12:50	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
66	07/10/19 12:50	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	23/09/19 15:01	PRS - SJZ9196D	 Load PDF	
No	Finalized On	Ah Lim Motor Company (Sin Ming)	Thumbnail	Print
1	12/09/19 14:14	Driver's Particulars [Linked Accident Report Documents]	 Load TIF	
2	23/09/19 09:33	Sketch Plan [Linked Accident Report Documents]	 Load TIF	

Linked Accident Report Documents

View

Assessment Reports				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Ah Lim Motor Company (Sin Ming)		Thumbnail	Print
1	12/09/19 14:17	Accident Statement		Load HTM	
2	23/09/19 09:33	Addendum Sheet		Load TIF	
3	23/09/19 11:13	Accident Statement Addm. #1		Load HTM	
Photos/Images				3 per page	<input checked="" type="checkbox"/>
No	Finalized On	Ah Lim Motor Company (Sin Ming)		Thumbnail	Print
1	12/09/19 14:13	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
2	12/09/19 14:13	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
3	12/09/19 14:13	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
4	12/09/19 14:13	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
5	12/09/19 14:13	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
6	12/09/19 14:13	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
7	12/09/19 14:13	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
8	12/09/19 14:13	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
9	12/09/19 14:13	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
10	12/09/19 14:13	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
11	12/09/19 14:13	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
Documentation				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Ah Lim Motor Company (Sin Ming)		Thumbnail	Print
1	12/09/19 14:14	Driver's Particulars		Load TIF	
2	23/09/19 09:33	Sketch Plan		Load TIF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/CTI19016744/GQF3E2

Date: 10/10/2019

REFERENCE

Handling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMCVSN30401419000

Claimant
Vehicle No : SJZ9196DInsured
Vehicle No : GBJ5805K

Date of Loss: 09/09/2019

Nature of Claim: TP

Claim
No: SNM19D204328C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SJZ9196D**

Make & Model: VOLKSWAGEN SCIROCCO, 1.4 (A)

Engine No: CAV235759

Reg. Date: 05/01/2011 (Man. Year: 2010)

Chassis No: WWWZZZ13ZBV016344

Colour: Red

Odometer: 188104 km

Engine Capacity: 1390 cc

Market Value/New Car

Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	245/35Z R19	Rear Tyre Size:	245/35Z R19
Front Left Side:	Firenza 5 mm	Rear Left Side:	Firenza 5 mm
Front Right Side:	Firenza 5 mm	Rear Right Side:	Firenza 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 23/09/2019

Date Inspected: 24/09/2019 Inspected At:

Team Autopro Pte Ltd (Sin Ming)
385 Sin Ming Drive, #01-02 Vicom
Inspection Centre
Singapore 575718

Estimated Period of Repair: 5.0 days

Adjuster: XING GUO QIANG

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$2,000.00 - \$3,000.00

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 10 Oct 2019)
Parts:	M1-COUPE	VOLKSWAGEN SCIROCCO 1.4 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJZ9196D)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >