

NATIONAL Assessment Centre Services

(wef 1 Jan 2005)

NA 1907316

Date In: 23/9/15-15	Job description	Date & Time Completed	Done by
Ref No: NA 1907316/424	SAS e-filing		
Veh No: 6061552L	E-mail (within 3hrs, AIC 2hrs)		
D.O.A: 23/9/15-11:25	i-Motor Claim Form	NA 1907316-001	23/9/15 16:00
OD / TP / Reporting Only	i-Motor W/O (Within: OD 2hrs, TP 4hrs)		
	i-Photo Uploaded		
TP Insurer:	Assessment/Survey Report		
	Ass't Report by Fax / Hand to Owner/Wksp		

Preferred Wksp / INC Assign Wksp / QW: (

Tel:

Fax:

TP Particulars:

Veh No: 6061552L

INC () / Non-INC ()

Owner / Driver: (

Tel:

Policy No: (

Period: (

Cover Type: (

Confirmed by: (

Date:

Time:

Insured/Driver Liability: () % [Note-Est. Status (WO): N: 0-20%; P: 21-79% P: 80-100%]

Year of Registration: () Warranty: YES () / NO ()

Excess: (\$) Loading: \$1,000 () / \$2,000 ()

General Remarks:

() Walk-In Customer: Customer's information strictly Confidential & Strictly NO refer of repairer.

() Total Loss Case: to e-mail Insurer URGENTLY.

Drive-In () / Towed-In () ; Invoice: YES () / NO () ; Towing Co: ()

Remarks: (INC hotline: 6788 6616)

Date & Time Completed

Done by

1) Apply for Transport Allowance () / Courtesy Car ()

2) QC Check / Post Repair Inspection ()

3) Upload Resurvey Photo [Repair Cost > \$3000] ()

Injury:

Date/Time

Actions

Invoice Preparation Checklist

Am't (\$)

Am't (\$)

Est. Bill

Add. Bill

Claimant's Particulars:

Driver/Owner:

Contact No:

Damaged Portion:

QC Checked by (Engr-In-Charge):

Auditors' Comments:

Ref. 1:

Ref. 2 / 3:

1) AR: Accident Reporting (\$30);

2) DA: Damage Assessment (\$100); INC (\$80)

3) TF: Towing Fee \$40/\$45

4) FT: Follow-Through Survey \$120

5) FT: Follow-Through Survey (Resurvey) \$30

For claiming against INC Only (wef 10 Jan 2005)

6) TR: Re-inspection \$75

7) N1: Idac DA + SMRT Survey \$160

8) NTUC Additional Services:-

OD*

*N5: Courtesy Car / Tpt Allowance \$5

*N6: Repair Co-ordination \$10

*N7: Post Repair Inspection \$25

*N8: DV / Collect Excess Coordination \$5

TP (N11): TP (N-in INC) against INC \$20

9) N12: Idac Mobile 30

Invoice dated

Fee Charged

Invoice dated

Fee Charged

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	23/09/2019 15:29
Date Of Accident	23/09/2019 11:25
Exact Location Of Accident	BLK 3017 BEDOK NORTH ST 5 CARPARK
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	GBG1585L
Insured/Policyholder	
Name Of Registered Owner	RAILWAY OLD COFFEE FOOD POINT (PTE) LTD
Co Reg No	201127893C
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-91798765
Alternative Phone No	OFFICE-91798765

Vehicle Particulars

Manufacturer	NISSAN
Model	NV200 1.5 MT ABS AIRBAG 2WD 6DR E5 W/RC
Exact Purpose for which vehicle was being used at time of accident	WORKING
Are you claiming under your own insurance policy for repair to your vehicle?	YES
If No, Please state action to be taken	

Vehicle Category	COMMERCIAL VEHICLE
------------------	--------------------

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5091928947-02
Cover Note Number	

Driver

Name of Driver	TAN HONG SOON
NRIC No	S1430502E
Date Of Birth	18/10/1960
Occupation	OUTDOOR
Date Of Driving Pass	01/02/2017
Driving Experience	2 YEARS AND 7 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-91798765
Fax Number	
Contact Number	OFFICE-91798765
EMail Address	NOEMAIL

Address	BLK 299B COMPASSVALE STREET #13-100
Postcode	542299
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - MAJOR/MINOR RD
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

ON STATED DATE AND TIME, AS I WANTED TO EXIT FROM GANTRY OF BLK 3007 BEDOK NORTH ST 5 MULTISTORY CARPARK, I CHECK MY BLINDSPOT AND TURN ON MY VEHICLE INDICATOR BEFORE I CAN PROCEED. WHERE THERE WAS NO ONCOMING VEHICLES ON BOTH DIRECTIONS. I PROCEED TO TURN RIGHT. SUDDENLY I FELT AN IMPACT OF MY VEHICLE AND REALIZED THAT VEHICLE B WAS TRVELLING ALONG MAJOR ROAD AND HIT ONTO MY VEHICLE FRONT PORTION. AFTER AN IMPACT, MY VEHICLE ROLLED BACK A LITTLE AND MY VEHICLE REAR HEADLAMP HIT ONTO PROPERTY.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GBB9553C <i>Toyota Ayas Mori mt</i>
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	MD TAHA BIN JUMAHAT
NRIC/Passport Number	S6808434B
Contact Number	
Address	
Postcode	
Insurance Company Name	

Nature Of Damage

No. Of Passenger (Including Driver)

1

SKETCH PLAN

IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "**Personal Information**") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "**Insurers**"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "**Purposes**")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

SKETCH PLAN

Blk 3017 Bedok North St 5 carpark.

A= G06K885L
B= G15B9553C

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Refer to Statement.

DECLARATION

I/We declare the foregoing particulars are true in every respect.



Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

eBaoTech

GeneralClaim

Hello, NAC_PAYA_UBI_800601

[Change Language](#)[Change Password](#)[Log Out](#)[My Desktop](#)[Notice of Loss](#)

Policy Query

Policy No. Date of Accident

Vehicle No.(For Motor) Certificate Number

Select	Policy No.	Certificate Number	Policyholder Name	Policyholder NRIC	Product	Cover Type	Vehicle No.	Insured Object	Commence Date	Expiry Date
☐	5091928947-02		RAILWAY OLD COFFEE FOOD POINT (PTE.) LTD.	201127893C	GCV	Comprehensive	GBG1585L	GBG1585L	15/06/2019	14/06/2020

 Policy Information

Policy No.	5091928947-02	Policyholder Name	RAILWAY OLD COFFEE FOOD PC	Policyholder NRIC	201127893C
Certificate No.					
Address	1 KAKI BUKIT VIEW #01-01A TECHVIEW SINGAPORE 415941				
Product Name	COMMERCIAL VEHICLE INSURAI Plan	Group Policy Flag	N		
Policy Issue Date	07/06/2019	Effective Date	15/06/2019 00:00	Expiry Date	14/06/2020 23:59
Excess Type	Per Accident	All Claims Excess			
Third Party Excess	0	Own damage Excess	600	Windscreen Excess	100
Additional Excess		OS Premium	0		
Outside Singapore OD Excess		Outside Singapore TP Excess		Young/Inexperience Driver Excess	
Agent	KINETIC INSURANCE AGENCY	Agent Tel.	66946128	GST Flag	Y
Co-insurance Flag	No				
Open Policy Info					
Certificate Info					

 Policyholder Mailing Address

Address 1	1 KAKI BUKIT VIEW	Address 2	#01-01A TECHVIEW	Address 3	SINGAPORE 415941
Address 4		Address Type	Singapore address	Post Code	415941
Unit No.	01-01A	Related Policy Number	5091928947-02		

 Insured Object: GBG1585L

 Endorsements

Sequence	Date of Endorsement	Endorsement Type	Endorsement Status	Endorsement Content
Continue Cancel				

Claim Handling

Accident MT/1063606

Policy No.	5091928947-02	Vehicle No.	GBG1585L	GST Registration No.	
Certificate No.					
Policyholder Name	RAILWAY OLD COFFEE FOOD POINT (PTE.) LTD.			Policyholder NRIC	201127893C
Product Code	COMMERCIAL VEHICLE INSURANCE	Cover Type	Comprehensive	Loading	0
Contact No.(Mobile)	91798765	Contact No.(Office)	0	Contact No.(Home)	0
Email Address		Special Remark		eCode	
KPK	☒ No ☐ Yes	TCA	☒ No ☐ Yes	eCode Reason	
NCD Protection	No	NCD Entitlement(%)	15	Private Hire	No

Accident Details

Report Date	23/09/2019 15:58	Accident Report Within 24 hrs	Yes	Accident Type	Collision - Major Minor Road
Date of Accident	23/09/2019	Time of Accident hh:mm	11:25	Country of Accident	Singapore
Reporting Centre		Orange Force		ICM No.	
Accident Location	BLK 3017 BEDOK NORTH ST 5 CARPARK				

Total Excess Applicable

Excess Type	Per Accident	Windscreen Excess	100.00	
OD Standard Excess	600.00	TP Standard Excess	0.00	
YIED OD Excess	0.00	YIED TP Excess		Driver is Covered?
Additional Excess				
Total OD Excess Applicable	600.00	Total TP Excess Applicable		

Benefits

GST Registered Information

GST Registered	No	GST Registration Date	
GST Registration No.		GST Status Verified	Yes
Modification History	23/09/2019 16:00:34 System changed GST Status Verified from No to Yes		

Policyholder Mailing Address

Address 1	1 KAKI BUKIT VIEW	Address 2	#01-01A TECHVIEW	Address 3	SINGAPORE 415941
Address 4		Address Type	Singapore address	Post Code	415941
Unit No.	01-01A	Related Policy Number	5091928947-02		

OI Driver Info

Driver Name	Unnamed Driver	Driver Type	Unnamed Driver	Driver DOB	18/10/1960
Unnamed driver Name	TAN HONG SOON	Driver NRIC	S1430502E	Driving Experience	2
Register Date of Driver License	01/02/2017	Driver Age	58	Contact No.(Home)	0
Contact No.(Mobile)	91798765	Contact No.(Office)	0	Address 3	COMPASSVALE GREEN
Address 1	BLK 299B	Address 2	COMPASSVALE STREET	Post Code	542299
Address 4	SINGAPORE 542299	Address Type	Singapore address		
Unit No.	13-100				
Does he own a Singapore Registered car?	☐ Yes ☒ No	Driver Vehicle No.		Driver Insurer Company	

Declaration

Breathalyser or Blood Test Reading?	0 mg	Any injury?	☐ Yes ☒ No
-------------------------------------	------	-------------	---

Modification History

Claim 001 **New**

Claim Type *	OD-MD	Insured Name	RAILWAY OLD COFFEE FOOD PC	Insured NRIC	201127893C	
Contact No.(Mobile)		Contact No.(Home)	NIL	Contact No.(Office)	NIL	
Email Address		OT Vehicle Number	GBG1585L	TP Vehicle Number	GBB9553C	
Claimant Type Claimant Type *	Please Select	Type of Benefit *	Please Select			
Claimant Name *		Claimant NRIC *				
Claimant Address						
Claim Description	GBG1585L / GBB9553C ON 23 Sept 2019				Name of Preferred Workshop	STK AUTO (S) PTE LTD
Preferred Workshop Contact No.	63860669	Insured Liability *	Fully at Fault			
Require Finalisation	Yes	Preferred Repair Option	Preferred Workshop (refer below)	GIA report	Received	
Date Registered	23/09/2019 16:02	Claim Close Date		Date Received	23/09/2019 00:00	
Report Taken By	Jackson			OD Excess Collected by Workshop		

☒ Print AK letter

Save Submit

Attachment

Accident No.	MT/1063606	Claim No.	001
Last Doc. Received	☒ Yes ☐ No	Upload Date	23/09/2019 16:04

Path *	Category *	Confidential	Urgency *	Description *
Browse... Clear	Please Select	NO	Normal	
Browse... Clear	Please Select	NO	Normal	
Browse... Clear	Please Select	NO	Normal	
Browse... Clear	Please Select	NO	Normal	
Browse... Clear	Please Select	NO	Normal	
Browse... Clear	Please Select	NO	Normal	

☐ Send Message

Attachment List						
Attachment	Uploaded By/Date	Category	Urgency	Description	Msg Sent? (CO)	
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICE) on 23 Sep 2019 16:04	NRIC/ Driving License	Y	NRIC/ Driving License 2019-9-23		
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICE) on 23 Sep 2019 16:04	SAS	Normal	SAS 2019-9-23		
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICE) on 23 Sep 2019 16:03	Photos	Normal	Photos 2019-9-23		
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICE) on 23 Sep 2019 16:03	Photos	Normal	Photos 2019-9-23		
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICE) on 23 Sep 2019 16:03	Photos	Normal	Photos 2019-9-23		
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICE) on 23 Sep 2019 16:03	Photos	Normal	Photos 2019-9-23		
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICE) on 23 Sep 2019 16:03	Photos	Normal	Photos 2019-9-23		
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICE) on 23 Sep 2019 16:02	Photos	Normal	Photos 2019-9-23		
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICE) on 23 Sep 2019 16:02	Photos	Normal	Photos 2019-9-23		
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICE) on 23 Sep 2019 16:02	Photos	Normal	Photos 2019-9-23		
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICE) on 23 Sep 2019 16:02	Photos	Normal	Photos 2019-9-23		
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICE) on 23 Sep 2019 16:02	Photos	Normal	Photos 2019-9-23		
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICE) on 23 Sep 2019 16:02	Photos	Normal	Photos 2019-9-23		
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICE) on 23 Sep 2019 16:02	Photos	Normal	Photos 2019-9-23		
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICE) on 23 Sep 2019 16:02	Photos	Normal	Photos 2019-9-23		
Video List						
Uploaded By/Date	Folder Date	File Name		Source	Actor	
Display in New Window Scan and uploading						

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	893C
Vehicle Details	
Vehicle No.:	GBG1585L
Vehicle to be Exported:	No
Intended Deregistration Date:	26 Sep 2019
Vehicle Make:	NISSAN
Vehicle Model:	NV200 1.5 MT ABS AIRBAG 2WD 6DR E5 W/RC
Primary Colour:	Black
Manufacturing Year:	2017
Engine No.:	K9KC400D057129
Chassis No.:	VSKYBAM20Z0145252
Maximum Power Output:	-
Open Market Value:	\$20,119.00
Original Registration Date:	15 Jun 2017
First Registration Date:	15 Jun 2017
Transfer Count:	0
Actual ARF Paid:	\$1,006.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	14 Jun 2027
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
QP Paid:	\$38,501.00
COE Rebate Amount:	\$29,718.00
Total Rebate Amount:	\$29,718.00

The information contained herein is correct as at 23 Sep 2019

DOA = 23/9/19

MV - 46500

PV - 29718

NV - 16700

#

MV - 45 - 46 1/2

OK

Balance → 7 year 9 months

depreciation 6000

6000 ÷ 12 = 500 month

42000 + 4500 +

= 46500

Enquire Vehicle Transfer Fee

Vehicle Details

Vehicle No.

GBG1585L

Make / Model

NISSAN / NV200 1.5 MT ABS AIRBAG 2WD 6DR E5 W/RC

Vehicle Type :

A50 - Goods (Closed) Van/Van Panel (Delivery)

Vehicle Attachment 1 :

No Attachment

Vehicle Scheme :

Normal

Chassis No. :

VSKYBAM20Z0145252

Propellant :

Diesel

Engine No. :

K9KC400D057129

Motor No. :

-

Engine Capacity :

1461 cc

Power Rating :

-

imum Power Output :



Maximum Laden Weight :

2000 kg

Unladen Weight :

1260 kg

Year Of Manufacture :

2017

Original Registration Date :

15 Jun 2017

Lifespan Expiry Date :

14 Jun 2037

COE Category :

C - Goods Vehicle & Bus

Quota Premium :

\$38,501.00

COE Expiry Date :

14 Jun 2027

Road Tax Expiry Date :

14 Jun 2020

PARF Eligibility Expiry Date :

-

Inspection Due Date :

14 Jun 2020

Intended Transfer Date :

24 Sep 2019

CO2 Emission :

138.00 (g/km)

CEV/VES Rebate Utilised Amount :

-

CO Emission :

-

HC Emission :

-

NOx Emission :



mission :



CONNECTING CAR BUYERS & SELLERS.

We'll handle your loans, insurance & other paperwork for FREE.

[Find out more](#)


Nissan NV200

Price Range ▾

Depreciation ▾

2017 ▾

Vehicle Type ▾


[Advanced Search](#)
[Home](#) » [Used Cars](#) » [Direct Owners](#) » Nissan NV200 1.5M

Nissan NV200 1.5M

[Overview](#)
[Financial](#)
[Accessories](#)
[Similar](#)
[Research](#)
[Photos](#)
[Map](#)
DIRECT OWNER

Price	\$51,800	Lifespan	30-May-2037
Depreciation ⓘ	\$6,740 /yr View models with similar depre	Reg Date	31-May-2017 (7yrs 8mths 6days COE left)
Mileage	34,500 km (14.9k /yr)	Manufactured ⓘ	2016
Road Tax ⓘ	N.A.	Transmission	Manual
Dereg Value ⓘ	\$23,516 as of today (change)	OMV ⓘ	\$20,122
COE ⓘ	\$30,600	ARF ⓘ	\$1,007
Engine Cap	1,461 cc	No. of Owners ⓘ	1
Curb Weight ⓘ	1,260 kg		
Type of Vehicle	Van		



Features

MT, ABS, Airbag, ZWD, 6 Dr E5 With Reverse Camera. View specs of the Nissan NV200 (2011)

Accessories

Reverse Sensors, Power Window, Sufficient Storage Space, Bottle Holders, Remote Control Key, Etc.

Description

Only Deal With Direct Owner, Careful Driver, Accident Free, Regular Service, Behind, Carpeted And 2 Ventilated Fans. Warranty, 3 Years Plus 2 Years Or 140,000 Km Whichever Comes First.

Category

Direct Owner Sale

Status

Available

Resources



Car Valuation - Free

Find out the market value of your existing car for free. Get started



Vehicle Evaluation

Afraid of lemons? Request to have this car evaluated professionally. Find out more


Posted on: 05-Aug-2019 | Last Updated on: 20-Sep-2019

Upfront Payment


[» more Financial info](#)

Transfer Fee ⓘ	\$25	
Down Payment ⓘ	\$5,180 (change)	Maximum 90% Loan
1st Instalment ⓘ	\$687	Based on 3.4% interest rate
Insura	You'll also need a valid car insurance to drive this vehicle. 18% off with code CAR18	
Compare		

Powered by



Price Chart



Click on the point to view the vehicle

[Shortlist](#)
[Compare](#)
[Add note](#)
[Report Error](#)
[More Actions](#)

Seller Information

Contact Person(s)	Ben Ho
Contact No.	91891899
Enquiry	Contact Seller

ESSENTIAL TRANSACTION FORMS

- » Indemnity form
- » Sales agreement
- » Receipt
- » Hand-over form
- » Ownership Transfer



GET HELP WITH
PAPERWORK



sgCarMart Connect handles your transaction paperwork - send us your completed Sales Agreement,

ASS. REC. BY: H. ANN

REF:

NTUC → own

Assessor:

Mobile: YES / NO

ASSIGNMENT (IDAC)

COE Expiry = 14/06/2027

By CSO- Nature of Accident:

- | | |
|--------------------------------------|-----------------------------|
| 1) Vehicle hit Vehicle: | 2) Vehicle hit ?? |
| a) Motorcar () | a) Pedestrian () |
| b) M/cycle () | b) Animal () |
| c) Bicycle () | |
| 3) Vehicle hit Road Side Objects: | |
| a) Govn. Property () | b) Road Work Object () |
| (Eg: signboard, barrier, tree etc) | c) Private Property () |
| 4) Vehicle drop into drain () | |
| 5) Damage due to Act of God: | |
| a) Fallen Object () | b) Flood () |
| c) Other, _____ | |
| 6) Parked & Found Damaged: | |
| a) Vandalism () | b) Hit by Moving Object () |
| 7) Theft Case | |
| a) Stolen () | b) Damage found () |
| | when recovered. |
| 8) Fire | |
| a) Whilst driving () | b) Parked () |
| 9) Accident date more than 24hrs () | |

Remarks for internal information

Remarks to appear in Works Order & Assessment report

- | |
|-----------------------------|
| 1) Potential Total Loss () |
| 2) SRS Light on () |
| 3) ABS Light on () |

By Assessor- 1) Vehicle Information

Veh No: GBG 1585L Yr Regn: 15/06/2017
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / MPV
 / Truck / Trailer or _____
 Make & Model: NISSAN NU200 1.5MT C.C. 1461
 Colour: Black Transmission Type: Auto / Manual
 Eng/No: _____ Sp. Reading: 43025 km
 C/No: JSKYBAM 2070145252
 Gen. Cond: Good / Fair / Poor / Burnt or _____
 Steering: Inorder / Jammed / Leaked / Burnt or _____
 Brake: Inorder / Jammed / Leaked / Burnt or _____
 Modi: Nil / S/Rim / STD A/Rim or _____
 Tyre Size: F: 175/70/R14C
 R: 175/70/R14C
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or _____
 Front: Good Rear: Good
 R/Bal. 5 mm R/Bal. 5 mm
 U/Bal. 5 mm U/Bal. 5 mm
 Parallel Import: Yes / No Towed-In: Yes / No
 Repair Type: LS / I.B.I Towing Required: Yes / No
 No of Repair Days: 11 day Vehicle in Idac: Yes / No
 D.O.I. 24/9/17 Time: 5:15 pm

By Assessor- 2) Comments

- Damages not due to recent accident.
- Damages do not seem hit onto:

a. Vehicle ()	b. Motorcycle ()	c. Bicycle ()	d. Pedestrian ()
e. Animal ()	f. Govn Object ()	g. Road Work Object ()	
h. Private Property ()	i. Drain ()	j. Road Kerb/Grass Verge ()	
- Vehicle does not seem damaged as a result of:

a. Fallen Object ()	b. Flood ()	c. Vandalism ()	d. Fire ()
e. Moving Object ()	f. Stolen ()	g. Stolen & Recovered ()	

Time Started:

Time completed:

1) CSO

2) ASS

3) Entire Operation Completed Time:

(0)Item (1)Accepted (2)Rejected (3)Noticed (4)Can (5)Satisfied
(6)Satisfied (6)Satisfied (6)Satisfied (6)Satisfied (6)Satisfied
(6)Satisfied (6)Satisfied (6)Satisfied (6)Satisfied (6)Satisfied
(6)Satisfied (6)Satisfied (6)Satisfied (6)Satisfied (6)Satisfied

ACTION PLAN

(i) $P_{\text{equil}}(V) = P_{\text{equil}}(V_0) = P_{\text{ext}}(V_0)$
(ii) $k_B T_{\text{equil}} = k_B T_0$

Appendix

Vehicle No: _____

GBG 1585 L

Vehicle No: 4B6713852				
NAC	INC	Item	CON	AC Qty
2062	993748	Rear Sidegate		
2063	994225	Rear Sidegate Lock		
2064	993749	Rear Sidegate Hinge		
2065	994226	Sidegate Lower Panel		
2066	994227	Sidegate Railing		
2067	994208	Side Cover Hook		
2068	991965	Side Step Panel		
2069	994496	Side Step Panel Stopper		
2070	992857	Rear Body Panel		
2071	992866	Rear Body Panel Inner		
2072	995329	Sliding Door LH		
2073	995328	Sliding Door RH		
2074	994295	Sliding Door Handle		
2075	994300	Sliding Door Lock		
2076	994313	Sliding Door Rubber		
2077	994291	Sliding Door Bottom Roller		
2078	994317	Sliding Door Top Roller		
2079	994306	Sliding Door Rail		
2080	994315	Sliding Door Stepboard		
2081	994316	Sliding Door Stepboard Garnish		
1224	993621	Rear LH Mudflap		
1225	993933	Rear LH Wheel Rim		
1226	994025	Rear LH Rim Cover		
1227	995065	Rear LH Tyre		
1234	993622	Rear RH Mudflap		
1235	993934	Rear RH Wheel Rim		
1236	994025	Rear RH Rim Cover		
1237	995065	Rear RH Tyre		
1252	992179	Fuel Tank		
1253	992184	Fuel Tank Bracket		
1186	990247	Sticker		
		tailgate sticker 70km/hance	✓	1
		Rear Fender 4114	AT ✓	1
		Front supt panel lower		
		Air Guide 4114 RH		2 245

(See end of text)

Assessor:

Claim Handling

Task Transfer Exit

Accident MT/1063606

LOS SAL SUB

Policy No.	5091928947-02	Vehicle No.	GBG1585L	GST Registration No.	
Certificate No.					
Policyholder Name	RAILWAY OLD COFFEE FOOD POINT (PTE.) LTD.			Policyholder NRIC	201127893C
Product Code	COMMERCIAL VEHICLE INSURANCE	Cover Type	Comprehensive	Loading	0
Contact No.(Mobile)	91798765	Contact No.(Office)	0	Contact No.(Home)	0
Email Address		Special Remark		eCode	1:1
KFK	☒ No ☐ Yes	TCA	☒ No ☐ Yes	eCode Reason	
NCD Protection	No	NCD Entitlement(%)	15	Private Hire	No

Accident Details

Report Date	23/09/2019 15:58	Accident Report Within 24 hrs	Yes	Accident Type	Collision - Major Minor Road
Date of Accident	23/09/2019	Time of Accident hh:mm	11:25	Country of Accident	Singapore
Reporting Centre	NATIONAL ASSESSMENT CENTR	Orange Force	No	ICM No.	
Accident Location	BLK 3017 BEDOK NORTH ST 5 CARPARK				

Total Excess Applicable

Excess Type	Per Accident	Windscreen Excess	100.00		
OD Standard Excess	600.00	TP Standard Excess	0.00		
YIED OD Excess	0.00	YIED TP Excess		Driver is Covered?	
Additional Excess					
Total OD Excess Applicable	600.00	Total TP Excess Applicable			

Benefits

GST Registered Information

GST Registered	No	GST Registration Date	
GST Registration No.		GST Status Verified	Yes
Modification History	23/09/2019 16:00:34 System changed GST Status Verified from No to Yes		

Policyholder Mailing Address

Address 1	1 KAKI BUKIT VIEW	Address 2	#01-01A TECHVIEW	Address 3	SINGAPORE 415941
Address 4		Address Type	Singapore address	Post Code	415941
Unit No.	01-01A	Related Policy Number	5091928947-02		

OT Driver Info

Driver Name	Unnamed Driver	Driver Type	Unnamed Driver		
Unnamed driver Name	TAN HONG SOON	Driver NRIC	S1430502E	Driver DOB	18/10/1960
Register Date of Driver License	01/02/2017	Driver Age	58	Driving Experience	2
Contact No.(Mobile)	91798765	Contact No.(Office)	0	Contact No.(Home)	0
Address 1	BLK 2998	Address 2	COMPASSVALE STREET	Address 3	COMPASSVALE GREEN
Address 4	SINGAPORE 542299	Address Type	Singapore address	Post Code	542299
Unit No.	13-100				
Does he own a Singapore Registered car?	☐ Yes ☒ No	Driver Vehicle No.		Driver Insurer Company	

Declaration

Breathalyser or Blood Test Reading?	0 mg	Any Injury?	☐ Yes ☒ No
Modification History			

Investigation

Claim 001 OD-MD

Claim Case Officer Yap Chae Ling

LOS SAL SUB

Claim Type	OD-MD	Insured Name	RAILWAY OLD COFFEE FOOD PC	Insured NRIC	201127893C
Contact No.(Mobile)		Contact No.(Home)	NIL	Contact No.(Office)	NIL
Email Address		OT Vehicle Number	GBG1585L	TP Vehicle Number	GBB9553C
Claimant Type		Type of Benefit			
Claimant Name		Claimant NRIC			
Claimant Address					
Claim Description	GBG1585L / GBB9553C ON 23 Sept 2019			Name of Preferred Workshop	STK AUTO (S) PTE LTD
Preferred Workshop Contact No.	63860669	Insured Liability	Fully at Fault	GIA report	Received
Require Finalisation	Yes	Preferred Repair Option	Preferred Workshop (refer below)	Date Received	23/09/2019 00:00
Date Registered	23/09/2019 16:05	Claim Close Date		Total Loss but Repaired	
Report Taken By	Jackson	Workshop Repairer		OD Excess Collected by Workshop	
☒ Print AK letter					
Modification History					

Special Claim Creation Approval

Approval	Reason
Remarks	

damage assessment Attachment

Vehicle Info

Vehicle Make	NISSAN	Vehicle Model	NV200	Engine Capacity	0.74
Date of Registration	15/06/2017	Class No.	VSKYBAM2020145252	Parallel Import *	☐ Yes ☒ No
Towing Required *	☒ Yes ☐ No	Vehicle in IDAC *	☒ Yes ☐ No	Survey Current Status	
Type of Tender *	Own Damage	Assessor Name *	HOCK AN		
IDAC/Workshop Name	NATIONAL ASSESSMENT CENTR	IDAC/Workshop Location	51 UBI AVENUE 1 #01-25 PAYA		

Windscreen Parts & Labour
Cost

Total Loss * ☐ Yes ☒ No

Market Value(\$)

Scrap Value(\$)

Economical Repair Value(\$)

Remark:

REMARK:NO OF REPAIR DAY:11 DAYS. 1 X FRT BUMPER TOW COVER - REPLACE. 2 X FRT BUMPER SIDE COVER - REPLACE. 6 X FRT GRILLE CLIPS - REPLACE. 1 X FRT GRILLE CHROME MOULDING - REPLACE. 1 X FRT WIPER TANK - UNCONFORM. 1 X AIR CON LIQUID PIPE - UNCONFORM. 1 X AIR DUCT - REPLACE. 1 X FRT LH FUSE RELAY BOX - REPLACE. 1 X FRT INTER COOLER ASSY - REPLACE. 1 X REAR END PANEL - REPAIR. 1 X REAR LH TAIL LAMP PANEL - REPLACE. 1 X REAR RH TAIL LAMP PANEL - REPAIR. 1 X REAR DOOR COMPANY STICKER - REPLACE. 1 X LH TAILGATE EMBLEM - REPLACE. 1 X TAILGATE LOGO - REPLACE. 2 X FRT SUPPORT PANEL LOWER AIR GUIDE - UNCONFORM.

Remark for Supplementary

Damage Listing

Find a Part	No.	Part No.	Description	Qty *	Repair Code *	
root						
Not Applicable	1	32200101	NUMBER PLATE (FRONT)	1	Replace	X
ABS	2	32200201	NUMBER PLATE BASE (FRONT)	1	Replace	X
ABSORBER	3	16000101	BUMPER (FRONT)	1	Replace	X
ACCELERATOR	4	16002401	BUMPER CLIPS (FRONT)	12	Replace	X
ACTIONATOR	5	16005901	BUMPER SPONGE (FRONT)	1	Replace	X
ADVERTISMENT STICKER	6	16001301	BUMPER BRACKET (FRONT LEFT)	1	Replace	X
AIR BAG	7	16001302	BUMPER BRACKET (FRONT RIGHT)	1	Replace	X
AIR BLOWER	8	16005001	BUMPER REINFORCEMENT (FRONT)	1	Replace	X
AIR BOX	9	16005101	BUMPER RETAINER (FRONT LEFT)	1	Replace	X
AIR CHAMBER BOX	10	16005102	BUMPER RETAINER (FRONT RIGHT)	1	Replace	X
AIR CLEANER	11	16002901	BUMPER FOG LAMP COVER (FRONT LEFT)	1	Replace	X
AIR COMPRESSOR	12	16002902	BUMPER FOG LAMP COVER (FRONT RIGHT)	1	Unconform	X
AIR CON	13	16002701	BUMPER FOG LAMP (FRONT LEFT)	1	Replace	X
AIR CON (VAN)	14	16002702	BUMPER FOG LAMP (FRONT RIGHT)	1	Unconform	X
AIR COOLER	15	27100101	GRILLE (FRONT)	1	Replace	X
AIR DISTRIBUTOR	16	27100801	GRILLE EMBLEM (FRONT)	1	Replace	X
AIR FILTER	17	27700101	HEAD LAMP (LEFT)	1	Replace	X
AIR FLOW	18	27700102	HEAD LAMP (RIGHT)	1	Replace	X
AIR GRILLE	19	27701401	HEAD LAMP PANEL (LEFT)	1	Replace	X
AIR HORN	20	27701402	HEAD LAMP PANEL (RIGHT)	1	Replace	X
AIR INTAKE	21	41300101	SUPPORT PANEL (FRONT)	1	Replace	X
AIR RESONATOR BOX	22	149001	BONNET	1	Replace	X
AIR THROTTLE BODY AND SENSOR	23	14903401	BONNET LOCK (LOWER)	1	Unconform	X
ALARM	24	14902202	BONNET HINGE (RIGHT)	1	Replace	X
ALTERNATOR	25	14902201	BONNET HINGE (LEFT)	1	Replace	X
ALUMINIUM PANEL - SIDE	26	149041	BONNET RUBBER (CENTRE)	1	Replace	X
AMPLIFIER	27	112023	AIR CON CONDENSER	1	Replace	X
ANTENNA	28	344001	RADIATOR	1	Unconform	X
ANTI ROLL	29	344005	RADIATOR COWLING	1	Unconform	X
APRON	30	344007	RADIATOR EXPANSION TANK	1	Unconform	X
ARCH	31	243014	ENGINE LOWER COVER	1	Replace	X
ARM REST	32	19600501	CHASSIS MEMBER (FRONT LEFT)	1	Repair	X
ASH TRAY	33	19600502	CHASSIS MEMBER (FRONT RIGHT)	1	Repair	X
AUTO CLUTCH	34	25400102	FENDER (FRONT LEFT)	1	Repair	X
AUTO COOLER PIPE	35	25400801	FENDER INNER PANEL (FRONT LEFT)	1	Repair	X
AUTO CRUISE MOTOR	36	25400901	FENDER INNER SHIELD (FRONT LEFT)	1	Replace	X
AUTO TRANSMISSION	37	25400103	FENDER (FRONT RIGHT)	1	Repair	X
AXLE	38	25400802	FENDER INNER PANEL (FRONT RIGHT)	1	Repair	X
BACK REST (WC)	39	25400902	FENDER INNER SHIELD (FRONT RIGHT)	1	Replace	X
BACK SEAT	40	26600102	FUSE BOX (CENTRE)	1	Replace	X
BALANCE	41	16000102	BUMPER (REAR)	1	Replace	X
BATTERY	42	16001303	BUMPER BRACKET (REAR LEFT)	1	Replace	X
BEADING (WC)	43	16005103	BUMPER RETAINER (REAR LEFT)	1	Replace	X
BELT COVER (WC)	44	35300101	REVERSE SENSOR (LEFT)	1	Unconform	X
BELT TENSIONER	45	42000101	TAIL LAMP (LEFT)	1	Replace	X
BODY	46	42000102	TAIL LAMP (RIGHT)	1	Replace	X
BODY (WC)	47	23300204	DOOR (REAR RIGHT)	1	Repair	X
BOLT CAP (WC)	48	419001	TAIL GATE	1	Replace	X
BOLT HEAD COVER (WC)	49	419014	TAIL GATE GLASS RUBBER	1	Replace	X
BONNET	50	419013	TAIL GATE GLASS MOULDING	1	Replace	X
BOOT	51	419015	TAIL GATE GLASS SEALANT	1	Replace	X
BOX (WC)	52	41901801	TAIL GATE HINGE (LEFT)	1	Unconform	X
BOX BRACKET (WC)	53	41901802	TAIL GATE HINGE (RIGHT)	1	Unconform	X
BOX CARRIER (WC)	54	419035	TAIL GATE STICKER	1	Replace	X
BOX DOOR	55	25400105	FENDER (REAR LEFT)	1	Replace	X
BOX STICKER (WC)						
BRACE PANEL						
BRAKE						
BRAKE - ABS						
BRAKE (WC)						
BUMPER						
CABIN						
CAMBER						
CAMSHAFT						
CAR ALDIO SYSTEM						
CAR JACK						
CARBURATOR						
CARGO						
CARRIAGE						
CARRIER MOUNTING						
CASTOR						
CATALYTIC CONVERTOR						
CD CHANGER						
CD PLAYER						
CDI UNIT (WC)						
CENTRE BOTTOM						
CENTRE BRACKET						
CENTRE CONSOLE						
CENTRE COWLING (WC)						
CENTRE CROSS MEMBER						
CENTRE EXHAUST						
CENTRE FARING (WC)						

Save Submit

LKK Paya Ubi

From: Tan Siew Choo <siewchoo.tan@income.com.sg>
Sent: Thursday, 26 September 2019 2:28 PM
To: STK STK; NAC
Subject: GBG1585L, OD claim no : MT/1063606

Importance: High

Dear IDAC and STK Auto,

Learnt that veh is in IDAC (IDAC – pls confirm), do assist with the necessary arrangement asap.

Dear STK Auto,

Awarded to your workshop at the agreed COR of \$8,500/- **parts by parts**, with no further supplementary.

Our surveyor will finalise COR upon completion.

OD excess of \$600/- is applicable.

Survey required and you have to arrange personally at mtsurvey@income.com.sg

Kindly update owner on the repair status and the nos of repair days required before repairing veh.

FOR PAYMENT: Please forward the Invoice & Discharge Voucher together within 14 days after the repair has been done/ finalized with Surveyor to my email.

Regards.

Tan Siew Choo
Senior Executive
Motor Insurance
T +65 6430 7882
www.income.com.sg



At Income, we are 'In with You' on Performance, Growth, Innovation and Impact. These attributes reflect what we promise as an employer and what we want our people to exemplify.
Find out more at income.com.sg/careers



Our Ref: MT/CA/OD/051/1063606-001/YCL/TSC

26 Sep 2019

STK AUTO (S) PTE LTD

8 KAKI BUKIT AVENUE 4

#03-21 PREMIER @ KAKI BUKIT

SINGAPORE 415875

Dear Sir

CLAIM NUMBER: MT/1063606-001

REPAIR OF VEHICLE NUMBER: GBG1585L

We are pleased to inform you that you are successful in your tender to repair the vehicle. The details are as follows:

Award Date: 26 Sep 2019

Make: NISSAN

Model: NV200

Estimated Repair Days: 15

Location: NATIONAL ASSESSMENT CENTRE SERVICES

Address: 51 UBI AVENUE 1 #01-25 PAYA UBI INDUSTRIAL PARK SINGAPORE 408933

Benefits Applicable: N/A

Excess Applicable: 600.00

Please note that supplementary items will not be allowed.

If you have any queries, please contact Yap Chee Ling at 64307882 or email us at motor@income.com.sg.

Yours sincerely

Jenny Pe

Deputy Vice President

Motor Insurance

Disclaimer

This e-mail contains privileged or confidential information which is intended only for the use of the recipient(s) named above. If you have received this message in error, please notify the sender immediately and delete all copies of it. Thank you.



NATIONAL ASSESSMENT CENTRE SERVICES
(LKK GROUP)

51 Ubi Ave 1, #01-25, Paya Ubi Industrial Park,
Singapore 408933, TEL: 6841 0055 FAX: 6841 6315



Vehicle Movement Form

Vehicle Check-In

Vehicle No: GBG 1585L Date In: _____ Time In: _____ with Keys: Yes / No

For Office use

Attended by: _____

Workshop Collection of Vehicle

Workshop: STK AUTO CS PTE LTD

Collection Date: 26/09/2019 Time: 14:35 with Keys: Yes / No

Tow Truck No: YP7085D Tow Man: 许金荣 NRIC: G8211821M

Signature: Tan Gaojun

For office use

Attended by: Shan Hui

81237849 / 97872158

Approved by: _____

Workshop Return of Vehicle

Workshop: _____

Returned Date: _____ Time: _____ with Key: Yes / No

* Tow In / Drive In

Tow Man / Workshop Representative: _____ NRIC: _____

Signature: _____

For office use

Attended by: _____

Owner Collection of Vehicle

Collection Date: _____ Time: _____ with Key: Yes / No

Owner: _____ NRIC: _____

Signature: _____

For office use

Attended by: _____

Approved by: _____