

ASS. REC. BY:

REF: CS/MSG/9016758/USf3

n2

Special Instruction:

Salvage/ marcus

ASSIGNMENT (Office)

From (Person): Paulin Tham of MS19 Date/Time: 23.9.19 16:34pm

Estimated Cost: \_\_\_\_\_ Bill to: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SKA 1613 P Insured: SKX 7916E

at Workshop m/s Zoom Autoworks Tel: 94507920

of 130 Bedok Reservoir Road

Policy No: 80452559AT2 Claim No: \_\_\_\_\_

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

Make of Veh: \_\_\_\_\_ D.O.A. 19.9.2019

(Client's Record)

CA / REV / REP. / REV 24 HRS impn H.O.D. Endorsement: \_\_\_\_\_

Date/Time: 23.9.19 4.42pm Person Contacted: Elin Vehicle IN/OUT

Date/Time	Action/Instruction ( ✓ ) Estimate Insp: <u>Bobby Biz #01-53</u>
	<u>SKA 1613 P x</u>
	<u>SKX 7916E x</u>
<u>23/9/19</u>	<u>@ 15:39 pm revert pending estimate from repairer to Pauline via email merimer.</u>

W/merimer

(DB/11/13) wef  
ASS. REC. BY: Marcus

REF:

MS16/

**ASSIGNMENT**

From: \_\_\_\_\_ Date: \_\_\_\_\_  
Estimated Cost: \_\_\_\_\_  
OD / TP / WS / TP RES / OD RES / EVA / INV / MV  
To Inspect Vehicle No: SKA 1613P  
at Workshop m/s: Zoom  
of \_\_\_\_\_  
Insured: \_\_\_\_\_  
Policy No. \_\_\_\_\_  
Claims No. \_\_\_\_\_  
Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_  
(Client's Record)  
Make of Veh: \_\_\_\_\_

Veh No: SKA 1613P Yr Regn: 8.19  
Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /  
Truck / Trailer or CA /  
Make: SKODA superb c.c. 1798  
Colour: Blue A/C: Insured / Std / NI / NA  
Sp. Reading: 1377 T/Radio: Insured / Std / NI / NA  
Eng/No: \_\_\_\_\_  
C/No: TMBBL7NPXK7068825  
Gen. Cond: Good / Fair / Poor / Burnt  
Steering: In order / Jammed / Leaked / Burnt or  
Brake: In order / Jammed / Leaked / Burnt or  
Modi: Nil / S/Rim / STD A/Rim or  
Tyre Size: F: 235/45 2018

N/S	O/S

(Policy Condition)  
Remark: **The veh had commenced its repair at the time of inspection.**

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
TOYO / YOKO or

Bal. or Market Value: \_\_\_\_\_  
IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No  
GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No  
Est. Repairs: 7 days Res.: Yes or No  
Lum Sum: 20 % 3 Val.: Yes or No

Front 6 mm Rear 6 mm  
R/Bal. 6 mm R/Bal. 6 mm  
L/Bal. 6 mm L/Bal. 6 mm  
D.O.A. 19/9/19 D.O.I. 24/9/19

CA / REV / REP. / 24 HRS 739A  
Date: \_\_\_\_\_ Person Contacted: HA 60266  
Vehicle: IN / OUT

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or  
O/S body  
The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
<u>9/10/19</u>	<u>L/S \$8000 confirmed with Elin. (\$12,648.50 Red - 61%)</u>
	<u>10/10/2019</u>

RECEIVED 10 OCT 2019

Date/Time, File Pass to? 10/10/19  
1) Typist  : Preli. Report  
 : Final Report

Days Of Repair: 7  
Resurvey No. of Trip: 2

Date/Time, File Return to? \_\_\_\_\_  
2) \_\_\_\_\_

Add Fee:  : Site Insp (\$ )  
 : Interview (\$ )  
 : Tech. Invs (\$ )  
 : Weekend (\$ )

Survey Fee:	
Transportation:	<u>200</u>
Photos	<u>11</u>
Others	
TOTAL	<u>211</u>

Report Format :  
Lump Sum / I.B.I: (\$ 8,000/- L/S)

### ...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	23 Sep 2019 14:09		23 Sep 2019 16:34 Assign				<b>New Assignment</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	<a href="#">Show All</a>
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS		[Created by insurer]
Insured:	PACKIRISAMY MARIAMMAL, ID: S1356752B	
Main Claimant:	LIAN TENG BOON, ID: S1234739A	
Vehicle Reg. No.:	SKA1613P	Date of Loss: 19/09/2019 21:00 - :59 [13 Months and 25 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP	Policy/Cover Note No.: 80452559AT2 (Comprehensive) Coverage: 29/12/2018 - 28/12/2019
Vehicle Reg. No. (Insured):	SKX7916E	Policy No. (Claimant): Excess:
Repairer:	Zoom Autowerks Pte Ltd (Bedok) 130 Bedok Reservoir Road, #08-1339, 470130 Eunos - Tel:	
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Pauline Tham - 6594 2545]	
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 24/09/2019]	
Driver/Custodian (Insured):	MANIYAM MANOKARAN ( / Male) , NRIC: S0239308E Email:	
Adj Asg. Remarks:	on WP. Liab: unclear. Agree on SJE. Assign: Marcus Chua from LKK Auto Consultants Pte Ltd. Contact: Elin Cai @ 9450 7920.	

ASSOCIATED MAIL RECEIVED	<a href="#">View All</a>	<a href="#">Compose Case Mail</a>
There are no mail for this case.		

ALL ASSOCIATED TASKS										<a href="#">View All</a>	<a href="#">Search Tasks</a>	<a href="#">Create New Task</a>	<a href="#">Complete</a>
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?				
No results.													

## View Sent Message

This mail is associated with :

**\*SKA1613P (606600)  
[SKX7916E]**

TP  
LIAN TENG BOON  
Sep 19 2019 9:00PM  
[PACKIRISAMY MARIAMMAL]  
Zoom Autowerks Pte Ltd

Resend View Recipients Print Message Delete Message Forward

**From** LKK Auto Consultants Pte Ltd (LKK\_HQ), sent on 25/09/2019 15:39 PM.  
**To** pauline\_tham@sg.msg-asia.com  
**CC** sur@lkkauto.com  
**Subject** SKA1613P (606600) [SKX7916E] TP

Dear Pauline,

Please be informed that we have inspected the vehicle SKA 1613P on 24/09/2019.

We are pending estimate from repairer.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

### DOCUMENTS SUMMARY

There are no documents.

> Back to OneMotoring

## Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	739A
Vehicle Details	
Vehicle No.:	SKA1613P
Vehicle to be Exported:	No
Intended Deregistration Date:	25 Sep 2019
Vehicle Make:	SKODA
Vehicle Model:	SUPERB 1.8 TSI (A) NAVI
Primary Colour:	Blue
Manufacturing Year:	2019
Engine No.:	CJS305795
Chassis No.:	TMBBL7NPXK7068895
Maximum Power Output:	132.0 kW (177 bhp)
Open Market Value:	\$26,624.00
Original Registration Date:	29 Aug 2019
First Registration Date:	29 Aug 2019
Transfer Count:	0
Actual ARF Paid:	\$29,274.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	28 Aug 2029
PARF Rebate Amount:	\$21,955.00
Intended COE Rebate Details	
COE Expiry Date:	28 Aug 2029
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$38,602.00
COE Rebate Amount:	\$38,311.00
<b>Total Rebate Amount:</b>	<b>\$60,266.00</b>

The information contained herein is correct as at 25 Sep 2019

OK

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	20/09/2019 15:13
Date Of Accident	19/09/2019 21:45
Exact Location Of Accident	NEWTON CIRCUS
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKA1613P
<b>Insured/Policyholder</b>	
Name Of Registered Owner	LIAN TENG BOON
NRIC No	S1234739A
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-97365375
Alternative Phone No	OTHERS-97365375

### Vehicle Particulars

Manufacturer	SKODA
Model	SUPERB 1.8 TSI (A) NAVI
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

### Insurance Company

Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	VPA/P2327332
Cover Note Number	

### Driver

Name of Driver	LIAN JENN KAI,AMANDUS
NRIC No	S9130725A
Date Of Birth	03/09/1991
Occupation	INDOOR
Date Of Driving Pass	14/02/2019
Driving Experience	0 YEAR AND 7 MONTH
Gender	MALE
Mobile Number	(LOCAL) +65-97365375
Fax Number	
Contact Number	
EMail Address	NOEMAIL

Address 22 SIN MING WALK #05-02 SPORE 575571  
 Postcode  
 Was driver an employee of the Insured's Company NO  
 If No, Relationship of the Driver with the Insured CHILDREN  
 Vehicle Registration Number of Driver's Own Vehicle -  
 -  
 -  
 Insurance Company of Driver's Own Vehicle -  
 -  
 -

**General Information of the Accident**

Type Of Accident SIDE SWIPE  
 Weather Conditions CLEAR  
 Road Surface DRY

**Other Information**

Was any foreign vehicle involved in this accident? NO  
 Number of vehicles (including own vehicle) involved in the accident 2  
 Was any body injured in the Accident? NO  
 Was any injured conveyed to hospital by ambulance? NO  
 Was any other material or property damaged? YES  
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO  
 Number of Passengers (Including Driver) 1

**Details of Police Action**

Was the accident reported to the police? NO  
 If Yes, Please state which Police Station  
 Was notice of intended Prosecution given? NO  
 If Yes, against whom?

**Circumstances of Accident**

REFER TO SKETCH PLAN

**Attachment(s)**

Are accident photos available for attachment? YES  
 Was there any video captured by Car Camera? NO  
 Was there any audio recorded? NO

**DETAILS OF OTHER VEHICLE PROPERTY 1**

Vehicle Registration Number SKX7916E  
 Vehicle Make/Model/Colour TOYOTA / COROLLA ALTIS CLASSIC 1.6 CVT  
 Details Of Properties  
 Vehicle Category PRIVATE CAR  
 Name of Driver  
 NRIC/Passport Number  
 Contact Number  
 Address  
 Postcode  
 Insurance Company Name  
 Nature Of Damage  
 No. Of Passenger (Including Driver)

# Sketch Plan

## SKETCH PLAN


### IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurer/s companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purposes of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes;
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims;
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated; or
  - (ii) for complying with requirements under any regulations, laws or court orders.

  
\_\_\_\_\_  
Policyholder's Signature  
Date & Time

  
\_\_\_\_\_  
Driver's Signature  
(if driver is not the policyholder)  
Date & Time

  
\_\_\_\_\_  
Reporting Centre Personnel's Signature  
Name: *S. Gan*  
NRIC/FIN No.:



Sketch Plan #2

SKETCH PLAN

Vehicle A: SKA1613P

Vehicle B: GEX7916E




DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On the stated date & time, I, vehicle A, SKA1613P, was travelling straight along lane 3 of Newton Circus. At the exit of Scotts Road, vehicle B, GEX7916E, suddenly filtered into my lane and collided onto my vehicle's right portion.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

  
Driver's Signature  
(If driver is not the policyholder)

  
Driver's Signature  
(If driver is not the policyholder)  
Date & Time

  
Reporting Centre Personnel's Signature  
Name: J. G. G.  
NRI / IN No.



# ZOOM AUTOWERKS PTE LTD

130 Bedok Reservoir Road  
 #08-1339 Singapore 470130  
 Tel: 9450 7920  
 \* zoomautowerks@gmail.com

23 September 2019

REG NO.: SKA 1613 P  
 MAKE/MODEL: SKODA SUPERB

*not Authorised  
 done  
 2/5 #8000/  
 24/9/19  
 take phl. Authority*

**ESTIMATED REPAIR COST FOR THE VEHICLE MENTIONED ABOVE**

QTY	DESCRIPTION LIST ITEMS	AMT(\$)
1	Front door -R/H	body \$ 1,408.00
1	Front door inner board	\$ 800 1,694.00 X
1	Front door lock	\$ 246 446.00
1	Front door outer handle	\$ 117 127.60 X
1	Front door protector -lower	\$ 255 255.00
1	Front door rubber	\$ 189 189.00
1	Rear door -R/H	20/ \$ 783 1,566.00
2	Rear door hinges	\$ 123 246.40 X
1	Rear door inner board	\$ 1199 1,199.00 X
1	Rear door inner lock	\$ 363 363.00 X
1	Rear door outer handle	\$ 97 97.00 X
1	Rear door protector - lower	\$ 265 265.00
1	Rear door regulator	\$ 286 286.00 X
1	Rear door regulator motor	\$ 260 260.00 X
1	Rear door rubber	\$ 141 141.00
1	Rear windscreen inner seal	\$ 107 107.00 X
1	Rear bumper	CU7 \$ 1317 1,317.00
1	Rear bumper side retainer	\$ 68 68.00 X
1	Rocker panel O/S 1820	body \$ 2365 2,365.00
1	Rear fender inner shield	\$ 187 187.00
1	Rear fender inner shield clip (1 set)	\$ 50 50.00
1	Rear wheel hub with bearing	\$ 427 427.00 X
1	Rear shock absorber	\$ 356 356.00 X
1	Rear knuckle arm	\$ 935 935.00 X
1	Rear lower arm	\$ 535 535.00 X
1	Rear stay arm	\$ 175 175.00 X
		\$ 15,065.00
	Less 10%	\$ 1,506.50
		\$ 13,558.50

*2-7674  
 102  
 690660*

**SPECIAL NETT ITEMS**

1	Rear windscreen sealant	\$ 11	80.00	X
1	Rear bumper clip (1 set)	\$ 11	50.00	✓
1	Rear tyre	\$ 11	450.00	X
1	Rear wheel rim	\$ 11	1,250.00	880 s.w
		\$	<u>1,830.00</u>	

**S/N LABOUR CHARGES**

1	To remove, replaced damaged lamps and check up rear wiring.	\$	80.00	30
2	To remove and refit inner garnishes.	\$	150.00	80
3	To remove and refit rear undercarriage.	\$ 11	300.00	X
4	To conduct wheel alignment.	\$	150.00	60
5	To remove and refit rear windscreen glass.	\$ 11	180.00	X
6	To remove, refit doors fittings and replace damaged parts, transfer all	\$	400.00	120
7	To apply undercoating.	\$	200.00	90
8	Panel beating.	\$	2,000.00	800
9	To re-spray painting on the affected areas.	\$	1,800.00	1000
		\$	<u>5,260.00</u>	

**GRAND TOTAL :**

**\$ 20,648.50**

1001660  
22

LKK Auto Consultants hence notify the Repairer of the following:

- To ensure vehicle/after spray painting
- To ensure coverage parts) during recovery
- Parts of the vehicle not to be replaced
- Third party claims from "General Provisions" basis
- No repair (cost/expense) is allowed
- Supplementary claim(s) must be recovered and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933  
Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

### VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CS/MSG19016758/USF3N2  
**Date:** 11/10/2019

#### REFERENCE

<b>Handling Insurer:</b> MSIG Insurance (Singapore) Pte. Ltd.	<b>Policy No:</b> A80452559AT2
<b>Claimant Vehicle No :</b> SKA1613P	<b>Insured Vehicle No :</b> SKX7916E
<b>Date of Loss:</b> 19/09/2019	<b>Nature of Claim:</b> TP <span style="float: right;"><b>Claim No:</b> 606600</span>

#### DESCRIPTION & IDENTIFICATION OF VEHICLE

<b>Reg No:</b> SKA1613P	<b>Engine No:</b> CJS305795
<b>Make &amp; Model:</b> SKODA SUPERB, 1.8	<b>Chassis No:</b> TMBBL7NPXK7068895
<b>Reg. Date:</b> 29/08/2019 (Man. Year: 2019)	<b>Odometer:</b> 1377 km
<b>Colour:</b> Blue	
<b>Engine Capacity:</b> 1798 cc	
<b>Market Value/New Car Price:</b> N/A	
<b>Sum Insured (S\$):</b> Market Value/New Car Price	

#### CONDITION OF VEHICLE AT THE TIME OF SURVEY

<b>General Condition:</b>	<b>Steering (Serviceable):</b> Yes	<b>Footbrake (Serviceable):</b> Yes
<b>Handbrake (Serviceable):</b> Yes	<b>Engine Modification:</b> No	<b>Pre-accident Condition:</b>

#### CONDITION OF TYRES

<b>Front Tyre Size:</b> 235/45ZR18	<b>Rear Tyre Size:</b> 235/45ZR18
<b>Front Left Side:</b> Pirelli 6 mm	<b>Rear Left Side:</b> Pirelli 6 mm
<b>Front Right Side:</b> Pirelli 6 mm	<b>Rear Right Side:</b> Pirelli 6 mm

*The above values represent the remaining tyre treads depth*

#### COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	15,388.50	7,836.60	7,551.90	49.07
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,260.00	2,180.00	3,080.00	58.56
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>20,648.50</b>	<b>10,016.60</b>	<b>10,631.90</b>	<b>51.49</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>8,000.00</b>		
<b>Nett Amount (S\$)</b>	<b>20,648.50</b>	<b>8,000.00</b>	<b>12,648.50</b>	<b>61.26</b>

#### INSPECTION

<b>Date of Assignment:</b> 23/09/2019		
<b>Date Inspected:</b> 24/09/2019	<b>Inspected At:</b>	Bartley Biz Center #01-53 Repairer: Zoom Autowerks Pte Ltd 130 Bedok Reservoir Road, #08-1339 Singapore 470130
<b>Estimated Period of Repair:</b> 7.0 days		

**Adjuster:** MARCUS CHUA

**Manager:** Hiew May Fung

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

<b>Reference</b>	
<b>Part Source:</b> MRM-SG	Version: 1.0 (Last Synchronised: 11 Oct 2019)
<b>Parts:</b> 144	SKODA SUPERB 1.8 (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b> Repairer's	(Price-denominated Standard List)
<b>Print Code:</b> (Unsubmitted, no print-code for SKA1613P)	
<b>Validity:</b> These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b> Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT DOOR-R/H	Badly Dented	1,408.00 FL	*1,408.00 FL
2	1		*FRONT DOOR INNER BOARD	Serviceable	1,694.00 FL	*- FL
3	1		*FRONT DOOR LOCK	Shorted	446.00 FL	*446.00 FL
4	1		*FRONT DOOR OUTER HANDLE	Not Necessary	127.60 FL	*- FL
5	1		*FRONT DOOR PROTECTOR-LOWER	Cut	255.00 FL	*255.00 FL
6	1		*FRONT DOOR RUBBER	Necessary	189.00 FL	*189.00 FL
7	1		*REAR DOOR-R/H	Dented/Bent	1,566.00 FL	*1,566.00 FL
8	2		*REAR DOOR HINGES	Not Necessary	246.40 FL	*- FL
9	1		*REAR DOOR INNER BOARD	Not Necessary	1,199.00 FL	*- FL
10	1		*REAR DOOR INNER LOCK	Not Necessary	363.00 FL	*- FL
11	1		*REAR DOOR OUTER HANDLE	Not Necessary	97.00 FL	*- FL
12	1		*REAR DOOR PROTECTOR-LOWER	Cut	265.00 FL	*265.00 FL
13	1		*REAR DOOR REGULATOR	Not Necessary	286.00 FL	*- FL
14	1		*REAR DOOR REGULATOR MOTOR	Not Necessary	260.00 FL	*- FL
15	1		*REAR DOOR RUBBER	Necessary	141.00 FL	*141.00 FL
16	1		*REAR WINDSCREEN INNER SEAL	Not Necessary	107.00 FL	*- FL
17	1		*REAR BUMPER	Cut/Torn	1,317.00 FL	*1,317.00 FL
18	1		*REAR BUMPER SIDE RETAINER	Not Necessary	68.00 FL	*- FL
19	1		*ROCKER PANEL O/S	Badly Dented	2,365.00 FL	*1,850.00 FL
20	1		*REAR FENDER INNER SHIELD	Deformed	187.00 FL	*187.00 FL
21	1		*SET REAR FENDER INNER SHIELD CLIP	Necessary	50.00 FL	*50.00 FL
22	1		*REAR WHEEL HUB WITH BEARING	Not Necessary	427.00 FL	*- FL
23	1		*REAR SHOCK ABSORBER	Not Necessary	356.00 FL	*- FL
24	1		*REAR KNUCKLE ARM	Not Necessary	935.00 FL	*- FL
25	1		*REAR LOWER ARM	Not Necessary	535.00 FL	*- FL
26	1		*REAR STAY ARM	Not Necessary	175.00 FL	*- FL
27	1		*REAR WINDSCREEN SEALANT	Not Necessary	80.00 FS	*- FS
28	1		*SET REAR BUMPER CLIP	Necessary	50.00 FS	*50.00 FS
29	1		*REAR TYRE	Not Necessary	450.00 FS	*- FS
30	1		*REAR WHEEL RIM	Cut	1,250.00 FS	*880.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>16,895.00</b>	<b>8,604.00</b>
<b>- List Item Discount on L Items 10.00/10.00% (\$\$)</b>	1,506.50	767.40
<b>Total Parts (\$\$)</b>	<b>15,388.50</b>	<b>7,836.60</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REMOVE,REPLACED DAMAGED LAMPS AND CHECK UP REAR WIRING	New	80.00	30.00
2	TO REMOVE AND REFIT INNER GARNISHES	New	150.00	80.00
3	TO REMOVE AND REFIT REAR UNDERCARRIAGE	New	300.00	0.00
4	TO CONDUCT WHEEL ALIGNMENT	New	150.00	60.00
5	TO REMOVE AND REFIT REAR WINDSCREEN GLASS	New	180.00	0.00
6	TO REMOVE,REFIT DOORS FITTINGS AND REPLACE DAMAGED PARTS,TRANSFER ALL	New	400.00	120.00
7	TO APPLY UNDERCOATING	New	200.00	90.00
8	PANEL BEATING	New	2,000.00	800.00
9	TO RE-SPRAY PAINTING ON THE AFFECTED AREAS	New	1,800.00	1,000.00
<b>Gross Labour Cost (S\$)</b>			<b>5,260.00</b>	<b>2,180.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >