

BMW Dealer

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X
Toll-Free Number (1800-2255269)

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax. 64796601 (AfterSales)
64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

23 SEP 2019

E S T I M A T E

Estimate No. : b1 52826
Date Estimated : 23/09/2019
Prepared By : Joseph Yaguel

Page No. : 1 of 5

- ESTIMATE REPAIR FOR -
YEO PWU-JERN ANGI (YANG PUZHEN)
19 SHELFORD ROAD
#04-48

SINGAPORE 288408

- ACCOUNT - 121
AIG Asia Pacific Insurance Pte. Ltd.
78 Shenton Way
#08-16 Chartis Building
Singapore 079120

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SLQ747Y	WBA2E320705H46229	28/06/2017	216d G TOURER	0

DESCRIPTIONVALUE

Replacing left front fender, left wing mirror, rework front bumper and left front door

2550 3,825.00

Spray front bumper, left front fender, left front door, left wing mirror

2593 2,882.00

To check steering geometry and conduct wheel alignment according to BMW specification (1X)

451 531.00

To replace tyre and wheel rim including balancing. (1x).

80 94.00

To check electrical wiring systems at the front section for proper function including adjustments of headlights.

150 177.00

Sundries

? 150.00

Total Labour 1: 7,659.00

DESCRIPTIONQTYPRICVALUE

ALLOY RIM 7.5X17 DOUBLE SPK 385

1

798.00

ent 798.00

FRT LH FENDER

1

627.15

ht 627.15

MODEL DESIGNATION LETTERING SIDE (L

1

46.30

new 46.30

LH OUTSIDE MIRROR COVER CAP PRIMED

1

121.40

RX 121.40

LH LOWER HOUSING SECTION

1

25.05

en 25.05

LH EXTERIOR MIRROR W/O MOUNTING PAR

1

491.25

dis 491.25

LH ADDITIONAL TURN INDICATOR LAMP

1

59.05

? 59.05

Total Parts : 2,168.20

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 197401559W GST Reg. No M2-0020081-x
Toll-Free Number (1800-2255269)

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax. 64796601 (AfterSales)
64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

E S T I M A T E

Estimate No. : b1 52826
Date Estimated : 23/09/2019
Prepared By : Joseph Yaguel

Page No. : 2 of 5

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SLQ747Y	WBA2E320705H46229	28/06/2017	216d G TOURER	0

Claims OD / 3rd Party / Uninsured losses / Direct Settlement

Regn No. _____ Claim No. _____

Date&Time 7/10/11 12:50 Excess S\$ _____

Surveyor's Name Tanpin Sign [Signature]

Surveyor's Tel 94995747 Authorised Yes / No _____

Authorised Date WP Time _____

RESURVEY PARTS PHOTO BY SURVEYOR Yes / No _____ PML Yes / No _____

Surveyor's E-mail Tanpin@deland.com

No. of Working Days Recommend 5 days - 6 days

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



Labour 1	:	7,659.00
Parts	:	2,168.20
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	687.90
Grand Total	:	<u>10,515.10</u>

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY**

** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **