

ASS. REC. BY:

Tanglin

REF:

AUG.

16776 (1101)

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

\$165K

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

China

Veh No:

555 1170P

Yr Regn:

2019, June

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

BMW X1

c.c.

1499

Colour

Bronze

A/C:

Insured / Std / NI / NA

Sp. Reading

8384

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

WSA JG120X03677719

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

225/50R18

R:

-

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

D.O.I.

22/6/19

Survey held at

PML

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Rep. Format:

Lump Sum / L.B.B. /

Days Of Repair:

Resurvey No. of Trip:

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

Survey Fee:

Transportation:

S + RS, SI

Photos

Others

TOTAL

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type: Singapore NRIC

Owner ID: 052D

Vehicle Details

Vehicle No.: SJJ1170P

Vehicle to be Exported: No

Intended Deregistration
Date: 22 Oct 2019

Vehicle Make: B.M.W.

Vehicle Model: X1 SDRIVE18i LED NAV

Primary Colour: Brown

Manufacturing Year: 2019

Engine No.: 31805599B38B15A

Chassis No.: WBAJG120X03G77719

Maximum Power
Output: 103.0 kW (138 bhp)

Open Market Value: \$36,905.00

Original Registration
Date: 24 Jun 2019

First Registration Date: 24 Jun 2019

Transfer Count: 0

Actual ARF Paid: \$43,667.00

Intended PARF Rebate Details

PARF Eligibility: Yes

PARF Eligibility Expiry
Date: 23 Jun 2029

PARF Rebate Amount: \$32,750.00

Intended COE Rebate Details

COE Expiry Date: 23 Jun 2029

COE Category: B - Car above 1600cc or
97kW (130bhp)

COE Period(Years): 10

QP Paid: \$35,906.00

COE Rebate Amount: \$34,719.00

Total Rebate Amount: \$67,469.00

The information contained herein is correct as at 22 Oct 2019

OK