

ASS. REC. BY:

REF: CS/TMI/9016787/KHf307 Special Instruction:

Surveior: Kainn

ASSIGNMENT (Office)

From (Person): Hona Gun Ber Song of TMI Date/Time: 24.9.19

Estimated Cost: Bill to:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV/CS

To Inspect Vehicle No: SH 7700 S Insured: GBC 2506E

at Workshop m/s Comfortdelgro Tel: 62148300

of 59 layang Drive

Policy No: MV007552 Claim No: M1907417

Sum Insured: Excess:

Make of Veh: D.O.A. 20.9.2019

(Client's Record)

CA / REV / REP. / REV 24 HRS

Date/Time: 24.9.19 9.54 a.m. Person Contacted: Junadi

H.O.D. Endorsement:

Vehicle IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	SH 7700 S - CC4 / Asm 19002349 / NF9392 D.O.A - 04/07/2019
	GBC 2506 E-x

RECEIVED 26 SEP 2019

Surveyor: Kalvin

REF: _____

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspected Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SH 7720 S Yr Regn: 18 Oct, 2018Type: M. Car / M. Cycle / Bus / Van / Lorry / ~~Truck~~ / Prime Mover /

Truck / Trailer or

Make: Hyundai Zava C.C. 1.5LColour: Blue A/C: Insured / Std / NI / NASp. Reading: 70578 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: KALC 851C106411 4775Gen. Cond: Good / Fair / Poor / BurntSteering: Inorder / Jammed / Leaked / Burnt orBrake: Inorder / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD / Rim orTyre Size: F: 195/65R15

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 9 mm R/Bal. 9 mmL/Bal. 9 mm L/Bal. 9 mmD.O.A. 20/9/19 D.O.I. 23/1/19Survey held at C/DHE (Loyang)

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

O/S Front

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
25/9/19	Chk 1983295 / 26p. (Red: 629.92; 16%) To kid Pp

Date/Time, File Pass to?

26/9 Typist

Date/Time, File Return to?

2)

☐ : Prell. Report☒ : Final ReportDays Of Repair: 2Resurvey No. of Trip: 1Add Fee: ☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)Survey Fee: 250

Transportation: _____

S + RS. \$ _____

Photos _____

11

261

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	23 Sep 2019 Sendback Est	23 Sep 2019 10:45 S\$2,054.68	24 Sep 2019 09:36 Assign				New Assignment Cancel Case
Supp #1	23 Sep 2019 14:42 Sendback Est	23 Sep 2019 14:43 S\$3,163.92	24 Sep 2019 09:36 Assign			Combine Suppl.	New Assignment Cancel Case

Main

Reference

Claim Details

Documents

Show All

CLAIM SUBFOLDER DETAILS

Insured:	CHUA KHENG HWEE FOOD TRADING, Co. Reg. No.: 52845180D		
Main Claimant:	CTPL		
Vehicle Reg. No.:	SH7720S	Date of Loss:	20/09/2019 00:00 - :59 [11 Months and 2 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / M1907417	Policy/Cover Note No.:	MV007552 (Comprehensive) Coverage: 19/09/2019 - 18/09/2020
Vehicle Reg. No. (Insured):	GBC2506E	Policy No. (Claimant):	
		Excess:	S\$2,500.00
Repairer:	ComfortDelGro Engineering Pte Ltd (Loyang) 59 Loyang Drive, 508969 Loyang - Tel: 6214 8300		
Handling Insurer:	Tokio Marine Insurance Singapore Ltd (HQ) - Tel: 6221 6111 ... [Handled by Fiona Gan Bee Song - 65926378]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 03/10/2019]		
Adj Asg. Remarks:	OI HAS NOT RPT THE ACCDT		

ASSOCIATED MAIL RECEIVED

View All

Compose Case Mail

There are no mail for this case.



ALL ASSOCIATED TASKS

View All

Search Tasks

Create New Task

Complete

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Team: ARC Repair TP(CLSO)1

JOB CARD

Sales Order:

JC NO.: 305335302

MEMBER
COMFORT TRANSPORTATION PTE LTD
MEMBER NO. 7010045
ADDRESS 383 SIN MING DRIVE
Singapore SINGAPORE 575717
(R) 65508755 (O)
(P)


UNT CARD NO.

REGN NO.: SH 7720S	MILEAGE
MAKE : HYUNDAI	FUEL E.....1/2.....F
MODEL IONIQ(G2)	DATE/TIME IN 23.09.2019 08:45
YR OF MANU. 18.10.2018	TARGET DATE
CHASSIS CODE KMHC851CVKU114775	COMPLETION DATE/TIME:

JOB DESCRIPTION

Accident Date: 20.09.2019
NATURE: 3P 20.09.19

S/NO LABOR CODE DESCRIPTION



ED & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

gement Slip

Exit Pass

Vehicle No.: SH 7720S

JU TOKIO LKK

Vehicle No.:

SH 7720S

Service Advisor

Signature/Date

Name of Service Advisor

Date

med to Service Reception upon collection

To be kept by Security Guard

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT	
Date Of Report	22/09/2019 10:31
Date Of Accident	20/09/2019 18:00
Exact Location Of Accident	JURONG PIER RD AND JLN BUROH ROUNDABOUT
Country/State of Loss	SINGAPORE
DETAILS OF OWN VEHICLE	
Vehicle Registration Number	SH7720S
Insured/Policyholder	
Name Of Registered Owner	COMFORT TRANSPORTATION PTE LTD
Co Reg No	199303821R
Email Address	FLEETSAFETY@CDGTAXI.COM.SG
Mobile Phone No	
Alternative Phone No	OFFICE-65508768
Vehicle Particulars	
Manufacturer	HYUNDAI
Model	IONIQ
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI
Insurance Company	
Name of Insurance Company	MS FIRST CAPITAL INSURANCE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	YES
Policy Number	D-18088936MFSH
Cover Note Number	
Driver	
Name of Driver	DANIEL ANG KOK PENG (DANIEL HONG GUOPING)
NRIC No	S7325763H
Date Of Birth	24/07/1973
Occupation	OUTDOOR
Date Of Driving Pass	25/03/2010
Driving Experience	9 YEARS AND 5 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96307111
Fax Number	
Contact Number	
EMail Address	NOEMAIL

Address	BLK 138D YUAN CHING ROAD #12-163
Postcode	614138
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - TAXI DRIVER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	HIT AND RUN / VANDALISM / DAMAGED WHILST PARKED
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : - GENDER: : MALE

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
POLICE STATION NAME [OTHER]	JURONG NPP
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

PLS REFER TO ATTACHED / POLICE REPORT : T/20190920/2194

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	-
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GBC2506E
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	TOKIO MARINE INSURANCE SINGAPORE LTD

Nature Of Damage

LEFT REAR

No. Of Passenger (Including Driver)

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

COMFORT TRANSPORTATION PTE LTD
GG REG. NO. 199303621K

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Loke Ww Yiang

GIA/RIAC Sketch Plan Page 1/2

SKETCH PLAN

Diagram illustrating the process of a packet being dropped by a router:

- A packet labeled "A" is shown entering a router.
- The router is labeled "Droptable".
- The packet is shown being dropped by the router.
- The router is labeled "Droptable".
- The packet is shown being dropped by the router.

Labels in the diagram:

- Router: Droptable
- Packet: A
- Destination: D
- Source: S

Text below the diagram:

A = SH 7700 S
B = GBC 2506 E

Text at the bottom right:

Julian
Play Pd

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Attached police report
T/20190920/2194

DECLARATION

I/We declare the foregoing particulars are true in every respect.

COMFORT TRANSPORTATION PTE LTD

CD REG NO. 199203821K

Policyholder's Signature _____

Date & Time:

Driver's Signature _____
(If driver is not the policyholder)

Date & Time:

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:



**SINGAPORE
POLICE FORCE**



T/20190920/2194

1 of 3

Police Station Of Origin:
Jurong NPP
158 Yung Loh Road #01-58 SINGAPORE
610158
Tel No: 1800-2659999

Report No. T/20190920/2194

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 20/09/2019 21:41	Vide Report No.:	Station Diary No.: 71
--	------------------	--------------------------

Informant's Particulars

Name of Informant: DANIEL ANG KOK PENG			Address: APT BLK 138D YUAN CHING ROAD #12-163 SINGAPORE 614138	
ID Type / ID No.: NRIC NO / S7325763H			Contact No.: Home/Office: Mobile: 96307111	
Nationality: SINGAPORE CITIZEN			Email:	
Sex: Male	Age: 46	Date of Birth: 24/07/1973	Type of Informant: Driver	
Race: Chinese			Language:	Institution / School Name:
Occupation: Taxi driver			Driving Licence Information: Class: 3 Date of Expiry:	

General Information of the Accident

Type of Accident:	Non-Injury Hit and Run	Drink Drive: No	Date/Time of Accident: 20/09/2019 18:00	Type of Location: Roundabout
Location: Along Road 1 Traveling Toward Road 2 JURONG PIER ROAD				
Roundabout				
Weather: Clear		Road Surface: Dry		Road Speed Limit:
Traffic Flow: One Way		Traffic Control: Not Controlled		Traffic Volume: Light
Type of Collision: Between Moving Vehicles - Side Swipe - Same Direction				Anyone conveyed by ambulance: No

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
GBC2506E	Lorry				No Damage	0
SH7720S	Car				Slightly Damaged	1

Details of Person Involved

Any Pedestrian Involved: No	
No. of Pedestrians Injured: NIL	Use of Pedestrian Crossing: NA



**SINGAPORE
POLICE FORCE**



T/20190920/2194

Police Station Of Origin:
Jurong-NPP
158 Yung Loh Road #01-58 SINGAPORE
610158
Tel No: 1800-2659999

2 of 3

Report No. T/20190920/2194

CONTINUATION OF REPORT

Driver			
Name	DANIEL ANG KOK PENG	ID No.	S7325763H
Related Vehicle	NIL	Contact No.	96307111
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: 3 Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

Brief Details.

On 20/09/2019 at about 1800hrs, I was driving along Jurong Pier Road and I entered the roundabout. I was on the left lane while there was another lorry that was driving on my right. I wanted to exit at the second exit. As I was driving past the first exit, the said lorry made a left turn illegally overtaking in front of me. The lorry managed to overtake me however, the left side of the lorry hit onto my front right headlight cover causing it to be scratched. My passenger managed to take a photo of the lorry license plate. The lorry did not stop and drove away. At that point of time I have one passenger in my car. I have an in car camera that was recording. No one was injured.



**SINGAPORE
POLICE FORCE**



T/20190920/2194

3 of 3

Police Station Of Origin:
Jurong NPP
158 Yung Loh Road #01-58 SINGAPORE
610158
Tel No: 1800-2659999

Report No. T/20190920/2194

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the **report number** as reference.

Signature Of Officer Recording The Report:

J/

Sgt 2 NIFAIL HADI BIN NORMAN

Signature Of Interpreter:

Not applicable

Officer In Charge Of Case:

TP / HRT /

Sr Staff Sgt IRMAN BIN MOHAMAD SAID

Contact No.: 65476145

Signature Of Informant:

Date/Time:

20/09/2019 21:41

Classification Of Case:

Authentication Stamp

NP158

Signature: _____

Singapore Police Force

ComfortDelGro Engineering Pte Ltd (Co Reg.No:199506048W)

59 Loyang Drive
Singapore 508969
Tel: 6214 8300

TP INSURER: **Tokio Marine Insurance Singapore Ltd (HQ)**
CTPL

Singapore

PARTICULARS OF CLAIM

Claim Type:	THIRD PARTY	Ref. No:	
Policy No:		Date of Loss:	20/09/2019
Vehicle Reg. No.:	SH7720S	Driveable?	YES
Party At Fault:	UNKNOWN		
Make/Model:	HYUNDAI IONIQ HYBRID, 1.6 GLS DCT (A)	Vehicle Reg. Date:	18/10/2018
Vehicle Colour:	BLUE	Gen Condition:	GOOD
Engine No:	G4LEJU110363	Chassis No:	KMHC851CVKU114775
Odometer:	0 KM		
Paint Type:			
List Item Discount:	20.00 %		
Total Loss?	NO		
Est. Duration of Repair (day)	3		

Present Location: COMFORTDELGRO ENGINEERING PTE LTD (LOYANG)

COST OF CLAIMS	Amount
Parts	1,293.68
Miscellaneous Items	11.00
Labour	750.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (S\$)	2,054.68
+ GST 7.00% (S\$)	143.83
Nett Amount (S\$)	2,198.51

This claim is handled by: JUMANI BIN MASUDIN

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS**Reference****Part Source:** MRM-SG Version: 1.0 (Last Synchronised: 23 Sep 2019)**Parts:** 192 HYUNDAI IONIQ HYBRID 1.6 GLS DCT (A) (Catalogue:Merimen Singapore 1.0)**Labour:** Repairer's (Price-denominated Standard List)**Print Code:** ComfortDelGro Engineering Pte Ltd/SH7720S/23/09/2019 10:45**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk *.**Estimates on Parts**

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*HEADLAMP ASSY RH <i>hazard</i>	20.00	0.00	*418.30 FL <i>3455.00</i>
2	1		*FRT BUMPER ASSY <i>X 1450</i>	20.00	0.00	*1,196.80 FL <i>499.90</i>
Sub Total (S\$)						1,617.10 <i>3954.90</i>
- List Item Discount on L Items (S\$)						323.42
Total Parts (S\$)						1,293.68

F=Franchise part. L=ListItemDisc.

ComfortDelGro Engineering Pte Ltd/SH7720S/23/09/2019 10:45. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

3163.92

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
Miscellaneous Items			
1	1	OD/TP Case (Insurer)	11.00
Sub Total (S\$)			11.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
Labour Items			
1	PANEL BEATING	New	400.00 ³²⁰
2	SPRAYPAINT	New	300.00 ²⁰⁰
3	WIRING	New	50.00 ²⁰
Gross Labour Cost (S\$)			750.00

ComfortDelGro Engineering Pte Ltd/SH7720S/23/09/2019 10:45. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

Katrina 11/10/19

23/9/19 11:20h

2 Pys

P/P

After Rep. photo

3924.92

LKK Auto Consultants hence notify the Repairer of the following:

- To be surveyed before/after spray painting
- To be surveyed damaged part(s) during resurvey
- All repairs are subject to confirmation
- All repairs are on a "Without Prejudice" basis
- All repairs are subject to confirmation
- All repairs are subject to confirmation
- All repairs are subject to confirmation

Acknowledged by Repairer
Signature: _____
Date: _____

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305335302
REGN NO : SH 7720S
MILEAGE : 0000000000
MAKE : HYUNDAI
MODEL : IONIQ(G2)
DATE OF REGN : 18.10.2018
DATE/TIME IN : 23.09.2019 08:45
ACCIDENT DATE : 20.09.2019

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001 04-01-0104-2915-G IONIQVC LAMP ASSY-HEAD RH 1 3,455.00 20.00 2,764.00

SUB-TOTAL : 2,764.00

JOB NATURE

0000 PB PANEL BEATING 320.00
0001 SP SPRAYPAINT CHARGE 200.00
0002 L MERIMEN 11.00

SUB-TOTAL : 531.00

TOTAL : 3,295.00

MVA NAME & SIGNATURE
DATE :

AUTHORISED : YES / NO
SURVEYOR NAME & SIGNATURE
DATE :

COMFORTDELGRO ENGINEERING

Our Job Ref No 305335302
Date : 24/09/2019

ComfortDelGro Engineering Pte Ltd
59 Loyang Drive Singapore 508969
Fax: 6546 8156

FINALIZATION FORM

To : LKK
Attn : KALVIN
: SH 7720S

Fax :

305333809 20/09/2019


The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-


1. The repair job shall bill to: TOKIO --- GBC2506E
###
2. The finalized amount shall be:

(a) Spare Parts after List discount		\$2,764.00
(b) Labour Charges	###	\$531.00
Total for Part-By-Part Repair Cost		\$3,295.00
	###	
(c.) Lumpsum Repair (if applicable)		
Total for Lumpsum repair cost after Less: 20%		
Final Lumpsum Repair cost		

3. Estimated normal period for repairs: 2 working days
4. We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days
5. Thank you for your assistance.

We confirm the estimates and finalized amount

Signature : 
Name : JUMANI
Tel : 6214 8315
Fax : 65468156

Signature : 
Name : Kalvin
Date : 25/9/19

For Official Use Only

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid		N		
3. Survey Fees				
4. LTA Search Fee	\$7.49			
5. Medical Fees (on behalf of driver, if applicable)				
6. Overrun				

Remarks:

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	23 Sep 2019 Sendback Est	23 Sep 2019 10:45 S\$2,054.68	24 Sep 2019 09:36 Edit Adj Rpt	S\$3,295.00 Edit Estimates	S\$3,295.00 View Rpt		Pending for Survey Report Cancel Case
Supp #1	23 Sep 2019 14:42	23 Sep 2019 14:43 S\$3,163.92	24 Sep 2019 09:36			(Combined)	Combined with Main Uncombine Suppl.

Main	Reference	Claim Details	Documents	Show All
-------------	------------------	----------------------	------------------	--------------------------

CLAIM SUBFOLDER DETAILS

Insured:	CHUA KHENG HWEE FOOD TRADING, Co. Reg. No.: 52845180D		
Main Claimant:	CTPL		
Vehicle Reg. No.:	SH7720S	Date of Loss:	20/09/2019 00:00 - :59 [11 Months and 2 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / M1907417	Policy/Cover Note No.:	MV007552 (Comprehensive) Coverage: 19/09/2019 - 18/09/2020
Vehicle Reg. No. (Insured):	GBC2506E	Policy No. (Claimant):	
		Excess:	S\$2,500.00
Repairer:	ComfortDelGro Engineering Pte Ltd (Loyang) 59 Loyang Drive, 508969 Loyang - Tel: 6214 8300		
Handling Insurer:	Tokio Marine Insurance Singapore Ltd (HQ) - Tel: 6221 6111 ... [Handled by Fiona Gan Bee Song - 65926378]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KALVIN ANG WEI KUN] ... [Final Rpt due 03/10/2019]		
Adj Asg. Remarks:	OI HAS NOT RPT THE ACCDT		

ASSOCIATED MAIL RECEIVED

[View All](#)
[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)
[Search Tasks](#)
[Create New Task](#)
[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

SH7720S (M1907417)
[GBC2506E]
TP
CTPL
Sep 20 2019 12:00AM
[CHUA KHENG HWEE FOOD TRADING]
ComfortDelGro Engineering Pte Ltd

Upload Documents		Upload Photos	Compose New Letter	View View In Browser	
Assessment Reports				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	ComfortDelGro Engineering Pte Ltd (Loyang)		Thumbnail	Print
1	23/09/19 10:45	Repairer Estimates		Load HTM	
2	23/09/19 14:43	Repairer Estimates Suppl. #1		Load HTM	
Photos/Images				3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	25/09/19 08:01	General View		Load JPG	<input checked="" type="checkbox"/>
2	25/09/19 08:01	General View		Load JPG	<input checked="" type="checkbox"/>
3	25/09/19 08:01	General View		Load JPG	<input checked="" type="checkbox"/>
4	25/09/19 08:01	General View		Load JPG	<input checked="" type="checkbox"/>
5	25/09/19 08:01	General View		Load JPG	<input checked="" type="checkbox"/>
6	25/09/19 08:01	General View		Load JPG	<input checked="" type="checkbox"/>
7	25/09/19 08:01	General View		Load JPG	<input checked="" type="checkbox"/>
8	25/09/19 08:01	General View		Load JPG	<input checked="" type="checkbox"/>
9	25/09/19 08:01	General View		Load JPG	<input checked="" type="checkbox"/>
10	25/09/19 08:01	General View		Load JPG	<input checked="" type="checkbox"/>
11	25/09/19 08:01	General View		Load JPG	<input checked="" type="checkbox"/>
12	25/09/19 08:01	General View		Load JPG	<input checked="" type="checkbox"/>
13	25/09/19 08:01	General View		Load JPG	<input checked="" type="checkbox"/>
14	25/09/19 08:01	General View		Load JPG	<input checked="" type="checkbox"/>
15	25/09/19 08:01	General View		Load JPG	<input checked="" type="checkbox"/>
16	25/09/19 08:01	General View		Load JPG	<input checked="" type="checkbox"/>
17	25/09/19 08:01	General View		Load JPG	<input checked="" type="checkbox"/>
18	25/09/19 08:01	General View		Load JPG	<input checked="" type="checkbox"/>
19	25/09/19 08:01	General View		Load JPG	<input checked="" type="checkbox"/>
20	25/09/19 08:01	General View		Load JPG	<input checked="" type="checkbox"/>
21	25/09/19 08:07	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
22	25/09/19 08:07	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
23	25/09/19 08:07	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
24	25/09/19 08:07	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
25	25/09/19 08:07	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
26	25/09/19 08:07	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
Documentation				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	ComfortDelGro Engineering Pte Ltd (Loyang)		Thumbnail	Print
1	23/09/19 10:46	E-filed GIA report		Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)**Show Remarks To:** ☐ Repairer ☐ Handling InsurerNote: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/TMI19016787/K1TF3E2

Date: 27/09/2019

REFERENCE

Handling Insurer: Tokio Marine Insurance Singapore Ltd Policy No: MV007552
Claimant
Vehicle No : SH7720S **Insured Vehicle No :** GBC2506E
Date of Loss: 20/09/2019 **Nature of Claim:** TP **Claim No:** M1907417

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SH7720S
Make & Model: HYUNDAI IONIQ HYBRID, 1.6 GLS DCT (A) **Engine No:** G4LEJU110363
Reg. Date: 18/10/2018 (Man. Year: 2018) **Chassis No:** KMHCH851CVKU114775
Colour: Blue **Odometer:** 70578 km
Engine Capacity: 1580 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Good **Steering (Serviceable):** Yes **Footbrake (Serviceable):** Yes
Handbrake (Serviceable): Yes **Engine Modification:** No **Pre-accident Condition:** Average

CONDITION OF TYRES

Front Tyre Size: 195/65R15 **Rear Tyre Size:** 195/65R15
Front Left Side: Davanti 9 mm **Rear Left Side:** Davanti 9 mm
Front Right Side: Davanti 9 mm **Rear Right Side:** Davanti 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,457.60	2,764.00	1,693.60	37.99
Miscellaneous Items	11.00	11.00	0.00	0.00
Labour	750.00	520.00	230.00	30.67
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	5,218.60	3,295.00	1,923.60	36.86
+ GST 7.00/7.00% (S\$)	365.30	230.65	134.65	36.86
Nett Amount (S\$)	5,583.90	3,525.65	2,058.25	36.86

INSPECTION

Date of Assignment: 24/09/2019 **Present Location:** ComfortDelGro Engineering Pte Ltd (Loyang)
Date Inspected: 23/09/2019 **Inspected At:** ComfortDelGro Engineering Pte Ltd (Loyang)
59 Loyang Drive
Singapore 508969
Estimated Period of Repair: 2.0 days

Adjuster: KALVIN ANG WEI KUN**Manager:** DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 26 Sep 2019)
Parts:	192	HYUNDAI IONIQ HYBRID 1.6 GLS DCT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SH7720S)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*HEADLAMP ASSY RH	Repeated	418.30 FL	*- FL
2	1		*FRT BUMPER ASSY	Repeated	1,198.80 FL	*- FL
Supplementary #1						
3	1		*HEADLAMP ASSY RH	Grazed	3,455.00 FL	*3,455.00 FL
4	1		*FRT BUMPER ASSY	Repair	499.90 FL	*- FL
Sub Total (S\$)					5,572.00	3,455.00
- List Item Discount on L Items 20.00/20.00% (S\$)					1,114.40	691.00
Total Parts (S\$)					4,457.60	2,764.00

F=Franchise part. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
Miscellaneous Items				
1	1	OD/TP Case (Insurer)	11.00	11.00
Sub Total (S\$)			11.00	11.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING	New	400.00	320.00
2	SPRAYPAINT	New	300.00	200.00
3	WIRING	New	50.00	0.00
Gross Labour Cost (S\$)			750.00	520.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >