

PLEASE ARRANGE TO SURVEY VEHICLE AT
NO.8 KAKI BUKIT AVE 4 GATE 2
#03-21
SINGAPORE 415875

LINDA LIAO
STK AUTO (S) PTE LTD

Date : 20/9/19

To : CHINA TAIPING INSURANCE (SINGAPORE) PTE LTD

Attn : Motor Claim Department

Owner : GOODWILL ENTERTAINMENT HOLDING PTE LTD

CHINA TAIPING INSURANCE (SINGAPORE) PTE LTD

Certificate Number : DMCVSN1826881901

Accident Date : 18/9/19

Vehicle Number : GBH6629G

Make & Model : NISSAN NV350 PANEL VAN

ESTIMATED REPAIR COST DETAILS

S/N	DESCRIPTION	QTY	REPAIR AMOUNT	SURVEYOR APP.
1	BONNET Dist	1	\$ 580.00	
2	FRONT FIRE PANEL R	1	\$ 1,500.00	X
3	FRONT WIPER PANEL R	1	\$ 450.00	X
4	FRONT WIPER PANEL GARNISH ?	1	\$ 200.00	
5	FRONT WIIPER LINK RH	1	\$ 250.00	X
6	FRONT WIPER LINK LH	1	\$ 250.00	X
7	FRONT WIPER LINK MOTOR	1	\$ 550.00	X
8	FRONT WINDSCREEN GLASS shattered	1	\$ 850.00	
9	FRONT WINDSCREEN GLASS MOULDING nec	1	\$ 180.00	
10	FRONT WINDSCREEN PILLAR RH R	1	\$ 950.00	X
11	FRONT WINDSCREEN PILLAR LH Buc	1	\$ 950.00	
12	RH HEADLAMP Cut	1	\$ 350.00	
13	LH HEADLAMP Smashed	1	\$ 350.00	
14	RH HEADLAMP BRACKET RH	1	\$ 65.00	X
15	LH HEADLAMP BRACKET LH	1	\$ 65.00	X
16	RH HEADLAMP PANEL	1	\$ 350.00	X
17	LH HEADLAMP PANEL	1	\$ 350.00	X
18	FRONT WHEEL ARCH RH	1	\$ 650.00	X
19	FRONT WHEEL ARCH LH	1	\$ 650.00	
20	FRONT WHELL ARCH GARNISH RH RA new	1	\$ 165.00	
21	FRONT WHEEL ARCH GARNISH LH ?	1	\$ 165.00	
22	CROSS MENBER NN	1	\$ 1,800.00	X
23	ENGINE LOWER GARNISH ?	1	\$ 370.00	
24	FRONT CHASSIS RH	1	\$ 550.00	X
25	FRONT CHASSIS LH	1	\$ 550.00	X
26	FRONT GRILLE missing	1	\$ 550.00	

27	FRONT GRILLE BRACKET RH	} NN	1	\$	55.00	X
28	FRONT GRILLE BRACKET LH	} NN	1	\$	55.00	X
29	FRONT GRILLE LOGO	nc	1	\$	65.00	
30	FRONT BUMPER	Dist	1	\$	450.00	
31	FRONT BUMPPER FOG LAMP COVER RH	NN	1	\$	135.00	X
32	FRONT BUMPER FOG LAMP COVER LH	Dist	1	\$	135.00	
33	FRONT BUMPER RETAINER RH	} NN	1	\$	90.00	X
34	FRONT BUMPER RETAINER LH	} NN	1	\$	90.00	X
35	FRONT BUMPER BRACKET RH	NN	1	\$	65.00	X
36	FRONT BUMPER BRACKET LH	Bent	1	\$	65.00	
37	FRONT BUMPER REINFORCEMENT	Bent	1	\$	550.00	
38	FRONT BUMPER GRILLE CENTRE	crq	1	\$	400.00	
39	AIR DUCT	Def	1	\$	150.00	
40	AIR CLEANER BOX ASSY	?	1	\$	650.00	
41	AIR CLEANER HOSE	?	1	\$	150.00	
42	AIR CLEANER HOSE TOP	?	1	\$	250.00	
43	AIR CLEANER HOUSING	?	1	\$	350.00	
44	AIR CLEANER INTAKE DUCT	?	1	\$	550.00	
45	AIR CLEANER INTAKE HOSE	?	1	\$	280.00	
46	AIR CLEANER OUTET HOSE	?	1	\$	280.00	
47	AIR CLEANER OUTER HOUSIG	?	1	\$	650.00	
48	AIR CLANER PIPE	?	1	\$	390.00	
49	AIR CON BLOWER	?	1	\$	2,100.00	
50	AIR CON BLOWER MOTOR	?	1	\$	3,500.00	
51	AIR CON COIL	?	1	\$	650.00	
52	AIR RESONATOR	?	1	\$	120.00	
53	TURBER	?	1	\$	3,500.00	
54	TURBER PIPE	?	1	\$	250.00	
55	INTER COOLER	?	1	\$	2,800.00	
56	INTER COOLER PIPE	NN	1	\$	450.00	X
57	OIL COOLTER	Bent	1	\$	1,500.00	
58	OIL COOLER PIPER	Bent	1	\$	165.00	
59	WIPER TANK	?	1	\$	210.00	
60	WIPER TANK MOTOR	?	1	\$	560.00	
61	WIPER TANK COVER	?	1	\$	87.00	
62	DRAF SHAFT	NN	1	\$	1,500.00	X
63	HORN LOWER	?	1	\$	120.00	
64	HORN HIGH	?	1	\$	120.00	
65	FRONT WIPER HARNESS	NN	1	\$	3,500.00	X
66	LH FRONT CONER PANEL	Dented	1	\$	350.00	
67	RH FRONT CONER PANEL	R	1	\$	350.00	X
68	AIR CON CONDERSOR	?	1	\$	500.00	
69	AIR CON CONDENSOR DRY HOSE	Bent	1	\$	180.00	
70	AIR CON DISCHARGE HOSE	} Bent	1	\$	350.00	
71	AIR CON RECIVE HOSE	} Bent	1	\$	270.00	
72	RECEIVED DRIVER	Dented	1	\$	180.00	
73	RADIATOR	?	1	\$	550.00	
74	RADIATOR FAN COWLING	?	1	\$	350.00	
75	RADIATOR FAN BLADE	?	1	\$	320.00	
76	RADIATOR FAN MOTOR	?	1	\$	450.00	
77	RADIATOR SPARE TANK	?	1	\$	95.00	
78	RADIATOR BRACKET RH	?	1	\$	65.00	

79	RADIATOR BRACKET LH	?	1	\$	65.00	
80	RADIATOR BOTTOM HOSE	?	1	\$	150.00	
81	RADIATOR MOUNTING TOP	?	1	\$	150.00	
82	DASHBOARD	?	1	\$	860.00	
83	DASHBOARD COVER	?	1	\$	650.00	
84	DASHBOARD REINFORCEMENT	?	1	\$	750.00	
85	DASHBOARD METER	NN	1	\$	850.00	X
86	PASSENGER DASHBOARD GARNISH	?	1	\$	250.00	
87	PASSENGER DASHBOARD TOOL BOX	?	1	\$	350.00	
88	STEERING LOWER GARNISH	NN	1	\$	20.00	X
89	STEERING RCK PINION		1	\$	2,100.00	X
90	DRIVER'S STEERING	NN	1	\$	1,500.00	X
91	GEAR LEVER GARNISH		1	\$	650.00	X
92	LH FRONT SHOCK ABSORBER		1	\$	180.00	X
93	LH FRONT LOWER ARM	NN	1	\$	200.00	X
94	LH FRONT KNOCKE ARM		1	\$	250.00	X
95	LH FRONT KNOCKE ARM BEARING		1	\$	165.00	X
96	LH FRONT DOOR	Dist	1	\$	850.00	
97	LH FRONT DOOR HINGE UPPER	Bent	1	\$	75.00	
98	LH FRONT DOOR HINGE LOWER		1	\$	75.00	
99	LH FRONT DOOR CHECKER	Bent	1	\$	55.00	
100	LH FRONT DOOR HANDLE OUTER	NN	1	\$	100.00	X
101	LH FRONT DOOR HANDLE INNER		1	\$	120.00	X
102	LH FRONT DOOR GLASS	shattered	1	\$	500.00	
103	LH FRONT DOOR GLASS REGULATOR MOT	NN	1	\$	350.00	X
104	LH FRONT DOOR GLASS REGULATOR SWIT	dm	1	\$	150.00	
105	LH FRONT DOOR GLASS SWITCH COVER	NN	1	\$	150.00	X
106	LH FRONT DOOR SPEAKER	NN	1	\$	360.00	X
107	LH FRONT DOOR WEATHERSTRIP	Cut	1	\$	200.00	
108	LH FRONT DOOR LOCK	dm	1	\$	250.00	
109	LH FRONT DOOR INNER PILLAR	R	1	\$	1,500.00	X
110	LH FRONT DOOR OUTER PILLAR	Dist	1	\$	1,500.00	
111	LH FRONT DOOR STEP PANEL	Bent	1	\$	200.00	
112	LH FRONT DOOR STEP PANEL GARNISH	Dented	1	\$	130.00	
113	LH FRONT DOOR INNER TRIMBOARD	crq	1	\$	500.00	
114	LH FRONT DOOR CENTRE PILLAR	Dented	1	\$	1,500.00	
115	RH FRONT DOOR	R	1	\$	850.00	X
116	RH FRONT DOOR HINGE UPPER		1	\$	75.00	X
117	RH FRONT DOOR HINGE LOWER	NN	1	\$	75.00	X
118	RH FRONT DOOR CHECKER		1	\$	55.00	X
119	RH FRONT DOOR PILLAR	R	1	\$	1,500.00	X
120	RH SLIDING DOOR	Dented	1	\$	1,200.00	
121	RH REAR FENDER	R	1	\$	1,200.00	X
122	DRIVER SEAT		1	\$	950.00	X
123	PASSENGER SEAT	NN	1	\$	950.00	X
124	DRIVER SEAT BUCKLE RH		1	\$	450.00	X
125	LH FRONT SEAT BELT		1	\$	900.00	X
126	RH FRONT SEAT BELT	NN	1	\$	900.00	X
127	PASSENGER SEA BUCKLE LH		1	\$	550.00	X
128	FUSE BOX	?	1	\$	1,500.00	
129	FUSE BOX COVER	?	1	\$	250.00	
130	RH TAILLAMP	wt	1	\$	180.00	

Sub Total	\$ 73,977.00
Make up 15% on Parts	\$ 11,096.55
Total	\$ 85,073.55

Special Nett Item

1	FRONT NUMBER PLATE Bent	1	\$ 65.00	30
2	TOWING FEE	1	\$ 300.00	60
4	FRONT DOOR SEALANT RH	1	\$ 65.00	X
5	FRONT DOOR SEALANT LH	1	\$ 65.00	X
6	FRONT CAMERA	1	\$ 365.00	X
7	FRONT BUMPER TOWING COVER RH & LH nrc	2	\$ 100.00	20
8	IU BRACKET nrc	1	\$ 65.00	30
9	COOLANT nrc	1	\$ 65.00	50
10	BONNET STOPPER NN	10	\$ 100.00	X
11	IU BRACKET R	1	\$ 65.00	X
12	AIR FILTER ?	1	\$ 35.00	
13	ENGINE OIL	1	\$ 100.00	X
14	OIL FILTER } NN	1	\$ 45.00	X
15	FRONT GRILLE CLIPS nrc	10	\$ 65.00	20
16	FRONT WIPER BALDE RH	1	\$ 65.00	X
17	FRONT WIPER BLADE LH	1	\$ 65.00	X
18	FRONT FENDER INNER SHIELD CLIPS	10	\$ 65.00	X
19	FRONT BUMPER CLIPS nrc	10	\$ 65.00	30
20	HEADSET MONITOR NN	1	\$ 350.00	X
21	RH FRONT DOOR STICKER	1	\$ 25.00	
22	LH FRONT DOOR STICKER	1	\$ 25.00	
23	FRONT WINDSCREEN SEALANT	1	\$ 50.00	
	Sub Total		\$ 2,210.00	

ESTIMATED REPAIR COST DETAILS

Labour & Misc

1	LABOUR TO FACILIATE REPAIR	\$ 4,500.00	2400
2	R & R ENGINE COMPARTMENT	\$ 250.00	?
3	RUST PROOF ON AFFECTED AREAS	\$ 50.00	✓
4	R & R FRONT WINDSCREEN	\$ 150.00	120
5	TO VACCUM AIR CON SYSTEM & REFILL GAS	\$ 120.00	✓
6	TO CHECK LIGHTING AND FOCUS HEADLAMP	\$ 150.00	30
7	TO REMOVE AND REFITX DASHBOARD TO ASSIST WORK	\$ 250.00	20
8	TO RE-ALIGN EXHAUST CATALYST CONVERTER	\$ 25.00	X
9	TO CHECK ELECTORICAL WIRING FOR FORNT LIG	\$ 130.00	30
10	TO RESET AND PROGRAM ECU AND FAULT CODE	\$ 250.00	X
11	TO DISMANTLE SEATS & REPLACE NEW PARTS	\$ 350.00	X
12	TO CONDUCT CHASSIS LIGNMENT	\$ 350.00	250
13	TO TRANSFER RH FRONT DOOR AND REFIT NEW DOOR	\$ 150.00	X
14	TO REMOVE AND REFIT LH FRONT DOOR	\$ 150.00	80
15	TO SPRAY PAINT RH SLIDING DOOR	\$ 250.00	200
16	TO SPRAAY PAINT LH SLIDING DOOR	\$ 250.00	200
17	TO SPRAY PAINT ON LH REAR FENDER	\$ 250.00	✓
18	TO SPRAY PAINT TAILGATE	\$ 250.00	✓
19	TO SPRAY PAINT REAR BUMPER	\$ 250.00	200

20	TO SPRAY PAINT RH FRONT DOOR	\$	150.00	✓
21	TO SPRAY PAINT FRONT BUMPER	\$	250.00	200
22	TO SPRAY PAINT BONNET	\$	250.00	200
23	TO SPRAY PAINT FRONT BUMPER REINFORCEMENT	\$	250.00	X
	Sub Total	\$	9,025.00	
	Grand Total	\$	96,308.55	

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: