





| PRE-REPAIR INSPECTION REPORT   |                                  |   |                         |  |
|--|----------------------------------|---|-------------------------|--|
| LONPAC INSURANCE BHD   |                                  | Ref: CS3/LPC19016809/T1tf3s2  |                         |  |
| 300 BEACH ROAD   |                                  | Date: 11-10-2019  |                         |  |
| #17-04/07 THE CONCOURSESINGAPORE 199555  |                                  |    |                         |  |
|  |                                  | Code: LPC2  |                         |  |
| <b>1. Policy Particulars :- (THIRD PARTY CLAIM)</b>  |                                  |   |                         |  |
| Insured Veh.   | SKM 8009A                        | Veh. Inspected  | XE 1001E                |  |
| Policy No.   |                                  | Coverage (\$)   | 0.00                    |  |
| Claim No.  | 19/19/19/VP05/022393             | Excess (\$)   | 0.00                    |  |
| Assign From  | KENNY LIM CHING GHEE             | Assign Date   | 24/09/2019              |  |
| <b>2. Vehicle Particulars &amp; Condition</b>  |                                  |   |                         |  |
| Make & Model   | MITSUBISHI FUSO                  | c.c   | 11967                   |  |
| Engine No.   | HIDDEN                           | Year of Reg.  | 2015                    |  |
| Chassis No.  | --                               | Colour  | BLUE                    |  |
| Odometer   | 168937 KM                        | Steering  | IN ORDER                |  |
| Brakes   | IN ORDER                         | Modification  | NIL                     |  |
| General  | GOOD                             |   |                         |  |
| <b>3. Conditions of Tyres</b>  |                                  |   |                         |  |
|  | Size                             | Make  | Balance                 |  |
| R/H Front Tyre   | 295/80 R22.5                     | HANKOOK   | 8 mm                    |  |
| L/H Front Tyre   | 295/80 R22.5                     | HANKOOK   | 8 mm                    |  |
| R/H Rear Tyre  | 295/80 R22.5 (D)                 | HANKOOK   | 8/8 mm                  |  |
| L/H Rear Tyre  | 295/80 R22.5 (D)                 | HANKOOK   | 8/8 mm                  |  |
| <b>4. Description of Damages</b>   |                                  |   |                         |  |
| THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.   |                                  |  |                         |  |
| <b>5. General Information</b>  |                                  |   |                         |  |
| Accident Date  | 17/09/2019                       | Inspect Date / Time   | 25/09/2019 ( 02:00 PM ) |  |
| Survey held at   | 20 BAH SOON PAH ROAD (SEMBAWANG) |   |                         |  |
| Repairer   | CONVINCE AUTO PTE LTD            |   |                         |  |
| <b>5a. Remarks</b>   |                                  |   |                         |  |
| A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.<br>B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.<br>THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.<br>C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. |                                  |   |                         |  |

Report Ref No. CS3/LPC19016809/T1tf3s2

**Inspected By**



MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor



K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.