

ASS. REC. BY:

REF:

CS/INC19016811/719d3e2

Special Instruction:

Surveyor: Tan HuiASSIGNMENT (Office)From (Person): Annie Koh

of

INC

Date/Time:

24/9/19 @ 9:20am

Estimated Cost:

Bill to:

OD (T) / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

PC4642R

Insured:

GBE 2998H

at Workshop m/s

ULB Engineering

Tel:

62681281

of

2C Julien Restaurant

Policy No:

Claim No:

M7/106 3347-002

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

19/9/2019

CA / REV / REP. / REV 24 HRS

Date/Time: 10:00am @ 24/9/19

Person Contacted:

Ann  
Ah Xing  
Ah Xing

H.O.D. Endorsement:

Vehicle IN OUT

Date/Time

Action/Instruction

Tan HuiPC4642R- NA/MSG19016603/h420th 19/09/2019GBE 2998H-x05/11/19 @12:05pm checked with Ah Xing, they didn't repair the vehicle.05/11/19Submit Prelim. report. - The vehicle has not send for repair.

Taufik

REF:

INC

2023 Dec.  
2013 Dec.

From	Date	Vehicle No.	PC4642R	at Repair	
Estimated Cost		Type	M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /		
OD / TP / WS / TP RES / OD RES / EVA / INV / MV		Truck / Trailer or			
To inspect Vehicle No.		Make	LS454 LT134P		7790
at Workshop no.		Colour	Purple	A/C	Insured / Std / NI / NA
of		Sp. Reading		T/Radio	Insured / Std / NI / NA
Insured		Eng/No	JALL7134PC		7000046
Policy No.		C/No			
Claims No.		Gen. Cond.	Good / Fair / Poor / Burnt		
Sum Insured	Excess:	Steering	Inorder / Jammed / Leaked / Burnt or		
(Client's Receipt)		Brake	Inorder / Jammed / Leaked / Burnt or		
Make of Veh.		Modi	NI / S/Rim / STD A/Rim or		
(Policy Condition)		Tyre Size	F: 295 / 80R22.5		(D)
Remark: The veh had commenced its repair at the time of inspection.		R:			
			BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /		
			TOYO / YOKO or		
Bal. or Market Value.	\$38K	Front		Rear	
IDAC Accident Report	Consistent? : Yes or No	R/Bal.	8 mm	R/Bal.	S/S mm
GIA / PE Seen	Consistent? : Yes or No	L/Bal.	8 mm	L/Bal.	8/8 mm
Est. Repairs	6 days Res: Yes or No	D.O.A.		D.O.I.	24/9/19C 1130
Lum Sum	% 3 Val: Yes or No	Survey held at	UCB		20 Jm Permitt
CA / REV / REP. / 24 HRS		Des. of Damages	Frnt / Rear / O/S / N/S / U/C / Rooftop or		
Date	Person Contacted		Rear O/S		
			Vehicle IN / OUT		
			The U/C / Chassis frame / Body Structure affected due to collision		

N/S	O/S

Date / Time Action / Instruction # Battery week

Taufik  
Pls check parts prices.

RECEIVED 05 NOV 2019

25/9.

Date/Time: File Pass to?

05/11/2019

☒ : Preli. Report

☐ : Final Report

Date/Time: File Return to?

Days Of Repair:

Resurvey No. of Trip:

Add Fee:

<input type="checkbox"/>	Site Insp.	1\$
<input type="checkbox"/>	Interview	1\$
<input type="checkbox"/>	Test	1\$
<input type="checkbox"/>	Work	1\$

Survey Fee

Transportation

240
240

Report Format :

Lump Sum / L.B / P.C.

## Nivitha (LKK Auto)

**From:** Annie Koh <annie.koh@income.com.sg>  
**Sent:** Tuesday, 24 September 2019 9:26 AM  
**To:** 'assignments@lkkauto.com'; Admin-D (LKKAuto)  
**Cc:** Thio Tse Kiat; Teng Ken Leong  
**Subject:** RE: TP CASES FARMED OUT TO LKK ON 24/09/2019

Dear LKK,

Please assist to survey the following vehicles as per Mr Teng's instruction :-

SN	Surveyor	Claim No.	Vehicle	WorkShop Name	WorkShop Address	WorkShop Contact	Survey Time	SJE	Zone	Additional Remarks
1	Eric Tang	MT/1062171-002	XE2117Z	HOME ADDRESS	4 BENOI ROAD SINGAPORE 629878	Mr. Cai Wang / 96194774	10:00-12:00	XD5577P	12/9/19	Workshop : Sin Trans Engineering Pte Ltd
2	Charlotte Chew	MT/1063347-002	PC4642R	UCB ENGINEERING PTE LTD	2C JALAN PESAWAT JURONG SINGAPORE 619359	ah siang / 62681281		GBE2998H	19/9/19	62684816- Ah Siang or Mr Tan 97381908
3	Jared Liu	MT/1062081-001	SLK5002L	VOLKSWAGEN CENTRE SINGAPORE	247 ALEXANDRA ROAD SINGAPORE 159934	charmaine kong / 63057176	14:00-16:00	GBD2176T	9/9/19	
4	David Phua	MT/1023269-001	SJA6522Y	TAN CHONG MOTOR SALES PTE LTD	913 BUKIT TIMAH ROAD SINGAPORE 589623	ZUHRI / 67038916	14:00-16:00	GBH5671P	19/11/18	Owner waiting

**Please contact workshops.**

Please revert to officer-in-charge after survey.

Thank you.

Annie Koh  
Senior Admin Assistant, Motor Insurance  
T +65 6430 7899  
[www.income.com.sg](http://www.income.com.sg)



---

#### Disclaimer

This e-mail contains privileged or confidential information which is intended only for the use of the recipient(s) named above. If you have received this message in error, please notify the sender immediately and delete all copies of it. Thank you.

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	719N
Vehicle Details	
Vehicle No.:	PC4642R
Vehicle to be Exported:	No
Intended Deregistration Date:	25 Sep 2019
Vehicle Make:	ISUZU
Vehicle Model:	LT134P
Primary Colour:	Multicolor
Manufacturing Year:	2012
Engine No.:	6HK1622180
Chassis No.:	JALLT134PC7000046
Maximum Power Output:	-
Open Market Value:	\$103,172.00
Original Registration Date:	27 Dec 2013
First Registration Date:	27 Dec 2013
Transfer Count:	3
Actual ARF Paid:	\$5,159.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	26 Dec 2023
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
QP Paid:	\$48,001.00
COE Rebate Amount:	\$20,723.00
Total Rebate Amount:	\$20,723.00

The information contained herein is correct as at 25 Sep 2019

OK

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	19/09/2019 16:44
Date Of Accident	19/09/2019 13:05
Exact Location Of Accident	PIE(TUAS) AT TOH TUCK FLYOVER
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	PC4642R
<b>Insured/Policyholder</b>	
Name Of Registered Owner	SIN ANN TRAVEL & COACH SERVICES PTE LTD
Co Reg No	201500719N
Email Address	FENGLEIREN80@GMAIL.COM
Mobile Phone No	(LOCAL) +65-85883239
Alternative Phone No	OFFICE-NOPHONE

### Vehicle Particulars

Manufacturer	ISUZU
Model	LT134P-7.8 D (A)

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category BUS

### Insurance Company

Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	P2153793
Cover Note Number	

### Driver

Name of Driver	NG KIM HOCK
NRIC No	S0807360J
Date Of Birth	08/11/1953
Occupation	OUTDOOR
Date Of Driving Pass	15/09/2010
Driving Experience	9 YEARS AND 0 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96696408
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	229 YISHUN ST 21 #09-560
Postcode	760229
Was driver an employee of the Insured's Company	YES
If No, Relationship of the Driver with the Insured	
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	CHAIN COLLISION
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	4
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	22

#### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

REFER TO SKETCH PLAN

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GBE2998H
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	JASMAN BIN TIRON
NRIC/Passport Number	S1450469I
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

#### DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number	GW226L
-----------------------------	--------

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category

COMMERCIAL VEHICLE

Name of Driver

CHAN SOO PIN

NRIC/Passport Number

S2014340A

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

#### DETAILS OF OTHER VEHICLE PROPERTY 3

Vehicle Registration Number

YP3497A

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category

COMMERCIAL VEHICLE

Name of Driver

YUSSAINI BIN BAKAR

NRIC/Passport Number

S7247714F

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)



SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature  
Date & Time:

Driver's Signature  
(if driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

I AM AWARE THAT MY INSURER MAY HAVE A 14 DAYS TIMEFRAME FOR ME TO SUBMIT AN OWN DAMAGE CLAIM UNDER MY OWN POLICY. I WILL CHECK MY POLICY FOR MORE DETAILS.

## SKETCH PLAN



PIE (TMS)  
@ Toh Tuck Flyover

(K) PC4642P

(B) 4BE2998H

(C) GW226L

(D) YP3497A

## DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 19/09/19 @ around 1305 hrs, I was travelling along PIE towards TMS direction.

While at around Toh Tuck Flyover, the vehicles in front had jammed brakes & I also applied my brake & I almost come to a stop suddenly I felt an impact on my rear & pushed me forwards, after that I went down to check & found that Vehicle B had collided onto my vehicle & caused my rear right portion & front portion damages. It is a chain collision on this accident.

## DECLARATION

I/We declare the foregoing particulars are true in every respect.



Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

- ☐ Claim own policy  
☐ Claim third party  
☒ Claim OD at other works hop UB Engineering  
☐ For record purpose

Policy No. P2153793

Insurer: AXA Veh. No. PC4642P

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:



# UCB Engineering Pte Ltd

GST Registration Number: 19-9501338-G

Business Reg. No. 199501338G

Our ref: 190907.SA(PA4642R)

23<sup>rd</sup> September 2019

Sin Ann Travel & Coach Services Pte Ltd  
Blk 520 Tampines Central 8  
#15-51 Tampines Central 8  
Singapore 522520

## QUOTATION

without Prejudice

Dear Sir,

### COST OF REPAIR FOR PC 4642 R

#### QTY DESCRIPTIONS

QTY	DESCRIPTIONS
1pc	Rear bumper
1	Rear bumper iron structure
1 pc	Rear compartment door
1 pc	Rear lamp – RH
1 pc	Radiator door aluminium panel

QTY	DESCRIPTIONS
1	Labour charges for remove & replace the above damaged parts
	Checking alignment & patching fiberglass
	To putty & spray painting onto complete rear body panel
1	Wiring charges

PRICE  
S\$

2,750.00  
650.00  
3,250.00  
850.00  
950.00

2,500.00

1,200.00  
30.00

Total

12,180.00

(SGD: Twelve Thousand One Hundred And Eighty Only)

Price quoted above is subjected to 7% GST

Yours faithfully,  
Tan Tiong Chia

LKK Auto Consultants hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

2C Jalan Pesawat, Jurong, Singapore 619359

Tel: 6268 1281 Fax: 6268 1282

E-mail: [unitedcb@singnet.com.sg](mailto:unitedcb@singnet.com.sg)

parts 10%

8650

10% 7785

450

1800

1000

# 67418434

97495749

24/9/19 @ 1130

luncheon

Resurvey after repair

Shuc (Insurance)

06 days




# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref : CS/INC19016811/T1qd3e2				
73 BRAS BASAH ROAD #05-01 NTUC TRADE UNION HOUSESINGAPORE 189556			Date : 15-11-2019	
ATTN: CHARLOTTE CHEW			Code : INC	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	GBE 2998H	Veh. Inspected	PC 4642R	
Policy No.		Coverage (\$)	0.00	
Claim No.	MT/1063347-002	Excess (\$)	0.00	
Assign From	ANNIE KOH	Assign Date	24/09/2019	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model	ISUZU LT134P	c.c	7790	
Engine No.	HIDDEN	Year of Reg.	2013	
Chassis No.	JALLT134PC7000046	Colour	PURPLE	
Odometer	-	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre	295/80 R22.5	BRIDGESTONE	8 mm	
L/H Front Tyre	295/80 R22.5	BRIDGESTONE	8 mm	
R/H Rear Tyre	295/80 R22.5 (D)	BRIDGESTONE	8/8 mm	
L/H Rear Tyre	295/80 R22.5 (D)	BRIDGESTONE	8/8 mm	
<b>4. Description of Damages</b>				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION. DAMAGES SEE DETAILS.				
<b>5. General Information</b>				
Accident Date	19/09/2019	Inspection Date	24/09/2019	
Survey held at	UCB ENGINEERING PTE LTD 2C, JALAN PESAWAT, JURONG, SINGAPORE 619359			
<b>5a. Remarks</b>				
A)THE VEHICLE HAS NOT SEND IN FOR REPAIRS. B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
<b>5b. Estimate Days of Repair</b>				
ESTIMATED NORMAL PERIOD FOR REPAIR:		6 Working Days		



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

### ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. PC 4642R

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b>REPLACEMENT OF PARTS</b>			
1	REAR BUMPER	CRACKED	2,750.00	2,750.00
1	REAR BUMPER IRON STRUCTURE	TO REPAIR SEE LABOUR	650.00	-
1	REAR COMPARTMENT DOOR	CRACKED	3,250.00	3,250.00
1	REAR LAMP - RH	CRACKED	850.00	850.00
1	RADIATOR DOOR ALUMINIUM PANEL	BENT	950.00	950.00
	LESS 10% DISCOUNT		-	-780.00
			8,450.00	7,020.00
	<b>LABOUR</b>			
	LABOUR CHARGES FOR REMOVE & REPLACE THE ABOVE DAMAGED PARTS. CHECKING ALIGNMENT & PATCHING FIBERGLASS. INCLUSIVE OF THE REPAIR OF REAR BUMPER IRON STRUCTURE.		2,500.00	1,800.00
	TO PUTTY & SPRAY PAINTING ONTO COMPLETE REAR BODY PANEL.		1,200.00	1,000.00
	WIRING CHARGES.		30.00	30.00
			3,730.00	2,830.00
	<b>GRAND TOTAL</b>		<b>12,180.00</b>	<b>9,850.00</b>
	<b>RECOMMENDED COST OF REPAIRS (REPAIR COST NOT CONCLUDE)</b>			<b>9,850.00</b>

Report Ref No. CS/INC19016811/T1qd3e2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons), B.Bus, MBA, PEng, PE,  
MInstAEA, MASME, MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.