



**TP Claims against NTUC Income: Follow-Through Survey**

Date : 18/10/2019

S/No	Income Reference	Claimant (Owner / Taxi Company)	Claimant Vehicle No.	Income Vehicle No.	Date of Accident	Time of Accident	Estimate
1	<b>MT/1063635-002</b>	SMRT TAXIS PTE LTD	SHF 412T	SLW 6652R	22/09/2019	13:10	\$ 10,032.90
2	<b>MT/1066688-002</b>	COMFORTDELGRO ENGINEERING PTE LTD	SHC 138SY	SLS 745S	14/10/2019	8:40	\$ 1,821.95
3	<b>MT/1035111-002</b>	SMRT TAXIS PTE LTD	SHB 833H	SMH 5077A	08/03/2019	8:30	\$ 17,840.51

Hello, NAC\_PAYA\_UBI\_800601

[My Desktop](#)  
[Notice of Loss](#)

## Policy Query

Policy No.

Vehicle No.(For Motor)

Date of Accident

Certificate Number

22/09/2019 09:01

SLW6652R

Search

Select	Policy No.	Certificate Number	Policyholder Name	Policyholder NRIC	Product	Cover Type	Vehicle No.	Insured Object	Commence Date	Expiry Date
<input type="radio"/>	5096979944-01		GLIDERS AUTO TRADING	53375166K	GFT	drive CLASSIC	SLW6652R	SLW6652R	27/12/2018	

Continue

> Back to OneMotoring

## Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	369K
Vehicle Details	
Vehicle No.:	SHF412T
Vehicle to be Exported:	No
Intended Deregistration Date:	24 Sep 2019
Vehicle Make:	TOYOTA
Vehicle Model:	PRIUS HYBRID 1.8 CVT
Primary Colour:	Maroon
Manufacturing Year:	2017
Engine No.:	2ZR8266118
Chassis No.:	JTDKB3FU103577259
Maximum Power Output:	90.0 kW (120 bhp)
Open Market Value:	\$29,007.00
Original Registration Date:	19 Dec 2017
First Registration Date:	19 Dec 2017
Transfer Count:	0
Actual ARF Paid:	\$5,000.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	18 Dec 2025
PARF Rebate Amount:	\$3,750.00
Intended COE Rebate Details	
COE Expiry Date:	18 Dec 2025
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	8
PQP Paid:	\$34,159.00
COE Rebate Amount:	\$26,608.00
<b>Total Rebate Amount:</b>	<b>\$30,358.00</b>
Message	
Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 24 Sep 2019

OK

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	23/09/2019 11:02
Date Of Accident	22/09/2019 13:10
Exact Location Of Accident	RIVER VALLEY ROAD
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHF412T
<b>Insured/Policyholder</b>	
Name Of Registered Owner	SMRT TAXIS PTE LTD
Co Reg No	198905369K
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-800000000

### Vehicle Particulars

Manufacturer	TOYOTA
Model	FRIUS TAXI-1.8 (A)
Exact Purpose for which vehicle was being used at time of accident	HIRE AND REWARD
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI

### Insurance Company

Name of Insurance Company	MS FIRST CAPITAL INSURANCE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	YES
Policy Number	D-19093197MFSH
Cover Note Number	

### Driver

Name of Driver	YEOW CHEE KEONG
NRIC No	S7343684B
Date Of Birth	19/11/1973
Occupation	OUTDOOR
Date Of Driving Pass	04/07/1997
Driving Experience	22 YEARS AND 2 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-80000000
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	534
Postcode	
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	SIDE SWIPE
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	3
Passenger 1	NAME: : UNKNOWN GENDER: : FEMALE
Passenger 2	NAME: : UNKNOWN GENDER: : FEMALE

#### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

I WAS DRIVING STRAIGHT ALONG RIVER VALLEY ROAD AT THE SECOND LEFT LANE WITH TWO PASSENGERS ON BOARD WHEN THE VEHICLE SLW6652R FROM THE RIGHT LANE CUT INTO MY LANE AND COLLIDED ONTO THE RIGHT REAR PORTION OF MY TAXI.

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLW6652R
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	MOHAMMAD FAIRUZ BIN SALIM
NRIC/Passport Number	
Contact Number	
Address	

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)






SKETCH PLAN


IMPORTANT NOTICE


1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

  
Policyholder's Signature  
Date & Time:

  
Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

  
Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

## Case Details

Case Reference Number :

TAX/09/19/2082

Type of Repair : Accident Repair

Vehicle Registration Number : SHF412T

Company Type : SMRT Taxis Pte Ltd

Estimation ID : EST-8615-ID

Assigned By : Taxi Claims Manager Team

Insurance Company Name : NTUC Income Insurance Co-operative Ltd

Accident Date and Time : 22/09/2019 05:10 AM

Vehicle Age(In Months) : 21

## Documents / Photographs

View Documents / Photographs

Total Documents: 1

## Estimation Details

### Spare Part's Cost Detail

BOM Type	Costing Type	Portion	Material Number	SMRT Recommendation							Surveyor Approval			
				Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			COVER, RR BUMPER ASSY	1	423.90	423.90	25.00	317.92	Replace	1	0	Repair	R
One Time Key In	Main			CLIPS PIECE, FRT & RR BUMPER	10	1.50	15.00	25.00	11.25	Replace	0	0	Not Give	X SVC
One Time Key In	Main			FILLER, RR BUMPER, RH	1	119.90	119.90	25.00	89.93	Replace	0	0	Not Give	X SVC
One Time Key In	Main			PIXEL STICKER	2	60.00	120.00	0.00	120.00	Replace	2	120.00	Replace	/ Nec
One Time Key In	Main			PAD, RR BUMPER, RH & LH, 1	2	3.80	7.60	25.00	5.70	Replace	0	0	Not Give	X SVC
One Time Key In	Main			PAD, RR BUMPER, RH & LH, 2	2	3.80	7.60	25.00	5.70	Replace	0	0	Not Give	X SVC
One Time Key In	Main			PAD, RR BUMPER, RH & LH, 3	2	3.80	7.60	25.00	5.70	Replace	0	0	Not Give	X SVC
One Time Key In	Main			SEAL, RR BUMPER ARM, RH & LH	2	11.00	22.00	25.00	16.50	Replace	0	0	Not Give	X SVC
One Time Key In	Main			RETAINER, RR BUMPER, RH	1	112.70	112.70	25.00	84.53	Replace	1	84.53	Replace	/ Nec
One Time Key In	Main			SEAL, RR BUMPER, RH	1	85.20	85.20	25.00	63.90	Replace	0	0	Not Give	X SVC
Total Spare Part Cost									5,153.45	Surveyor Total 823.13				
Lump Sum Discount (%)									0.00	Lump Sum Dis (%) 0				
Final Spare Part Cost									5,153.45	Final Sur Total 823.13				

BOM Type	Costing Type	Portion	Material Number	SMRT Recommendation							Surveyor Approval			
				Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			GUARD, RR BUMPER, LOWER	1	558.30	558.30	25.00	418.72	Replace	0	0	Not Give	X SVC
One Time Key In	Main			COVER, GUARD RR BUMPER LOWER	1	14.80	14.80	25.00	11.10	Replace	0	0	Not Give	X SVC
One Time Key In	Main			PAD, RR BUMPER, CTR	3	2.20	6.60	25.00	4.95	Replace	0	0	Not Give	X SVC
One Time Key In	Main			LENS & BODY ASSY, RR BUMPER, RH	1	486.80	486.80	10.00	438.12	Replace	0	0	Not Give	X SVC
One Time Key In	Main			COVER, REAR FLOOR UNDER, RH	1	169.50	169.50	25.00	127.13	Replace	0	0	Not Give	X SVC
One Time Key In	Main			PANEL SUB-ASSY, FENDER REAR RH	1	624.80	624.80	25.00	618.60	Replace	1	618.60	Replace	/ PD
One Time Key In	Main			DUCT ASSY, QUARTER VENT, RH & LH	1	65.00	65.00	25.00	48.75	Replace	0	0	Not Give	X SVC
One Time Key In	Main			LINER, REAR FENDER, RH	1	135.80	135.80	25.00	101.85	Replace	0	0	Not Give	X SVC
One Time Key In	Main			MOULDING ASSY, BODY ROCKER PANEL, LH	1	576.00	576.00	25.00	432.00	Replace	0	0	Not Give	X SVC
One Time Key In	Main			PANEL SUB-ASSY, REAR DOOR, LH	1	1,243.90	1,243.90	25.00	932.93	Replace	0	0	Not Give	X SVC
One Time Key In	Main			WHEEL, DISC	1	1,555.10	1,555.10	25.00	1,166.32	Replace	1	0	Repair	R
One Time Key In	Main			CAP SUB-ASSY, WHEEL	1	175.80	175.80	25.00	131.85	Replace	0	0	Not Give	X SVC
Total Spare Part Cost									5,153.45	Surveyor Total 823.13				
Lump Sum Discount (%)									0.00	Lump Sum Dis (%) 0				
Final Spare Part Cost									5,153.45	Final Sur Total 823.13				

#### Labour's Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO REPAIR RH REAR PORTION	845.00	600	
Total:			845.00	600.00	

### Spray Cost Detail



S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO RESPRAY REAR BUMPER	378.00	200	
2	Main	TO RESPRAY FILLER RR BUMPER RH	180.00	0	
3	Main	TO RESPRAY REAR FENDER RH	378.00	200	
4	Main	TO RESPRAY ROCKER PANEL MOULDING	180.00	0	
5	Main	TO RESPRAY RH REAR DOOR	378.00	0	
6	Main	RESPRAY WHEEL CAP	180.00	0	
7	Main	TO RESPRAY RIM	180.00	50	
Total:			1,854.00	450.00	

### Other Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO CHECK WIRING AND SYSTEM FUNCTION	80.00	20	/ Nec
2	Main	TO APPLY RUST-PROOFING ON AFFECTED AREA	100.00	30	/ Nec
3	Main	TO DO WHEEL ALIGNMENT / TYRE BALANCING	120.00	60	/ Nec
4	Main	TO REMOVE AND REFIT TYRE RIM (SPRAYING PURPOSE)	120.00	20	/ Nec.
5	Main	TO TEST AND REFIX REVERSE SENSOR SYSTEM	120.00	0	
6	Main	TO WASH AND VACUUM	60.00	0	
Total:			600.00	130.00	

## Summary

	Estimator Assesment(\$)	Surveyor Assesment(\$)
Total Spare Part Detail	5,153.45	823.13
Total Labour Cost	845.00	600.00
Total Spray Painting	1,854.00	450.00
Other	600.00	130.00
Overall Total	8,452.45	2,003.13
Lump Sum Repair Option		

	Estimator Assessment(\$)	Surveyor Assessment(\$)
Lump Sum Total	0.00	2,003.13
Surveyor Approved Amount		2,003.13
No of Repair Days*	6	5/6
Remarks		P/P Repair, Take before spray.
Surveyor Name		STEVE CHEN
Signature		 25/9/19
Survey Date	24/09/2019	<input type="button" value="Save"/> <input type="button" value="Clear"/>

Repair Day - 6 days.

Steve.  
24/09/2019  
P/P Repair, before spray

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature: \_\_\_\_\_  
Date: \_\_\_\_\_

10032.90

# **REQUEST FOR SUPPLYMENT PARTS**

Contractor:		WEGA ENGINEERING PTE LTD	
Accident Case Number	704/04/19/2082	Date of Collection	25/9/19
Vehicle No	SHE 412 T	Date of Request	30/9/19
Vehicle Model	TOYOTA PRIUS 4	Number of Days to Extend (If any)	1083- ✓

S/N	Part Number	Part Description	Quantity	Unit Price
		To Request one more working day ✓		

\*\*\*Please submit photographs for damaged parts\*\*\*

I, (Name) Steve (LKK) 30/9/19  
 (Position) CLARK



Do solemnly and sincerely declare that Supplementary Parts are raised for replacement for the aforesaid vehicle.

Signature of person making this declaration  
 [To be signed in front of an authorised witness]  
 I acknowledge that this declaration is true and correct, and I make it with the understanding and belief that a person who makes a false declaration is liable to the damages of perjury.

For SMRT Staff	
Acknowledge By	ARC Executive / Supervisor / SA
Approval By	Surveyor / In-house Staff
Parts Ordering	SMRT Store / Contractor Supply Form 22 / WCH
Photo Submitted	YES / NO

Form 22 / 19 / WCH Reservation Number: \_\_\_\_\_  
 Date of submission: \_\_\_\_\_

Section A - Accident Details	
Registration Number	SHF412T
Case Reference Number	TAX/09/19/2082
Registration Date	19/12/2017
Company Type	SMRT Taxis Pte Ltd
Make	TOYOTA
Model	PRIUS4
Name of Driver	YEOW CHEE KEONG ( YAO ZHIQIANG )
Type of Accident	Side Swipe
Accident Date and Time	22/9/2019 1:10 PM
Accident Reported Date and Time	23/9/2019 11:03 AM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	24103483
Special Instruction to ARC, if any	BP / NTUC - LKK
Prepared Date and Time	24/9/2019 11:47 AM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates		
Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$845.00	\$800.00
Total Spray Cost	\$1,854.00	\$450.00
Total Spare Part Cost	\$5,153.45	\$823.13
Total Other Cost	\$600.00	\$130.00
<b>TOTAL COST</b>	<b>\$8,452.45</b>	<b>\$2,003.13 (P/P)</b>
Lump Sum Total	\$0.00	\$0.00
Number of Repair Days	7.0	6.0
Prepared / Adjusted By	Tuck Foo Kok	STEVE CHEN (LKK) / NTUC
ARC / Surveyor Sign Off Date	01/10/2019 8:34 AM	01/10/2019 11:31 AM
Signature		
Remarks	Total number of repair days = 6 days. SUP = + 1 day.	
	P/P Repair. Take before spray.	



## SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
68 Woodlands Industrial Park EA, Singapore 757705
FAX Number: 63655592
Estimator Telephone Number: 98662023
Accident Reporting Number: 68662072

Date Generated : 17/10/2019

User ID : PehSuan

## Section C - Quotation and Accident Invoice Details

Quotation Number	QN-1910-0309	Invoice Number	
Quotation Date	16.10.2019	Invoice Date	
Invoice Amount		Prepared Date	

## Section D - Details of Repair Estimates

## Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REPAIR RH REAR PORTION	\$845.00	\$600.00
Total Labour	\$845.00	\$600.00

## Part 2 - Spray Painting &amp; Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO RESPRAY REAR BUMPER	\$378.00	\$200.00
TO RESPRAY FILLER RR BUMPER RH	\$180.00	\$0.00
TO RESPRAY REAR FENDER RH	\$378.00	\$200.00
TO RESPRAY ROCKER PANEL MOULDING	\$180.00	\$0.00
TO RESPRAY RH REAR DOOR	\$378.00	\$0.00
RESPRAY WHEEL CAP	\$180.00	\$0.00
TO RESPRAY RIM	\$180.00	\$50.00
Total Spray Painting & Panel Beating	\$1,854.00	\$450.00

## Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO CHECK WIRING AND SYSTEM FUNCTION	\$80.00	\$20.00
TO APPLY RUST-PROOFING ON AFFECTED AREA	\$100.00	\$30.00
TO DO WHEEL ALIGNMENT / TYRE BALANCING	\$120.00	\$60.00
TO REMOVE AND REFIT TYRE RIM (SPRAYING PURPOSE)	\$120.00	\$20.00
TO TEST AND REFIX REVERSE SENSOR SYSTEM	\$120.00	\$0.00
TO WASH AND VACUUM	\$60.00	\$0.00
Total Other Costs	\$600.00	\$130.00

## Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
		5215947913	COVER, RR BUMPER ASSY	1.00	\$423.90	100.00	\$0.00	Replace	Repair
		5216116010	CLIPS PIECE, FRT & RR BUMPER	0.00	\$1.50	0.00	\$0.00	Replace	Not Given
		5256547900	FILLER, RR BUMPER, RH	0.00	\$119.90	0.00	\$0.00	Replace	Not Given
			PIXEL STICKER	2.00	\$60.00	0.00	\$120.00	Replace	Replace
		5246247030	PAD, RR BUMPER, RH & LH, 1	0.00	\$3.80	0.00	\$0.00	Replace	Not Given
		5246247020	PAD, RR BUMPER, RH & LH, 2	0.00	\$3.80	0.00	\$0.00	Replace	Not Given
		5246247010	PAD, RR BUMPER, RH & LH, 3	0.00	\$3.80	0.00	\$0.00	Replace	Not Given
		5219147030	SEAL, RR BUMPER ARM, RH & LH	0.00	\$11.00	0.00	\$0.00	Replace	Not Given
		5257547040	RETAINER, RR BUMPER, RH	1.00	\$112.70	25.00	\$84.53	Replace	Replace





## SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd  
50 Woodlands Industrial Park E4, Singapore 757705  
FAX Number 63585592  
Estimator Telephone Number 68982823  
Accident Reporting Number 6862572

Date Generated : 12/10/2019

User ID : PohSuan

	52591470 50	SEAL, RR BUMPER, RH	0.00	\$85.20	0.00	\$0.00	Replace	Not Given	X
	52453470 10	GUARD, RR BUMPER, LOWER	0.00	\$558.30	0.00	\$0.00	Replace	Not Given	X
	52169470 20	COVER, GUARD RR BUMPER LOWER	0.00	\$14.80	0.00	\$0.00	Replace	Not Given	X
	52461470 10	PAD, RR BUMPER, CTR	0.00	\$2.20	0.00	\$0.00	Replace	Not Given	X
	81581470 10	LENS & BODY ASSY, RR BUMPER, RH	0.00	\$486.80	0.00	\$0.00	Replace	Not Given	X
	58398470 50	COVER, REAR FLOOR UNDER, RH	0.00	\$169.50	0.00	\$0.00	Replace	Not Given	X
	61601471 50	PANEL SUB-ASSY, FENDER REAR RH	1.00	\$824.80	25.00	\$618.60	Replace	Replace	X
	62940470 10	DUCT ASSY, QUARTER VENT, RH & LH	0.00	\$65.00	0.00	\$0.00	Replace	Not Given	X
	65637470 60	LINER, REAR FENDER, RH	0.00	\$135.80	0.00	\$0.00	Replace	Not Given	X
	75860479 00	MOULDING ASSY, BODY ROCKER PANEL, LH	0.00	\$576.00	0.00	\$0.00	Replace	Not Given	X
	67004472 10	PANEL SUB-ASSY, REAR DOOR, LH	0.00	\$1,243.90	0.00	\$0.00	Replace	Not Given	X
	42611474 50	WHEEL, DISC	1.00	\$1,555.10	100.00	\$0.00	Replace	Repair	X
	42602471 80	CAP SUB-ASSY, WHEEL	0.00	\$175.80	0.00	\$0.00	Replace	Not Given	X
Total				\$6,633.60		\$823.13			

## Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
Total									

823.13  
+ 600.00  
+ 580.00  

---

2003.13

**National Assessment Centre Services**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref: NS/INC19016853/Eqf3e2

73 BRAS BASAH ROAD

#05-01 NTUC TRADE UNION HOUSESINGAPORE Date: 24-10-2019

189556



Code: INC4

**1. Policy Particulars :- THIRD PARTY CLAIM**

Insured Veh.	SLW 6652R	Veh. Inspected	SHF 412T
Policy No.	5096979944-01	Coverage (\$)	0.00
Claim No.	MT/1063635-002	Excess (\$)	0.00
Assign From		Assign Date	24/09/2019

**2. Vehicle Particulars & Condition**

Make & Model	TOYOTA PRIUS	c.c	1798
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	JTDKB3FU103577259	Colour	MAROON
Odometer	184439	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	FAIR		

**3. Conditions of Tyres**

	Size	Make	Balance
R/H Front Tyre	195/65 R15	FALKEN	5 mm
L/H Front Tyre	195/65 R15	FALKEN	5 mm
R/H Rear Tyre	195/65 R15	FALKEN	5 mm
L/H Rear Tyre	195/65 R15	FALKEN	5 mm

**4. Description of Damages**

THE VEHICLE SUSTAINED DAMAGES AT THE O/S REAR PORTION. DAMAGES SEE DETAILS.
--

**5. General Information**

Accident Date	22/09/2019	Inspection Date	24/09/2019
Survey held at	SMRT AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705		

**5a. Remarks**

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
---

**5b. Estimate Days of Repair**

ESTIMATED NORMAL PERIOD FOR REPAIR:	6 Working Days
-------------------------------------	----------------

**National Assessment Centre Services**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 2

**ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHF 412T**

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b><u>REPLACEMENT OF PARTS</u></b>				
1	RETAINER, RR BUMPER, RH (DISC 25%)	NECESSARY	112.70	84.53
1	PANEL SUB-ASSY, FENDER REAR RH(DISC 25%)	DENTED	824.80	618.60
2	PIXEL STICKER @\$60.00 (SN)	NECESSARY	120.00	120.00
10	CLIPS PIECE, FRT & RR BUMPER @\$1.50	SERVICEABLE	15.00	-
1	FILLER, RR BUMPER, RH	SERVICEABLE	119.90	-
2	PAD, RR BUMPER, RH & LH, 1 @\$3.80	SERVICEABLE	7.60	-
2	PAD, RR BUMPER, RH & LH, 2 @\$3.80	SERVICEABLE	7.60	-
2	PAD, RR BUMPER, RH & LH, 3 @\$3.80	SERVICEABLE	7.60	-
2	SEAL, RR BUMPER ARM, RH & LH @\$11.00	SERVICEABLE	22.00	-
1	SEAL, RR BUMPER, RH	SERVICEABLE	85.20	-
1	GUARD, RR BUMPER, LOWER	SERVICEABLE	558.30	-
1	COVER, GUARD RR BUMPER LOWER	SERVICEABLE	14.80	-
3	PAD, RR BUMPER, CTR @\$2.20	SERVICEABLE	6.60	-
1	LENS & BODY ASSY, RR BUMPER, RH	SERVICEABLE	486.80	-
1	COVER, REAR FLOOR UNDER, RH	SERVICEABLE	169.50	-
2	DUCT ASSY, QUARTER VENT, RH & LH	SERVICEABLE	65.00	-
1	LINER, REAR FENDER, RH	SERVICEABLE	135.80	-
1	MOULDING ASSY, BODY ROCKER PANEL, LH	SERVICEABLE	576.00	-
1	PANEL SUB-ASSY, REAR DOOR, LH	SERVICEABLE	1,243.90	-
1	CAP SUB-ASSY, WHEEL	SERVICEABLE	175.80	-
1	COVER, RR BUMPER ASSY	TO REPAIR SEE LABOUR	423.90	-
1	WHEEL, DISC	TO REPAIR SEE LABOUR	1,555.10	-
			6,733.90	823.13
<b><u>LABOUR</u></b>				
PANEL BEATING & BODY WORK. INCLUSIVE OF THE REPAIR OF COVER, RR BUMPER ASSY AND WHEEL, DISC			845.00	600.00
SPRAY PAINT.			1,854.00	450.00
TO CHECK WIRING AND SYSTEM FUNCTION.			80.00	20.00

Report Ref No. NS/INC19016853/Eqf3e2



## National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO APPLY RUST-PROOFING ON AFFECTED AREA.		100.00	30.00
	TO DO WHEEL ALIGNMENT / TYRE BALANCING.		120.00	60.00
	TO REMOVE AND REFIT TYRE RIM (SPRAYING PURPOSE).		120.00	20.00
	TO TEST AND REFIX REVERSE SENSOR SYSTEM.	NOT NECESSARY	120.00	-
	TO WASH AND VACUUM.	NOT NECESSARY	60.00	-
			3,299.00	1,180.00
GRAND TOTAL			10,032.90	2,003.13

RECOMMENDED COST OF REPAIRS (CONFIRMED)				2,003.13
---	--	--	--	----------

Report Ref No. NS/INC19016853/Eqf3e2

CHEN TSUE YEE

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,  
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.