

Kanchana

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W. GST Reg. No. M2-0020081-X



Final Report

Estimate No. : **b1 52852**
Date Estimated : **25/09/2019**
Prepared By : **Inthiran A/L Thurasamy**

- ESTIMATE REPAIR FOR -
William Woo Siew Wing
26 Mei Hwan Crescent

Singapore 568471

- ACCOUNT - 121
AIG Asia Pacific Insurance Pte. Ltd.
78 Shenton Way
#08-16 Chartis Building
Singapore 079120

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SKB855J	WBAJX62060BJ239	08/10/2018	630i GT	0

DESCRIPTION	ACCOUNT: ORIGINAL PRICE	DISC. %	NETT
To replace front bumper and licence plate holder including to remove and install body parts in order to carry out painting job.	850.00	0	850.00 ✓
To respray front bumper.	934.00	0	934.00 ✓
To check electrical wiring systems at the front section for proper function including adjustments of headlights.	150.00	0	150.00 ✓
To supply front emboss number plate.	83.00	0	83.00 ✓
To remove old PDC assembly, replace damaged parts and reconnect to new bumper including conduct checks for proper function.	150.00	0	150.00 ✓
Sundries.	80.00	0	80.00 ✓

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
FRT BUMPER PANEL PRIMED (M/PDC/PMA)	1,935.50	1	0	1,935.50 ✓
LICENCE PLATE HOLDER (M)	84.80	1	0	84.80 ✓

	OD	3RD PARTY	DATE	WORKING DAYS
FAX TO FAX NO		Rasul UKK	28/10/19	3
FAX TO FAX NO				
FAX TO FAX NO				
CONFIRMED DATE				

Total Labour :	2,247.00
Total Parts :	2,020.30
Total Labour & Parts :	4,267.30
GST @7%:	298.71
Grand Total :	4,566.01

LOSS OF USE = \$120 X 3 DAYS.
GIA SEARCH FEE - \$2.00

BMW Dealer

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X
Toll-Free Number (1800-2255269)

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax. 64796601 (AfterSales)
64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

25 SEP 2019

E S T I M A T E

Estimate No. : b1 52852	Page No. : 1 of 5
Date Estimated : 25/09/2019	
Prepared By : Inthiran A/L Thurasamy	

- ESTIMATE REPAIR FOR - William Woo Siew Wing 26 Mei Hwan Crescent Singapore 568471	- ACCOUNT - 121 AIG Asia Pacific Insurance Pte. Ltd. 78 Shenton Way #08-16 Chartis Building Singapore 079120
--	--

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SKB855J	WBAJX62060BJ23982	08/10/2018	630i GT	0

DESCRIPTION	VALUE
To replace front bumper, air flap and attachments.	850 / 2,580.00
Painting front bumper.	934 / 1,088.00
To check electrical wiring systems at the front section for proper function including adjustments of headlights.	150 / 177.00
To supply front emboss number plate. 4 ✓	✓ 83.00
To remove old PDC assembly, replace damaged parts and reconnect to new bumper including conduct checks for proper function.	150 / 177.00
Sundries.	✓ 80.00
Total Labour 1:	<u>4,105.00</u>

DESCRIPTION	QTY	PRIC	VALUE
FRT RH GRILLE (SPORT) ? X8vc	1	171.10	171.10
Grille, fron ? X8vc	1	171.10	171.10
Trim cover, 2 ✓	1	1,935.50	1,935.50
SET MOUNTING PDC/PMA SENSOR FRT (M) X8vc	1	137.20	137.20
AIR FLAPS TOP ? X8vc	1	285.80	285.80
LICENCE PLATE HOLDER (M) 4 ✓	1	84.80	84.80
Total Parts :			<u>2,785.50</u>

BMW Dealer

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X
Toll-Free Number (1800-2255269)

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax. 64796601 (AfterSales)
64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

E S T I M A T E

Estimate No. : b1 52852
Date Estimated : 25/09/2019
Prepared By : Inthiran A/L Thurasamy

Page No. : 2 of 5

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SKB855J	WBAJX62060BJ23982	08/10/2018	630i GT	0

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Claims OD / Third Party / Uninsured losses / Direct Settlement	
Regn No.	Claim No.
Date of Time 01/10/19 @ 1000	Excess S\$
Surveyor's Name Rasul	Sign
Surveyor's Tel 90010068	Authorised Yes / No
Authorised Date	Time
REPAIR PARTS PHOTO BY SURVEYOR Yes / No PML Yes / No	
Surveyor's Email	
No. of Working Days Recommend 3 days	

Labour 1	:	4,105.00
Parts	:	2,785.50
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	482.34
Grand Total	:	7,372.84

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY**

** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **