

22/03/2002

ASS. REC. BY:

REF:

CS/ASM19016903/ET d307

Special Instruction:

Surveyor: Stev LASSIGNMENT (Office)From (Person): Kitty Teo

of

ASM (XIA)

Date/Time:

24/9/2019

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLH 9750A

Insured:

at Workshop m/s

Elite AM

Tel:

6339 7378.

of

280 Woodlands Ind. Purces #01-17

Policy No:

Claim No:

S9M 02179

Sum Insured:

Excess:

0-00

Make of Veh:

(Client's Record)

D.O.A.

20/09/2019CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

11:20am 25/9/19

Person Contacted:

ChristyVehicle IN/OUT

Date/Time

Action/Instruction

SchmidtSLH9750A-x30/9-Revised via Smart claim.N/2 final Bill in Smart claim.

ASS. REC. BY:

skwe

REF:

ASM(AXA) CS/ ASM 19016903/etd3

ASSIGNMENT

From:

Date:

30/9/19

Estimated Cost:

☒ OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

SLH 9750A

at Workshop m/s

Elite AM

of 280 woodlands Ind. Park ES #

Insured:

01-17

Policy No.

Claims No.

Sum Insured:

Excess:

TBA

(Client's Record)

Make of Veh:

11am (waiting)

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

XX	
N/S	O/S

Bal. or Market Value:

56K

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

☒ CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SLH 9750A

Yr Regn: 24/NOV/2016

Type: ☒ M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Chevrolet Cruze

C.C. 1598

Colour

Black.

A/C: Insured / Std / NI / NA

Sp. Reading

59828

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

KL1JA69E9GK344834

Gen. Cond: ☒ Good / ☒ Fair / Poor / BurntSteering: ☒ Inorder / Jammed / Leaked / Burnt orBrake: ☒ Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F: 215/50 R17

R: 215/50 R17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

5

mm

R/Bal.

5

mm

L/Bal.

5

mm

L/Bal.

5

mm

D.O.A.

20/09/2019

D.O.I. 30/09/2019

Survey held at

Elite.

Des. of Damages: ☒ Frt / ☒ Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Step 1

PLS check parts prices.

Lump Sum \$1550- cred' @ 984.60; 85%

RECEIVED 05 NOV 2019

Date/Time, File Pass to?

1) All Typist

Date/Time, File Return to?

2)

Rep. Formed:

Lump Sum / E.D. /

1550



Preli. Report



Final Report

Days Of Repair:

3

Resurvey No. of Trip:

1

Add Fee:



Site Insp (\$



Interview (\$



Tech. Invs (\$



Weekend (\$

Survey Fee:

Transportation:

S + RS. SI

Photos

Others

TOTAL

290

290



Service Request Details

Claim

S9M02179

Reference

None 

Loss Date

September 20, 2019

Report Date

Sep 20, 2019 3:52:56 PM

Request Date

September 24, 2019

Due Date

October 1, 2019

Vendor Name

LKK AUTO CONSULTANTS PTE LTD (OD)

Type of Loss

Own Damage

Services

Accelerated survey and authorize

Actions

Next Step

Agree to perform service

Decline Work

Accept Work

Vehicle Information

Incident Vehicle Registration #

SLH9750A

CRUZE 1.6

999

TEH HUEY MIN
BLK 815C CHOA CHU KANG, AVE 7 #15-49, KEAT HONG QUAD, 683815, Singapore
SHIJAMBPL@GMAIL.COM

Claim Handler

TEO Kitty
6568804602
kitty.teo@axa.com.sg

Additional Instructions
WS - ELITE XS - \$0

1

Messages Invoices History Documents Assessment Metrics Notes

New Message

KUMAR Shailendra

From: Elite AM <eliteamclaim@gmail.com>
Sent: Monday, September 23, 2019 5:16 PM
To: SG AXA Insurance SM AXA SGP - Motor Survey
Cc: SG AXA Insurance SM Claims Service Team
Subject: [EXTERNAL] Claim OD For Vehicle No: SLH9750A
Attachments: 23092019171119.pdf

Categories: Shailendra

Hi,

Good day! Kindly refer to attached and please arrange surveyor come down for survey. Thanks!

Regards,

Christy

Steve Chen (LKK Auto)

From: Elite Automotive <elite.automotive13@gmail.com>
Sent: Thursday, October 24, 2019 3:28 PM
To: Steve Chen (LKK Auto)
Cc: Denise Tay (LKKAuto)
Subject: Re: SLH9750A Finalize

Hi Steve,

Good day! We accept the offer. Thanks!

Regards,

Christy

On Mon, 21 Oct 2019 at 18:55, Steve Chen (LKK Auto) <SteveChen@lkkauto.com> wrote:

Dear Christine,

Kindly refer our finalize \$1550 (L/S, before GST). 3 repair days.

Kindly confirm.

Thanks

Best Regards,

Steve Chen| Assistant Automotive Assessor



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Immediate Advice

Date: 30/9/2019

To : AXA Insurance Pte Ltd

Survey details

Date of loss	20-Sep-19
Date of appointment	30-Sep-19
Date of survey	30-Sep-19
Location of survey	Elite AM

Vehicle Details:

Claim Type:	Own Damage
Vehicle number	SLH 9750A
Make and Model	Chervrolet Cruze
Date of registration	24/11/2016
Excess	NIL
Market Value	\$56,000
Parf Rebate	\$46,995
Nett Loss	\$9,005

Repair details

Initial Estimate	\$10,435
------------------	----------

Proposed/Revised repair cost:

Parts	\$1,703
Check item	\$1,346
Labour	\$630
Total	\$3,697
Lump Sum(if applicable)	

Number of days of repair	3
--------------------------	---

Remarks:

we have authorise repair
Damage consistent

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	992I
Vehicle Details	
Vehicle No.:	SLH9750A
Vehicle to be Exported:	Yes
Intended Deregistration Date:	20 Sep 2019
Vehicle Make:	CHEVROLET
Vehicle Model:	CRUZE NB 1.6D 6AT
Primary Colour:	Black
Manufacturing Year:	2016
Engine No.:	F16D4160880416
Chassis No.:	KL1JA69E9GK344834
Maximum Power Output:	86.0 kW (115 bhp)
Open Market Value:	\$13,918.00
Original Registration Date:	24 Nov 2016
First Registration Date:	24 Nov 2016
Transfer Count:	0
Actual ARF Paid:	\$13,918.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	23 Nov 2026
PARF Rebate Amount:	\$10,438.00
Intended COE Rebate Details	
COE Expiry Date:	23 Nov 2026
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$50,951.00
COE Rebate Amount:	\$36,557.00
Total Rebate Amount:	\$46,995.00

The information contained herein is correct as at 20 Sep 2019

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	20/09/2019 17:40
Date Of Accident	20/09/2019 07:15
Exact Location Of Accident	LORONG 6 TOA PAYOH SLIP ROAD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLH9750A
Insured/Policyholder	
Name Of Registered Owner	TEH HUEY MIN
NRIC No	S7482992I
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-96234710
Alternative Phone No	OTHERS-96234710

Vehicle Particulars

Manufacturer	CHEVROLET
Model	CRUZE NB-1.6 D 6AT (A)
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	YES
If No, Please state action to be taken	
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	GA17982/1
Cover Note Number	

Driver

Name of Driver	SAM JI SOON
NRIC No	S7373974H
Date Of Birth	14/06/1973
Occupation	INDOOR
Date Of Driving Pass	11/02/2009
Driving Experience	10 YEARS AND 7 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96169365
Fax Number	
Contact Number	
EMail Address	J1500704@GMAIL.COM

Address	APT BLK 815C CHOA CHU KANG AVENUE 7 #15-49
Postcode	683815
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	SPOUSE
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO SKETCH PLAN

Attachment(s)


Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SGG69H
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	LINDA
NRIC/Passport Number	
Contact Number	96782678
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Sketch Plan

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 20th Sep 2019, at 7:07am, at slip road of Lor 6, Toa Payoh, when the traffic light turned 'green', I was want to go toward PLE. I thought at front of me the car had already moved, but unfortunately it was not, and I accidentally knock the rear of her car.

DECLARATION

✓/We declare the foregoing particulars are true in every respect.

Policyholder's Signature

Date & Time:

20/9/19, 5:05pm

Driver's Signature

(If driver is not the policyholder)

Date & Time:

20/9/19, 5:05pm

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:

ELITE AM PTE LTD

280 Woodlands Industrial Park E5, #01-17,

Harvest @ Woodlands Singapore 757322

Tel: 6339 7378 Fax: 6339 7475

Vehicle Number : SLH9750A

Vehicle Model : CHEVROLET CRUZE

Chassis Number : KLIJA69E9GK344834

Estimated Repair Cost

S/N	Parts Description	Qty	Cost Price
1	FRONT BUMPER / CRU	1	\$ 1213.00
2	FRONT BUMPER CLIPS / APC	10	\$ 20.00
3	FRONT BUMPER RETAINER LH & RH / DR	2	\$ 20.00
4	FRONT BUMPER REINFORCEMENT ?	1	\$ 860.00
5	FRONT BUMPER INNER SPONGE ?	1	\$ 74.00
6	FRONT GRILLE (UPPER) ?	1	\$ 220.00
7	FRONT BUMPER CENTER GRILLE / DR	1	\$ 250.00
8	FRONT BUMPER LOWER GRILLE ?	1	\$ 70.00
9	"CHEVROLET" LOGO /	1	\$ 45.00
10	HEADLAMP LH & RH X	2	\$ 4314.00
Spare Parts Total Price			\$ 7086.00
Cost Price +10%			708.60
			\$ 7,794.60

Special Nett Items:		Qty	
1	FRONT NUMBER PLATE WITH HOLDER / DR	1	\$ 60.00 50/
Special Nett Total			\$ 60.00
Spare Part's Total Price			\$ 7854.60

ELITE AM PTE LTD

280 Woodlands Industrial Park E5, #01-17,

Harvest @ Woodlands Singapore 757322

Tel: 6339 7378 Fax: 6339 7475

Vehicle Number : SLH9750A

Vehicle Model : CHEVROLET CRUZE

Chassis Number : KLIJA69E9GK344834

S/N	Labour Descriptions	Charges
1	LABOUR CHARGES TO REMOVE & INSTALL FRONT END ATTACHMENTS & FITTINGS TO ENABLE REPAIRS; TO REPLACE DAMAGED PARTS AS LISTED ABOVE.	\$ 1200.00 300
2	TO SPRAY PAINTING ON: BONNET (INNER, OUTER), FRONT BUMPER, INNER PANEL.	\$ 1000.00 250
3	TO CHECK ELECTRICAL WIRING & LIGHTS FUNCTION, INCLUSIVE FOCUS HEADLIGHTS.	\$ 100.00 30
4	CHECK & CLEAR FAULT CODES AFTER NECESSARY ACCIDENT REPAIRS.	\$ 280.00 X

Labour Total \$ 2580.00

Parts & Labour Total \$ 10434.60

Store (CLKK) OD - Authorse 30/9/19, 11.00am
3 chys
L/S
Ry AL spy

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

ELITE AM PTE LTD

280 Woodlands Industrial Park E5, #01-17,

Harvest @ Woodlands Singapore 757322

Tel: 6339 7378 Fax: 6339 7475

Vehicle Number : SLH9750A

Vehicle Model : CHEVROLET CRUZE

Chassis Number : KLIJA69E9GK344834

Estimated Repair Cost

S/N	Parts Description	Qty	Cost Price
1	FRONT BUMPER / CRU	1	\$ 1213.00 1100
2	FRONT BUMPER CLIPS / MC	10	\$ 20.00 /
3	FRONT BUMPER RETAINER LH & RH / DR	2	\$ 20.00 /
4	FRONT BUMPER REINFORCEMENT ? X NMI	1	\$ 860.00 X
5	FRONT BUMPER INNER SPONGE ? X NMI	1	\$ 74.00 X
6	FRONT GRILLE (UPPER) ? X NMI	1	\$ 220.00 X
7	FRONT BUMPER CENTER GRILLE / DR	1	\$ 250.00 /
8	FRONT BUMPER LOWER GRILLE ? X NMI	1	\$ 70.00 X
9	"CHEVROLET" LOGO / CUT	1	\$ 45.00 /
10	HEADLAMP LH & RH X NMI	2	\$ 4314.00 X

Spare Parts Total Price

\$ 7086.00 1435

Cost Price +10%

708.60 -10%

\$ 7794.60 1291.50

Special Nett Items:		Qty	
1	FRONT NUMBER PLATE WITH HOLDER / DR	1	\$ 60.00 50
Special Nett Total			\$ 60.00
Spare Part's Total Price			\$ 7854.60

P - 1291.50
 M - 50
 L - 580
 1921.50

L/S - 1537.20
 = 1550

ELITE AM PTE LTD

280 Woodlands Industrial Park E5, #01-17,
Harvest @ Woodlands Singapore 757322

Tel: 6339 7378 Fax: 6339 7475

Vehicle Number : SLH9750A

Vehicle Model : CHEVROLET CRUZE

Chassis Number : KLIJA69E9GK344834

S/N	Labour Descriptions	Charges
1	LABOUR CHARGES TO REMOVE & INSTALL FRONT END ATTACHMENTS & FITTINGS TO ENABLE REPAIRS; TO REPLACE DAMAGED PARTS AS LISTED ABOVE.	\$ 1200.00 300
2	TO SPRAY PAINTING ON: BONNET (INNER, OUTER), FRONT BUMPER, INNER PANEL.	\$ 1000.00 150
3	TO CHECK ELECTRICAL WIRING & LIGHTS FUNCTION, INCLUSIVE FOCUS HEADLIGHTS.	\$ 100.00 30
4	CHECK & CLEAR FAULT CODES AFTER NECESSARY ACCIDENT REPAIRS.	\$ 280.00 X

Labour Total \$ 2580.00

Parts & Labour Total \$ 10434.60

Steve (LKK)

OD - Authrise
3 chys

30/9/19, 11.00am

580

L/S

Ry AL spy

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: