

ASS. REC. BY:

Surveyor: Rasu

REF:

CS/CTI/9016908/R15d3ⁿ²

Special Instructions:

ASSIGNMENT (Office)

From (Person): Tan Kah leong of CTI Date/Time: 24/11/90 @ 4:31pm

Estimated Cost: Bill to:

OD / TP / WS / TP RES / OD RES / KVA / INV / MV / CS

To Inspect Vehicle No: SKP 8015R Insured: GZ 5197M

at Workshop n/s wearnes Tel: 81261237

of 249 Alexandra Road

Policy No: Claim No: SNM19D204434

Sum Insured: Excess:

Make of Veh: D.O.A.
(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: 11:46am @ 25/9/19 Person Contacted: paul Vehicle IN (OUT)

Date/Time	Action/Instruction
	Iskmail ✓
	SKP 8015R - X
	GZ 5197M - can / At 11/6/19520 / Rb/a3q 2
	2009.13/11/2011

ASS. REC. BY

Passive

REF:

768E

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: SKP 8015 Rat Workshop m/s WEAVERSof 45, LEMH KEE RDInsured: CTI

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

I am carrying
patriciaRemark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SKP 8015 R Yr Regn: 2014 / 07

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: INFINITI Q502-0T C.C. 1991Colour: RED A/C: Insured / Std / NI / NASp. Reading: 60291 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JN1BCAU3720450164

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt orBrake: Inorder / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 225/55R17R: -

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 6 mm R/Bal. 6 mmL/Bal. 6 mm L/Bal. 6 mmD.O.A. 19/02/19 D.O.I. 27/09/19Survey held at WEAVERS

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

O/S FR

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
21/11/19	Result Confirmed P/P \$ 8,170.81 @ 4 days with Patricia. (\$ 2,737.25 Red - 25%)
	RECEIVED 22 NOV 2019
	21/11/2019

Date/Time, File Pass by?

22/11/19

Code/Time, File Return to?

3

Report Format:

Lump Sum (L.S.): 8,170.81 P/PDays Of Repair: 4Resurvey No. of Trip: 1

Add Fee:

☐ Site Insp (\$)☐ Interview (\$)☐ Tech. Insp (\$)☐ Wheel end (\$)

Survey Fee:

Transportation:

\$ + RS. \$

Photos

Other:

TOTAL

220

Nivitha (LKK Auto)

From: Tan Kah Leong <KahLeong.Tan@sg.cntaiping.com>
Sent: Tuesday, 24 September 2019 4:31 PM
To: Paul Ong Qing Yong; assignments
Cc: Patricia Kueh Anak Slin; Tan Kah Leong
Subject: RE: OUR REF: SNM19D204434-GZ5197M-TKL- TP Claim for SKP8015R

Dear Xiao Chan

Please conduct PRS survey either at

1) 25/09/19 at 10.35am

Or

2) 27/09/2019 at 11 am

Please contact Paul from Wearnes at 81261237 for PRS. See Merimen later.

Regards

Chee So Chow on behalf on Tan Kah Leong
Assistant Executive
Claims Department

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road #15-00 Springleaf Tower Singapore 079909
DID: (65) 6389 6193 | F: (65) 6222 1033

W: www.sg.cntaiping.com | **FB:** www.facebook.com/chinataipingsg/

Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.

From: Paul Ong Qing Yong [mailto:paul.ong@wearnes.com]
Sent: Monday, September 23, 2019 3:15 PM
To: Tan Kah Leong <KahLeong.Tan@sg.cntaiping.com>
Cc: Patricia Kueh Anak Slin <patricia.kueh@wearnes.com>
Subject: RE: OUR REF: SNM19D204434-GZ5197M-TKL- TP Claim for SKP8015R

Please advise if able to re-arrange survey to either

25th September 1035hrs

OR

27th September 1100hrs

Paul Ong
Service Consultant
Bodyshop & Paint



Wearnes Automotive Pte Ltd
 249 Alexandra Road Singapore 159935
 M (65) 8126 1237 D (65) 6378 9336
www.wearnesauto.com paul.ong@wearnes.com

WEARNES

*This email, including any attachment, is confidential and may also be privileged.
 If you have received it in error, please notify us immediately by reply email and then delete this message from your system.
 Please do not copy it or use it for any purpose, or disclose its contents or any attachment to any other person. Thank you.*

From: Patricia Kueh Anak Slin <patricia.kueh@wearnes.com>
Sent: Saturday, September 21, 2019 10:02 AM
To: Tan Kah Leong <KahLeong.Tan@sg.cntaiping.com>
Cc: Paul Ong Qing Yong <paul.ong@wearnes.com>
Subject: RE: OUR REF: SNM19D204434-GZ5197M-TKL- TP Claim for SKP8015R

Dear Tan,

Please ignore below email. Kindly please re-arrange for pre repair survey on 26.09.19 at 10am. Location at Infiniti, 45 Leng Kee Road. Owner will be waiting.

Thank you.

Patricia Kueh
 Service Consultant
 Bodyshop & Paint



Wearnes Automotive Pte Ltd
 249 Alexandra Road Singapore 159935
 M (65) 9770 4368 D (65) 6378 9336
www.wearnesauto.com patricia.kueh@wearnes.com

WEARNES

*This email, including any attachment, is confidential and may also be privileged.
 If you have received it in error, please notify us immediately by reply email and then delete this message from your system.
 Please do not copy it or use it for any purpose, or disclose its contents or any attachment to any other person. Thank you.*

From: Patricia Kueh Anak Slin
Sent: Saturday, 21 September, 2019 9:49 AM
To: Tan Kah Leong <KahLeong.Tan@sg.cntaiping.com>
Cc: Paul Ong Qing Yong <paul.ong@wearnes.com>
Subject: RE: OUR REF: SNM19D204434-GZ5197M-TKL- TP Claim for SKP8015R

Dear Tan,

Please arrange pre repair survey on 24.09.19 at 10am. Location at 45 Leng Kee Road. Owner will be waiting.

Thank you.

Patricia Kueh
 Service Consultant
 Bodyshop & Paint



Wearnes Automotive Pte Ltd
 249 Alexandra Road Singapore 159935
 M (65) 9770 4368 D (65) 6378 9336
www.wearnesauto.com patricia.kueh@wearnes.com

WEARNES

*This email, including any attachment, is confidential and may also be privileged.
If you have received it in error, please notify us immediately by reply email and then delete this message from your system.
Please do not copy it or use it for any purpose, or disclose its contents or any attachment to any other person. Thank you.*

From: Patricia Kueh Anak Slin
Sent: Friday, 20 September, 2019 6:45 PM
To: Tan Kah Leong <KahLeong.Tan@sg.cntaiping.com>
Cc: Paul Ong Qing Yong <paul.ong@wearnest.com>
Subject: RE: OUR REF: SNM19D204434-GZ5197M-TKL- TP Claim for SKP8015R

Dear Tan,

Please arrange Marcus Chua.

Thank you.

Patricia Kueh
Service Consultant
Bodyshop & Paint



Wearnes Automotive Pte Ltd
249 Alexandra Road Singapore 159935
M (65) 9770 4368 D (65) 6378 9336
www.wearnestauto.com patricia.kueh@wearnest.com

*This email, including any attachment, is confidential and may also be privileged.
If you have received it in error, please notify us immediately by reply email and then delete this message from your system.
Please do not copy it or use it for any purpose, or disclose its contents or any attachment to any other person. Thank you.*

From: Tan Kah Leong <KahLeong.Tan@sg.cntaiping.com>
Sent: Friday, 20 September, 2019 6:09 PM
To: Patricia Kueh Anak Slin <patricia.kueh@wearnest.com>
Subject: RE: OUR REF: SNM19D204434-GZ5197M-TKL- TP Claim for SKP8015R

Dear Sirs

ACCIDENT INVOLVING GZ5197M AND SKP8015R ALONG SUNTEC CITY ROUNDABOUT ON 19/09/2019

We refer to your email below.

Kindly note the following:-

1. We would like to conduct pre-repair survey of the vehicle at the appointed workshop.
2. We propose the following list of surveyors to be nominated as the Single Joint Expert to conduct survey of the claimant's vehicle:-

1. ADRIAN LING	6. KENNETH KONG
2. Kelvin Ang	7. SIMON HO
3. SEE CHEW SENG	8. CHUA WEIJIE
4. MOHD FADHILAH BIN OSMAN	9. MARCUS CHUA
5. XING QUO QIANG	10. HENRY NG

3. If we do not hear from you within two days of this letter, you shall have deemed to have agreed that the surveyor appointed by us shall be Single Joint Expert for this matter.

4. As per the NIMA Protocol, the survey by our appointed surveyor would include survey of your vehicle pre-repair, after it is dismantled, and post repairs. Hence, you need to provide us / our surveyors with the list of items that were damaged and required to be replaced or repaired to facilitate an effective survey.
5. As stated above, please inform us and our surveyor after the claimant's vehicle had been repaired so that our surveyor can carry out post repair inspection before the vehicle is returned to your client. Please co-ordinate with our surveyor immediately after the repair is completed.

If you have any queries, please contact Tan Kah Leong at 6389 6196.

Yours faithfully

Regards

Tan Kah Leong
Assistant Executive
Claims Department

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road #15-00 Springleaf Tower Singapore 079909
DID: (65) 6389 6193 | F: (65) 6222 1033

W: www.sg.cntaiping.com | FB: www.facebook.com/chinataipingsg/

Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.

From: Claims Dept of CTI
Sent: Friday, September 20, 2019 5:51 PM
To: Tan Kah Leong <KahLeong.Tan@sg.cntaiping.com>; Chee So Chow <sochow.chee@sg.cntaiping.com>;
patricia.kueh@wearnes.com
Subject: OUR REF: SNM19D204434-GZ5197M-TKL- TP Claim for SKP8015R

Dear Kah Leong,

Please conduct PRS for SKP8015R.

Note : officer in charge – Kah Leong 63896193.

Thank you

Claims Department

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road #15-00 Springleaf Tower Singapore 079909
DID: (65) 63896116 | F: (65) 62247175

W: www.sg.cntaiping.com | FB: www.facebook.com/chinataipingsg/ | WeChat: 太平獅城 Taiping SG

Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.

From: Patricia Kueh Anak Slin [<mailto:patricia.kueh@wearnes.com>]
Sent: Friday, September 20, 2019 4:26 PM
To: Claims Dept of CTI
Cc: Paul Ong Qing Yong
Subject: TP Claim for SKP8015R

Hi,

Please refer attachments and advise if we can settle direct for this case.

Please arrange pre repair survey on 24.09.19 at 10am. Location at 45 Leng Kee Road. Owner will be waiting.

Thank you.

Patricia Kueh
Service Consultant
Bodyshop & Paint



Wearnes Automotive Pte Ltd
249 Alexandra Road Singapore 159935
M (65) 9770 4368 D (65) 6378 9336
www.wearnesauto.com patricia.kueh@wearnes.com

*This email, including any attachment, is confidential and may also be privileged.
If you have received it in error, please notify us immediately by reply email and then delete this message from your system.
Please do not copy it or use it for any purpose, or disclose its contents or any attachment to any other person. Thank you.*

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>

Shirley Hiew (LKK Auto)

From: Shirley Hiew (LKK Auto)
Sent: Friday, 22 November 2019 9:12 am
To: Patricia Kueh Anak Slin
Cc: Paul Ong Qing Yong
Subject: RE: SKP8015R Finalise

Dear Patricia,

Confirmed final fig \$ 8,170.81 @ 4 day of repairs before GST.

Final invoice and all supporting documents sent over to China Taiping Insurance (Singapore) Pte. Ltd.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Shir@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Patricia Kueh Anak Slin <patricia.kueh@wearnes.com>
Sent: Thursday, 21 November 2019 9:15 am
To: Rasul (LKKAuto) <Rasul@lkkauto.com>
Cc: Paul Ong Qing Yong <paul.ong@wearnes.com>
Subject: SKP8015R Finalise

Dear Rasul,

Please refer above attachments for final bill.

Thank you.

Patricia Kueh
Service Consultant
Bodyshop & Paint



Wearnes Automotive Pte Ltd
249 Alexandra Road Singapore 159935
M (65) 9770 4368 D (65) 6378 9336
www.wearnesauto.com patricia.kueh@wearnes.com

*This email, including any attachment, is confidential and may also be privileged.
If you have received it in error, please notify us immediately by reply email and then delete this message from your system.
Please do not copy it or use it for any purpose, or disclose its contents or any attachment to any other person. Thank you.*

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	20/09/2019 14:56
Date Of Accident	19/09/2019 17:40
Exact Location Of Accident	SUNTEC CITY ROADABOUT
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKP8015R
Insured/Policyholder	
Name Of Registered Owner	CHEO BOON MUI
NRIC No	S1716768E
Email Address	CBMUI@HOTMAIL.COM
Mobile Phone No	(LOCAL) +65-97509230
Alternative Phone No	OFFICE-97509230
Vehicle Particulars	
Manufacturer	INFINITI
Model	Q50-2.0 T PREMIUM (A)
Exact Purpose for which vehicle was being used at time of accident	SOCIAL
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR
Insurance Company	
Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	2100388935-04
Cover Note Number	
Driver	
Name of Driver	CHEO BOON MUI
NRIC No	S1716768E
Date Of Birth	11/03/1965
Occupation	INDOOR
Date Of Driving Pass	24/11/1993
Driving Experience	25 YEARS AND 9 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-97509230
Fax Number	
Contact Number	OFFICE-97509230
Email Address	CBMUI@HOTMAIL.COM

Address	27 LI HWAN TERRACE
Postcode	556955
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - CHANGE/CROSS LANE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

Please refer attachments.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Was there any audio recorded?	NO

Details of Witness 1

Name	MUHD FADINOH
Phone Number	
Email Address	

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GZ5197M
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	GOODS VEHICLE
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Complete and submit this Form to Allied World's Authorised Reporting Centre ("ARC") for filing.
2. Please report correctly the details of the accident to speed up the claims process.
3. This Form must be completed by the Policyholder and/or the Authorised Driver.
4. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
5. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
6. Any false reporting may be referred to the Traffic Police Department for investigation.

ACCIDENT STATEMENT

Date and Time of Accident	Date: 11/11/19 Time: 17:40
Exact Location of Accident	Suntec City Roundabout

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKP 8015K
-----------------------------	-----------

INSURED / POLICYHOLDER (OWN VEHICLE)

Name of Registered Owner (See Insurance Cert.)	Chee Boon Mui
Personal Identification - NRIC (Singaporean/PR)	S1716768E
- FIN/Passport Number	
- Not Applicable	

VEHICLE PARTICULARS (OWN VEHICLE)

Vehicle Make / Model	Manufacturer Infiniti Model Q50
Type of Vehicle*	<input checked="" type="radio"/> Saloon <input type="radio"/> MPV <input type="radio"/> CRV <input type="radio"/> Van <input type="radio"/> Lorry <input type="radio"/> Bus <input type="radio"/> M/cycle <input type="radio"/> Others, _____
Exact Purpose for which vehicle was being used at time of accident	Social
Are you claiming under your own insurance policy for repair to your vehicle?	<input type="radio"/> Yes <input checked="" type="radio"/> No (If No, Pls select: <input checked="" type="radio"/> Third Party <input type="radio"/> Reporting)
Vehicle Category	<input checked="" type="radio"/> Private <input type="radio"/> Commercial <input type="radio"/> Motorcycle

INSURANCE COMPANY (OWN VEHICLE)

Name of Insurance Company *	AIK Asia Pacific Insurance
Type of Policy	<input checked="" type="radio"/> Comprehensive <input type="radio"/> Third Party Fire & Theft <input type="radio"/> TP Only
Fleet Policy	<input type="radio"/> Yes <input checked="" type="radio"/> No
Policy Number	2100388935-04
Motor CI	

DRIVER

	<input checked="" type="radio"/> Same as Insured above
Name of Driver	Chee Boon Mui
Personal Identification - NRIC (Singaporean/PR)	S1716768E
- FIN/Passport Number	
Date of Birth	11 dd/ 03 mm/ 1965/yy
Driving Date Pass	24 dd/ 11 mm/ 1993/yy
Year of Driving Experience	25 Year(s) 9 Month(s)
Occupation	<input checked="" type="radio"/> Indoor <input type="radio"/> Outdoor
Gender	<input type="radio"/> Male <input checked="" type="radio"/> Female
Contact Number / Mobile Phone / Fax No.	9750 9230

Address of Driver	27 Li Huan Terrace
Email Address	Postcode (556955)
Was driver an employee of the Insured's Company?	<input type="radio"/> Yes <input checked="" type="radio"/> No
If No, Relationship of the Driver with the Insured	Owner
Vehicle Registration Number of Driver's Own	<input type="radio"/> Yes <input checked="" type="radio"/> No
Vehicle Registration Number of Driver's Own Vehicle (if applicable)	
Insurance Company of Driver's Own Vehicle (if applicable)	

GENERAL INFORMATION OF THE ACCIDENT

Type of Collision (Eg. Chain collision, Head-On collision, Side Swipe, Front to Rear)	Collision Cross Lane
Weather Conditions	<input checked="" type="radio"/> Clear <input type="radio"/> Raining <input type="radio"/> Others
Road Surface	<input checked="" type="radio"/> Dry <input type="radio"/> Wet <input type="radio"/> Others

OTHER INFORMATION

Was any foreign vehicle involved in this accident?	<input type="radio"/> Yes <input checked="" type="radio"/> No
Was any body injured in the accident?	<input type="radio"/> Yes <input checked="" type="radio"/> No
Was any other vehicle or property damaged?	<input checked="" type="radio"/> Yes <input type="radio"/> No
Was there any video captured by Car Camera?	<input checked="" type="radio"/> Yes <input type="radio"/> No
Number of Passengers (Including Driver)	1

DETAILS OF POLICE ACTION

Was the Accident reported to the Police?	<input type="radio"/> Yes <input checked="" type="radio"/> No (If Yes, please state which Police Station.)
Police Station Name	
Police Station Address	
Police Station Contact	Tel No. Fax No.
Was notice of intended Prosecution given?	<input type="radio"/> Yes <input checked="" type="radio"/> No (If Yes, against whom?)

DETAILS OF OTHER VEHICLE / PROPERTY 1

Vehicle Registration Number	GZ 5197M
Vehicle Make/ Model/ Colour	
Details of Properties	
Name of Driver	
Personal Identification - NRIC (Singaporean/PR)	
- FIN/Passport Number	
Contact Number	
Address	
Name of Insurance Company	China Taiping Insurance
Nature of Damage	
No. of Passenger (Including Driver)	

(Note - Please use page 3 if you need to add more vehicles)

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Traffic Police Department for investigation.
6. This report will be forwarded by the insurers to the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that :

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
- (ii) investigating the accident and/or my claims;
- (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
- (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
- (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
- (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sit(ed) outside of Singapore, for one or more of the above Purposes.



Policyholder's Signature / Date & Time

Driver's Signature (if driver is not the policyholder) / Date
& Time



Witnessed by Reporting Centre Personnel

Sketch Plan

As per video

Yesterday evening, at about 5.40pm, I was driving towards the Suntec Circle, a vehicle in the next lane, suddenly drive into my lane and knock my car. As it was FI season, there were ^{cisco} traffic police around and they directed us to a lane to stop our vehicles. I alight from my car and the driver of the other vehicle apologise to me. He mentioned he will have his office contact me for a settlement. I ~~asked~~ the cisco police ~~if~~ confirmed to me that I was right and the fault lies with the other party.

IMPORTANT NOTE

Under General Condition – Conduct of Claim of the Motor Policy, you have to decide within 21 days of occurrence or discovery of damage whether or not to claim under the policy. Please check your policy for more information.

Declaration

(We declare the foregoing particulars are true in every respect.)

Policyholder's Signature / Date & Time

20/9/2019

Driver's Signature (if driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel



WEARNES

LKK Auto Consultants hence notify

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

SERVICE ESTIMATE

78775 - C00001
Ms Cheo Boon Hui
9 Sengkang Square
#04-06
Compass Heights
Singapore 545075

SL: SERVICE SALES - PC

GST Reg.No: M28920628X

Inv.No. : B&P 0 Page 1

Inv.date : 20/09/2019

WIP No. : 37789

Veh.In/Out:

*Tel.No. : Mobile: 97509230

Reg.No. : SKP8015R

Reg.date : 10/10/2014

Mileage : 0

Chassis No: JH1BCAV37Z0450164

Closed by : Patricia Kueh Anak S

Svc Consultant :

Remarks : Ms Cheo Boon Hui

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
-------	-------------	----------	-------	-------	-----	--------	---

802	TO REPLACE FRT BUMPER, FENDER RH, HEADLAMP RH, ETC	0	2700.00	0		2,700.00 S	1800
800	TO PUTTY SPRAYPAINT ON FRT BUMPER, FENDER RH, ETC	0	2000.00	0		2,000.00 S	1600
280	TO CHECK WIRING INCLUDE RESETTING OF ALL ELECTRICAL MODULES	0	405.00	0		405.00 S	
	BUMPER FRT Q50 PREM	1.0 EA	705.70	655.13		705.70 S	
	BRACKET CTR RH BUMP	1.0 EA	52.00			52.00 S	
	BUMPER FRT RETAINER	1.0 EA	57.70			57.70 S	
	BUMPER FRT BASE SPOI	1.0 EA	115.30			115.30 S	
	BRACKET-BUMPER FRT R	1.0 EA	14.40	12.94		14.40 S	
	BRACKET-BUMPER FRT R	1.0 EA	20.30	18.27		20.30 S	
	IF31004GAMA/FENDER-F	1.0 EA	727.20			727.20 S	
	LAMP ASSY-RH	1.0 EA	3441.40	3097.26		3,441.40 S	
	ADHESIVE SEALER FL2	1.0 EA	669.10	602.19		669.10 S	

Gross Total. 10,908.10

Labour Total 5,105.00
Parts Total 5,803.10
Package Total 0.00

Net..... 10,908.10
GST @ 7.0% 763.57
Total..... 11,671.65
Paid..... 0.00
Please Pay.. 11,671.65

GST: S=StdRated; O=OutOfScope; Z=ZeroRated

SERVICE ESTIMATE

O - C00010 SL: CHINA TAIPING INSURANCE (SINGAPORE)
 CHINA TAIPING INSURANCE (SINGAPORE) PTE LTD GST Reg.No:M28920628X
 3 ANSON ROAD Inv.No. : B&P 0 Page 1
 #16-00, SPRINGLEAF TOWER Inv.date : 20/11/2019
 SINGAPORE 079909 WIP No. : 37789
 Veh.In/Out: 14/11/2019 20/11/2019
 *Tel.No. : 63896111
 Reg.No. : SKP8015R
 Reg.date : 10/10/2014
 Mileage : 61,689
 Chassis No: JN1BCAV37Z0450164
 Closed by : Patricia Kueh Anak S
 Svc Consultant : ACC
 Remarks : Ms Cheo Boon Mui

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
802	TO REPLACE FRT BUMPER, HEADLAMP RH, REPAIR FENDER RH,ETC	0	1800.00	0		1,800.00	S
800	TO PUTTY SPRAYPAINT ON FRT BUMPER,FENDER RH,ETC	0	1600.00	0		1,600.00	S
280	TO CHECK WIRING INCLUDE RESETTNG OF ALL ELECTRICAL MODULES	0	405.00	0		405.00	S
	BUMPER FRT Q50 PREM	1.0 EA	705.70	10		635.13	S
	BRACKET-BUMPER FRT R	1.0 EA	14.40	10		12.96	S
	BRACKET-BUMPER FRT R	1.0 EA	20.30	10		18.27	S
	LAMP ASSY-RH	1.0 EA	3441.40	10		3,097.26	S
	ADHESIVE SEALER FL2	1.0 EA	669.10	10		602.19	S

Gross Total. 8,170.81

Labour Total 3,805.00
 Parts Total 4,365.81
 Package Total 0.00

Net..... 8,170.81
 GST @ 7.0% 571.96
 Total..... 8,742.77
 Paid..... 0.00
 Please Pay.. 8,742.77

GST: S=StdRated; O=OutOfScope; Z=ZeroRated

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CT119016908/R1SD3N2

Date: 25/11/2019

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSN17396018011	
Claimant Vehicle No :	SKP8015R	Insured Vehicle No :	GZ5197M	
Date of Loss:	19/09/2019	Nature of Claim:	TP	Claim No: SNM19D204434C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKP8015R	Engine No:	27493030223454
Make & Model:	INFINITI Q50, 2.0 T Premium (A)	Chassis No:	JN1BCAV37Z0450164
Reg. Date:	10/10/2014 (Man. Year: 2014)	Odometer:	60291 km
Colour:	Red		
Engine Capacity:	1991 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	225/55 R17	Rear Tyre Size:	225/55 R17
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	5,803.10	4,365.81	1,437.29	24.77
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,105.00	3,805.00	1,300.00	25.47
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	10,908.10	8,170.81	2,737.29	25.09
+ GST 7.00/7.00% (S\$)	763.57	571.96	191.61	25.09
Nett Amount (S\$)	11,671.67	8,742.77	2,928.90	25.09

INSPECTION

Date of Assignment:	01/10/2019	
Date Inspected:	27/09/2019 Inspected At:	Wearnes Automotive Pte Ltd (Alexandra Road) 249 Alexandra Road Singapore 159935
Estimated Period of Repair:	4.0 days	

Adjuster: MOHD RASUL

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 25 Nov 2019)
Parts:	143	INFINITI Q50 2.0 T Premium (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKP8015R)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BUMPER FRT Q50 PREM	Scratched	705.70 FS	*635.13 FS
2	1		*BRACKET CTER RH BUMP	Serviceable	52.00 FS	*- FS
3	1		*BUMPER FRT RETAINER	Serviceable	57.70 FS	*- FS
4	1		*BUMPER FRT BASE SPOI	Serviceable	115.30 FS	*- FS
5	1		*BRACKET-BUMPER FRT R	Necessary	14.40 FS	*12.96 FS
6	1		*BRACKET-BUMPER FRT R	Necessary	20.30 FS	*18.27 FS
7	1		*IF31004GAMA/FENDER-F	Repair	727.20 FS	*- FS
8	1		*LAMP ASSY-RH	Scratched	3,441.40 FS	*3,097.26 FS
9	1		*ADHESIVE SEALER F12	Necessary	669.10 FS	*602.19 FS
F=Franchise part. S=SpcNet.						
Total Parts (S\$)					5,803.10	4,365.81

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REPLACE FRT BUMPER,FENDER RH,HEADLAMP RH,ETC	New	2,700.00	1,800.00
2	TO PUTTY SPRAYPAINT ON FRT BUMPER,FENDER RH,ETC	New	2,000.00	1,600.00
3	TO CHECK WIRING INCLUDE RESETTING OF ALL ELECTRICAL MODULES	New	405.00	405.00
Gross Labour Cost (\$\$)			5,105.00	3,805.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >