

INS. CASE OWNER: Melchior | CC 4/III1901 6945, Eng | LKK: 53
IDAC:

Surveyor: STEVE | DOI: VI/A/CA | Date / Time: 25/1/20
Registered in Merimen: VI/A/CA

Pre-assign / CCU / FTE

Insured Vehicle No.: PC 5942T | Claim No.: 018MP0001 854
 Name of Insured: TONG TAE TRANSPORT SERVICE PTE | Policy No.: VI/A/CA
 Insured Tel No.: HP: VI/A/CA | Make / Model: TOYOTA
 Excess Sec II :SS | D.O.A: VI/A/CA | Place of Accident: WOODLANDS AVE 3
 Is driver the owner? (YES / NO) | Nature of Accident: SMB 2/2/20
 If NO, Driver Name / Age: OH KIM VEE | OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO
 Driver Tel No.: | (VI/- YES / NO) | Insured Liability: % Final ? Yes/No

INSRS: SMKT | INSRS: | INSRS: | INSRS: | INSRS:
 WSP: | WSP: | WSP: | WSP: | WSP:
 Tel: | Tel: | Tel: | Tel: | Tel:
 Liability: | Liability: | Liability: | Liability: | Liability:
 RMKS: | RMKS: | RMKS: | RMKS: | RMKS:

Date/ Time	STAGE	DATE / PIC
	Non-Reporting hr (1st):	
	Non-Reporting hr (2nd):	
	Non-Reporting hr (Final):	
	Notification hr (if non-pickup):	
	Call OI:	
	After call hr to OI:	
	Documentation Check List:	Handler Typist
	Notification hr (if non-pickup)	<input checked="" type="checkbox"/>
	After call hr to OI:	<input checked="" type="checkbox"/>
	Authorisation To Act:	<input checked="" type="checkbox"/>
	Release Voucher:	<input checked="" type="checkbox"/>
	Final Repair Bill:	<input checked="" type="checkbox"/>
	Car Rental Invoice:	<input checked="" type="checkbox"/>
	Towing Invoice:	<input checked="" type="checkbox"/>
	LTA / GIA:	<input checked="" type="checkbox"/>
	Medical Bill:	<input checked="" type="checkbox"/>
	PIR:	<input checked="" type="checkbox"/>
	Mandate/Reject Instruction:	<input checked="" type="checkbox"/>
	LOD:	<input checked="" type="checkbox"/>
	Payment Breakdown Form:	<input checked="" type="checkbox"/>
	Post-Repair Photos:	<input checked="" type="checkbox"/>
	Others:	<input checked="" type="checkbox"/>

PRELIMINARY ADVICE Date/Time: | Sent By:

FINALIZATION Date/Time: | Confirm with: | Confirm by: STEVE

Repair Cost: 818 | \$S 976.00 | 2 days Reduction: 8357 | \$ 27 | Email Call

FINAL SETTLEMENT Date/Time: 12/2/2020 | Confirm with: WEI TUCK | Email Call

Final Liability: % 100 (Agreed / Assessed) BOLA S/N No.: 15 | If NO or B 28, Ass. Lia:

Repair Cost: \$S 976.00

Loss of Rental (LOR): \$S - (days)

Loss of Use (LOU): \$S 900.00 (5700 x 3 days)

Loss of Income (LOI): \$S - (5 x days)

LOR only LOU only LOR + LOU LOR + LO [Tick only one]

GIA/LTA Search: \$S 7.00

Medical: \$S -

Disbursement: \$S - (e.g. Tow/ Independent)

Legal Cost: \$S -

Total: \$S 1883.00 | Global Sum \$S: 1800.00

FINAL PAYMENT Date/Time: | Confirm with: | Email Call

Payee 1: \$S 1800.00 | Name 1: SMKT PURES LTD.

Payee 2: (Strike if N.A.) \$S | Name 2:

Payee 3: (Strike if N.A.) \$S | Name 3:

COPY SENT
12/2/2020

1) Claim status: Normal/Reject/Private Settle
 2) Report Format: TP
 3) Survey fee: \$350



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
50 Woodlands Industrial Park EA, Singapore 757705
FAX Number : 63665592
Estimator Telephone Number : 65662623
Accident Reporting Number : 84662672

Date Generated : 24/09/2019

User ID : GohKK2

Section D - Details of Repair Estimates										
Part 1 - Labour Works										
Job Scope		Quotation from ARC				Adjusted by Surveyor, if applicable				
TO REMOVE & INSTALL ALL ABOVE ITEMS AND REPAIR OTHERS DAMAGED AFFECTED AREA.		\$795.00				530				
Total Labour		\$795.00								
Part 2 - Spray Painting & Panel Beating Related Works										
Job Scope		Quotation from ARC				Adjusted by Surveyor, if applicable				
PROVIDE LABOUR AND MATERIAL TO PUTTY AND RESPRAY ABOVE REPAIR ITEMS		\$538.00				446				
Total Spray Painting & Panel Beating		\$538.00								
Part 3 - Other Costs - Accident and Accident Repair Related Expense										
Job Scope		Quotation from ARC				Adjusted by Surveyor, if applicable				
Total Other Costs						X				
Part 4 - Spare Parts / Material Usage										
Part Number	Partion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved	
8011069	VE	31155514	POD, TAIL LIGHT-RH, FOR AQL ES90 DO BUS	1.00	\$1,703.25	100.00	\$0.00	Repair	R.	
Total					\$1,703.25		\$0.00			
Added Spare Parts / Material Usage After Surveyor Signed off										
Part Number	Partion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check	
Total										

530
446

976



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
80 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63665592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672


Date Generated : 24/09/2019

User ID : GohKK2

Section A - Accident Details	
Registration Number	SMB3529H
Case Reference Number	BUS09191068
Registration Date	1/9/2014
Company Type	SMRT Buses Ltd
Make	ALEXANDER DENNIS
Model	ENVIRO 500
Name of Driver	Ng Yeow Chin
Type of Accident	Side Swipe
Accident Date and Time	19/9/2019 6:20 PM
Accident Reported Date and Time	20/9/2019 10:11 AM
Is Surveyor Required?	No
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle Issued?	No
Job Card Number	
Special Instruction to ARC, if any	SMB3529H-RIGHT REAR PORTION PC5942T (TP) INSURED WITH IB
Prepared Date and Time	24/9/2019 3:49 PM
Chassis Number	SFD76CLR5EMTL3458
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates		
Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$795.00	\$0.00
Total Spray Cost	\$536.00	\$0.00
Total Spares Part Cost	\$0.00	\$0.00
Total Other Cost	\$0.00	\$0.00
TOTAL COST	\$1,333.00	\$0.00
Lump Sum Total	\$1,350.00	\$0.00
Number of Repair Days	3.0	2
Prepared / Adjusted By	Boon Chew Tay	
ARC / Surveyor Sign Off Date	24/09/2019 3:56 PM	
Signature		
Remarks		

Section C - Quotation and Accident Invoice Details			
Quotation Number		Invoice Number	
Quotation Date		Invoice Date	
Invoice Amount		Prepared Date	



Repair Day - 2 days
 Steve @ 25/09/2019 @ 2.15pm
 Lump Sum Repair, after spray
 TP without prejudice.

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	292D
Vehicle Details	
Vehicle No.:	SMB3529H
Vehicle to be Exported:	No
Intended Deregistration Date:	25 Sep 2019
Vehicle Make:	ALEXANDER DENNIS
Vehicle Model:	ENVIRO500
Primary Colour:	Silver
Secondary Colour:	Black
Manufacturing Year:	2014
Engine No.:	22120165
Chassis No.:	SFD76CLR5EMTL3458
Maximum Power Output:	-
Open Market Value:	\$470,004.00
Original Registration Date:	01 Sep 2014
First Registration Date:	01 Sep 2014
Transfer Count:	0
Actual ARF Paid:	\$0.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Rebate Amount:	\$0.00
Total Rebate Amount:	\$0.00

The information contained herein is correct as at 25 Sep 2019

OK





SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd	
80 Woodlands Industrial Park E4, Singapore 757705	
FAX Number : 63665592	
Estimator Telephone Number : 68662623	
Accident Reporting Number : 68662672	

Date Generated : 27/09/2019

User ID : CatherineLee

Section A - Accident Details	
Registration Number	SMB3529H
Case Reference Number	BUS/09/19/1068
Registration Date	1/9/2014
Company Type	SMRT Buses Ltd
Make	ALEXANDER DENNIS
Model	ENVIRO 500
Name of Driver	Ng Yeow Chin
Type of Accident	Side Swipe
Accident Date and Time	19/9/2019 8:20 PM
Accident Reported Date and Time	20/9/2019 10:11 AM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	24103527
Special instruction to ARC, if any	SMB3529H-RIGHT REAR PORTION PC5842T (TP) INSURED WITH III
Prepared Date and Time	24/9/2019 3:49 PM
Chassis Number	SFD76CLR5EMTL3458
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates		
Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$795.00	\$530.00
Total Spray Cost	\$538.00	\$445.00
Total Spare Part Cost	\$0.00	\$0.00
Total Other Cost	\$0.00	\$0.00
TOTAL COST	\$1,333.00	\$975.00
Lump Sum Total	\$1,350.00	\$0.00
Number of Repair Days	3.0	2.0
Prepared / Adjusted By	Boon Chew Tay	STEVE CHEN
ARC / Surveyor Sign Off Date	24/09/2019 3:55 PM	25/09/2019 2:24 PM
Signature		
Remarks		

Section C - Quotation and Accident Invoice Details			
Quotation Number		Invoice Number	
Quotation Date		Invoice Date	
Invoice Amount		Prepared Date	





SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd	
60 Woodlands Industrial Park E4, Singapore 757705	
FAX Number : 63665592	
Estimator Telephone Number : 68662623	
Accident Reporting Number : 68662572	

Date Generated : 27/09/2019

User ID : CatherineLee

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REMOVE & INSTALL ALL ABOVE ITEMS AND REPAIR OTHERS DAMAGED AFFECTED AREAS	\$795.00	\$530.00
Total Labour	\$795.00	\$530.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
PROVIDE LABOUR AND MATERIAL TO PUTTY AND RESPRAY ABOVE REPAIR ITEMS	\$538.00	\$448.00
Total Spray Painting & Panel Beating	\$538.00	\$448.00

Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Other Costs		

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
6011088	VE	31155514	POD.TAIL LIGHT.R/H.FOR ADL E500 DD BUS	1.00	\$1,703.25	100.00	\$0.00	Repair	Repair
Total					\$1,703.25		\$0.00		

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
Total									

001119



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd 80 Woodlands Industrial Park E4, Singapore 757708
FAX Number : 63665502
Estimator Telephone Number : 68622023
Accident Reporting Number : 68622072

Date Generated : 24/09/2019
User ID : G08K02

Section A - Accident Details	
Registration Number	SMB3529H
Case Reference Number	BU509716/1006
Registration Date	1/9/2014
Company Type	SMRT Buses Ltd
Make	ALEXANDER DENNIS
Model	ENVIRO 500
Name of Driver	Pg Yoon Chin
Type of Accident	Side Swipe
Accident Date and Time	19/09/2019 0:20 PM
Accident Reported Date and Time	20/09/2019 10:11 AM
Is Surveyor Required?	No
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle Issued?	No
Job Card Number	
Special Instruction to ARC, if any	SMB3529H RIGHT REAR PORTION PCB942T (TP) INSURED WITH IR
Prepared Date and Time	24/09/2019 3:49 PM
Chassis Number	SFD76CLR0EMTL3468
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates		
Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$795.00	\$0.00
Total Spray Cost	\$526.00	\$0.00
Total Spare Part Cost	\$0.00	\$0.00
Total Clear Coat	\$0.00	\$0.00
TOTAL COST	\$1,321.00	\$0.00
Lump Sum Total	\$1,350.00	\$0.00
Number of Repair Days	3.0	2
Prepared / Adjusted By	Baoon Chew Tay	
ARC / Surveyor Sign Off Date	24/09/2019 3:58 PM	
Signature		
Remarks		

Section C - Quotation and Accident Invoice Details			
Quotation Number		Invoice Number	
Quotation Date		Invoice Date	
Invoice Amount		Prepared Date	



Repair Day - 2 days
 Steve @ 25/09/2019 @ 2.15pm
 Lump Sum Repair, after spray
 TP without Prejudice.

LKK Auto Consultants hence notify the Repairer of the following:
 • To re-survey before the spray painting
 • To display damaged part(s) during re-survey
 • Parts prices are subject to confirmation
 • Third party survey is on a "without prejudice" basis
 • No legal modification is allowed
 • Supplementary item(s) must be re-surveyed and is subject to final approval from Insurance Company
 Acknowledged by Repairer:
 Signature:
 Date:

Nivitha (LKK Auto)

From: Motor Claim - III <motorclaim@iii.com.sg>
Sent: Wednesday, 25 September 2019 9:41 AM
To: Goh Kok Khoo (Auto Svcs/ARC/ARC/Buses); 'sur@lkkauto.com'; Admin-D (LKKAuto)
Cc: C Meenachi - III
Subject: RE: SMB3529H - Survey (III)
Attachments: ARC - Repair Estimate (75).pdf

11am @ 25/9/19
vehicle In
p: Ben Chew
s: Steve

Dear Sir / Mdm,

Please conduct a survey on TP vehicle SMB3529H and let us have your report urgently.

This claim will be handled by Ms Meena.

*Kindly upload this survey request email to merimen.

Thank You.

Best Regards,
Gabriel Wee



64 Cecil Street; #05 - IOB Building
Singapore 049711
Tel: 6347 6100, Ext - 248

From: Goh Kok Khoo (Auto Svcs/ARC/ARC/Buses) [mailto:GohKK2@smrt.com.sg]
Sent: 25 September, 2019 9:33 AM
To: Motor Claim - III <motorclaim@iii.com.sg>
Subject: RE: SMB3529H - Survey (III)

Hi,

- We selected LKK Auto Consultants Pte Ltd

Regards

From: Motor Claim - III [mailto:motorclaim@iii.com.sg]
Sent: 25 September 2019 09:30
To: Goh Kok Khoo (Auto Svcs/ARC/ARC/Buses)
Subject: RE: SMB3529H - Survey (III)

Dear Sir / Mdm,

We acknowledge receipt of your email.

We propose using one of the following motor surveyors:

- Automobile Inspection Services Pte Ltd
- VP Appraisal
- Form Team Adjusters Pte Ltd
- Infiniti Appraisal Service
- JP Knights Adjusters
- LBS Auto Consultants Pte Ltd
- Priority Services
- RT Appraisal
- LKK Auto Consultants Pte Ltd
- Vicom Assessment Centre Pte Ltd

Please notify us within 02 days of receipt of this letter for surveyor agreed on or if you have any objections to the above list.

Best Regards,
Gabriel Wee



64 Cecil Street; #05 - IOB Building
Singapore 049711
Tel: 6347 6100, Ext - 248

From: Goh Kok Khoo (Auto Svcs/ARC/ARC/Buses) [<mailto:GohKK2@smrt.com.sg>]

Sent: 24 September, 2019 4:26 PM

To: Motor Claim - III <motorclaim@iii.com.sg>

Cc: Catherine Lee Sau Chan (Auto Svcs/ARC/ARC/Buses) <catherineleesc@smrt.com.sg>; Gerald Tan Chwee Hock (Auto Svcs/ARC/ARC/Buses) <tanchweehock@smrt.com.sg>; Tay Boon Chew (Auto Svcs/ARC/ARC/Buses) <BoonChew.Tay@smrt.com.sg>; Balqish Binte Abdul Halil (Auto Svcs/Claims & IA/Claims & IA/Buses) <BalqishBAH@smrt.com.sg>; Karen Chan Siau Chin (Auto Svcs/Claims & IA/Claims & IA/Buses) <ChanSiauChin@smrt.com.sg>; Tan Wei Teck (Auto Svcs/Claims & IA/Claims & IA/Buses) <TanWeiTeck@smrt.com.sg>

Subject: SMB3529H - Survey (III)

Hi

Kindly arrange to survey the vehicle SMB3529H within 48 hours according to GIA guide line, involving your insured PC5942T.
Insurance Company : III

Vehicle is in Woodlands Bus Depot

Regards

Boon Chew
HP : 97399848

Kok Khoo
HP: 96451982

Kindly note that by submitting this claim to us, you are deemed to have agreed to us collecting, using, disclosing and processing your personal data, sharing your personal data with our service providers (located both inside and outside Singapore) and/or with other insurers in the general insurance industry, including the General Insurance Association of Singapore. This enables us to ensure proper processing, handling and/or dealing with your claim, which includes investigating the said claim, and complying with applicable laws. If you do not agree to the same, kindly let us know immediately.

DISCLAIMER:

This email is intended solely for the person to whom it has been addressed.

It may contain confidential and/or legally privileged information.

If you are not the person for whom this e-mail was intended, or if this e-mail has reached you by mistake, please delete it immediately and inform us of the error and also be hereby notified that any use, distribution, transmission, printing, copying or dissemination

of this information in any way or in any manner is strictly prohibited and may be unlawful. Internet communications may not be entirely secure or accurate as information could be

intercepted, corrupted, lost, delayed or contain viruses.

Therefore, we do not accept liability for any errors or omissions in the content of this message or any delay in delivery which may arise as a result of Internet transmission or any modification.

Print this email only if it is absolutely necessary and help in preservation of environment.

India International Insurance Pte Ltd.

Registration No. 198703792-K

Kindly note that by submitting this claim to us, you are deemed to have agreed to us collecting, using, disclosing and processing your personal data, sharing your personal data with our service providers (located both inside and outside Singapore) and/or with other insurers in the general insurance industry, including the General Insurance Association of Singapore. This enables us to ensure proper processing, handling and/or dealing with your claim, which includes investigating the said claim, and complying with applicable laws. If you do not agree to the same, kindly let us know immediately.

DISCLAIMER:

This email is intended solely for the person to whom it has been addressed.

It may contain confidential and/or legally privileged information.

If you are not the person for whom this e-mail was intended, or if this e-mail has reached you by mistake, please delete it immediately and inform us of the error and also be hereby notified that any use, distribution, transmission, printing, copying or dissemination

of this information in any way or in any manner is strictly prohibited and may be unlawful. Internet communications may not be entirely secure or accurate as information could be

intercepted, corrupted, lost, delayed or contain viruses.

Therefore, we do not accept liability for any errors or omissions in the content of this message or any delay in delivery which may arise as a result of Internet transmission or any modification.

Print this email only if it is absolutely necessary and help in preservation of environment.

India International Insurance Pte Ltd.

Registration No. 198703792-K

Print Received Message

This mail is associated with :

***SMB3529H (MFL2019D0001120)**
[PC5942T]
TP
SMRT BUSES LTD
Sep 19 2019 12:00AM
[TONG TAR TRANSPORT SERVICE PTE LTD]
SMRT Automotive Services Pte Ltd

From India International Insurance Pte Ltd (HQ) (III_SG), sent on 07/12/2019 10:23 AM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$1800.00) - SMB3529H - Claim Handler: C. Meenachi

Approved:1800.00:OUR RECOMMENDATION IS AS FOLLOWS : COR \$976.00 LOSS OF USE(\$300x3DAYS) 900.00
SEARCH FEE 7.00 TOTAL 1,883.00 TRY FOR GLOBAL \$1,80

...CLAIM SUBFOLDER...(Pending for Survey Report)

Direct Settlement

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	05 Dec 2019 Edit Reg		25 Sep 2019 00:00 Edit Adj Rpt	S\$976.00 Edit Estimates	S\$976.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured:	TONG TAR TRANSPORT SERVICE PTE LTD , Co. Reg. No.: 197800458K								
Main Claimant:	SMRT BUSES LTD , Co. Reg. No.: 198202292D								
Vehicle Reg. No.:	SMB3529H	Date of Loss:	19/09/2019 00:00 - :59 [60 Months and 18 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / MFL2019D0001120	Policy/Cover Note No.:	D18MFL0001888						
Vehicle Reg. No. (Insured):	PC5942T	Policy No. (Claimant):	D-19093203MFBP						
Repairer:	SMRT Automotive Services Pte Ltd (Woodlands) 60 Woodlands Industrial Park E4, 757705 Woodlands - Tel: 68662628								
Handling Insurer:	India International Insurance Pte Ltd (HQ) - Tel: 63476100 ... [Handled by C. Meenach] - 6347 6073]								
Claimant's Insurer:	MS First Capital Insurance Ltd (HQ) - Tel: 62222311								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by CHEN TSUE YEE] ... [Final Rpt due 04/10/2019]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
<ul style="list-style-type: none"> • III_SG (07/12/2019): Alert - Adj Mandate Approved (S\$1800.00) - SMB3529H - Claim Handler: C. Meenachi • III_SG (18/10/2019): Alert - Adj Mandate Approved (S\$0.00) - SMB3529H - Claim Handler: C. Meenachi 									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SMB3529H (MFL2019D0001120)
 [PC5942T]
 TP
 SMRT BUSES LTD
 Sep 19 2019 12:00AM
 [TONG TAR TRANSPORT SERVICE PTE LTD]
 SMRT Automotive Services Pte Ltd

Upload Documents			Upload Photos			Compose New Letter			View	View in Browser
Photos/Images									3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print					
1	27/09/19 17:21	Odometer Reading		Load JPG	<input checked="" type="checkbox"/>					
2	27/09/19 17:21	Chassis Number		Load JPG	<input checked="" type="checkbox"/>					
3	27/09/19 17:21	General View		Load JPG	<input checked="" type="checkbox"/>					
4	27/09/19 17:21	General View		Load JPG	<input checked="" type="checkbox"/>					
5	27/09/19 17:21	General View		Load JPG	<input checked="" type="checkbox"/>					
6	27/09/19 17:21	General View		Load JPG	<input checked="" type="checkbox"/>					
7	27/09/19 17:21	General View		Load JPG	<input checked="" type="checkbox"/>					
8	27/09/19 17:21	General View		Load JPG	<input checked="" type="checkbox"/>					
9	27/09/19 17:21	General View		Load JPG	<input checked="" type="checkbox"/>					
10	27/09/19 17:21	General View		Load JPG	<input checked="" type="checkbox"/>					
11	27/09/19 17:21	General View		Load JPG	<input checked="" type="checkbox"/>					
12	27/09/19 17:21	General View		Load JPG	<input checked="" type="checkbox"/>					
13	27/09/19 17:21	General View		Load JPG	<input checked="" type="checkbox"/>					
14	27/09/19 17:21	General View		Load JPG	<input checked="" type="checkbox"/>					
15	27/09/19 17:21	General View		Load JPG	<input checked="" type="checkbox"/>					
16	27/09/19 17:21	General View		Load JPG	<input checked="" type="checkbox"/>					
17	27/09/19 17:21	General View		Load JPG	<input checked="" type="checkbox"/>					
18	27/09/19 17:21	General View		Load JPG	<input checked="" type="checkbox"/>					
19	27/09/19 17:21	General View		Load JPG	<input checked="" type="checkbox"/>					
20	27/09/19 17:21	General View		Load JPG	<input checked="" type="checkbox"/>					
21	27/09/19 17:21	General View		Load JPG	<input checked="" type="checkbox"/>					
22	27/09/19 17:21	General View		Load JPG	<input checked="" type="checkbox"/>					
23	27/09/19 17:22	After Repair Photo		Load JPG	<input checked="" type="checkbox"/>					
24	27/09/19 17:22	After Repair Photo		Load JPG	<input checked="" type="checkbox"/>					
25	27/09/19 17:22	After Repair Photo		Load JPG	<input checked="" type="checkbox"/>					
26	27/09/19 17:22	After Repair Photo		Load JPG	<input checked="" type="checkbox"/>					
27	27/09/19 17:22	After Repair Photo		Load JPG	<input checked="" type="checkbox"/>					
28	27/09/19 17:22	After Repair Photo		Load JPG	<input checked="" type="checkbox"/>					
29	27/09/19 17:22	After Repair Photo		Load JPG	<input checked="" type="checkbox"/>					
30	27/09/19 17:22	After Repair Photo		Load JPG	<input checked="" type="checkbox"/>					
31	27/09/19 17:22	After Repair Photo		Load JPG	<input checked="" type="checkbox"/>					
32	27/09/19 17:22	After Repair Photo		Load JPG	<input checked="" type="checkbox"/>					
33	27/09/19 17:22	After Repair Photo		Load JPG	<input checked="" type="checkbox"/>					
34	27/09/19 17:22	After Repair Photo		Load JPG	<input checked="" type="checkbox"/>					
Documentation									3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print					
1	25/09/19 16:00	EMAIL FROM III DD 25092019		Load PDF						
2	25/09/19 16:00	TP ESTIMATE		Load PDF						
3	27/09/19 17:19	TP ESTIMATE- MARKED		Load PDF						
4	27/09/19 17:19	TP GIA REPORT		Load PDF						
5	24/10/19 12:35	FINAL REPAIR INVOICE		Load PDF						
6	24/10/19 12:35	LOD		Load PDF						
7	24/10/19 12:35	LTA SEARCH INVOICE		Load PDF						
8	13/02/20 11:35	AUTHORISATION TO ACT FORM		Load PDF						

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail Print
9	13/02/20 11:35	DISCHARGE VOUCHER		Load PDF
No	Finalized On	India International Insurance Pte Ltd (HQ)		Thumbnail Print
1	26/09/19 08:52	Singapore Accident Statement		Load PDF

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/III19016915/EGS3Q2

Date: 13/02/2020

REFERENCE

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	D18MFL0001888
Claimant Vehicle No :	SMB3529H	Insured Vehicle No :	PC5942T
Date of Loss:	19/09/2019	Nature of Claim:	TP
		Claim No:	MFL2019D0001120

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMB3529H		
Make & Model:	ALEXANDER DENNIS ENVIRO500, 8.8 D (A)	Engine No:	22120165
Reg. Date:	01/09/2014 (Man. Year: 2014)	Chassis No:	SFD76CLR5EMTL3458
Colour:	Silver	Odometer:	350284 km
Engine Capacity:	8849 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	305/70R22.5	Rear Tyre Size:	305/70R22.5
Front Left Side:	Firenza 5 mm	Rear Left Side:	Firenza 5 mm
Front Right Side:	Firenza 5 mm	Rear Right Side:	Firenza 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,703.25	0.00	1,703.25	100.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,333.00	976.00	357.00	26.78
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	3,036.25	976.00	2,060.25	67.86
+ Loss of Use (3.0 x S\$300.00/day) (S\$)		900.00		
+ Doc/Search Fee (S\$)		7.00		
Nett Liability (S\$)		1,883.00		
Global Sum Settlement (S\$)		1,800.00		

INSPECTION

Date of Assignment:	25/09/2019		
Date Inspected:	25/09/2019	Inspected At:	SMRT Automotive Services Pte Ltd (Woodlands) 60 Woodlands Industrial Park E4 Singapore 757705
Estimated Period of Repair:	2.0 days		

Adjuster: CHEN TSUE YEE

Manager: Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 05 Dec 2019)	
Parts:	N/A	ALEXANDER DENNIS ENVIRO500 8.8 D (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMB3529H)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
1	1		*POD TAIL LIGHT :R/H ,FOR ADL E500 OD BUS	Repair	1,703.25 F	*- F	
					Total Parts (S\$)	1,703.25	0.00

F=Franchise part.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE & INSTALL ALL ABOVE ITEMS AND REPAIR OTHERS DAMAGED AFFECTED AREAS	New	795.00	530.00
2	PROVIDE LABOUR AND MATERIAL TO PUTTY AND RESPRAY ABOVE REPAIR ITEMS	New	538.00	446.00
Gross Labour Cost (S\$)			1,333.00	976.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >