

ASS. REC. BY:

REF

CS3/CTI19016927/Bc d3⁵²

Special Instruction:

Surveyor:

ASSIGNMENT (Office)

From (Person):

Chong Boon Sen

of

CTI

Date/Time:

25/9/19 4:04pm

Estimated Cost:

Bill to:

OI / TI / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SJA 5588P

Insured:

GR 9081D

at Workshop m/s

Team Auto pro

Tel:

6258 1955

of

160 Sing Ming Drive # 01-14

Policy No:

DMCVSN30687718000

Claim No:

8NM19D204511C02

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

29/09/2019

26/9/19

H.O.D. Endorsement:

CA / REV / REP. / REV 24 HRS

Date/Time:

4:50pm 25/9/19

Person Contacted:

Pecuh

Vehicle IN/OUT

Date/Time

Action/Instruction

Estimate /

SJA 5588P-X

GR 9081D-NBA / 19/19016869/p

D.O.A : 29/9/2019

Dismantle: 27/9/2019

After repair: 1/10/2019

ASS. REG. BY:

REF:

CTE

ASSIGNMENT

From:

Date: 26/9/2019

Estimated Cost:

OD ☒ WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

SJA 5588P

at Workshop m/s

Team Autopro

of

160 Sin Ming Drive # 01-14

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

5

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

up

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SJA 5588P

Yr Regn: 27/11/2007

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Mercedes Benz E 230

c.c 2497

Colour:

Grey

A/C: Insured / Std / NI / NA

Sp. Reading:

157375

T/Radio: Insured / Std / NI / NA

Eng/No:

27292230708962

C/No:

WDB2110522B213260

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F: 225/55R16 Toyota

R: 225/55R16 Hankook

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

2011 / Hankook

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

24/9/19

D.O.I.

26/9/19

Survey held at

Team Autopro

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Range 4,000/- - 5,000/-

PRS

Date/Time, File Pass to?

☐

Preli. Report

1)

☐

Final Report

Date/Time, File Return to?

2)

Days Of Repair:

5

Resurvey No. of Trip:

2

Survey Fee:

Transportation:

S + RS: SI

Photos:

Others:

TOTAL

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Week end (\$

Report Formed:

PRS

Lump Sum / FE: (\$

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	27 Sep 2019		27 Sep 2019 13:10 Edit Adj Rpt				Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS [Created by insurer]

Insured:				
Main Claimant:	TAN TIONG SENG , ID: S1097920Z			
Vehicle Reg. No.:	SJA5588P	Date of Loss:	24/09/2019 10:00 - :59	
Claim Type:	TP / SNM19D204511C02	Policy/Cover Note No.:	DMCVSN30687718000	
Vehicle Reg. No. (Insured):	GR9081D	Policy No. (Claimant):	2100051675-11	
		Excess:	S\$0.00	
Repairer:	Team Autopro Pte Ltd - Sin Ming (HQ) 160 SIN MING DRIVE #02-12 SIN MING AUTOCITY, 575722 Sin Ming - Tel: 9674 6635 / 9092 7279			
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Chong Boon Sen]			
Claimant's Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (SG) - Tel: 65-6419-3000			
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by Lim Teow Guan] ... [Final Rpt due 08/10/2019]			

ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Nivitha (LKK Auto)

From: Chong Boon Sen <boonsen.chong@sg.cntaiping.com>
Sent: Wednesday, 25 September 2019 4:04 PM
To: Chia Jia Rong
Cc: assignments
Subject: RE: OUR REF: SNM19D204511-GR9081D-CBS - : Pre Repair Inspection

**WITHOUT PREJUDICE
SAVE AS TO COSTS**

Dear Sir,

We regret to inform that we are not agreeable to your list of proposed surveyors and will be assigning our panel surveyor, M/s LKK Auto Consultants to conduct the Pre-repair survey.

Please contact our surveyor to conduct the post repair inspection before returning the repaired vehicle to the claimant.

Aside to LKK,

Please refer to the email below and liaise with third party workshop accordingly.

Thank you.

Chong Boon Sen

Claims Executive
Department

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #16-00 Springleaf Tower Singapore 079909
DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

W: www.sg.cntaiping.com | **FB:** www.facebook.com/chinataipingsg/ | **WeChat:** 太平獅城 Taiping SG 3 Anson
Road #16-00 Springleaf Tower Singapore 079909
DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

From: Chia Jia Rong [mailto:jiarong@roypartners.com.sg]
Sent: Wednesday, September 25, 2019 4:01 PM
To: Chong Boon Sen <boonsen.chong@sg.cntaiping.com>
Subject: RE: OUR REF: SNM19D204511-GR9081D-CBS - : Pre Repair Inspection

Dear Sirs,

We refer to your email below.

Our client reject your list of proposed motor surveyors and propose Mr. Ananda Kumar Biswas S/O B N Biswas of United Appraisal and Management Pte Ltd and Ms. Tan Ling Ling, Candy of Impact Analysis Consultants as the Single Joint Expert.

Pursuant to the new NIMA protocol, kindly let us know within **2 working days** of receipt of our letter whether you agree or has any objections to the motor surveyor proposed by our client, failing which you are deemed to have agreed to the appointment of any of the motor surveyors proposed by our client.

Please take note that with effect from 9th September 2019, we will be relocated to our new office at 133 New Bridge Road #08-09 Chinatown Point, Singapore 059413.

With regards,

Chia Jia Rong

M/s Roy & Partners
133 New Bridge Road
#08-09

China Town Point
Singapore 059413

Tel : 6536 8466 Fax : 6536 1963

Email : jiarong@roypartners.com.sg

IMPORTANT NOTE : The information in this email is confidential and may also be privileged. If you are not the intended recipient, any use or dissemination of the information and any disclosure or copying of this email is unauthorised and strictly prohibited. If you have received this email in error, please notify the sender immediately. You should also delete and destroy all copies of it. Thank you.

From: Chong Boon Sen [<mailto:boonsen.chong@sg.cntaiping.com>]

Sent: Wednesday, 25 September, 2019 1:54 PM

To: jiarong@roypartners.com.sg

Subject: RE: OUR REF: SNM19D204511-GR9081D-CBS - : Pre Repair Inspection

Without prejudice

Dear Sir,

LKK

STA

LBS

Chong Boon Sen

Claims Executive
Department

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #16-00 Springleaf Tower Singapore 079909

DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

W: www.sg.cntaiping.com | **FB:** www.facebook.com/chinataipingsg/ | **WeChat:** 太平獅城 Taiping SG 3 Anson
Road #16-00 Springleaf Tower Singapore 079909

DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

From: Claims Dept of CTI

Sent: Wednesday, September 25, 2019 1:38 PM

To: Tan Kah Leong <KahLeong.Tan@sg.cntaiping.com>; Alfred Toh <alfred.toh@sg.cntaiping.com>;
Chee So Chow <sochow.chee@sg.cntaiping.com>; Chong Boon Sen <boonsen.chong@sg.cntaiping.com>;
jiarong@roypartners.com.sg

Subject: OUR REF: SNM19D204511-GR9081D-CBS - : Pre Repair Inspection

Dear Boon Sen,

Please assist to conduct PRS for SJA5588P.

Note : officer in charge – Kah Leong 63896193.

Thank you

Claims Department

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #15-00 Springleaf Tower Singapore 079909

DID: (65) 63896116 | F: (65) 62247175

W: www.sg.cntaiping.com | **FB:** www.facebook.com/chinataipingsg/ | **WeChat:** 太平獅城 Taiping SG

Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.

From: Chia Jia Rong [<mailto:jiarong@roypartners.com.sg>]

Sent: Wednesday, September 25, 2019 9:44 AM

To: Claims Dept of CTI

Subject: Pre Repair Inspection

Our Ref: MKR/404/9234/2019/as.jr;

Your Ref: Your insured vehicle no. GR 9081D;

Dear Sirs,

Attn: Motor claims department

CLAIMANT: TAN TIONG SENG (OWNER OF SJP 4215T)

ROAD TRAFFIC ACCIDENT INVOLVING VEHICLE NOS. SJA 5588P AND GR 9081D AT MAY FLOWER MARKET OPEN SPACE PARK ON 24.09.2019 AT ABOUT 1000 HOURS.

We refer to the above matter.

We act for TAN TIONG SENG, the owner of motor car No. **SJA 5588P**.

We are instructed by our client to notify you of a road traffic accident on 24.09.2019 at about 1000 hours along MAY FLOWER MARKET OPEN SPACE PARK involving our client's motor car registration number **SJA 5588P** and motor vehicle registration number **GR 9081D** driven by your insured at the material time. A copy of the Singapore Accident Statement report is attached.

As a result of the accident, our client's motor car **SJA 5588P** has been damaged. Before our client proceed to repair the damaged motor car, please let us know within two (2) working days of your receipt of this notice whether you would like to conduct a pre-repair survey of our client's motor car **SJA 5588P** at our client's repairer workshop, M/s Team AutoPro Pte Ltd change at No. 160 Sin Ming Drive #01-14 Singapore 575722. Your said surveyor may contact Mr. Alan Koh/Frederick Lim at 9092 7279/9674 6635. If we do not receive any reply from you within the stipulated timeline, our client shall proceed to repair the motor car without further reference to you.

With regards,

Chia Jia Rong

M/s Roy & Partners
133 New Bridge Road
#08-09

China Town Point
Singapore 059413

Tel : 6536 8466 Fax : 6536 1963

Email : jiaorong@roypartners.com.sg

IMPORTANT NOTE : The information in this email is confidential and may also be privileged. If you are not the intended recipient, any use or dissemination of the information and any disclosure or copying of this email is unauthorised and strictly prohibited. If you have received this email in error, please notify the sender immediately. You should also delete and destroy all copies of it. Thank you.

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	25/09/2019 10:43
Date Of Accident	24/09/2019 10:00
Exact Location Of Accident	MAY FLOWER MARKET OPEN SPACE CARPARK
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJA5588P
Insured/Policyholder	
Name Of Registered Owner	TAN TIONG SENG
NRIC No	S1097920Z
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-96364684
Alternative Phone No	OTHERS-96364684

Vehicle Particulars

Manufacturer	MERCEDES-BENZ
Model	E230
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	THIRD PARTY
Fleet Policy	NO
Policy Number	2100051675-11
Cover Note Number	

Driver

Name of Driver	TAN TIONG SENG
NRIC No	S1097920Z
Date Of Birth	30/07/1946
Occupation	INDOOR
Date Of Driving Pass	30/01/1973
Driving Experience	46 YEARS AND 7 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96364684
Fax Number	
Contact Number	OTHERS-96364684
Email Address	NOEMAIL

Address	18 FUDU WALK
Postcode	789511
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	HIT AND RUN / VANDALISM / DAMAGED WHILST PARKED
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	5
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	0

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	THOMSON NEIGHBOURHOOD POLICE POST
Police Station Address	ROAD: BLK 25 SIN MING ROAD , POSTCODE: 570025 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: 1800-4529999 - FAX NO: 6 5535740
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

PLEASE REFER TO SKETCH AND POLICE REPORT T/20190924/2065

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GR9081D
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	

No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number SMA2219P
Vehicle Make/Model/Colour
Details Of Properties
Vehicle Category PRIVATE CAR
Name of Driver
NRIC/Passport Number
Contact Number
Address
Postcode
Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 3

Vehicle Registration Number SKK9073S
Vehicle Make/Model/Colour
Details Of Properties
Vehicle Category PRIVATE CAR
Name of Driver
NRIC/Passport Number
Contact Number
Address
Postcode
Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 4

Vehicle Registration Number SBK3113G
Vehicle Make/Model/Colour
Details Of Properties
Vehicle Category PRIVATE CAR
Name of Driver
NRIC/Passport Number
Contact Number
Address
Postcode
Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver)

Accident Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:



Driver's Signature
(If driver is not the policyholder)
Date & Time

23/09/2019
Reporting Centre Personnel Signature
Name:
NRIC/FIN No:

Accident Sketch Plan

SKETCH PLAN

mayflower open space carpark



V.A) SJAS588P
V.B) GR 9081D
V.C) SMA 221AP
V.D) SKK 9073S
V.E) SBK 311361

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I was parked stationary on lot 74, everything was intact before I left. We then went to the market, and came back shortly to retrieve our vehicles. We then notice there was alot of people around the car park. We then realised vehicle 'B' had collided against my stationary vehicle front right portion. We then know that it was vehicle 'D' SKK9073S did a reverse and went up the kerb and collided against vehicle 'E' rear portion, and vehicle 'D' full acceleration to the front collided against vehicle 'C' & 'B' which caused it to collide against my car front right portion.

Police Report 7/2015 0924/2015

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time

Driver's Signature
(If driver is not the policyholder)
Date & Time

Reporting Centre Person's Signature
Name:
NRIC/FIN No.

POLICE REPORT



**SINGAPORE
POLICE FORCE**



T/20190924/2065

Police Station Of Origin
Thomson NPP
25 Sin Ming Road #01-180 SINGAPORE
570025
Tel No. 1800-4529999

1 of 3

Report No. T/20190924/2065

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 24/09/2019 13:09		Vide Report No.: F/20190924/0073		Station Diary No.: 26	
Informant's Particulars					
Name of Informant: TAN TIONG SENG			Address: 18 FUDU WALK SINGAPORE 789511		
ID Type / ID No.: NRIC NO / S1097920Z			Contact No.: Home/Office: Mobile: 96364684		
Nationality: SINGAPORE CITIZEN			Email:		
Sex: Male	Age: 73	Date of Birth: 30/07/1946	Type of Informant: Driver		
Race: Chinese			Language: English		Institution / School Name:
Occupation: Retiree			Driving Licence Information: Class: 3 Date of Expiry:		

General Information of the Accident

Type of Accident:	Injury Attended by Police	Drink Drive: No	Date/Time of Accident: 24/09/2019 10:00	Type of Location: Car Park
Location: Along Road 1 ANG MO KIO AVENUE 4 Bk 163 Ang Mo Kio Ave 4 Open Space Carpark near Mayflower Market				
Weather: Clear		Road Surface: Dry		Road Speed Limit:
Traffic Flow: Two Way		Traffic Control: Not Controlled		Traffic Volume: Moderate
Type of Collision: Moving Vehicle Against - Parked Vehicle				Anyone conveyed by ambulance: No

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
GR9081D	Lorry				Seriously Damaged	0
SBK3113G	Car				Seriously Damaged	0
SJA5588P	Car	MERCEDES BENZ	E230	Grey	Seriously Damaged	0
SKK9073S	Car				Seriously Damaged	0
SMA2219P	Car				Seriously Damaged	0

POLICE REPORT



**SINGAPORE
POLICE FORCE**



T/20190924/2065

Police Station Of Origin:
Thomson NPP
25 Sin Ming Road #01-180 SINGAPORE
570025
Tel No: 1800-4529999

2 of 3

Report No. T/20190924/2065

CONTINUATION OF REPORT

Details of Vehicle Insurance				
Vehicle No.	Insurance Company	Insurance No	Effective	Expiry Date
SJA5588P	AIG ASIA PACIFIC INSURANCE PTE. LTD.	2100051675-11	27/11/2018	26/11/2019

Details of Person Involved			
Any Pedestrian Involved: No			
No. of Pedestrians Injured: NIL		Use of Pedestrian Crossing: NA	
Driver:			
Name	TAN TIONG SENG		ID No S1097920Z
Related Vehicle	SJA5588P (Car)		Contact No. 96364684
Hospital/Clinic	NIL		Class of Driving Licence & Expiry Date Class: 3 Date of Expiry: NIL
Date Treatment	NIL		Date Discharge NIL
No. of Days granted Medical Leave	NIL		Degree of Injury NIL

Brief Details.

On 24/09/2019 at about 0930hrs, I had parked my vehicle at Blk 163 Ang Mo Kio Ave 4 Open space carpark, near Mayflower Market. My vehicle(SJA5588P) was parked at Lot no 74. Before I left, I made a check on my vehicle and everything was intact. At about 1030hrs, I then came back to retrieve my vehicle when I discovered that a vehicle(GR9081D) had collided onto the driver side of my vehicle. I was then informed by the police officers that attended, that a vehicle(SKK9073S) had lost control causing multiple collisions and driver was already conveyed to the hospital. I was told that the driver of the vehicle(SKK9073S) attempted to park but had lost control of his vehicle causing it to knock onto vehicle GR9081D which then collided onto my vehicle. I am unsure of what really happened as I was not present during the incident. I was then informed by the attending police officers to lodge a traffic accident report. I am also lodging this report to facilitate my insurance claims.

POLICE REPORT



SINGAPORE
POLICE FORCE



T/20190924/2065

Police Station Of Origin
Thomson NPP
25 Sin Ming Road #01-180 SINGAPORE
570025
Tel No: 1800-4529999

3 of 3

Report No: T/20190924/2065

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report E / Sgt 2 QAMARUL FITRI BIN JEFFREY	Signature Of Informant
Signature Of Interpreter: Not applicable	Date/Time: 24/09/2019 13:09
Officer In Charge Of Case: TP / GIT / Sr Staff Sgt NOR HIDAYU BINTE ABDUL SIA @AD POLICE FORCE Contact No: 65476423	Classification Of Case
Authentication Stamp NP168 SIGNATURE	

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC
Owner ID: 920Z

Vehicle Details

Vehicle No.: SJA5588P
Vehicle to be Exported: No
Intended Deregistration Date: 27 Sep 2019
Vehicle Make: MERCEDES BENZ
Vehicle Model: E230
Primary Colour: Grey
Manufacturing Year: 2007
Engine No.: 27292230708962
Chassis No.: WDB2110522B213260
Maximum Power Output: 150.0 kW (201 bhp)
Open Market Value: \$52,847.00
Original Registration Date: 27 Nov 2007
First Registration Date: 27 Nov 2007
Transfer Count: 0
Actual ARF Paid: \$58,132.00

Intended PARF Rebate Details

PARF Eligibility: Forfeited
PARF Eligibility Expiry Date: -
PARF Rebate Amount: \$0.00

Intended COE Rebate Details

COE Expiry Date: 26 Nov 2027
COE Category: B - Car (1601cc & above)
COE Period(Years): 10
PQP Paid: \$50,168.00
COE Rebate Amount: \$40,968.00
Total Rebate Amount: \$40,968.00

The information contained herein is correct as at 27 Sep 2019

OK

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	27 Sep 2019		27 Sep 2019 13:10 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS [Created by insurer]

Insured: -, Co. Reg. No.: -	
Main Claimant: TAN TIONG SENG , ID: S1097920Z	
Vehicle Reg. No.: SJA5588P	Date of Loss: 24/09/2019 10:00 - :59 [141 Months and 28 Days From LTA Reg Date (Man Yr)]
Claim Type: TP / SNM19D204511C02	Policy/Cover Note No.: DMCVSN30687718000
Vehicle Reg. No. (Insured): GR9081D	Policy No. (Claimant): 2100051675-11
	Excess: S\$0.00
Repairer: Team Autopro Pte Ltd - Sin Ming (HQ) 160 SIN MING DRIVE #02-12 SIN MING AUTOCITY, 575722 Sin Ming - Tel: 9674 6635 / 9092 7279	
Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Chong Boon Sen]	
Claimant's Insurer: AIG Asia Pacific Insurance Pte. Ltd. (SG) - Tel: 65-6419-3000	
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by Lim Teow Guan] ... [Final Rpt due 08/10/2019]	

ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SJA5588P (SNM19D204511C02)**
[GR9081D]

TP

TAN TIONG SENG
Sep 24 2019 10:00AM































[-]

Team Autopro Pte Ltd - Sin Ming











Upload Documents Upload Photos Compose New Letter









View View in Browser ▼

Assessment Reports			1 per page ▼	<input checked="" type="checkbox"/>
No	Finalized On	National Assessment Centre Services (Bukit Merah)	Thumbnail	Print
1	25/09/19 11:04	Accident Statement	Load HTM	
Photos/Images			3 per page ▼	<input checked="" type="checkbox"/>
No	Finalized On	National Assessment Centre Services (Bukit Merah)	Thumbnail	Print
1	25/09/19 10:59	Accident Photo [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
2	25/09/19 10:59	Accident Photo [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
3	25/09/19 10:59	Accident Photo [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
4	25/09/19 10:59	Accident Photo [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
5	25/09/19 10:59	Accident Photo [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
6	25/09/19 10:59	Accident Photo [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
7	25/09/19 10:59	Accident Photo [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
8	25/09/19 10:59	Accident Photo [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
9	25/09/19 10:59	Accident Photo [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
10	25/09/19 10:59	Accident Photo [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
11	25/09/19 10:59	Accident Photo [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
12	25/09/19 10:59	Accident Photo [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	07/10/19 09:59	General View	Load JPG	<input checked="" type="checkbox"/>
2	07/10/19 09:59	General View	Load JPG	<input checked="" type="checkbox"/>
3	07/10/19 09:59	General View	Load JPG	<input checked="" type="checkbox"/>
4	07/10/19 09:59	General View	Load JPG	<input checked="" type="checkbox"/>
5	07/10/19 09:59	General View	Load JPG	<input checked="" type="checkbox"/>
6	07/10/19 09:59	General View	Load JPG	<input checked="" type="checkbox"/>
7	07/10/19 09:59	General View	Load JPG	<input checked="" type="checkbox"/>
8	07/10/19 09:59	General View	Load JPG	<input checked="" type="checkbox"/>
9	07/10/19 09:59	General View	Load JPG	<input checked="" type="checkbox"/>
10	07/10/19 09:59	General View	Load JPG	<input checked="" type="checkbox"/>
11	07/10/19 09:59	General View	Load JPG	<input checked="" type="checkbox"/>
12	07/10/19 09:59	General View	Load JPG	<input checked="" type="checkbox"/>
13	07/10/19 09:59	General View	Load JPG	<input checked="" type="checkbox"/>
14	07/10/19 09:59	General View	Load JPG	<input checked="" type="checkbox"/>
15	07/10/19 09:59	General View	Load JPG	<input checked="" type="checkbox"/>
16	07/10/19 09:59	General View	Load JPG	<input checked="" type="checkbox"/>
17	07/10/19 09:59	General View	Load JPG	<input checked="" type="checkbox"/>
18	07/10/19 09:59	General View	Load JPG	<input checked="" type="checkbox"/>
19	07/10/19 09:59	General View	Load JPG	<input checked="" type="checkbox"/>
20	07/10/19 09:59	General View	Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	
No	Finalized On	National Assessment Centre Services (Bukit Merah)	Thumbnail	Print
21	07/10/19 09:59	General View	 Load JPG	<input checked="" type="checkbox"/>
22	07/10/19 09:59	General View	 Load JPG	<input checked="" type="checkbox"/>
23	07/10/19 09:59	General View	 Load JPG	<input checked="" type="checkbox"/>
24	07/10/19 09:59	General View	 Load JPG	<input checked="" type="checkbox"/>
25	07/10/19 09:59	General View	 Load JPG	<input checked="" type="checkbox"/>
26	07/10/19 09:59	General View	 Load JPG	<input checked="" type="checkbox"/>
27	07/10/19 09:59	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
28	07/10/19 09:59	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
29	07/10/19 09:59	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
30	07/10/19 09:59	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
31	07/10/19 09:59	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
32	07/10/19 09:59	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
33	07/10/19 09:59	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
34	07/10/19 09:59	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
35	07/10/19 09:59	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
36	07/10/19 09:59	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
37	07/10/19 09:59	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
38	07/10/19 09:59	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
39	07/10/19 09:59	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
40	07/10/19 10:00	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
41	07/10/19 10:00	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
42	07/10/19 10:00	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
43	07/10/19 10:00	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
44	07/10/19 10:00	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
45	07/10/19 10:00	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	
No	Finalized On	National Assessment Centre Services (Bukit Merah)	Thumbnail	Print
1	25/09/19 11:03	Accident Sketch Plan [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
2	25/09/19 11:03	Accident Sketch Plan [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
3	25/09/19 11:03	POLICE REPORT [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
4	25/09/19 11:03	POLICE REPORT [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
5	25/09/19 11:03	POLICE REPORT [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>

Linked Accident Report Documents

Assessment Reports			View	View in Browser
No	Finalized On	National Assessment Centre Services (Bukit Merah)	Thumbnail	Print
1	25/09/19 11:04	Accident Statement	 Load HTM	
Photos/Images			3 per page	
No	Finalized On	National Assessment Centre Services (Bukit Merah)	Thumbnail	Print
1	25/09/19 10:59	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
2	25/09/19 10:59	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
3	25/09/19 10:59	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
4	25/09/19 10:59	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
5	25/09/19 10:59	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
6	25/09/19 10:59	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
7	25/09/19 10:59	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
8	25/09/19 10:59	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
9	25/09/19 10:59	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page ▼	✓
No	Finalized On	National Assessment Centre Services (Bukit Merah)	Thumbnail	Print
10	25/09/19 10:59	Accident Photo	 Load JPG	✓
11	25/09/19 10:59	Accident Photo	 Load JPG	✓
12	25/09/19 10:59	Accident Photo	 Load JPG	✓
Documentation			1 per page ▼	✓
No	Finalized On	National Assessment Centre Services (Bukit Merah)	Thumbnail	Print
1	25/09/19 11:03	Accident Sketch Plan	 Load JPG	✓
2	25/09/19 11:03	Accident Sketch Plan	 Load JPG	✓
3	25/09/19 11:03	POLICE REPORT	 Load JPG	✓
4	25/09/19 11:03	POLICE REPORT	 Load JPG	✓
5	25/09/19 11:03	POLICE REPORT	 Load JPG	✓

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/CTI19016927/BCD3S2

Date: 11/10/2019

REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMCVSN30687718000

Claimant Vehicle No: SJA5588P Insured Vehicle No: GR9081D

Date of Loss: 24/09/2019 Nature of Claim: TP Claim No: SNM19D204511C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SJA5588P**

Make & Model: MERCEDES-BENZ E230, 2.5 (A) Engine No: 27292230708962

Reg. Date: 27/11/2007 (Man. Year: 2007) Chassis No: WDB2110522B213260

Colour: Grey Odometer: 157375 km

Engine Capacity: 2497 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Fair Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/55 ZR16 Rear Tyre Size: 225/55 ZR16

Front Left Side: Toyo 6 mm Rear Left Side: Hankook 6 mm

Front Right Side: Toyo 6 mm Rear Right Side: Hankook 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 27/09/2019

Date Inspected: 26/09/2019 Inspected At: Team Autopro Pte Ltd - Sin Ming (HQ)
160 SIN MING DRIVE #02-12 SIN MING
AUTOCITY
Singapore 575722

Estimated Period of Repair: 5.0 days

Adjuster: Lim Teow Guan

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

10/11/2019

Adjuster Report

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$4,000.00 - \$5,000.00

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 10 Oct 2019)
Parts:	143	MERCEDES-BENZ E230 2.5 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJA5588P)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >