

Ashe

ESTIMATED ACCIDENT REPAIR COST



Surveyor Pasni - LKK Anticonsultants

ACCIDENT TIME REPORTED	11:50hrs
ACCIDENT DATE	11-Sep-19
BUS CAPTAIN NAME	LIM WOEI LOCK
THIRD PARTY CLAIM AGAINST	AIG

BUS REGISTRATION NUMBER	SBS6354R
BUS TYPE (SD/DD)	SD
BUS ROUTE NUMBER	
BUS ADVERTS (Y/N)	N

SECTION 1: PARTS & CONSUMABLE ITEMS (MATERIAL COST)

Part No.	Part or Item Description	Quantity	Total Cost
	"SG BUS" LOGO NA /	Special Nett	\$300.00
	WHITE & GREY STICKER m /	Special Nett	30 \$40.00
			330
		7% GST	\$23.80
		PARTS TOTAL COST	\$363.80

SECTION 2: ASSESSMENT / REPAIR / SPRAY PAINT (LABOUR COST)

LABOUR ITEM (PLEASE SPECIFY IF ITS ASSESSMENT, REPAIR OR SPRAY PAINT)			TOTAL COST
TO REMOVE & REPLACE "SG BUS" LOGO AND WHITE-GREY STICKER			\$650.00
TO REMOVE , REPAIR, PUTTY AND RE-INSTAL O/S/R SIDE & LOWER PANEL			\$650.00
SPRAY PAINTING SIDE & LOWER PANEL			\$1,280.00

ESTIMATED ACCIDENT REPAIR COST



SECTION 3: REPAIRS TO BUS ADVERTISEMENT VINYL/PANELS (ADVERTISEMENT COST)

TOTAL ADVERTISEMENT REPAIR COST	
---------------------------------	--

SECTION 4: RECOVERY OF ACCIDENT BUS (TOWING COST)

TOTAL TOWING COST	
-------------------	--

SECTION 5: NUMBER OF DAYS UNDER ACCIDENT REPAIR (LOSS OF USE COST)

		Date In For Repairs		
		Date Out From Repairs		
		Number of Days Under Repair		0
BUS TYPE (SD / DD)		LOSS OF USE COST		\$900.00

SUMMARY	
SECTION NO.	COST
1	\$363.80
2	\$2,760.60
3	-
4	-
5	\$900.00
GRAND TOTAL	\$4,024.40

Repair
Hr 900/1068
2 days
25/09/19 @ 1600
Ready after repair

PAGE 2

LKK Auto Consultants hence notify the Repairer of the following:
 • To resurvey before/after spray painting
 • To display damaged part(s) during resurvey
 • Parts prices are subject to confirmation
 • Third party survey is on a "Without Prejudice" basis
 • No illegal modification(s) is allowed
 • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

330
 1390

 1720

2 days