

11/11/2011

ASS. REC. BY:

Surveyor

REF: C/TPD19016942/P2

Special Instruction:

ASSIGNMENT (Office)

From (Person): Kamaliah Kamic

of SPP

Date/Time: 25/9/2019

Estimated Cost:

Bill to:

OD/TP/WS/TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: GBD F30G

Insured:

at Workshop m/s

Tel:

of

Policy No: MHASPF06000025(81)1

Claim No: TP/1P/39969/2019

Sum Insured:

Excess:

D.O.A 26/6/2019

Make of Veh:

(Client's Record)

H.O.D. Endorsement:

CA / REV / REP. / REV 24 HRS

Date/Time:

Person Contacted:

Vehicle IN/OUT

Date/Time	Action/Instruction () Estimate
	GBD F30G-X

E90
opp

Not in
Res in

IO In-Charge: SIO Yazid

f) **Case IAFP-IB-20190908 - Mechanical Inspection of Motor Car, SDJ5565D (TP/IP/ 50683/2019)**

On 15 August 2019 (Thursday) at about 2.25 pm, the driver claimed that the steering wheel of his motor car, SDJ5565D, suddenly felt very stiff for no apparent reason which he could not control, causing it to lost control and collided onto the centre divider railing and a traffic light post along Sengkang East Road by Anchorvale Drive.

Vehicles to be inspected: SDJ5565D - Driver (Involved Party)

IO In-Charge: SIO Emmy Tan

g) **Case IAFP-IB-20190908 - Mechanical Inspection of Motor Van, GBD730G (TP/IP/ 39969/2019)**

On the 26 June 2019 (Wednesday) sometime around 6.38 a.m., the driver was driving the said motor van along a two-way road of Clementi Loop and made a right turn into a unit. In the midst of making a right turn in front of the said unit, the driver collided onto a pedestrian and caused serious injuries on the pedestrian. General inspection is required to inspect if there is/are any mechanical faults to the motor van.

Vehicles to be inspected: GBD730G - Driver (Potential Defendant)

IO In-Charge: IO Sufiyan Khairi

h) **Case IAFP-IB-20190908 - Mechanical Inspection of Motorcycle, FBD7531B (TP/IP/ 56345/2019)**

On 8 September 2019 (Sunday) sometime before 3.38a.m., the deceased was riding his motorcycle on unknown lane along Airport towards End near to Lamp post 38 when he struck the right kerbside and self-skidded. The deceased landed on lane 1 and sustained multiple injuries due to the accident. Hence, he was conveyed by an ambulance to SKGH however on the same day at 4.41am, the deceased was pronounced dead in the said hospital.

Vehicles to be inspected: FBD7531B - Rider (Deceased)

IO In-Charge: SIO Adrian Lim

2. These request has been approved by my management.

3. Thank you Sirs.

cc: FAIT Team, SIO Norashikin, SIO Emmy & IO Sufiyan, fyp

Best regards,

Kamaliah Kamis (Miss)
Senior Investigation Officer | Fatal Accident Investigation Team
Traffic Police Department | Singapore Police Force
DID: (65) 6547 6435 | FAX: (65) 6547 6352