

A.C. REC. BY:

REF: es/HA190/6995/Kvd3

Special Instruction:

Surveyor: Kenneth

ASSIGNMENT (Office)

From (Person): Mr Yinnul

of

AGDate/Time: 26/9/19 @ 3.46pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SJW1709 T

Insured:

GBF 6122L

at Workshop m/s

Massive Trading

Tel:

9108 2728

of

BLR 5038 Anne Ind. Park 2 #01-405

Policy No:

Claim No:

0507260137SG

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 26/09/2019

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: 5.34pm @ 26/9/19

Person Contacted:

AnthonyVehicle IN OUT

Date/Time	Action/Instruction
	<u>Johny</u> ✓
	<u>SJW1709T-X</u>
	<u>GBF 6122L - es/SM019016979 / Agf3</u>
	<u>D.O.A: 26/9/2019</u>
<u>4/10/19</u>	<u>@ 10.24am LS \$4900 confirmed with Anthony (Ref 3519.08, 4290)</u>

ASS. REC. BY:

REF: A16/

ASSIGNMENT

From: _____

Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____


Sum Insured: _____

Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____

Consistent? : Yes or No

GIA / PR Seen: _____

Consistent? : Yes or No

Est. Repairs: _____

05 days

Res.: Yes or No

Lum Sum: _____

20 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: 3/29

Person Contacted: _____

Vehicle: IN / OUT

Veh No: PTW170PTYr Regn: 12, 92Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Traller or _____

Make: Toy Corollac.c. 1587Colour: M. Grey

A/C: Insured / Std / NI / NA

Sp. Reading: 161347

T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: AE101

3027128

Gen. Cond: Good / Fair / Poor / BurntSteering: Inorder / Jammed / Leaked / Burnt orBrake: Inorder / Jammed / Leaked / Burnt orModl: NII / S/Rim / STD / R/Rim orTyre Size: F: 185/70R14

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Continental

Front

Rear

R/Bal. 6 mmR/Bal. 6 mmL/Bal. 6 mmL/Bal. 6 mmD.O.A. 26/9/19D.O.I. 26/9/19

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

1

File pass to
GIA & EN not ready

RECEIVED 8 OCT 2019

Date/Time, File Pass to?

☐

: Prell. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

4/10 - typist

Days Of Repair: 5Resurvey No. of Trip: 2

Survey Fee:

Transportation: 250S - R.S. 11

Fees

Others

TOTAL

261

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

Tech Invs (\$

☐

Weekend (\$

Report Format :

Lump Sum / I.B.I. (\$) merimen
4900/-

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	27 Sep 2019 Edit Reg		26 Sep 2019 00:00 Edit Adj Rpt				Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured: MENG LEE SHIRT CO, Co. Reg. No.: 20227300L									
Main Claimant: WONG LOKE KIT, ID: S1531032D									
Vehicle Reg. No.:	SJW1709T	Date of Loss:	26/09/2019 08:00 - :59						
Claim Type:	TP / 0507260137SG	Policy/Cover Note No.:							
Vehicle Reg. No. (Insured):	GBF6122L	Policy No. (Claimant):							
		Excess:							
Repairer: Massive Trading & Auto () Blk 5038 #01-405, Ang Mo Kio Industrial Pk 2, 569541 Ang Mo Kio - Tel:									
Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Chan, Kian-Meng]									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KENNETH KONG] ... [Final Rpt due 07/10/2019]									
ASSOCIATED MAIL RECEIVED				View All Compose Case Mail					
<ul style="list-style-type: none"> AIG_SG (27/09/2019): TP GIA REPORT 									
ALL ASSOCIATED TASKS				View All Search Tasks Create New Task Complete					
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

PRE-REPAIR INSPECTION REQUEST – SJW1709T vs GBF6122L (OI) on D.O.A.: 26/09/2019

From: Hor, Yinrul
To: 'assignments@lkkauto.com'; Admin A (admin-a@lkkauto.com)
Cc: Fong, Andy-SY; Chin, Lee-Ying; Abu Kassim, Noor Mariesa; Azlan, Syazairdina; Chan, Yoke Shi; Lim, Sheng Yang; Mithoosingh, Aashweenjeetkaur; Parthiban, Theerthan; Subramaniam, Divy
Sent: 9/26/2019 3:46:10 PM
Attachments:  20190926143902955.pdf  20190926143902955.pdf

Hi,

Please refer to the enclosed request from **Teo Keng Siang LLC**.

Kindly carry out Policy coverage verification first before conducting the pre-repair inspection within 48 hours

If you have any queries/concerns, please let us know.

Kindly assist to assign **Kenneth Kong** as Single Joint Expert as requested.

Thanks & Regards,

Hor Yin Rul (Viviane)
AIG
FNOL Adjuster I
Singapore FNOL | Claims Operations – Auto

Tel: 8001206556 | Ext: 1902208
Yinrul.Hor@aig.com | www.aig.sg

From: Janice Kee [mailto:janice.kee@ksteoptr.com]
Sent: Thursday, September 26, 2019 3:27 PM
To: Hor, Yinrul
Cc: Fong, Andy-SY; Chin, Lee-Ying; Abu Kassim, Noor Mariesa; Azlan, Syazairdina; Chan, Yoke Shi; Lim, Sheng Yang; Mithoosingh, Aashweenjeetkaur; Parthiban, Theerthan; Subramaniam, Divyashni; Anthony Cheong
Subject: [EXTERNAL] Re: PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE GBF6122L AND SJW1709T ON 26/09/2019

This message is from an external sender; be cautious with links and attachments.

Dear Sir

Our client has agree to the usage of Mr Kenneth Kong from LKK Auto Consultants Pte Ltd as the Single Joint Expert to conduct the Pre-Repair Survey.

Kindly proceed to engage Mr Kenneth Kong from LKK Auto Consultants Pte Ltd to perform the said Pre-Repair Survey in accordance to the NIMA Protocol.

Thank you.

Regards,
Janice Kee
c/o Teo Keng Siang LLC
111 North Bridge Road,
#29-07/08 Peninsula Plaza,
Singapore 179098
Tel: 6333 4222 Fax: 6333 5676

On Thu, Sep 26, 2019 at 3:06 PM Hor, Yinrul <Yinrul.Hor@aig.com> wrote:

This is a secure, encrypted message. To read it, open the attachment.

这是安全加密信息。如要阅读此信息，请开启附件。

นี่คือการรักษาความปลอดภัยข้อความที่เข้ารหัสลับ เพื่ออ่านมัน
ให้เปิดไฟล์แนบมา

이것은 안전하고 암호화된 메시지입니다. 그것을 읽으려
면 첨부 파일을 엽니다.

Ini adalah pesan, aman terenkripsi. Untuk membacanya,
membuka attachment.

[Click here](#) by 2019-10-03 15:06 +08 to read your message.
After that, open the attachment.

[More Info](#)

Disclaimer This email and its content are confidential and intended solely for the use of the addressee. Please notify the sender if you have received this email in error or simply delete it.

Secured by Proofpoint Encryption, Copyright © 2009-2017 Proofpoint, Inc. All rights reserved.

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

From: Yinrul.Hor@aig.com
To: Janice.kee@ksteopr.com
Cc: Andy-SY.Fong@aig.com, Lee-Ying.Chin@aig.com, NoorMariesa.AbuKassim@aig.com, Syazairdina.Azlan@aig.com, yokeshi.chan@aig.com, ShengYang.Lim@aig.com, Aashweenjeetkaur.Mithoosingh@aig.com, Theerthan.Parthiban@aig.com, Divyashni.Subramaniam@aig.com
Subject: aigencrypt PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE GBF6122L AND SJW1709T ON 26/09/2019
Date: Thu, 26 Sep 2019 07:06:20 +0000
Without Prejudice

Your Reference : TKSF/M492-ACC-42564.19/sf
Our Reference : GBF6122L

Dear Sir/Madam,

We refer to your Notice of Accident of even date.

We intend to conduct a pre-repair survey of the damage to your client's/your customer's vehicle jointly with your client/your motor workshop. We propose to use one of the motor surveyors named in the attached list to conduct the joint pre-repair survey as a single joint expert:

Name of Surveyor	Company Name
AIG In House Surveyor	AIG Asia Pacific Insurance Pte Ltd
Lawrence Ng Chun Kee	Priority Services
Jeffrey Ong Leng Kiat	Priority Services
Jimmy Lee	Priority Services
EC Looi	Automobile Inspection Services Pte Ltd
Pang Kiah Keen (Frankie)	Formteam Adjusters Pte Ltd
Ng You Han	Formteam Adjusters Pte Ltd
Soon HanXin (Gary)	Formteam Adjusters Pte Ltd
Chow Bo Xiong	Formteam Adjusters Pte Ltd
Chua Soo Teck (Benjamin)	Formteam Adjusters Pte Ltd
Kalvin Ang	LKK Auto Consultants Pte Ltd
Xing Guo Qiang	LKK Auto Consultants Pte Ltd
Marcus Chua	LKK Auto Consultants Pte Ltd
Mohamad Taufikh	LKK Auto Consultants Pte Ltd
Adrian Ling	LKK Auto Consultants Pte Ltd
Mohammed Rasul	LKK Auto Consultants Pte Ltd
Kenneth Kong	LKK Auto Consultants Pte Ltd

Please let us know within two (2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert. You may select one or more of the listed motor surveyors. We will bear the cost of the pre-repair survey carried out by the single joint expert.

Thanks & Regards,

Hor Yin Rul (Viviane)
AIG
FNOL Adjuster I
Singapore FNOL | Claims Operations - Auto

Tel: 8001206556 | Ext: 1002208
Yinrul.Hor@aig.com | www.aig.sg

From: Janice Kee [mailto:janice.kee@ksteopr.com]
Sent: Thursday, September 26, 2019 2:41 PM
To: Parthiban, Theerthan; Fong, Andy-SY; Chin, Lee-Ying; Abu Kassim, Noor Mariesa; Azlan, Syazairdina; Chan, Yoke Shi; Hor, Yinrul; Lim, Sheng Yang; Mithoosingh, Aashweenjeetkaur; Subramaniam, Divyashni
Cc: Anthony Cheong
Subject: [EXTERNAL] Your Ref: GBF 6122 L Our Ref: TKSF/M492-ACC-42564.19/sf

This message is from an external sender; be cautious with links and attachments.

Dear Sir,

We attach herewith our Pre-repair survey letter for your attention.

Kindly let us have the surveyor list for our attention.

Thank you

Regards,
Janice Kee
c/o Teo Keng Siang LLC

111 North Bridge Road,
#29-07/08 Peninsula Plaza,
Singapore 179098
Tel: 6333 4222 Fax: 6333 5676

Teo Keng Siang LLC

Advocates & Solicitors • Notary Public • Commissioner For Oaths

111 North Bridge Road #29-07/08 Peninsula Plaza Singapore 179098
ROC: 201510228C GST Reg No.: 201510228C

Tel: 6333 4222 Fax: 6333 5676 / 5688
Email: KSTEOCO@singnet.com.sg
(FAX - NOT FOR SERVICE OF COURT DOCUMENTS)

Our Ref : TKSF/M492-ACC-42564.19/sf(mc)
Your Ref : GBF 6122 L
Date : 26 September 2019

Secretary in charge: Janice
Tel : 6333 4222 (ext 60)
Fax : 6333 5676 / 6333 5688
Email : janice.kee@ksteoptr.com

To: AIG Asia Pacific Insurance Pte. Ltd
AIG Building
78 Shenton Way
#07-16 Singapore 079120
Attn: Motor Claims Dept

WITHOUT PREJUDICE
BY PDX# 8181 & FAX 6835 7416 ONLY

Cc: Meng Lee Shirt Co (Owner)
Ho Foong Nee (Driver)
C/o 51 Ubi Avenue 1
#01-01 Paya Ubi Industrial Park
Singapore 408933

BY POST ONLY



Dear Sirs

RE: ACCIDENT INVOLVING SJW 1709 T / GBF 6122 L / GBC 391 G ON 26/9/19 ALONG BARTLEY ROAD EAST TOWARDS TAMPINES AVE 10

We are instructed by Wong Loke Kit to notify you of a road traffic accident on 26/9/19 at about 08:30 hours at **ALONG BARTLEY ROAD EAST TOWARDS TAMPINES AVE 10** involving our client's vehicle registration number **SJW 1709 T** and vehicle registration number **GBF 6122 L** driven by you at the material time. A copy of our client's Singapore accident statement is enclosed. Kindly let us have a copy your Singapore accident statement report on an urgent basis.

As a result of the accident, our client's vehicle has been damaged. Before our client proceed to repair the damaged vehicle, please let us know within 2 working days of your receipt of this notice whether you or your insurer would like to conduct a pre-repair survey of the vehicle. If we do not receive any reply from you within the stipulated timeline, our client shall proceed to repair the vehicle without further reference to you.

Please note that our client's motor vehicle **SJW 1709 T** is now at the following workshop:-

Massive Trading & Auto
Blk 5038 Ang Mo Kio Industrial Park 2
#01-405
Singapore 569541
Contact: 9108 2728 Anthony

Yours faithfully,

M/s Teo Keng Siang LLC
encs

Teo Keng Siang
LL.M(Singapore),
LL.B (Hons) (Singapore)

****Survey was conducted by:-**

Name of Surveyor:

Date of Survey:

Time of Survey:

Signature

Wong Yong Sheng, Kenneth
LL.B (Hons) University of Bristol

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	032D
Vehicle Details	
Vehicle No.:	SJW1709T
Vehicle to be Exported:	No
Intended Deregistration Date:	04 Oct 2019
Vehicle Make:	TOYOTA
Vehicle Model:	COROLLA 1.6A
Primary Colour:	Grey
Manufacturing Year:	1992
Engine No.:	4AB116827
Chassis No.:	AE1013027128
Maximum Power Output:	-
Open Market Value:	\$17,225.00
Original Registration Date:	17 Dec 1992
First Registration Date:	17 Dec 1992
Transfer Count:	1
Actual ARF Paid:	\$25,838.00
Intended PARF Rebate Details	
PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	31 Mar 2029
COE Category:	A - Car (1600cc & below)
COE Period(Years):	10
PQP Paid:	\$25,525.00
COE Rebate Amount:	\$24,221.00
Total Rebate Amount:	\$24,221.00

The information contained herein is correct as at 04 Oct 2019

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the Insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIa Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	26/09/2019 13:22
Date Of Accident	26/09/2019 08:30
Exact Location Of Accident	BARTLEY RD EAST TWDS TAMPINES AVE 10
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJW1709T
Insured/Policyholder	
Name Of Registered Owner	WONG LOKE KIT
NRIC No	S1531032D
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-91918088
Alternative Phone No	OTHERS-91918088

Vehicle Particulars

Manufacturer	TOYOTA
Model	COROLLA

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	THIRD PARTY
Fleet Policy	NO
Policy Number	0086728788-15
Cover Note Number	

Driver

Name of Driver	WONG SUI YANG
NRIC No	S9528067F
Date Of Birth	26/07/1995
Occupation	INDOOR
Date Of Driving Pass	25/04/2016
Driving Experience	3 YEARS AND 5 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-98338433
Fax Number	
Contact Number	
EMail Address	NOEMAIL

Address	BLK 325 BT BATOK ST 33 #08-09
Postcode	650325
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	CHILDREN
Vehicle Registration Number of Driver's Own Vehicle	- - -
Insurance Company of Driver's Own Vehicle	- - -

General Information of the Accident

Type Of Accident	CHAIN COLLISION
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	3
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

ON 26/09/2019 @ 0830HRS, I WAS TRAVELLING ALONG BARTLEY RD TOWARDS TAMPINES AVE 10. I WAS DRIVING IN THE MOST RIGHT LANE. DUE TO HEAVY TRAFFIC, THE CAR INFRONT OF MINE SLOWED DOWN THUS I FOLLOWED SUIT AND SLOWED DOWN MY CAR. SUDDENLY, I FELT AN STRONG IMPACT FROM THE REAR OF MY VEHICLE. I EXITED MY VEHICLE AND REALISED IT WAS A COLLISION OF 3 VEHICLES.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	KIV, SUBMIT BY CLAIMANT W/S
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GBF6122L
Vehicle Make/Model/Colour	VAN
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	HO FOONG NEE
NRIC/Passport Number	S7635865F
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	

No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number	GBC391G
Vehicle Make/Model/Colour	VAN
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	YUN BO
NRIC/Passport Number	S2656667C
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

SKETCH PLANIMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorized Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) 'My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated; or
 - (ii) for complying with requirements under any regulations, laws or court orders.


Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Sketch Plan #2 Pg. 1

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 26/9/2019 @ abt 0830hrs, I was travelling along Bartley Rd towards Tampines Ave 10. I was driving in the most right lane. Due to heavy traffic, the car in front of mine slowed down thus I followed suit and slowed down my car. Suddenly, I felt a strong impact from the rear of my vehicle. I exited my vehicle and realised it was a collision of 3 vehicles.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature

Date & Time:

Global Security Malaysia 112

Driver's Signature

(If driver is not the policyholder)

Date & Time:

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:

Massive Trading & Auto

Mailing address : Blk 225 #07-579 Ang Mo Kio Ave 1 Singapore 560225
H/p 91082728

Fax : 64816131

Wong Loke Kit
Blk 325 Bukit Batok St 33
#08-09
Singapore 650325

Vehicle No : SJW 1709 T
Make : Toyota Corolla
Year : 1992

Not Authorized
11 Sep @ 4900h
Running After Point
5 days

Qty	Description	Unit Price	Amount
-----	-------------	------------	--------

Estimate Cost Of Repair

1 pc	Rear boot lid		\$755.10	—
2 pcs	Rear boot lid hinges	\$56.10	\$112.20	X
1 pc	Rear boot lid inner lock		\$285.70	—
1 pc	Rear boot lid emblem " Logo "		\$55.20	—
1 pc	Rear boot lid emblem " Corolla "		\$63.70	—
1 pc	Rear boot lid emblem " 1.6 "		\$35.60	—
1 pc	Rear boot lid emblem " Gli "		\$32.10	—
1 pc	Rear boot lid reflector		\$750.70	—
2 pcs	Rear no plate lamp	ols \$65.10	\$130.20	✓
1 pc	Rear boot rubber	nd 6m	\$205.30	50% 102-65m
1 pc	Rear end panel		\$705.90	—
1 pc	Rear end panel inner garnish		\$255.10	—
2 pcs	Rear tail-lamp assy	ng cm \$485.10	\$970.20	—
2 pcs	Rear tail-lamp lower garnish	\$167.20	\$334.40	—
1 pc	Rear spare tyre panel		\$752.30	X
1 pc	Rear spare tyre cover board		\$305.10	✓
1 pc	Rear bumper		\$553.10	✓
1 pc	Rear bumper beam		\$339.60	—
2 pcs	Rear bumper bracket	\$110.20	\$220.40	X
2 pcs	Rear bumper side retainer	\$85.10	\$170.20	✓
			\$7,032.10	
			Less 25 %	\$1,758.02
				\$5,274.08

S Nett

1 pc	Rear no plate
20 pcs	Bumper clip
1 pc	Rear reverse camera

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

	Rd	\$40.00	✓
\$3.00	nd	\$60.00	50% m
shot	for	\$300.00	250% m
		\$400.00	
balance c/f		\$5,674.08	

SJW 1709 T

balance b/f \$5,674.08

Labour Charges

Remove/renew the above parts including knocking, welding & cutting.

\$1,200.00 *700*

To putty & spray paint rear accident affected portion.

\$1,200.00 *800*

Check/reconnect wiring.

\$45.00 *200*

To spray anti rust on accident affected portion.

\$150.00 *600*

Remove/refit rear boot upholstery to facilitate repair.

\$150.00 *600*

Total \$8,419.08

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/AIG19016995/KVD3N2

Date: 08/10/2019

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No:
 Claimant Vehicle No : SJW1709T Insured Vehicle No : GBF6122L
 Date of Loss: 26/09/2019 Nature of Claim: TP Claim No: 0507260137SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SJW1709T Engine No: 4AB116827
 Make & Model: TOYOTA COROLLA, 1.6 (A) Chassis No: AE1013027128
 Reg. Date: 17/12/1992 (Man. Year: 1992) Odometer: 161347 km
 Colour: Metallic Grey
 Engine Capacity: 1587 cc
 Market Value/New Car Price: N/A
 Sum Insured (\$\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 185/70R14 Rear Tyre Size: 185/70R14
 Front Left Side: Continental 6 mm Rear Left Side: Continental 6 mm
 Front Right Side: Continental 6 mm Rear Right Side: Continental 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	5,674.08	4,700.25	973.83	17.16
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,745.00	1,640.00	1,105.00	40.26
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	8,419.08	6,340.25	2,078.83	24.69
Approved Total (Overridden) (\$\$)		4,900.00		
Nett Amount (\$\$)	8,419.08	4,900.00	3,519.08	41.80

INSPECTION

Date of Assignment: 26/09/2019
 Date Inspected: 26/09/2019 Inspected At: Massive Trading & Auto
 Blk 5038 #01-405, Ang Mo Kio Industrial
 Pk 2
 Singapore 569541

Estimated Period of Repair: 5.0 days

Adjuster: KENNETH KONG

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BOOT LID	Bent	755.10 FL	*755.10 FL
2	2		*REAR BOOT LID HINGES	Repair	112.20 FL	*- FL
3	1		*REAR BOOT LID INNER LOCK	Dented	285.70 FL	*285.70 FL
4	1		*REAR BOOT LID EMBLEM LOGO	Necessary	55.20 FL	*55.20 FL
5	1		*REAR BOOT LID EMBLEM COROLLA	Necessary	63.70 FL	*63.70 FL
6	1		*REAR BOOT LID EMBLEM 1.6	Necessary	35.60 FL	*35.60 FL
7	1		*REAR BOOT LID EMBLEM GLI	Necessary	32.10 FL	*32.10 FL
8	1		*REAR BOOT LID REFLECTOR	Cracked	750.70 FL	*750.70 FL
9	1		*REAR NO PLATE LAMP	O/s Cracked	130.20 FL	*65.10 FL
10	1		*REAR END PANEL	Bent	705.90 FL	*705.90 FL
11	1		*REAR END PANEL INNER GARNISH	Dented	255.10 FL	*255.10 FL
12	2		*REAR TAIL-LAMP ASSY	Mtg Cracked	970.20 FL	*970.20 FL
13	2		*REAR TAIL-LAMP LOWER GARNISH	Buckled	334.40 FL	*334.40 FL
14	1		*REAR SPARE TYRE PANEL	Repair	752.30 FL	*- FL
15	1		*REAR SPARE TYRE COVER BOARD	Cracked	305.10 FL	*305.10 FL
16	1		*REAR BUMPER	Buckled	553.10 FL	*553.10 FL
17	1		*REAR BUMPER BEAM	Bent	339.60 FL	*339.60 FL
18	2		*REAR BUMPER BRACKET	Repair	220.40 FL	*- FL
19	2		*REAR BUMPER SIDE RETAINER	Distorted	170.20 FL	*170.20 FL
20	1		*REAR NO PLATE	Dented	40.00 FS	*40.00 FS
21	20		*BUMPER CLIP	Necessary	60.00 FS	*50.00 FS
22	1		*REAR REVERSE CAMERA	Shorted	300.00 FS	*250.00 FS
23	1		*REAR BOOT RUBBER (50%)	Dented/Cut	153.98 FS	*102.65 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	7,380.78	6,119.45
- List Item Discount on L Items 25.00/25.00% (\$\$)	1,706.70	1,419.20
Total Parts (\$\$)	5,674.08	4,700.25

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	REMOVE/RENEW THE ABOVE PARTS INCLUDING KNOCKING,WELDING & CUTTING	New	1,200.00	700.00
2	TO PUTTY & SPRAY PAINT REAR ACCIDENT AFFECTED PORTION	New	1,200.00	800.00
3	CHECK/RECONNECT WIRING	New	45.00	20.00
4	TO SPRAY ANTI RUST ON ACCIDENT AFFECTED PORTION	New	150.00	60.00
5	REMOVE/REFIT REAR BOOT UPHOLSTERY TO FACILITATE REPAIR	New	150.00	60.00
Gross Labour Cost (S\$)			2,745.00	1,640.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >

Shaqilah (LKK Auto)

From: Shaqilah (LKK Auto) <report@lkkauto.com>
Sent: Tuesday, 8 October 2019 10:56 AM
To: 'janet.tan@eqinsurance.com.sg'
Cc: chewht@lkkauto.com
Subject: DMPPHQ18-003767 : TP Direct Settlement - Accident Involving SCU 8992M (OI) and SMF 4507T (TP) on 03/12/2018
Attachments: LKK REPORT AND PHOTO.pdf; TP DS SUPPORTING DOCUMENT.pdf

Dear Sir/Madam,

Please be informed that the above-mentioned case had been settled.

Enclose herewith final report & relevant documents for your necessary action please.

Thank you.

Best Regards,

Shaqilah | Reports

LKK Auto Consultants Pte.Ltd.

Phone: 6256-3561 Ext.111 Fax: 6741-4108 email: report@lkkauto.com

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #01-25 Singapore 408933