



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 26/09/2019

User ID : GohIQ2

Section A - Accident Details	
Registration Number	SG5788R
Case Reference Number	BUS/09/19/1067
Registration Date	19/8/2018
Company Type	SMRT Buses Ltd
Make	MAN
Model	A95
Name of Driver	Tay Choon Pin
Type of Accident	Side Swipe
Accident Date and Time	23/9/2019 1:15 PM
Accident Reported Date and Time	23/9/2019 2:15 PM
Is Surveyor Required?	No
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle Issued?	No
Job Card Number	
Special Instruction to ARC, if any	SG5788R-LEFT FRONT PORTION SHA2983A (TP) INSURED WITH III
Prepared Date and Time	26/9/2019 11:52 AM
Chassis Number	WMAA95Z23G7003343
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates		
Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$795.00	\$0.00
Total Spray Cost	\$446.00	\$0.00
Total Spare Part Cost	\$0.00	\$0.00
Total Other Cost	\$0.00	\$0.00
TOTAL COST	\$1,241.00	\$0.00
Lump Sum Total	\$1,250.00	\$0.00
Number of Repair Days	3.0	2.
Prepared / Adjusted By	Ben Chew Tay	
ARC / Surveyor Sign Off Date	26/09/2019 11:55 AM	
Signature		
Remarks		

Section C - Quotation and Accident Invoice Details			
Quotation Number		Invoice Number	
Quotation Date		Invoice Date	
Invoice Amount		Prepared Date	

Steve
26/09/2019
R/b - 2 days.
TP without Prejudice

PIP
Lump Sum
after spray



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63655592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 26/09/2019

User ID : GohKK2

Section D - Details of Repair Estimates									
Part 1 - Labour Works									
Job Scope		Quotation from AR				Adjusted by Surveyor, if applicable			
TO REMOVE & INSTALL ALL ABOVE ITEMS AND REPAIR OTHERS DAMAGED AFFECTED AREAS.		\$795.00				530			
Total Labour		\$795.00							
Part 2 - Spray Painting & Panel Beating Related Works									
Job Scope		Quotation from AR				Adjusted by Surveyor, if applicable			
PROVIDE LABOUR AND MATERIAL TO PUTTY AND RESPRAY ABOVE REPAIR ITEMS		\$446.00				354.			
Total Spray Painting & Panel Beating		\$446.00							
Part 3 - Other Costs - Accident and Accident Repair Related Expense									
Job Scope		Quotation from AR				Adjusted by Surveyor, if applicable			
Total Other Costs									
Part 4 - Spare Parts / Material Usage									
Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
6010153	Body	F01001-CW264	COVER HEADLAMP-FRT LH FOR MAN A22 BUS	1.00	\$974.70	100.00	\$0.00	Repair	X R
Total					\$974.70		\$0.00		
Add Spare Parts / Material Usage After Surveyor Signed off									
Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
Total									

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

under P/P - 884