




## SMRT Accident Vehicle Repair Estimates

<b>SMRT Automotive Services Pte Ltd</b>
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 26/09/2019

User ID : GohKK2

Section A - Accident Details	
Registration Number	SG5788R
Case Reference Number	BUS/09/19/1067
Registration Date	19/8/2016
Company Type	SMRT Buses Ltd
Make	MAN
Model	A95
Name of Driver	Tay Choon Pin
Type of Accident	Side Swipe
Accident Date and Time	23/9/2019 1:15 PM
Accident Reported Date and Time	23/9/2019 2:15 PM
Is Surveyor Required?	No
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	
Special Instruction to ARC,if any	SG5788R-LEFT FRONT PORTION SHA2983A ( TP ) INSURED WITH III
Prepared Date and Time	26/9/2019 11:52 AM
Chassis Number	WMAA95ZZ3G7003343
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates		
Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$795.00	\$0.00
Total Spray Cost	\$446.00	\$0.00
Total Spare Part Cost	\$0.00	\$0.00
Total Other Cost	\$0.00	\$0.00
<b>TOTAL COST</b>	<b>\$1,241.00</b>	<b>\$0.00</b>
<b>Lump Sum Total</b>	<b>\$1,250.00</b>	<b>\$0.00</b>
Number of Repair Days	3.0	
Prepared / Adjusted By	Boon Chew Tay	
ARC / Surveyor Sign Off Date	26/09/2019 11:55 AM	
Signature		✘
Remarks		

Section C - Quotation and Accident Invoice Details			
Quotation Number		Invoice Number	
Quotation Date		Invoice Date	
Invoice Amount		Prepared Date	



## SMRT Accident Vehicle Repair Estimates

<b>SMRT Automotive Services Pte Ltd</b>
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 26/09/2019

User ID : GohKK2

### Section D - Details of Repair Estimates

#### Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REMOVE & INSTALL ALL ABOVE ITEMS AND REPAIR OTHERS DAMAGED AFFECTED AREAS.	\$795.00	
<b>Total Labour</b>	<b>\$795.00</b>	

#### Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
PROVIDE LABOUR AND MATERIAL TO PUTTY AND RESPRAY ABOVE REPAIR ITEMS	\$446.00	
<b>Total Spray Painting &amp; Panel Beating</b>	<b>\$446.00</b>	

#### Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
<b>Total Other Costs</b>		

#### Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
6010153	Body	F01001-CW264	COVER,HEADLAMP:FRT ,LH,FOR MAN A22 BUS	1.00	\$974.70	100.00	\$0.00	Repair	
<b>Total</b>					<b>\$974.70</b>		<b>\$0.00</b>		

#### Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
<b>Total</b>									