

SGH1396B (PC3779L) - Submitted by: Automobile Inspection Services Pte Ltd (HQ)



1/39: Accident Photo



2/39: Accident Photo



3/39: Accident Photo

SGH1396B [PC3779L] - Submitted by: Automobile Inspection Services Pte Ltd (HQ)



4/39: Accident Photo



5/39: Accident Photo



6/39: Accident Photo



SGH1396B (PC3779L) - Submitted by: Automobile Inspection Services Pte Ltd (HQ)



7/39: Chassis Number



8/39: Accident Photo



9/39: Accident Photo

SGH1396B [PC3779L] - Submitted by: Automobile Inspection Services Pte Ltd (HQ)



10/39: Accident Photo



11/39: Accident Photo



12/39: Accident Photo

SGH1396B [PC3779L] - Submitted by: Automobile Inspection Services Pte Ltd (HQ)



13/39: Accident Photo



14/39: Accident Photo



15/39: Accident Photo



SGH1396B [PC3779L] - Submitted by: Automobile Inspection Services Pte Ltd (HQ)



16/39: Accident Photo



17/39: Dismantled Parts taken on 13/11/18



18/39: Dismantled Parts

SGH1396B [PC3779L] - Submitted by: Automobile Inspection Services Pte Ltd (HQ)



19/39: Dismantled Parts



20/39: Dismantled Parts



21/39: Dismantled Parts



SGH1396B [PC3779L] - Submitted by: Automobile Inspection Services Pte Ltd (HQ)



22/39: Dismantled Parts



23/39: Dismantled Parts



24/39: Dismantled Parts



SGH1396B [PC3779L] - Submitted by: Automobile Inspection Services Pte Ltd (HQ)



25/39: Dismantled Parts



26/39: Dismantled Parts



27/39: Dismantled Parts

SGH1396B [PC3779L] - Submitted by: Automobile Inspection Services Pte Ltd (HQ)



28/39: Dismantled Parts



29/39: Dismantled Parts




30/39: Dismantled Parts



SGH1396B [PC3779L] - Submitted by: Automobile Inspection Services Pte Ltd (HQ)



31/39: Dismantled Parts



32/39: Dismantled Parts



33/39: Dismantled Parts



SGH1396B [PC3779L] - Submitted by: Automobile Inspection Services Pte Ltd (HQ)



34/39: Reinspection Photo taken on 15/11/18



35/39: Reinspection Photo



36/39: Reinspection Photo

SGH1396B (PC3779L) - Submitted by: Automobile Inspection Services Pte Ltd (HQ)



37/39: Reinspection Photo



38/39: Reinspection Photo



39/39: Reinspection Photo

pls. 39



