

ASS. REC. BY:

REF: C53/CT19017039/Fcf302

Special Instruction:

Surveyor: RamASSIGNMENT (Office)From (Person): Chang Born Senof CTEDate/Time: 27.9.19 11.05 a.m

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CSTo Inspect Vehicle No: SDM 8380JInsured: YIV 8544Aat Workshop m/s Lian Hong PainterTel: 64535779of 160 sm ming briva #106-10Policy No: DMCVSN16477919033.Claim No: SNMMMD704457C02

Sum Insured:

Excess:

Make of Veh:

D.O.A. 20-9-2019

(Client's Record)

CA / REV / REP. / REV 24 HRS

Date/Time: 27.9.19 11.14 a.m

Person Contacted:

hunding

H.O.D. Endorsement:

Vehicle IN / OUT


Date/Time	Action/Instruction ( <u>X</u> ) Estimate
	<u>SDM 8380J - X</u>
	<u>YIV 8544A - X</u>
	<u>Dismantle: 27/9/2019</u>
	<u>After repair: 1/10/2019</u>

## ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_  
 Estimated Cost: \_\_\_\_\_  
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV  
 To Inspect Vehicle No: SOM 8380J  
 at Workshop m/s: Lian Heng  
 of 160 SIN MING DRIVE #06-10  
 Insured: \_\_\_\_\_  
 Policy No: \_\_\_\_\_  
 Claims No: \_\_\_\_\_  
 Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_  
 (Client's Record)  
 Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its  
 repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Report: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Vehicle: IN / OUT

Veh No: SOM 8380J Yr Regn: JUL / 2015  
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /  
 Truck / Trailer or

Make: Bmw 520i c.c. 1997  
 Colour: white A/C: Insured / Std / NI / NA  
 Sp. Reading: 836157 T/Radio: Insured / Std / NI / NA  
 Eng/No: \_\_\_\_\_

C/No: WBA5A320200828431Gen. Cond: Good / Fair / Poor / BurntSteering: Inorder / Jammed / Leaked / Burnt orBrake: Inorder / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 225/55 R17  
 R: 225/55 R17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
 TOYO / YOKO or

Front

Rear

R/Bal. 6 mm R/Bal. 6 mmL/Bal. 6 mm L/Bal. 6 mmD.O.A. 20/09/2019 D.O.I. 27/09/19Survey held at Lian HengDes. of Damages: Frnt Rear / O/S / N/S / U/C / Rooftop orFrnt

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Range: \$3800 - \$4500Repair days: 4 daysMV: \$98067PV: \$70136NV: \$27931

RECEIVED 15 OCT 2019

Date/Time, File Pass to?

☐ : Preli. ReportDays Of Repair: 4

1)

☐ : Final ReportResurvey No. of Trip: 2

Date/Time, File Return to?

2)

Add Fee: ☐ : Site Insp (\$☐ : Interview (\$☐ : Tech. Invs (\$☐ : Weekend (\$

Survey Fee:

Transportation:

) 3 + RS, 31

) Photos

) Others

) TOTAL

Report Format: PRE

Lump Sum / I.B.I: (\$

190

190

## ...CLAIM SUBFOLDER...(Pending for Survey Report)

### CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	10 Oct 2019		10 Oct 2019 15:57 <a href="#">Edit Adj Rpt</a>				<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	<a href="#">Show All</a>					
<b>CLAIM SUBFOLDER DETAILS</b> <span style="float: right;">[Created by insurer]</span>									
Insured:									
Main Claimant:	LOW CHEE MAN, ID: S2552316D								
Vehicle Reg. No.:	SDM8380J	Date of Loss:	20/09/2019 12:00 - :59						
Claim Type:	TP / SNM19D204451C02	Policy/Cover Note No.:	DMCVSN16477919033						
Vehicle Reg. No. (Insured):	YN8544A	Policy No. (Claimant):	5106765785						
		Excess:	S\$0.00						
Repairer:	Lian Heng Painter Company ( ) 160 SIN MING DRIVE, #06-10 SIN MING AUTOCITY, 575722 Sin Ming - Tel:								
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by <b>Chong Boon Sen</b> ]								
Claimant's Insurer:	NTUC Income Insurance Co-operative Ltd (HQ) - Tel:								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by <b>PARASURAM SHANMUGAM</b> ] ... <b>[Final Rpt due 21/10/2019]</b>								
<b>ASSOCIATED MAIL RECEIVED</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Compose Case Mail</a></span>									
There are no mail for this case.									
<b>ALL ASSOCIATED TASKS</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a></span>									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Summer Lee (LKK Auto)

---

**From:** Chong Boon Sen <boonsen.chong@sg.cntaiping.com>  
**Sent:** Friday, 27 September, 2019 11:05 AM  
**To:** Kavitha  
**Cc:** Charles Hoon; Jolene Kuik; henrygladys@singnet.com.sg; assignments  
**Subject:** RE: OUR REF: SNM19D204451-YN8544A-CBS & Yr ref: AP/2019/001732 CLAIM ARISING FROM A ROAD TRAFFIC ACCIDENT ON 20 SEPTEMBER 2019 AT ABOUT 12:30HRS INVOLVING MOTOR VEHICLES NO(S). SDM8380J AND YN8544A ALONG 7 TOH GUAN ROAD EAST 2ND LEVEL CAR PARK

**WITHOUT PREJUDICE**  
**SAVE AS TO COSTS**

Dear Sir,

We regret to inform that we are not agreeable to your list of proposed surveyors and will be assigning our panel surveyor, M/s LKK Auto Consultants to conduct the Pre-repair survey.

Please contact our surveyor to conduct the post repair inspection before returning the repaired vehicle to the claimant.

Aside to LKK,

Please refer to the email below and liaise with third party workshop accordingly.

Thank you.

**Chong Boon Sen**

Claims Executive  
Department

**China Taiping Insurance (Singapore) Pte. Ltd.**

3 Anson Road #16-00 Springleaf Tower Singapore 079909  
DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

**W:** [www.sg.cntaiping.com](http://www.sg.cntaiping.com) | **FB:** [www.facebook.com/chinataipingsg/](https://www.facebook.com/chinataipingsg/) | **WeChat:** 太平獅城 Taiping SG 3 Anson  
Road #16-00 Springleaf Tower Singapore 079909  
DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

---

**From:** Kavitha [mailto:kavitha@aplp.com.sg]  
**Sent:** Thursday, September 26, 2019 6:25 PM  
**To:** Chong Boon Sen <boonsen.chong@sg.cntaiping.com>  
**Cc:** Charles Hoon <charles@aplp.com.sg>; Jolene Kuik <jolene@aplp.com.sg>; henrygladys@singnet.com.sg  
**Subject:** RE: OUR REF: SNM19D204451-YN8544A-CBS & Yr ref: AP/2019/001732 CLAIM ARISING FROM A ROAD TRAFFIC ACCIDENT ON 20 SEPTEMBER 2019 AT ABOUT 12:30HRS INVOLVING MOTOR VEHICLES NO(S). SDM8380J AND YN8544A ALONG 7 TOH GUAN ROAD EAST 2ND LEVEL CAR PARK

**WITHOUT PREJUDICE**

Dear Sir/ Mdm,

We refer to your email of even date.

Our clients do not agree to your list of surveyors.

We are instructed to propose the use of one of the motor surveyors named below to conduct the joint pre-repair survey as a single joint expert:

- a) Alan Cheong
- b) TT Rajan
- c) Oh Han Cheong
- d) Andrew How
- e) Dave Ho Joo Koong
- f) Sincere Appraiser
- g) Seah Kwang Boon
- h) L H Teo
- i) Mr Willy Goh
- j) Nicky Seah
- k) Jayson Liaw

Please let us know within two (2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert. You may select one or more of the listed motor surveyors.

In the event you are not agreeable to our list of surveyor, please note that our client's vehicle can be inspected at:

**Lian Heng Painter Company**

160 Sin Ming Drive  
#06-10 Sin Ming Auto City  
Singapore 575722  
Contact : Ms Nomy (Tel : 64535779)

Please note that our clients' vehicle will only be available for pre-repair survey within the next two (2) working days. Our clients shall proceed to repair their vehicle thereafter without further notice or reference to you.

All our clients' rights are reserved.

*Please note our new office address as of 1<sup>st</sup> June 2019.*

**151 Chin Swee Road,  
#10-03/05 Manhattan House,  
Singapore 169876  
Tel no.: 6955 8899  
Office mobile no.: 9171 4767  
Fax no.: 6900 9899**

Regards,

**Kavitha**

**Secretary to Mr Charles Hoon**

**AP** Law Practice

151 Chin Swee Road #10-03/05 Manhattan House, Singapore 169876  
T: 6955 8899 F: 6900 9899 E: [kavitha@aplp.com.sg](mailto:kavitha@aplp.com.sg)  
Singapore UEN No.: 53380739E

**From:** Chong Boon Sen <[boonsen.chong@sg.cntaiping.com](mailto:boonsen.chong@sg.cntaiping.com)>

**Sent:** Thursday, 26 September 2019 5:35 PM

**To:** Kavitha <[kavitha@aplp.com.sg](mailto:kavitha@aplp.com.sg)>

**Subject:** RE: OUR REF: SNM19D204451-YN8544A-CBS & Yr ref: AP/2019/001732 CLAIM ARISING FROM A ROAD TRAFFIC ACCIDENT ON 20 SEPTEMBER 2019 AT ABOUT 12:30HRS INVOLVING MOTOR VEHICLES NO(S). SDM8380J AND YN8544A ALONG 7 TOH GUAN ROAD EAST 2ND LEVEL CAR PARK

Without prejudice

Dear Sir,

LKK

STA

LBS

**Chong Boon Sen**

Claims Executive

Department

**China Taiping Insurance (Singapore) Pte. Ltd.**

3 Anson Road #16-00 Springleaf Tower Singapore 079909

DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

**W:** [www.sg.cntaiping.com](http://www.sg.cntaiping.com) | **FB:** [www.facebook.com/chinataipingsg/](https://www.facebook.com/chinataipingsg/) | **WeChat:** 太平獅城 Taiping SG 3 Anson Road #16-00 Springleaf Tower Singapore 079909

DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

**From:** Claims Dept of CTI

**Sent:** Thursday, September 26, 2019 5:09 PM

**To:** Chong Boon Sen <[boonsen.chong@sg.cntaiping.com](mailto:boonsen.chong@sg.cntaiping.com)>; [kavitha@aplp.com.sg](mailto:kavitha@aplp.com.sg)

**Subject:** OUR REF: SNM19D204451-YN8544A-CBS & Yr ref: AP/2019/001732 CLAIM ARISING FROM A ROAD TRAFFIC ACCIDENT ON 20 SEPTEMBER 2019 AT ABOUT 12:30HRS INVOLVING MOTOR VEHICLES NO(S). SDM8380J AND YN8544A ALONG 7 TOH GUAN ROAD EAST 2ND LEVEL CAR PARK

Dear Boon Sen,

Please conduct PRS-SDM8380J- soonest possible

File with officer-in-charge- Chong Boon Sen-DID: 6389 6171.

Regards

Claims Department

**China Taiping Insurance (Singapore) Pte. Ltd.**

3 Anson Road #15-00 Springleaf Tower Singapore 079909

Tel: 6389 6116

Fax (65) 6224 7175 / 6224 7478

Email : [claimsdept@sg.cntaiping.com](mailto:claimsdept@sg.cntaiping.com)

Website:[www.sg.cntaiping.com](http://www.sg.cntaiping.com)

*Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.*

---

**From:** Kavitha [mailto:kavitha@aplp.com.sg]  
**Sent:** Thursday, 26 September, 2019 2:38 PM  
**To:** Claims Dept of CTI  
**Cc:** Charles Hoon; Jolene Kuik; henrygladys@singnet.com.sg  
**Subject:** Our ref: AP/2019/001732 CLAIM ARISING FROM A ROAD TRAFFIC ACCIDENT ON 20 SEPTEMBER 2019 AT ABOUT 12:30HRS INVOLVING MOTOR VEHICLES NO(S). SDM8380J AND YN8544A ALONG 7 TOH GUAN ROAD EAST 2ND LEVEL CAR PARK

Attn: Motor Claims Department

Dear Sirs,

Please find attached, our letter of even date

*Please note our new office address as of 1<sup>st</sup> June 2019.*

*151 Chin Swee Road,  
#10-03/05 Manhattan House,  
Singapore 169876  
Tel no.: 6955 8899  
Office mobile no.: 9171 4767  
Fax no.: 6900 9899*

Regards,

Kavitha

Secretary to Mr Charles Hoon

**AP** Law Practice

151 Chin Swee Road #10-03/05 Manhattan House, Singapore 169876

T: 6955 8899 F: 6900 9899 E: kavitha@aplp.com.sg

Singapore UEN No.: 53380739E

---

This email transmission is confidential and intended only for the addressee(s). It may contain information which is privileged as between solicitor and client or protected by litigation privilege. If you are not the intended recipient, please delete this message and all attachments and inform us by return email. No part of this message should be disclosed to any party, copied or used for any purpose. Thank you for your co-operation.

---

---

This email has been scanned by the Symantec Email Security.cloud service.  
For more information please visit <http://www.symanteccloud.com>

---

---

This email has been scanned by the Symantec Email Security.cloud service.  
For more information please visit <http://www.symanteccloud.com>

---

> Back to OneMotoring

## Enquire PARF/COE Rebate for Registered Vehicle

### Vehicle Owner Particulars

Owner ID Type: Singapore NRIC  
Owner ID: 316D

### Vehicle Details

Vehicle No.: SDM8380J  
Vehicle to be Exported: No  
Intended Deregistration Date: 27 Sep 2019  
Vehicle Make: B.M.W.  
Vehicle Model: 520i AT D/AB 2WD 4DR HID NAV  
Primary Colour: White  
Manufacturing Year: 2014  
Engine No.: B2790880N20B20B  
Chassis No.: WBA5A32020D828431  
Maximum Power Output: 135.0 kW (181 bhp)  
Open Market Value: \$36,438.00  
Original Registration Date: 10 Jul 2015  
First Registration Date: 10 Jul 2015  
Transfer Count: 1

Actual ARF Paid:

\$43,014.00  $\times 50\% = \$21,507$

### Intended PARF Rebate Details

PARF Eligibility: Yes  
PARF Eligibility Expiry Date: 09 Jul 2025  
PARF Rebate Amount: \$32,260.00

### Intended COE Rebate Details

COE Expiry Date: 09 Jul 2025  
COE Category: E - Open Category  
COE Period(Years): 10  
QP Paid: \$69,001.00  
COE Rebate Amount: \$37,876.00  
Total Rebate Amount: \$70,136.00

The information contained herein is correct as at 27 Sep 2019

Remaining : 5 years 9 months 20 days (69.6) OK

69.6 months

depr: \$13200/yearly \$1100/monthly

69.6 months  $\times$  \$1100 = \$76560

\$76560 + \$21507 = \$98067

New Age Polish SG No.1  
Leading Vehicle Surface  
Protection

A New Chapter - Skoda  
Singapore

BMW 520i Price Range Depreciation 2015 Vehicle Type

Advanced Search

Home » Used Cars » Don Motoring » BMW 5 Series 520i

## BMW 5 Series 520i

Overview

Financial

Insurance

Accessories

Similar

Research

Photos

Map

PREMIUM AD

<b>Price</b>	\$109,800		
<b>Depreciation</b> ⓘ	\$13,970 /yr View models with similar depre	<b>Reg Date</b>	30-Sep-2015 (6yrs 2days COE left)
<b>Mileage</b>	73,000 km (18.3k /yr)	<b>Manufactured</b> ⓘ	2015
<b>Road Tax</b> ⓘ	\$1,210 /yr	<b>Transmission</b>	Auto
<b>Dereg Value</b> ⓘ	\$75,624 as of today (change)	<b>OMV</b> ⓘ	\$42,644
<b>COE</b> ⓘ	\$61,300	<b>ARF</b> ⓘ	\$51,702
<b>Engine Cap</b>	1,997 cc	<b>Power</b>	135.0 kW (181 bhp)
<b>Curb Weight</b> ⓘ	1,615 kg	<b>No. of Owners</b> ⓘ	1
<b>Type of Vehicle</b>	Luxury Sedan		

### Features

2.0L TwinPower Turbo. 8 Speed Automatic Transmission. 181BHP. Keyless Entry/Start/Stop. Dark Bron Leather Upholstery. View specs of the BMW 5 Series Sedan (2010-2017)

### Accessories

BMW iDrive, GPS Navigation, Bluetooth, Comfort Access, Dual Electric Seats, PDC, Auto Boot Release, Power Tailgate, LED Headlamps, Reverse Camera.

### Description

FREE 1 Year Warranty & Maintenance Package! Facelifted Model With Digital Instrument Cluster! High Loan Approval Rate! Customized Loan Plans! Extended Warranty! One Owner Unit! Classy White With Dark Tan Interior! Full Featured Mid Luxury Sedan With This Refined F10 Series! Test Drive And Trade In Available!

### Category

PARF Car, Premium Ad Car

### Status

Available

### Resources



#### Vehicle Evaluation

Afraid of lemons? Request to have this car evaluated professionally. Find out more




#### Car Valuation - Free

Find out the market value of your existing car for free. Get started



### Price Chart

### Summary



Click on the point to view the vehicle

Shortlist

Compare

Add note

Report Error

More Actions

### Seller Information

#### Company

#### Don Motoring



» dealer's pricelist

Posted on: 31-Aug-2019 | Last Updated on: 07-Sep-2019

Upfront Deposit

» more Financial Info

## Need Items for Your Car?

We have thousands of car parts & accessories to explore.

The best online platform to sell and buy car parts & accessories - Marketplace

Advanced Search

[Home](#) » [Used Cars](#) » [Vantage Pre-Owned](#) » [BMW 5 Series 520i](#)

### BMW 5 Series 520i

[Overview](#)
[Financial](#)
[Insurance](#)
[Accessories](#)
[Similar](#)
[Research](#)
[Photos](#)

# VANTAGE PRE-OWNED

<b>Price</b>	\$96,800		
<b>Depreciation</b> ⓘ	\$13,510 /yr <a href="#">View models with similar depre</a>	<b>Reg Date</b>	30-Jun-2015 (5yrs 9mths 2days COE left)
<b>Mileage</b>	81,500 km (19.2k /yr)	<b>Manufactured</b> ⓘ	2014
<b>Road Tax</b> ⓘ	\$1,210 /yr	<b>Transmission</b>	Auto
<b>Dereg Value</b> ⓘ	\$69,692 as of today (change)	<b>OMV</b> ⓘ	\$36,438
<b>COE</b> ⓘ	\$71,509	<b>ARF</b> ⓘ	\$38,014
<b>Engine Cap</b>	1,997 cc	<b>Power</b>	135.0 kW (181 bhp)
<b>Curb Weight</b> ⓘ	1,615 kg	<b>No. of Owners</b> ⓘ	1
<b>Type of Vehicle</b>	Luxury Sedan		

#### Features

BMW TwinPower Turbo Inline 4 Cylinder, 181Bhp, 270Nm Torque, 0 To 100Km/H At 7.9 Secs, 8 Speed Steptronic Transmission, Top Speed 235Km/H. View specs of the BMW 5 Series Sedan (2010-2017)

#### Accessories

BMW I-Drive, GPS, Bi-Xenon Headlights, All Around Parking Sensors, Comfort Access, Rear Aircon, Cruise Control, Electric Tail Gate.

#### Description

Look No Further! Cheapest In Market! 1 Owner! Beautiful White On Black BMW 520i! Low Mileage Well Maintained By Single Owner! Buy With Added Peace Of Mind From Vantage Pre-Owned. A Member Of The Sime Darby Group. With Our Comprehensive 72-Points Mechanical And Safety Inspection. Finance And Trade In Welcomed. Book Your Appointment Today!

#### Category

PARF Car

#### Status

Available

#### Resources



Car Valuation - Free

Find out the market value of your existing car for free. Get started


Valuation

#### Map



Location Map

#### Price Chart



Click on the point to view the vehicle

Shortlist

Compare

Add note

Report Error

More Actions

#### Seller Information

##### Company

Vantage Pre-Owned

» dealer's pricelist

» 26 vehs sold | 28 vehs available

##### Address

305 Alexandra Road #02-01

Search cars nearby this location

##### Location

Vantage Automotive Centre

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	21/09/2019 11:32
Date Of Accident	20/09/2019 12:30
Exact Location Of Accident	7 TOH GUAN RD EAST 2ND LEVEL CAR PARK
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SDM8380J
<b>Insured/Policyholder</b>	
Name Of Registered Owner	LOW CHEE MAN
NRIC No	S2552316D
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-96782608
Alternative Phone No	OFFICE-96782608
<b>Vehicle Particulars</b>	
Manufacturer	BMW
Model	520I-2.0 AT D/AB 2WD 4DR HID NAV (A)
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR
<b>Insurance Company</b>	
Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5106765785
Cover Note Number	
<b>Driver</b>	
Name of Driver	LOW CHEE MAN
NRIC No	S2552316D
Date Of Birth	13/11/1960
Occupation	INDOOR
Date Of Driving Pass	06/11/1986
Driving Experience	32 YEARS AND 10 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96782608
Fax Number	
Contact Number	OFFICE-96782608
Email Address	NOEMAIL

Address	39 TOH TUCK CRESCENT
Postcode	596949
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-

#### General Information of the Accident

Type Of Accident	HIT AND RUN / VANDALISM / DAMAGED WHILST PARKED
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	0

#### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

REFER TO ATTACHED SKETCH PLAN

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	YN8544A
Vehicle Make/Model/Colour	MIT FUSO
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

**SKETCH PLAN**

**IMPORTANT NOTICE**

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:


- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

My vehicle was stationary parked in the car park and was informed by the workshop staff that vehicle 'B' had collided into my vehicle while making a three point turning.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

## ...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	10 Oct 2019		10 Oct 2019 15:57 <a href="#">Edit Adj Rpt</a>	<b>S\$0.00</b> <a href="#">Edit Estimates</a>	<b>S\$0.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b> <span style="float: right;">[Created by insurer]</span>									
Insured: -, Co. Reg. No.: -									
Main Claimant: <b>LOW CHEE MAN</b> , ID: S2552316D									
Vehicle Reg. No.: <b>SDM8380J</b>		Date of Loss: 20/09/2019 12:00 - :59 [50 Months and 10 Days From LTA Reg Date (Man Yr)]							
Claim Type: <b>TP / SNM19D204451C02</b>		Policy/Cover Note No.: DMCVSN16477919033							
Vehicle Reg. No. (Insured): <b>YN8544A</b>		Policy No. (Claimant): 5106765785							
		Excess: S\$0.00							
Repairer: <b>Lian Heng Painter Company ()</b> 160 SIN MING DRIVE, #06-10 SIN MING AUTOCITY, 575722 Sin Ming - Tel:									
Handling Insurer: <b>China Taiping Insurance (Singapore) Pte. Ltd. (HQ)</b> - Tel: 6389 6111 ... [Handled by <b>Chong Boon Sen</b> ]									
Claimant's Insurer: <b>NTUC Income Insurance Co-operative Ltd (HQ)</b> - Tel:									
Adjuster: <b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>PARASURAM SHANMUGAM</b> ] ... [Final Rpt due 21/10/2019]									
<b>ASSOCIATED MAIL RECEIVED</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Compose Case Mail</a></span>									
There are no mail for this case.									
<b>ALL ASSOCIATED TASKS</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a></span>									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Claim Documents

\*SDM8380J (SNM19D204451C02)

[YN8544A]

TP























































LOW CHEE MAN
















Sep 20 2019 12:00PM

[-]












Lian Heng Painter Company

Upload Documents		Upload Photos	Compose New Letter	View <span>View in Browser</span>	
<b>Assessment Reports</b>				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MBM Wheelpower Pte Ltd (HQ)		Thumbnail	Print
1	21/09/19 11:51	<b>Accident Statement</b>		Load HTM	
<b>Photos/Images</b>				3 per page	<input checked="" type="checkbox"/>
No	Finalized On	MBM Wheelpower Pte Ltd (HQ)		Thumbnail	Print
1	21/09/19 11:51	<b>Accident Photo</b> [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>
2	21/09/19 11:51	<b>Accident Photo</b> [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>
3	21/09/19 11:51	<b>Accident Photo</b> [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>
4	21/09/19 11:51	<b>Accident Photo</b> [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>
5	21/09/19 11:51	<b>Accident Photo</b> [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>
6	21/09/19 11:51	<b>Accident Photo</b> [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>
7	21/09/19 11:51	<b>Accident Photo</b> [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>
8	21/09/19 11:51	<b>Accident Photo</b> [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	10/10/19 16:39	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
2	10/10/19 16:39	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
3	10/10/19 16:39	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
4	10/10/19 16:39	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
5	10/10/19 16:39	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
6	10/10/19 16:39	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
7	10/10/19 16:39	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
8	10/10/19 16:39	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
9	10/10/19 16:39	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
10	10/10/19 16:39	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
11	10/10/19 16:39	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
12	10/10/19 16:39	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
13	10/10/19 16:39	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
14	10/10/19 16:39	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
15	10/10/19 16:39	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
16	10/10/19 16:39	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
17	10/10/19 16:39	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
18	10/10/19 16:39	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
19	10/10/19 16:39	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
20	10/10/19 16:39	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
21	10/10/19 16:39	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
22	10/10/19 16:39	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
23	10/10/19 16:39	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
24	10/10/19 16:39	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
25	10/10/19 16:39	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
26	10/10/19 16:39	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
27	10/10/19 16:39	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
28	10/10/19 16:39	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MBM Wheelpower Pte Ltd (HQ)	Thumbnail	Print
29	10/10/19 16:39	General View	 Load JPG	<input checked="" type="checkbox"/>
30	10/10/19 16:39	General View	 Load JPG	<input checked="" type="checkbox"/>
31	10/10/19 16:39	General View	 Load JPG	<input checked="" type="checkbox"/>
32	10/10/19 16:39	General View	 Load JPG	<input checked="" type="checkbox"/>
33	10/10/19 16:39	General View	 Load JPG	<input checked="" type="checkbox"/>
34	10/10/19 16:39	General View	 Load JPG	<input checked="" type="checkbox"/>
35	10/10/19 16:39	General View	 Load JPG	<input checked="" type="checkbox"/>
36	10/10/19 16:39	General View	 Load JPG	<input checked="" type="checkbox"/>
37	10/10/19 16:41	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
38	10/10/19 16:41	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
39	10/10/19 16:41	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
40	10/10/19 16:41	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
41	10/10/19 16:41	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
42	10/10/19 16:41	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
43	10/10/19 16:41	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
44	10/10/19 16:41	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
45	10/10/19 16:41	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
46	10/10/19 16:41	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
47	10/10/19 16:41	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
48	10/10/19 16:41	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
49	10/10/19 16:41	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
50	10/10/19 16:41	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
51	10/10/19 16:41	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
52	10/10/19 16:41	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
53	10/10/19 16:41	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
54	10/10/19 16:41	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
55	10/10/19 16:41	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
56	10/10/19 16:41	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
57	10/10/19 16:41	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
58	10/10/19 16:41	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
59	10/10/19 16:41	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
60	10/10/19 16:41	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
61	10/10/19 16:41	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
62	10/10/19 16:41	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
63	10/10/19 16:41	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
64	10/10/19 16:41	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
65	10/10/19 16:41	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
66	10/10/19 16:41	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
67	10/10/19 16:41	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
68	10/10/19 16:41	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
69	10/10/19 16:41	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
70	10/10/19 16:41	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
71	10/10/19 16:41	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
72	10/10/19 16:41	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
73	10/10/19 16:41	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
74	10/10/19 16:41	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
75	10/10/19 16:41	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
76	10/10/19 16:41	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
77	10/10/19 16:41	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
78	10/10/19 16:41	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
79	10/10/19 16:41	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
80	10/10/19 16:41	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
81	10/10/19 16:41	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
82	10/10/19 16:41	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
83	10/10/19 16:41	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
84	10/10/19 16:41	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MBM Wheelpower Pte Ltd (HQ)	Thumbnail	Print
85	10/10/19 16:41	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
86	10/10/19 16:41	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
87	10/10/19 16:41	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
88	10/10/19 16:41	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
89	10/10/19 16:41	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
90	10/10/19 16:41	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
91	10/10/19 16:41	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
92	10/10/19 16:42	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
93	10/10/19 16:42	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
94	10/10/19 16:42	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
95	10/10/19 16:42	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
96	10/10/19 16:42	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
97	10/10/19 16:42	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MBM Wheelpower Pte Ltd (HQ)	Thumbnail	Print
1	21/09/19 11:46	Sketch Plan [Linked Accident Report Documents]	 Load TIF	
2	21/09/19 11:46	Sketch Plan #2 [Linked Accident Report Documents]	 Load TIF	

## Linked Accident Report Documents

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MBM Wheelpower Pte Ltd (HQ)	Thumbnail	Print
1	21/09/19 11:51	Accident Statement	 Load HTM	
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Finalized On	MBM Wheelpower Pte Ltd (HQ)	Thumbnail	Print
1	21/09/19 11:51	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
2	21/09/19 11:51	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
3	21/09/19 11:51	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
4	21/09/19 11:51	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
5	21/09/19 11:51	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
6	21/09/19 11:51	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
7	21/09/19 11:51	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
8	21/09/19 11:51	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MBM Wheelpower Pte Ltd (HQ)	Thumbnail	Print
1	21/09/19 11:46	Sketch Plan	 Load TIF	
2	21/09/19 11:46	Sketch Plan #2	 Load TIF	

## Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
<b>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</b> <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			
<b>Show Remarks To:</b> <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/CT119017039/FCF3E2

Date: 15/10/2019

## REFERENCE

Handling Insurer: China Taiping Insurance  
(Singapore) Pte. Ltd.

Policy No: DMCVSN16477919033

Claimant  
Vehicle No : SDM8380JInsured  
Vehicle No : YN8544A

Date of Loss: 20/09/2019

Nature of Claim: TP

Claim  
No: SNM19D204451C02

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No: **SDM8380J**

Make &amp; Model: BMW 520I, 2.0 AT D/AB 2WD 4DR HID NAV (A)

Engine No: B2790880N20B20B

Reg. Date: 10/07/2015 (Man. Year: 2014)

Chassis No: WBA5A32020D828431

Colour: White

Odometer: 83657 km

Engine Capacity: 1997 cc

Market Value/New Car

Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

## CONDITION OF TYRES

Front Tyre Size: 225/55 R17 Rear Tyre Size: 225/55 R17  
Front Left Side: Pirelli 6 mm Rear Left Side: Pirelli 6 mm  
Front Right Side: Pirelli 6 mm Rear Right Side: Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Nett Amount (S\$)</b>	<b>0.00</b>	<b>0.00</b>	<b>0.00</b>	

## INSPECTION

Date of Assignment: 10/10/2019

Date Inspected: 27/09/2019 Inspected At:

Lian Heng Painter Company  
160 SIN MING DRIVE, #06-10 SIN  
MING AUTOCITY  
Singapore 575722

Estimated Period of Repair: 4.0 days

Adjuster: PARASURAM SHANMUGAM

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.  
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$3,800.00 -\$4,500.00

## REPAIR DETAILS

<b>Reference</b>		
<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 15 Oct 2019)
<b>Parts:</b>	143	BMW 520I 2.0 AT D/AB 2WD 4DR HID NAV (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SDM8380J)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

## Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.
---

**< END OF ESTIMATES >**