

ASS. REC. BY:

REF:

CS/LPC/19017043/06f302

Special Instruction:

Survivor: Marius

ASSIGNMENT (Office)

From (Person): Ong Li Li

of

LPCDate/Time: 27.9.19 11.50a.m

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

XE 1370 P

Insured:

YL 92188

at Workshop m/s

Mah Wan Motor

Tel:

6282 3336

of

No 3 & Drfu Lane 9

Policy No:

Claim No:

19/19/19/VCO5/022426

Sum Insured:

Excess:

Make of Veh:

D.O.A.

25.9.2019

(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

27.9.19 11.50a.m

Person Contacted:

Si Hui

Vehicle: IN / OUT

Date/Time

Action/Instruction (✓) Estimate

XE 1370 P - XYL 92188 - CS/E41 17005167 / Gvbn2D.O.A - 10/03/201731/10 @ 10:48 - sent email pending estimate.16/10 - sent MA via email

LPC

March 5

ASSIGNMENT

From: _____ Date: 2.10.2019

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: XE 1370P

at Workshop: Moh Han

at 38 Defu Lane 9

Insured: _____

Policy No: _____

Claims No: _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: Aster 10300m

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Est. or Market Value: _____

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 4 days Res: Yes or No

Lum Sum: 20 % 3 Val: Yes or No

CA / REV / REP. / 24 HRS mp 11A 3475

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: XE1370P (1 Regn) 116

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or (M)

Make: mit FV515 C.C. 11967

Colour: white A/C: Insured / Std / NI / NA

Sp. Reading: 391889 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: FV515JA10230

Gen. Cond: 8 / Fair / Poor / Burnt

Steering: 8 / Jammed / Leaked / Burnt or

Brake: 8 / Jammed / Leaked / Burnt or

Modi: (N) / S/Rim / STD A/Rim or

Tyre Size: F: 3.5 / R 222.5

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or hyper 2en

Front: 6 mm R/Bal. 6/6 mm

L/Bal. 6 mm L/Bal. 6/6 mm

D.O.A. 25/9/19 D.O.L. 2/10/19

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

MS R.

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time: 14/10/19 Action / Instruction: conf. call w/s \$4100 with sikhni

(Red: 10148.34; 71%)

RECEIVED 16 OCT 2019

Date/Time: File Pass to:

16/10 Typist

☐ : Prel. Report

☒ : Final Report

Days Of Repair: 4

Resurvey No. of Trip: _____

Add Fee: ☐ Site Insp \$☐ Interview \$☐ Tech. Insp \$☐ Meet and \$

Survey Fee:

Transportation:

\$ + \$6 \$

Fuel \$

Other:

TOTAL

350

TP
4100

0



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: 19/19/19/VC05/022426

Date: 03/10/2019

Our Ref: CS/LPC19017043/Utf3

The Motor Claims Department
LONPAC INSURANCE BHD

Dear Sirs/Mdm


PRELIMINARY ADVICE OF VEHICLE NO. XE 1370P.

Please be informed that we had conducted the inspection of the above-mentioned vehicle on 02/10/2019 at the premises of M/s Mah Lian Motor and have the following to report: -

Workshop Estimate Amount	: S\$ 14,248.34
Revised Estimate Amount	: S\$ 4,100.00(Lump Sum)
"Check" Items Amount	: S\$ 0.00
Market Value	: S\$ -
LTA Reimbursement Value	: S\$ -
Nett Value	: S\$ -

Description of Damage:

The vehicle sustained damages at the n/s front portion.



Repair days: 4

Comments/ Present Status:

Damages Consistent.

Yours faithfully
Kenneth
Licensed Appraiser

Summer Lee (LKK Auto)

From: ONG LI LI <llong@lonpac.com>
Sent: Friday, 27 September, 2019 11:50 AM
To: jactan@visionlawllc.com; assignments; Admin-D (LKKAuto)
Cc: MT_Claim_SG
Subject: Your Ref: AM.jt.Ins.M46.111675.19 Our Ref: 19/19/19/VC05/022426
Attachments: 4449_001.pdf

Without Prejudice
Save as to Costs


Dear Jac

Thank you for your confirmation on the appointment of a Single Joint Expert.

Dear Nivitha

Please refer to the attached and arrange TP survey.

Regards,
Ong Li Li
Senior Claims Executive | Lonpac Insurance Bhd
300 Beach Road #17-04/07 The Concourse
Singapore 199555
Tel : (65) 6250 7388 Ext. 254 Fax: (65) 6296 2706



From: ct-admin@visionlawllc.com [mailto:ct-admin@visionlawllc.com]
Sent: Friday, 27 September 2019 11:25 AM
To: MT_Claim_SG; llone@lonpac.com
Subject: Scan Image

Denise Tay (LKKAuto)

From: Denise Tay (LKKAuto)
Sent: Thursday, 3 October 2019 10:48 AM
To: Admin-D (LKKAuto); 'ONG LI LI'; SUR; assignments
Cc: 'MT_Claim_SG'
Subject: RE: Your Ref: AM.jt.Ins.M46.111675.19 Our Ref: 19/19/19/VC05/022426

Dear Sir/Madam,

Please be informed that we have inspected the vehicle XE 1370P on 02/10/2019
We are pending estimate from repairer.

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto) <admin-d@lkkauto.com>
Sent: Friday, 27 September 2019 11:55 AM
To: 'ONG LI LI' <llong@lonpac.com>; SUR <sur@lkkauto.com>; assignments <assignments@lkkauto.com>
Cc: 'MT_Claim_SG' <mt_claim@lonpac.com>
Subject: RE: Your Ref: AM.jt.Ins.M46.111675.19 Our Ref: 19/19/19/VC05/022426

Dear Sir/Madam,

Thank you for the assignment.

Please be informed that vehicle currently not in the workshop, repairer will arrange.

Best Regards,

Summer Lee | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: ONG LI LI <llong@lonpac.com>
Sent: Friday, 27 September, 2019 11:50 AM
To: jactan@visionlawllc.com; assignments <assignments@lkkauto.com>; Admin-D (LKKAuto) <admin-d@lkkauto.com>
Cc: MT_Claim_SG <mt_claim@lonpac.com>
Subject: Your Ref: AM.jt.Ins.M46.111675.19 Our Ref: 19/19/19/VC05/022426

Without Prejudice

Denise Tay (LKKAUTO)

From: Denise Tay (LKKAUTO)
Sent: Wednesday, 16 October 2019 2:34 PM
To: 'ONG LI LI'; Admin-D (LKKAUTO); SUR; assignments
Cc: MT_Claim_SG
Subject: RE: Your Ref: AM.jt.Ins.M46.111675.19 Our Ref: 19/19/19/VC05/022426
Attachments: PRELI ADVISED OF XE 1370P.pdf

Dear Sir/Madam,

Enclosed preliminary revised of vehicle **XE 1370P**
Number of days (estimated) : 4 days

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315


Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: ONG LI LI <llong@lonpac.com>
Sent: Thursday, 3 October 2019 12:02 PM
To: Denise Tay (LKKAUTO) <denisetay@lkkauto.com>; Admin-D (LKKAUTO) <admin-d@lkkauto.com>; SUR <sur@lkkauto.com>; assignments <assignments@lkkauto.com>
Cc: MT_Claim_SG <mt_claim@lonpac.com>
Subject: RE: Your Ref: AM.jt.Ins.M46.111675.19 Our Ref: 19/19/19/VC05/022426

Dear Denise

Attached is our Insured's GIA report.

Regards,
Ong Li Li
Senior Claims Executive | Lonpac Insurance Bhd
300 Beach Road #17-04/07 The Concourse
Singapore 199555
Tel : (65) 6250 7388 Ext. 254 Fax: (65) 6296 2706



From: Denise Tay (LKKAUTO) [<mailto:denisetay@lkkauto.com>]
Sent: Thursday, 3 October 2019 10:48 AM
To: Admin-D (LKKAUTO); ONG LI LI; SUR; assignments
Cc: MT_Claim_SG
Subject: RE: Your Ref: AM.jt.Ins.M46.111675.19 Our Ref: 19/19/19/VC05/022426

VISION LAW LLC

Advocates & Solicitors - Notary Public - Commissioner for Oaths
Agents for Trade Marks
(Incorporated with limited liability)

ERIC NG CHING BOON
WONG KENG LEONG RAYNEY
AUDREY WONG SU-HSIEN
PAUL YAP TAI SAN
ANJALLI DIO MUNIANDY
ANG KIM NOI DIANE
RAVENDRA KRISHNASAMY
TAN YINGXIAN, SELWYN
CHEONG YUNHUI, CLARISSA
SONIA LIM WEI LEI

Unique Entity Number :200721148H
✓ **HEAD OFFICE:** 133 New Bridge Road
#18-01/02 Chinatown Point
Singapore 059413

Branch: 490 Toa Payoh Lorong 6
#03-11 HDB Hub
Singapore 310490

✓ HEAD OFFICE

TEL : (65) 65342811 (Hunting)
FAX ✓ : (65) 65356802 (General)
: (65) 65355905 (Litigation)
E-mail : jactan@visionlawllc.com

BRANCH

TEL : 65 63580703
FAX : 65 63580448 (Conveyancing)

WHEN REPLYING PLEASE QUOTE OUR REFERENCE- KINDLY REPLY TO **HEAD OFFICE** FOR THIS MATTER

Our Ref: AM.jt.Ins.M46.111675.19
Your Ref: 19/19/VC05/022426

27 September 2019

LONPAC INSURANCE BERHAD

300 Beach Road
#17-04/07 The Concourse
Singapore 199555
Attention: Ms Ong Li Li

BY FAX: 62962706
email: mt_claim@lonpac.com
email: llone@lonpac.com

Dear Sirs,

**ACCIDENT INVOLVING XE 1370 P & YL 9268 B ON 25 SEPTEMBER 2019 ALONG TPE TOWARDS SLE AT ABOUT 1645 HOURS
(NOTICE TO INSURER TO CONDUCT PRE-REPAIR SURVEY WITHIN 2 WORKING DAYS PURSUANT TO PARAGRAPH 6.2 OF PRE-ACTION PROTOCOL FOR NIMA CASES)**

We refer to your email dated 26 September 2019 informing that you wish to conduct a pre-repair survey and your List of Surveyors.

Our client confirmed appointment of LKK Consultant as the Single Joint Expert for this matter.

Please be informed that the said vehicle can be inspected at:

Venue: Mah Lian Motor Vehicle Repairer
No.38 Defu Lane 9
Singapore 539278
Contact Person: Mr Goh / Ms Si Hui (6282 3336)

If you fail to conduct the pre-repair inspection within the next 2 working days excluding any intervening Saturday, Sunday or Public Holiday, the said workshop will commence repairs thereafter without further reference to you.

Yours faithfully

ANJALLI M
(HEAD OFFICE)

cc: XE 1370 P – By fax: 6289-3336 only

FOR SURVEYOR

Please initial here after completion of pre-repair inspection.
Thank you.

1st Survey on _____
Appointed surveyor : _____
(Name & Signature)

2nd Survey on _____
Appointed surveyor : _____
(Name & Signature)

3rd Survey on _____
Appointed Surveyor : _____
(Name & signature)

NB.: Any settlement of offer is on the express condition that this settlement is in respect of our client's claim for property-related damages only and shall not preclude our client from claiming injury-related damages arising from this accident.

CONFIDENTIALITY

THE INFORMATION CONTAINED IN THESE DOCUMENTS MAY BE PRIVILEGED AND CONFIDENTIAL AND IS INTENDED FOR THE EXCLUSIVE USE OF THE ADDRESSEE DESIGNATED ABOVE. If you are not the addressee, any disclosure, reproduction, distribution or other dissemination or use of this communication is strictly prohibited. If you have received this transmission in error please contact us immediately by telephone so that we can arrange for its return.

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	049R
Vehicle Details	
Vehicle No.:	XE1370P
Vehicle to be Exported:	No
Intended Deregistration Date:	03 Oct 2019
Vehicle Make:	MITSUBISHI
Vehicle Model:	FUSO FV51SJD2DEA
Primary Colour:	White
Manufacturing Year:	2015
Engine No.:	OM457LA457972C0314533
Chassis No.:	FV51SJA10230
Maximum Power Output:	-
Open Market Value:	\$86,150.00
Original Registration Date:	18 Jan 2016
First Registration Date:	18 Jan 2016
Transfer Count:	0
Actual ARF Paid:	\$4,308.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	17 Jan 2026
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
PQP Paid:	\$5,528.00
COE Rebate Amount:	\$3,475.00
Total Rebate Amount:	\$3,475.00

The information contained herein is correct as at 03 Oct 2019

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	26/09/2019 13:20
Date Of Accident	25/09/2019 16:45
Exact Location Of Accident	ALONG TPE TWDS SLE
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	XE1370P
-----------------------------	---------

Insured/Policyholder

Name Of Registered Owner	RESOURCE MANAGEMENT CORPORATION PTE. LTD.
Co Reg No	200306049R
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-96166325

Vehicle Particulars

Manufacturer	MITSUBISHI
Model	FUSO FV51SJD2DEA
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	COMMERCIAL VEHICLE

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5110398934-000019
Cover Note Number	

Driver

Name of Driver	RETHINAM KARTHI
NRIC No	F8357278R
Date Of Birth	27/05/1971
Occupation	OUTDOOR
Date Of Driving Pass	14/06/2016
Driving Experience	3 YEARS AND 3 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-83982188
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address, NIL
 Postcode
 Was driver an employee of the Insured's Company YES
 If No, Relationship of the Driver with the Insured
 Vehicle Registration Number of Driver's Own Vehicle -
 -
 -
 Insurance Company of Driver's Own Vehicle -
 -
 -

General Information of the Accident

Type Of Accident COLLISION - MAJOR/MINOR RD
 Weather Conditions CLEAR
 Road Surface WET

Other Information

Was any foreign vehicle involved in this accident? NO
 Number of vehicles (including own vehicle) involved in the accident 2
 Was any body injured in the Accident? NO
 Was any injured conveyed to hospital by ambulance? NO
 Was any other material or property damaged? YES
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
 Number of Passengers (Including Driver) 1

Details of Police Action

Was the accident reported to the police? NO
 If Yes, Please state which Police Station
 Was notice of intended Prosecution given? NO
 If Yes, against whom?

Circumstances of Accident

REFER SKETCH PLAN

Attachment(s)

Are accident photos available for attachment? YES
 Was there any video captured by Car Camera? NO
 Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number YL9268B
 Vehicle Make/Model/Colour
 Details Of Properties
 Vehicle Category COMMERCIAL VEHICLE
 Name of Driver SUBRAMANIAM SENTHIL KUMAR
 NRIC/Passport Number G7634899K
 Contact Number 86465464
 Address
 Postcode
 Insurance Company Name
 Nature Of Damage
 No. Of Passenger (Including Driver)

Accident Sketch Plan Pg. 1

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all Insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

RESOURCE MANAGEMENT CORPORATION PTE LTD

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Certificate of Insurance

MOTOR VEHICLES (THIRD PARTY RISKS AND COMPENSATION) ACT (CHAPTER 189)

MOTOR VEHICLES (THIRD PARTY RISKS AND COMPENSATION) RULES, 1960

ROAD TRANSPORT ACT, 1987 (MALAYSIA)

MOTOR VEHICLES (THIRD PARTY RISKS) RULES, 1959 (MALAYSIA)

Certificate Number : 5110398934-000019

Cover : Comprehensive

- | | |
|---|---|
| 1. Index mark and Registration Number of Vehicle | : XE1370P |
| Chassis Number | : FV51SJA10230 |
| 2. Name of Policyholder | : RESOURCE MANAGEMENT CORPORATION PTE LTD |
| 3. Effective Date of Insurance | : 24 Jun 2019 |
| 4. Expiry Date of Insurance | : 23 Jun 2020 |
| 5. Persons or Classes of Persons entitled to drive# | |
| (a) The Policyholder. | |
| (b) Any other person who is driving on the Policyholder's order or with his/her permission. | |
| Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle. | |
| 6. Limitations as to Use# | |
| (a) Use for social domestic and pleasure purposes and in connection with the Policyholder's business or profession. | |
| (b) Use for the carriage of passengers or goods in connection with the Policyholder's business. | |

This Policy does not cover

- (a) Use for hire or reward.
- (b) Use for racing, pace-making, reliability trial or speed-testing.
- (c) Use whilst drawing a trailer except the towing of any one disabled mechanically propelled vehicle.

Limitations rendered inoperative by Section 8 of the Motor Vehicle (Third Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

EXCESS (SECTION 1)	: S\$1,500
EXCESS (SECTION 2)	: N/A
WINDSCREEN EXCESS	: S\$100
INSURE WITH COE	: YES
HIRE PURCHASE COMPANY	: DAIMLER FINANCIAL SERVICES AFRICA & ASIA PACIFIC LTD
SUM INSURED	: MARKET VALUE OF INSURED VEHICLE AT TIME OF LOSS

I/We hereby Certify that the Policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia)

Agency : AVA INSURANCE BROKERS PTE LTD (00000690850)

Date of Issue : 13 Jun 2019 11:51 hrs

For NTUC INCOME INSURANCE CO-OPERATIVE LIMITED



Countersigned By:

Authorised Officer



Chief Executive

Accident Photo



Accident Photo



Accident Photo



MAH LIAN MOTOR VEHICLE REPAIRER

No.38 Defu Lane 9 Singapore 539278
 TEL: 62823336 FAX: 62893336 Email: mahlian@singnet.com.sg
 GST:M90362564P RCB NO:201327339E

not Authorized
Alan

M/S : LONPAC INSURANCE BERHAD
 300 Beach Road #17-04/07
 The Concourse ,Singapore 199555

TEL: - FAX: 6296 2706
 ATTN: Motor Claim Department

Your Ref No: RMC PTE LTD
 Claim Type: Third Party
 Accident Date: 25/09/2019
 TP Veh Reg No: YL9268B

Estimate No: ES1700568
 Date: 26 Sep 2019
 Policy No: 5110398934-000019
 Veh Reg No: XE1370P
 Make/Model: MITSUBISHI FUSO
 FV51SJD2DEA
 Chassis No: FV51SJA10230
 Engine No: OM457LA457972C031453
 Reg. Date: 18/01/2016

2/5 4100
4 day
2/10/19

Estimate Repair Cost to Vehicle No :XE1370P

Description	U/Price	Quantity	List Price	Amount
			SS	SS
List Price				
1 Door Assy - LH	5,542.30	1 PC	5,542.30	
2 Door Signal Lamp - LH	195.03	1 PC	195.03	
3 Door Pillar - LH	2,284.45	1 PC	2,284.45	X
4 Corner Panel - LH	468.21	1 PC	468.21	
5 Corner Panel Bottom Seal - LH	84.23	1 PC	84.23	X
6 Stand Panel - LH	744.59	1 PC	744.59	X
7 Front Center Bumper Reinforcement	884.79	1 PC	884.79	X
8 Front Center Bumper	273.12	1 PC	273.12	
9 Front Center Bumper Side Panel - LH	193.04	1 PC	193.04	
10 Front Center Bumper Side Reinforcement - LH	226.06	1 PC	226.06	
11 Front Bumper	2,259.31	1 PC	2,259.31	X
12 Front Bumper Side - LH	140.29	1 PC	140.29	X
13 Headlamp Rim - LH	181.18	1 PC	181.18	X
14 Foglamp Rim - LH	186.05	1 PC	186.05	X
15 Cabin Side Grip - LH	201.78	1 PC	201.78	X
			13,864.43	
	Less 25%		3,466.11	10,398.32
Labour				
16 Labour to dismantle windscreen & refit to renew cabin side grip .	150.00	1 JOB	150.00	X
17 Labour charge to cut & weld & dismantle & remove & refit all above parts .	1,800.00	1 JOB	1,800.00	800
18 Labour to rewire & connect all wiring .	120.00	1 JOB	120.00	30
19 To spray & painting all accident dented area .	1,200.00	1 JOB	1,200.00	600
20 To rust proofing accident dented area .	480.00	1 JOB	480.00	50
21 Labour to remove & refit front door LH assy , realignment .	100.00	1 JOB	100.00	60
			3,850.00	3,850.00

P-4810-58
252
3607.93
5147.53
4118.52

MAH LIAN MOTOR VEHICLE REPAIRER

No.38 Defu Lane 9 Singapore 539278
 TEL: 62823336 FAX: 62893336 Email: mahlian@singnet.com.sg
 GST:M90362564P RCB NO:201327339E

M/S : LONPAC INSURANCE BERHAD
 300 Beach Road #17-04/07
 The Concourse ,Singapore 199555

TEL: - FAX: 6296 2706
 ATTN: Motor Claim Department

Your Ref No: RMC PTE LTD
 Claim Type: Third Party
 Accident Date: 25/09/2019
 TP Veh Reg No: YL9268B

Estimate No: ES1700568
Date: 26 Sep 2019
Policy No: 5110398934-000019
Veh Reg No: XE1370P
Make/Model: MITSUBISHI FUSO
 FV51SJD2DEA
Chassis No: FV51SJA10230
Engine No: OM457LA457972C031453
Reg. Date: 18/01/2016

Estimate Repair Cost to Vehicle No :XE1370P

Description	U/Price	Quantity	List Price	Amount
			<u>S\$</u>	<u>S\$</u>
			Total	S\$ 14,248.34
			Add GST @ 7%	997.38
			Total Amount Payable	<u>S\$ 15,245.72</u>

TOTAL: SINGAPORE DOLLAR FIFTEEN THOUSAND TWO HUNDRED FORTY FIVE AND CENTS SEVENTY TWO ONLY

**For MAH LIAN MOTOR VEHICLE
 REPAIRER**

AUTHORISED SIGNATURE

LKK Auto Consultants hence notify
 the Repairer of the following:

- To re-survey before/after spray painting
- To display damaged part(s) during re-survey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be re-surveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD		Ref : CS/LPC19017043/Utf3n2		
300 BEACH ROAD #17-04/07 THE CONCOURSESINGAPORE 199555		Date : 18-10-2019		
		Code : LPC2		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	YL 9268B	Veh. Inspected	XE 1370P	
Policy No.		Coverage (\$)	0.00	
Claim No.	19/19/19/VC05/022426	Excess (\$)	0.00	
Assign From	ONG LI LI	Assign Date	27/09/2019	
2. Vehicle Particulars & Condition				
Make & Model	MITSUBISHI FV51S (M)	c.c	11967	
Engine No.	HIDDEN	Year of Reg.	2016	
Chassis No.	FV51SJA10230	Colour	WHITE	
Odometer	391869	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	315/80 R22.5	HIPERZEN	6 mm	
L/H Front Tyre	315/80 R22.5	HIPERZEN	6 mm	
R/H Rear Tyre	315/80 R22.5 (D/D)	HIPERZEN	6/6 6/6 mm	
L/H Rear Tyre	315/80 R22.5 (D/D)	HIPERZEN	6/6 6/6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	25/09/2019	Inspection Date	02/10/2019	
Survey held at	MAH LIAN MOTOR VEHICLE REPAIRER 38 DEFU LANE 9 SINGAPORE 539278			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. XE 1370P

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	DOOR ASSY-LH	BADLY DENTED / CRACKED	5,542.30	3,455.12
1	DOOR SIGNAL LAMP-LH	BROKEN	195.03	195.03
1	DOOR PILLAR-LH	TO REPAIR SEE LABOUR	2,284.45	-
1	CORNER PANEL-LH	CRACKED	468.21	468.21
1	CORNER PANEL BOTTOM SEAL-LH	NOT NECESSARY	84.23	-
1	STAND PANEL-LH	TO REPAIR SEE LABOUR	744.59	-
1	FRONT CENTER BUMPER REINFORCEMENT	NOT NECESSARY	884.79	-
1	FRONT CENTER BUMPER	BENT / TWISTED	273.12	273.12
1	FRONT CENTER BUMPER SIDE PANEL-LH	CRACKED	193.04	193.04
1	FRONT CENTER BUMPER SIDE REINFORCEMENT-LH	DISTORTED	226.06	226.06
1	FRONT BUMPER	TO REPAIR SEE LABOUR	2,259.31	-
1	FRONT BUMPER SIDE-LH	NOT NECESSARY	140.29	-
1	HEADLAMP RIM-LH	NOT NECESSARY	181.18	-
1	FOGLAMP RIM-LH	NOT NECESSARY	186.05	-
1	CABIN SIDE GRIP-LH	NOT NECESSARY	201.78	-
	LESS 25% DISCOUNT		-3,466.11	-1,202.65
			10,398.32	3,607.93
	LABOUR			
	LABOUR TO DISMANTLE WINDSCREEN & REFIT TI RENEW CABIN SIDE GRIP.	NOT NECESSARY	150.00	-
	LABOUR CHARGE TO CUT & WELD & DISMANTLE & REMOVE & REFIT ALL ABOVE PARTS.INCLUSIVE OF THE REPAIR OF DOOR PILLAR-LH,STAND PANEL-LH AND FRONT BUMPER.		1,800.00	800.00
	LABOUR TO REWIRE & CONNECT ALL WIRING.		120.00	30.00
	TO SPRAY & PAINTING ALL ACCIDENT DENTED AREA.		1,200.00	600.00
	TO RUST PROOFING ACCIDENT DENTED AREA.		480.00	50.00
	LABOUR TO REMOVE & REFIT FRONT DOOR LH ASSY,REALIGNMENT.		100.00	60.00
			3,850.00	1,540.00
	GRAND TOTAL		14,248.32	5,147.93



RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			4,100.00
---	--	--	----------

Report Ref No. CS/LPC19017043/Utf3n2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.