

ASS. REC. BY:

REF:

CS/CTI/9017050/Ayd3n2

Model Instruction:

Surveyor: Adnan

Meimich

ASSIGNMENT (Office)

From (Person):

Tan Kah Leong

of

CTI

Date/Time:

27/9/19 @ 11:49am

Estimated Cost:

Bill to:

OD/IT WS/TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No.:

SLM 7157A

Insured:

SMD 8461A

at Workshop info:

First Autoworks

Tel:

68441985

of

23 kaki Bukit Ave 4 #04-01

Policy No.:

DMPCSN 30663019000

Claim No.:

SNM19D204532C02

Sum Insured:

Receipt:

Make of Veh:

(Client's Record)

D.O.A.

24/09/2019

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

12:40pm @ 27/9/19

Person Contacted:

Suhaimi

Vehicles IN/OUT

Date/Time	Action/Instruction	Estimate	SJE Adnan
	SLM 7157A - NA/CTI/9016879/24		24/09/2019
	SMD 8461A - NA/CTI/9016879/24		24/09/2019

ASSIGNMENT

SLM7157A.

From: _____ Date: _____
 Estimated Cost: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: _____
 at Workshop m/s: _____
 of: _____
 Insured: _____
 Policy No: _____
 Claims No: _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
 repair at the time of inspection.

N/S	O/S

Bol. or Market Value: _____
 IDAC Accident Rpt: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: _____ days Res.: Yes or No
 Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: ~~SLM7157A~~ 2017 April
 Type: ☒ M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or
 Make: Opel Astra. cc: 999
 Colour: Silver. A/C: Insured / Std / NI / NA
 Sp. Reading: 45986. T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: WOLBE8EA3H8043060
 Gen. Cond: ☒ Good / Fair / Poor / Burnt
 Steering: ☒ In order / Jammed / Leaked / Burnt or
 Brake: ☒ In order / Jammed / Leaked / Burnt or
 Modi: Nil / S/Rim / STD A/Rim or
 Tyre Size: F: 225/45 R17.
 R: 225/45 R17.

☒ BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or

Front		Rear
R/Bal. 06 mm		R/Bal. 06 mm
L/Bal. 06 mm		L/Bal. 06 mm
D.O.A.		D.O.I. 30/09/19.

Survey held at 1st Antwork.

Des. of Damages: Frt / Rear / ☒ S / N/S / U/C / Rooftop or

Front of s.

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
10/1	TP China. PIP \$4688-20 (Red \$7234-20, 60%) Continue with Rennie.
	MV: PV: Nett.
	RECEIVED 20 JAN 2020

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2) 20/1/20 Typist

Days Of Repair: 5

Resurvey No. of Trip: 2

Add Fee: ☐ Site Insp (\$

☐ Interview (\$

☐ Tech. Insp (\$

☐ A/C and \$

Survey Fee:

Transportation:

3 - PE 31

Phone

Other

TOTAL

220

Report Formed:

Using 304/18/17

PIP \$4688-20

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est. Submitted	Adj. Assigned	Adj. Rpt	Adj. Submitted	Inv. Auth'd	Status
Main	27 Sep 2019		27 Sep 2019 11:49 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	ADLEE NAZREE BIN SUPARMAN, ID: 57342738Z		
Main Claimant:	BAN KOK POH DENUS JOEL, ID: 572105988		
Vehicle Reg. No.:	SLM7157A	Date of Loss:	24/09/2019 19:00 - :59 [29 Months and 17 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / SNM19D204532C02	Policy/Cover Note No.:	DMPCSN30663019000
Vehicle Reg. No. (Insured):	SMD8461A	Policy No. (Claimant):	DMPPHQ19-002389
		Excess:	S\$0.00
Repairer:	First Autoworks Pte Ltd (HQ) 23 KAKI BUKIT AVE 4 #04-01 SOUTH WING, 415933 Kaki Bukit - Tel:		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Tan Kah Leong - 63896193]		
Claimant's Insurer:	EQ Insurance Company Ltd (HQ) - Tel: 6223 9433		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 08/10/2019]		
Driver/Custodian (Insured):	SITI RADHIAH JAILANI (44 / Female) , NRIC: S7521981D Email:		
Adj. Asg. Remarks:	please assign Mr Adrian Ling for SJE. thank you		

ASSOCIATED MAIL RECEIVED

[View All](#)

[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)

[Search Tasks](#)

[Create New Task](#)

[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	598B
Vehicle Details	
Vehicle No.:	SLM7157A
Vehicle to be Exported:	No
Intended Deregistration Date:	10 Jan 2020
Vehicle Make:	OPEL
Vehicle Model:	ASTRA ST 1.0 AT
Primary Colour:	Silver
Manufacturing Year:	2017
Engine No.:	B1163427GT2X0812
Chassis No.:	W0LBEBEA3H8043060
Maximum Power Output:	77.0 kW (103 bhp)
Open Market Value:	\$19,545.00
Original Registration Date:	07 Apr 2017
First Registration Date:	07 Apr 2017
Transfer Count:	0
Actual ARF Paid:	\$5,000.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	06 Apr 2027
PARF Rebate Amount:	\$3,750.00
Intended COE Rebate Details	
COE Expiry Date:	06 Apr 2027
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$50,789.00
COE Rebate Amount:	\$36,770.00
Total Rebate Amount:	\$40,520.00

The information contained herein is correct as at 10 Jan 2020

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	25/09/2019 15:32
Date Of Accident	24/09/2019 19:00
Exact Location Of Accident	JUNCTION OF PASIR RIS DRIVE 2 & PARIS RIS ST 21
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLM7157A
Insured/Policyholder	
Name Of Registered Owner	BAN KOK POH DENUS JOEL
NRIC No	S7210598B
Email Address	XPER@HOTMAIL.COM
Mobile Phone No	(LOCAL) +65-91904224
Alternative Phone No	OTHERS-91904224

Vehicle Particulars

Manufacturer	OPEL
Model	ASTRA ST-999CC (A)
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	EQ INSURANCE COMPANY LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	DMPPHQ19-002389
Cover Note Number	

Driver

Name of Driver	BAN KOK POH DENUS JOEL
NRIC No	S7210598B
Date Of Birth	26/03/1972
Occupation	INDOOR
Date Of Driving Pass	25/03/1994
Driving Experience	25 YEARS AND 5 MONTHS
Gender	MALE
Mobile Number	+65-91904224
Fax Number	
Contact Number	OTHERS-91904224
EMail Address	XPER@HOTMAIL.COM

Address	BLK 181 PASIR RIS STREET 11 #06-16 SINGAPORE
Postcode	510181
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	- - -
Insurance Company of Driver's Own Vehicle	- - -

General Information of the Accident

Type Of Accident	COLLISION - CHANGE/CROSS LANE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO THE ATTACH STATEMENT RECORDED BY PEI WEN - PROGRESSIVE CAR CARE PTE LTD TEL 6741 5336

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SMD8461A
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow Insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature

Date & Time:

25/9/19

3:20pm

Driver's Signature

(If driver is not the policyholder)

Date & Time:

Reporting Centre Personnel's Signature




Name:

NRIC/PIN No.:

permen

Sketch Plan #2

SKETCH PLAN

	<p><u>Vehicle</u> A - S1M71STA B - SMD8461A</p> <p><u>Legend</u>  vehicle  Motorcycle</p>
---	--

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 24 Sep 2019 @at about 7pm, I was travelling along Pasir Ris Dr 2. As I approached the junction at Pasir Ris St 21, a motor car SMD8461D filter out from my right and collided into my car.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Please be advised that your insurer may have a fourteen (14) days clause whereby the claim against own policy must be made within the stipulated timeframe from the day of occurrence. Please check your policy for more details.

Policyholder's Signature

Date & Time

3:20pm
25/9/19

Driver's Signature

(If driver is not the policyholder)

Date & Time:

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:

penen

Addendum Sheet



GENERAL INSURANCE ASSOCIATION OF SINGAPORE RECORDS MANAGEMENT CENTRE
 8 Raffles Quay #18-00 Singapore 048580
 Tel (65) 6724 0010 Fax (65) 6724 0030
 Operating Hours : Monday to Friday, 09:00 - 17:00
 UEN: S643581206 / GST Reg. No.: M600017731

IMPORTANT NOTE: Please submit the completed Addendum form to the same Authorised Reporting Centre with whom you submitted the Original Report.

ADDENDUM

(A) PARTICULARS OF PERSON MAKING THE AMENDMENTS:

Original Report No: MPA 219127066 Vehicle Registration No: SLM 7157A
 Name (as shown in NRIC): Ban Kok Poh Dennis Joe NRIC/FIN/Passport No: S7210598B
 (*Vehicle Driver / Vehicle Owner) (*) Please delete as appropriate
 Address: _____ Singapore()
 Contact (Tel): _____ Mobile No.: 91904224
 Email Address: _____
 Date of Accident: 24/9/19 Time of Accident: 1900
 Place of Accident: Junction of pasir ris drive 2 & pasir ris st 21
 Insurance Company: EQ

(B) ADDITIONAL INFORMATION / AMENDMENTS:

I have made a report on the above mentioned accident and would like to include additional information or make the following amendments:

TP Vehicle No should be "SMD8461 A"

[Signature]

Policyholder / Driver's Signature

Date: 26/9/19

[Signature]

Reporting Centre Personnel's Signature

Name: _____
 NRIC/FIN No.: _____
 Date: _____

[Signature]

FIRST AUTOWORKS

Repair Estimate

Date : 26/09/2019

Reference: SLM7157A

To Whom It May Concern

Make: Opel
Astra

Dear Sir,

RE: VEHICLE : SLM7157A
CHASSIS NO. W0LBE8EA3H8043060
ENGINE NO.: B1163427GT2X0812

TP Clinic
Xonne

Name of insured : BAN KOK POH DENUS JOEL
Date of accident: 24/09/2019

We append hereunder the estimated cost of repairs to be carried out to the above vehicle.

Parts

No.	Qty	Part Description	Price (SGD)
1	1	BONNET <i>Neu</i>	1,880.00 *
2	1	FRT BUMPER <i>foin</i>	1,500.00 ✓
3	1	FRT BUMPER SIDE RETAINER RH, Guide <i>neu</i>	60.00 ✓
4	1	FRT BUMPER SIDE BRACKET RH <i>neu</i>	58.00 ✓
5	1	FRT BUMPER TOW COVER <i>neu</i>	40.00 *
6	1	FRT BUMPER CLIP SET - Rivet <i>neu</i>	40.00 ✓
7	1	RH HEADLAMP <i>neu</i>	820.00 *
8	1	FRT FENDER RH <i>Dented</i>	740.00 ✓
9	1	FRT EMBLEM <i>neu</i>	120.00 *
10	1	FRT RH FOG LAMP <i>neu</i>	320.00 *
11	1	FRT RH FOG LAMP COVER <i>neu</i>	110.00 *
12	4	FRT BUMPER PARKING SENSOR <i>neu</i>	420.00 *
13	4	FRT BUMPER PARKING SENSOR SEAL <i>neu</i>	40.00 *
14	1	FRT BUMPER PARKING SENSOR WIRE HARNESS <i>neu</i>	618.00 *
15	1	FRT FENDER INNERSHIELD RH <i>neu</i>	180.00 *
16	1	FRT ENGINE UNDER DUST COVER RH <i>neu</i>	80.00 *
17	1	FRT BUMPER UNDER DUST COVER <i>neu</i>	190.00 *
18	1	RH WING MIRROR <i>Regis</i>	720.00 *

Parts Total: 7,936.00
Less 10%: 793.60
Total : 7,142.40

Labour

No.	Labour Description	Price (SGD)
1	To dismantle / renew the accident damaged portion, to panel beating, reshape, straighten, orientate and align repair / replacement parts.	2800.00 <i>1300</i>
2	Carry out spray painting on accident affected area. (Frt bumper, LHF Fender)	1200.00 <i>1850.00</i> <i>2x550=1100</i> <i>mirror=100</i>
3	To disconnect wire harness of electrical component to facilitate repairs, reconnect and check electrical function after repair	40.00 <i>30</i>
4	To conduct 4 wheel alignment	50.00 *

Labour Total : 4,740.00

1st Autoworks Pte Ltd

23 Kaki Bukit Ave 4, #04-01 (South Wing) Next to Vicom Building, Singapore 415933 Tel : 6844 1985 Fax : 6844 5185

OtherNo.

1

Frt Number Plate

Other Description

xbl m

Price (SGD)

40.00 *

Other Total : 40.00

Total : \$11,922.40

Gst (7%) : \$834.57

GRAND TOTAL: \$12,756.97

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER WILL BE INFORMED PRIOR TO ACTION TAKEN. **PARTS PRICES ARE SUBJECT TO CHANGES.**

Yours faithfully



Service Advisor

Ronnie Tan

DID: 6844 1985 Fax:6844 5185

Adrian Ling -
P/P 30/05/19

05 Days.

total: 4688.20 (P/P)

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer:

Signature:

Date:

1st Autoworks Pte Ltd

23 Kaki Bukit Ave 4, #04-01 (South Wing) Singapore 415933 Tel: 68441985 Fax: 68445185

TAX INVOICE

China Taiping Insurance (Singapore) Pte. Ltd
3 Anson Road #16-00 Springleaf Tower
Singapore 038986

GST Ref. No: M2-0111811-4

Vehicle No: SLM7157A
Chassis No :W0LBE8EA3H8043060
Engine No: B1163427GT2X0812

Invoice No:

Invoice Date:

DESCRIPTION	AMOUNT SGD
-------------	---------------

Parts

No.	Qty.	Description	Price (SGD)
1	1	FRT BUMPER	1,500.00
2	1	FRT BUMPER SIDE RETAINER RH	60.00
3	1	FRT BUMPER SIDE BRACKET RH	58.00
4	1	FRT BUMPER CLIP SET	40.00
5	1	FRT FENDER RH	740.00

Total: 2398.00
Less 10%: 239.80
Parts Total : 2158.20


Labour

No.	Description	Price (SGD)
1	To dismantle / renew the accident damaged portion, to panel beating, reshape, straighten, orientate & align repair / replacement parts	1,300.00
2	Carry out spray painting on affect area frt portion (frt bumper, RH frt fender)	1,200.00
3	To disconnect front wire harness of electrical component to facilitate repair, reconnect & check electrical function after repair	30.00

Labour Total : 2530.00

Sub Total : \$4,688.20
GST (7%) \$328.17
Grand Total: \$5,016.37

Yours Faithfully,


Ronnie Tan
Service Advisor
Tel: 68441985 Fax: 68445185

E & O E

- ALL CHEQUE PAYMENTS SHOULD BE CROSSED AND MADE PAYABLE TO "1ST AUTOWORKS PTE LTD".
- PLEASE INDICATE THE INVOICE NO. ON THE REVERSE SIDE.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI19017050/AYD3N2
Date: 23/01/2020

REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMPCSN30663019000
Claimant Vehicle No: SLM7157A Insured Vehicle No: SMD8461A
Date of Loss: 24/09/2019 Nature of Claim: TP Claim No: SNM19D204532C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLM7157A
Make & Model: OPEL ASTRA ST, 999cc (A) Engine No: B1163427GT2X0812
Reg. Date: 07/04/2017 (Man. Year: 2017) Chassis No: W0LB8EA3H8043060
Colour: Silver Odometer: 45996 km
Engine Capacity: 999 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/45 R17 Rear Tyre Size: 225/45 R17
Front Left Side: Bridgestone 6 mm Rear Left Side: Bridgestone 6 mm
Front Right Side: Bridgestone 6 mm Rear Right Side: Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,182.40	2,158.20	5,024.20	69.95
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,740.00	2,530.00	2,210.00	46.62
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	11,922.40	4,688.20	7,234.20	60.68
+ GST 7.00/7.00% (S\$)	834.57	328.17	506.40	60.68
Nett Amount (S\$)	12,756.97	5,016.37	7,740.60	60.68

INSPECTION

Date of Assignment: 27/09/2019
Date Inspected: 30/09/2019 Inspected At: First Autoworks Pte Ltd (HQ)
Singapore 415933
Estimated Period of Repair: 5.0 days

Adjuster: ADRIAN LING

Manager: YVONNE WONG YIN CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 22 Jan 2020)	
Parts:	N/A	OPEL ASTRA ST 999cc (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLM7157A)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BONNET	Not Necessary	1,880.00 FL	*- FL
2	1		*FRT BUMPER	Torn	1,500.00 FL	*1,500.00 FL
3	1		*FRT BUMPER SIDE RETAINER RH ,GUIDE	Necessary	60.00 FL	*60.00 FL
4	1		*FRT BUMPER SIDE BRACKET RH	Necessary	58.00 FL	*58.00 FL
5	1		*FRT BUMPER TOW COVER	Not Necessary	40.00 FL	*- FL
6	1		*SET FRT BUMPER CLIP -RIVET	Necessary	40.00 FL	*40.00 FL
7	1		*RH HEADLAMP	Not Necessary	820.00 FL	*- FL
8	1		*FRT FENDER RH	Dented	740.00 FL	*740.00 FL
9	1		*FRT EMBLEM	Not Necessary	120.00 FL	*- FL
10	1		*FRT RH FOG LAMP	Not Necessary	320.00 FL	*- FL
11	1		*FRT RH FOG LAMP COVER	Not Necessary	110.00 FL	*- FL
12	4		*FRT BUMPER PARKING SENSOR	Not Necessary	420.00 FL	*- FL
13	4		*FRT BUMPER PARKING SENSOR SEAL	Not Necessary	40.00 FL	*- FL
14	1		*FRT BUMPER PARKING SENSOR WIRE HARNESS	Not Necessary	618.00 FL	*- FL
15	1		*FRT FENDER INNERSHIELD RH	Not Necessary	180.00 FL	*- FL
16	1		*FRT ENGINE UNDER DUST COVER RH	Not Necessary	80.00 FL	*- FL
17	1		*FRT BUMPER UNDER DUST COVER	Not Necessary	190.00 FL	*- FL
18	1		*RH WING MIRROR	Repair	720.00 FL	*- FL
19	1		*FRT NUMBER PLATE	Not Necessary	40.00 FS	*- FS

F=Franchise part, S=SpcNett, L=ListItemDisc.

Sub Total (S\$)	7,976.00	2,398.00
- List Item Discount on L Items 10.00/10.00% (S\$)	793.60	239.80
Total Parts (S\$)	7,182.40	2,158.20

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO DISMANTLE /RENEW THE ACCIDENT DAMAGED PORTION ,TO PANEL BEATING ,RESHAPE ,STRAIGHTEN ,ORIENTATE AND ALIGN REPAIR /REPLACEMENT PARTS	New	2,800.00	1,300.00
2	CARRY OUT SPRAY PAINTING ON ACCIDENT AFFECTED AREA (FRT BUMPER ,LHF FENDER)	New	1,850.00	1,200.00
3	TO DISCONNECT WIRE HARNESS OF ELECTRICAL COMPONENT TO FACILITATE REPAIRS ,RECONNECT AND CHECK ELECTRICAL FUNCTION AFTER REPAIR	New	40.00	30.00
4	TO CONDUCT 4 WHEEL ALIGNMENT	New	50.00	0.00
Gross Labour Cost (S\$)			4,740.00	2,530.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >