

ASS. REC. BY:

REF:

CS/FCI19017054/Es d3ⁿ²

Special Instruction:

Surveyor: Steve

ASSIGNMENT (Office)

CWS

From (Person): Sthenera

of

FCI

Date/Time:

5:19pm 28/9/19

Estimated Cost:

Bill to:

OD ☒ TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SKQ 7785C

Insured:

SHC 7481M

at Workshop m/s

Toh Ah Swee

Tel:

63660286

of

Blk 2 Krunji Teop #01-02 (off Krunji road)

Policy No:

Claim No:

D19006079MPST

Sum Insured:

Excess:

Make of Veh:

D.O.A.

18/09/2019

(Client's Record)

CA / REV / REP. / REV 24 HRS

(OS)

H.O.D. Endorsement:

Date/Time:

9:49am 27/9/19

Person Contacted:

Sally

Vehicle IN ☒ OUT

Date/Time

Action/Instruction

Bahmal /

SKQ 7785C-

SHC 7481M-X

10/10/19

@ 16:44 pm revised PA to Sthenera via email

Summary

Steve


REF:

ASSIGNMENT

From: Date: Veh No: SKQ 7785C Yr Regn: 26/12/14
 Estimated Cost: Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV Truck / Trailer or
 To Inspect Vehicle No: Make: Toyota Wish C.C. 1798
 at Workshop m/s Colour Grey A/C: Insured / Std / NI / NA
 of Sp. Reading 83478 T/Radio: Insured / Std / NI / NA
 Insured Eng/No:
 Policy No. CiNo: JTOG620W 60JA 01917
 Claims No. Gen. Cond: Good / Fair / Poor / Burnt
 Sum Insured: Excess: Steering: Inorder / Jammed / Leaked / Burnt or
 (Client's Record) Brake: Inorder / Jammed / Leaked / Burnt or
 Make of Veh: Modl: Nil / S/Rim / STD A/Rim or
 Tyre Size: F: 195/65R15
 R:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: Consistent? : Yes or No
 IDAC Accident Rpt: Consistent? : Yes or No
 GIA / PR Seen: Consistent? : Yes or No
 Est. Repairs: days Res.: Yes or No
 Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: Person Contacted:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or Pirelli
 Front Rear
 R/Bal. 5 mm R/Bal. 5 mm
 L/Bal. 5 mm L/Bal. 5 mm
 D.O.A. 18/9/19 D.O.I. 8/10/19
 Survey held at Toh Ah Swee
 Des. of Damages: Frt / Rear / O/S / NIS / UIC / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision

Date / Time Action / Instruction

17/10/19 MIV- 66K
 Finalize Conf- \$950, 3-days
 (\$ 3,504.75 - Red - 79%)

RECEIVED 18 OCT 2019

18/10/2019

Date/Time, File Pass to?

18/10/19

1) Typ 4

Date/Time, File Return to?

2)

Report Format :

Lump Sum / I.B.I: (\$ 950/- 45)

☐ : Proll. Report
☒ : Final Report

Days Of Repair: 3

Resurvey No. of Trip: 1

Add Fee: ☐ : Site Insp (\$)
☐ : Interview (\$)
☐ : Tech Invs (\$)
☐ : Weekend (\$)

Survey Fee:

Transportation:

) S + RS, SI

) Photos

) Others

TOTAL

135

50

50

30

265

MOTOR SURVEY ASSIGNMENT

Date	20-09-2019	Our Ref No. D19006079MFSH
Accident Date	18-09-2019	Claim Type. Third Party
Insured Vehicle	SHC7481M	Third Party Vehicle. SKQ7785C
Survey Location	BLK 2 KRANJI LOOP #01-02 (OFF KRANJI ROAD)	
Contact Person.	SALLY ANG	
Contact No.	63660286/ 0	Fax No. 63685943
Survey Type	WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM TO BE AGREED:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	TOH AH SWEE SPRAY PAINTING CO.	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	SITHARA	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Steve Chen (LKK Auto)

From: claims claims <claims@tohahswee.com.sg>
Sent: Friday, October 18, 2019 2:04 AM
To: Steve Chen (LKK Auto)
Subject: Re: FINALIZATION FOR VEHICLE SKQ7785C

Dear Steve,

Yes confirmed, L/S \$950 (B4 GST) for 3 repair days.

Thanks & Best Rgds,
Sally Ang
Toh Ah Swee Spray Painting Co.
Tel: 63660286
Fax: 63685943

P/S: Please be informed that our company will be relocate to 60 Jalan Lam Huat #07-33/34 Carros Centre S737869 with effective from 22/04/2019.

On Wed, Oct 16, 2019 at 5:51 PM Steve Chen (LKK Auto) <SteveChen@lkkauto.com> wrote:

Dear Sally,

Kindly refer our finalize \$950 (L/S, before GST). 3 repair days.

Kindly confirm.

Thanks

Best Regards,

Steve Chen | Assistant Automotive Assessor

Re: SURVEY ASSESSMENT - D19006079MFSH/1

Shirley Hiew (LKK Auto)

Thu 10/10/2019 4:44 PM

To: 'Sithara' <Sithara@msfirstcapital.com.sg>; 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>

Cc: SUR <sur@lkkauto.com>; assignments <assignments@lkkauto.com>

Dear Sithara,

Enclosed preliminary revised of vehicle SKQ 7785C.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte LtdPhone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto) <admin-d@lkkauto.com>**Sent:** Friday, 27 September 2019 10:35 AM**To:** 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>**Cc:** 'Sithara' <Sithara@msfirstcapital.com.sg>; SUR <sur@lkkauto.com>**Subject:** RE: SURVEY ASSESSMENT - D19006079MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

Please be informed that vehicle is not in the workshop, repairer will arrange.

Best Regards

G.NIVITHA**LKK Auto Consultants Pte Ltd**Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: CWS Motor Claims [mailto:cwsmotorclaims@msfirstcapital.com.sg]**Sent:** Thursday, 26 September 2019 5:19 PM**To:** ASSIGNMENTS@LKKAUTO.COM**Cc:** CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>; Sithara <Sithara@msfirstcapital.com.sg>**Subject:** PRI: SURVEY ASSESSMENT - D19006079MFSH/1

Vehicle Details

Vehicle No.	Make / Model
SKQ7785C	TOYOTA / WISH 1.8 CVT
Vehicle Type :	Vehicle Attachment 1 :
P11 - Passenger Station Wagon/Jeep/Land Rover	No Attachment
Vehicle Scheme :	Chassis No. :
Normal	JTDGG20W60J001917
Propellant :	Engine No. :
Petrol	2ZRB481309
Motor No. :	Engine Capacity :
-	1798 cc
Power Rating :	Maximum Power Output :
-	105.0 kW (140 bhp)
Maximum Laden Weight :	Unladen Weight :
1935 kg	1360 kg
Year Of Manufacture :	Original Registration Date :
2014	26 Dec 2014
Lifespan Expiry Date :	COE Category :
-	B - Car above 1600cc or 97kW (130bhp)
Quota Premium :	COE Expiry Date :
\$70,890.00	25 Dec 2024
Road Tax Expiry Date :	PARF Eligibility Expiry Date :
25 Dec 2019	25 Dec 2024
Inspection Due Date :	Intended Transfer Date :
25 Dec 2019	25 Sep 2019
CO2 Emission :	CEV/VES Rebate Utilised Amount :
159.00 (g/km)	\$5,000.00
CO Emission :	HC Emission :

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	845I
Vehicle Details	
Vehicle No.:	SKQ7785C
Vehicle to be Exported:	No
Intended Deregistration Date:	10 Oct 2019
Vehicle Make:	TOYOTA
Vehicle Model:	WISH 1.8 CVT
Primary Colour:	Grey
Manufacturing Year:	2014
Engine No.:	2ZRB481309
Chassis No.:	JTDGG20W60J001917
Maximum Power Output:	105.0 kW (140 bhp)
Open Market Value:	\$23,454.00
Original Registration Date:	26 Dec 2014
First Registration Date:	26 Dec 2014
Transfer Count:	0
Actual ARF Paid:	\$19,836.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	25 Dec 2024
PARF Rebate Amount:	\$14,877.00
Intended COE Rebate Details	
COE Expiry Date:	25 Dec 2024
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$70,890.00
COE Rebate Amount:	\$36,912.00
Total Rebate Amount:	\$51,789.00

The information contained herein is correct as at 10 Oct 2019

OK

卓亚水喷漆公司 TOH AH SWEE SPRAY PAINTING CO.

NO 60 JALAN LAM HUAT #07-33/34 CARROS CENTRE SINGAPORE 737869

TEL: 63660115 (WORKSHOP), 63660286 (OFFICE) FAX: 63685943

EMAIL: claims@tohahswee.com.sg

26/09/2019

FIRST CAPITAL INSURANCE LIMITED

36 ROBINSON ROAD

#16-01 CITY HOUSE

SINGAPORE 068877

ATTN: MOTOR CLAIMS DEPT

Stew (LKK) 8322 8813

Wm 8/10/19, 4:30 pm
3 dy
L/S
My AL sm

ESTIMATED REPAIR BILL

YOUR REF : SHC7481M
TYPE OF CLAIM : THIRD PARTY CLAIMS
CLAIMANT : TENG WEI LING EVELYN
VEHICLE NO. : SKQ7785C ✓
MAKE/ MODEL : TOYOTA WISH 1.8(A)
ACCIDENT DATE : 18/09/2019

MATERIAL COST

IPC BOOTLID x N/A
IPC BOOTLID CHROME x N/A
IPC BOOTLID LAMP RH x N/A
IPC TAIL LAMP RH x N/A
IPC REAR BUMPER ✓

\$ 1,522.00
\$ 468.00
\$ 478.00
\$ 480.00
\$ 565.00
\$ 3,513.00 - 75%
\$ 878.25 423.75
\$ 2,634.75

LESS : DISCOUNT 25%

MATERIAL COST - SPECIAL NETT

IPC REVERSE SENSOR ✓ 521

\$ 200 380.00

LABOUR CHARGE :

TO REMOVE AND REFIX REAR WINDSCREEN

TO REMOVE & REFIX REVERSE SENSOR & CHECK WIRING.

TO REMOVE DAMAGED PARTS, TO KNOCK OUT DENTS, TO STRAIGHEN, ADJUST, CHECK, RESHAPE INCLUDING CUTTING AND WELDING WHERE NECESSARY, TO REMOVE AND REINSTALL NECESSARY FITTINGS TO FACILIATE REPAIRS, TO REPLACE AND ALIGN THE ABOVE PARTS.

PUTTY AND SPRAY PAINTING ON RHS BODY AND ABOVE NEW AND REPAIRED PARTS INCLUDING SUPPLY OF PAINT MATERIALS

\$ 180.00 X
\$ 60.00 20

\$ 300 600.00

\$ 250 600.00

\$ 4,454.75

\$ 311.83

\$ 4,766.58

ADD : GST 7%

TOTAL :

SINGAPORE DOLLARS : FOUR THOUSAND SEVEN HUNDRED SIXTY SIX AND CENTS FIFTY EIGHT ONLY.

NOTE: THE ESTIMATED PERIOD OF REPAIRS IS FIVE (5) DAYS

TOH AH SWEE SPRAY PAINTING CO.

SALLY ANG (TEL : 63660286)

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
MS FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI19017054/Esd3n2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 21-10-2019	
		Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SHC 7481M	Veh. Inspected	SKQ 7785C
Policy No.		Coverage (\$)	0.00
Claim No.	D19006079MFSH	Excess (\$)	0.00
Assign From	SITHARA	Assign Date	26/09/2019
2. Vehicle Particulars & Condition			
Make & Model	TOYOTA WISH	c.c	1798
Engine No.	HIDDEN	Year of Reg.	2014
Chassis No.	JTDGG20W60J001917	Colour	GREY
Odometer	83478	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	FAIR		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	195/65 R15	PIRELLI	5 mm
L/H Front Tyre	195/65 R15	PIRELLI	5 mm
R/H Rear Tyre	195/65 R15	PIRELLI	5 mm
L/H Rear Tyre	195/65 R15	PIRELLI	5 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	18/09/2019	Inspection Date	08/10/2019
Survey held at	BLK 2, KRANJI LOOP #01-02		
Repairer	TOH AH SWEE SPRAY PAINTING CO.		
5a. Remarks			
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days	

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKQ 7785C

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	BOOTLID	NOT NECESSARY	1,522.00	-
1	BOOTLID CHROME	NOT NECESSARY	468.00	-
1	BOOTLID LAMP RH	NOT NECESSARY	478.00	-
1	TAIL LAMP RH	NOT NECESSARY	480.00	-
1	REAR BUMPER	DENTED	565.00	565.00
	LESS 25% DISCOUNT		-878.25	-141.25
			2,634.75	423.75
	SPECIAL NETT ITEMS			
1	REVERSE SENSOR (SN)	SHORTED	380.00	200.00
			380.00	200.00
	LABOUR			
	TO REMOVE AND REFIX REAR WINDSCREEN.	NOT NECESSARY	180.00	-
	TO REMOVE & REFIX REVERSE SENSOR & CHECK WIRING.		60.00	20.00
	TO REMOVE DAMAGED PARTS.TO KNOCK OUT DENTS,TO STRAIGHTEN.ADJUST,CHECK,RESHAPE INCLUDING CUTTING AND WELDING WHERE NECESSARY.TO REMOVE AND REINSTALL NECESSARY FITTINGS TO FACILIATE REPAIRS.TO REPLACE AND ALIGN THE ABOVE PARTS.		600.00	300.00
	PUTTY AND SPRAY PAINTING ON RHS BODY AND ABOVE NEW AND REPAIRED PARTS INCLUDING SUPPLY OF PAINT MATERIALS.		600.00	250.00
			1,440.00	570.00
	GRAND TOTAL		4,454.75	1,193.75
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			950.00

Report Ref No. CS/FCI19017054/Esd3n2

CHEN TSUE YEE

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.