

Cecilia



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 26/09/2019

User ID : GohKK2

Section A - Accident Details			
Registration Number	SMB1421Y		
Case Reference Number	BUS/09/19/1066		
Registration Date	8/7/2014		
Company Type	SMRT Buses Ltd		
Make	MAN		
Model	MAN NL320F(A22)		
Name of Driver	Zhang Shihui		
Type of Accident	Side Swipe		
Accident Date and Time	23/9/2019 7:28 PM		
Accident Reported Date and Time	24/9/2019 10:37 AM		
Is Surveyor Required?	Yes		
Survey by			
Vehicle Is Towed Back?	No		
Towed Back Date and Time			
Replacement Vehicle issued?	No		
Job Card Number			
Special Instruction to ARC, if any	SMB1421Y-RIGHT REAR PORTION SHD6832K (TP) INSURED WITH III		
Prepared Date and Time	26/9/2019 11:47 AM		
Chassis Number	WMAA2ZZZ2E7002135		
Mileage			
Work Shop			
Repair Completion Date and Time			
Section B - Summary of Repair Estimates			
Summary of Repair Estimates	Quotation from ARC	Adjusted by Surveyor, if applicable	
Total Labour Cost	\$1,325.00	\$0.00	
Total Spray Cost	\$728.00	\$0.00	
Total Spare Part Cost	\$160.00	\$0.00	
Total Other Cost	\$0.00	\$0.00	
TOTAL COST	\$160.00	\$0.00	
Lump Sum Total	\$150.00	\$0.00	
Number of Repair Days	3.0	2.0	
Prepared / Adjusted By	Kok Khooon Goh		
ARC / Surveyor Sign Off Date	26/09/2019 12:44 PM		
Signature			
Remarks			
Section C - Quotation and Accident Invoice Details			
Quotation Number		Invoice Number	
Quotation Date		Invoice Date	
Invoice Amount		Prepared Date	

Steve.

26/09/2019.

R/O - 2 days.

Tp without Prejudice

Lump Sum, after spray

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
80 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 26/09/2018

User ID : GohKK2

Section D - Details of Repair Estimates									
Part 1 - Labour Works									
Job Scope		Quotation from AR			Adjusted by Surveyor, if applicable				
TO REMOVE & INSTALL ALL ABOVE ITEMS AND REPAIR OTHERS DAMAGED AFFECTED AREAS.		\$1,325.00			1060				
Total Labour		\$1,325.00							
Part 2 - Spray Painting & Panel Beating Related Works									
Job Scope		Quotation from ARC			Adjusted by Surveyor, if applicable				
PROVIDE LABOUR AND MATERIAL TO PUTTY AND RESPRAY ABOVE REPAIR ITEMS		\$728.00			636				
Total Spray Painting & Panel Beating		\$728.00							
Part 3 - Other Costs - Accident and Accident Repair Related Expense									
Job Scope		Quotation from ARC			Adjusted by Surveyor, if applicable				
Total Other Costs									
Part 4 - Spare Parts / Material Usage									
Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
6009987	BODY RH	A01001-CW568	PANEL SIDE R6 FOR MAN A22 BUS	1.00	\$1,776.80	100.00	\$0.00	Repair	X R
6009988	BODY RH	A01001-CW567	PANEL SIDE R7 FOR MAN A22 BUS	1.00	\$885.50	100.00	\$0.00	Repair	X R
6010330	Body	5029	TRIM WHEELARCH FOR 18T OC500 LE BUS	1.00	\$124.20	100.00	\$0.00	Repair	X R
			STICKER SMRT	1.00	\$200.00	0.00	\$200.00	Replace	✓ Nec
Total					\$2,986.50		\$200.00		
Added Spare Parts / Material Usage After Surveyor Signed off									
Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
Total									
209 - 20% L/S 160 1696 1856 L/S - 1850									