



## SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672


Date Generated : 26/09/2019

User ID : BoonChewTay

### Section A - Accident Details

Registration Number	SG1711M
Case Reference Number	BUS/09/19/1061
Registration Date	4/5/2016
Company Type	SMRT Buses Ltd
Make	MAN
Model	A22
Name of Driver	Lim Hock Hoe
Type of Accident	Side Swipe
Accident Date and Time	19/9/2019 8:45 AM
Accident Reported Date and Time	20/9/2019 3:58 PM
Is Surveyor Required?	No
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	
Special Instruction to ARC, if any	SG1711M-RIGHT REAR PORTION SMF8659L (TP) INSURED WITH AIG
Prepared Date and Time	26/9/2019 1:12 PM
Chassis Number	WMAA22ZZ0F7002880
Mileage	
Work Shop	
Repair Completion Date and Time	

### Section B - Summary of Repair Estimates

Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$1,325.00	\$0.00
Total Spray Cost	\$878.00	\$0.00
Total Spare Part Cost	\$0.00	\$0.00
Total Other Cost	\$0.00	\$0.00
<b>TOTAL COST</b>	<b>\$2,203.00</b>	<b>\$0.00</b>
<b>Lump Sum Total</b>	<b>\$2,200.00</b>	<b>\$0.00</b>
Number of Repair Days	3.0	2.0
Prepared / Adjusted By	Boon Chew Tay	
ARC / Surveyor Sign Off Date	26/09/2019 1:17 PM	
Signature		<input checked="" type="checkbox"/>
Remarks		

### Section C - Quotation and Accident Invoice Details

Quotation Number		Invoice Number	
Quotation Date		Invoice Date	
Invoice Amount		Prepared Date	

Steve  
26/09/2019  
R/D - 2 days  
Lump Sum Repair  
After spray  
TP without prejudice.





## SMRT Accident Vehicle Repair Estimates

<b>SMRT Automotive Services Pte Ltd</b>
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 26/09/2019

User ID : BoonChewTay

### Section D - Details of Repair Estimates

#### Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REMOVE & INSTALL ALL ABOVE ITEMS AND REPAIR OTHERS DAMAGED AFFECTED AREAS.	\$1,325.00	1060
<b>Total Labour</b>	<b>\$1,325.00</b>	

#### Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
PROVIDE LABOUR AND MATERIAL TO PUTTY AND RESPRAY ABOVE REPAIR ITEMS	\$878.00	708
<b>Total Spray Painting &amp; Panel Beating</b>	<b>\$878.00</b>	

#### Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
<b>Total Other Costs</b>		

#### Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
6009988	BODY RH	A01001-CW567	PANEL, SIDE: R7, FOR MAN A22 BUS	1.00	\$885.50	100.00	\$0.00	Repair	X R
6009989	BODY RH	A01001-CW566	PANEL, SIDE: R8, FOR MAN A22 BUS	1.00	\$330.70	100.00	\$0.00	Repair	X R
6009990	BODY RH	A01001-CW565	PANEL, SIDE: R9 WITH FRAME, FOR MAN A22 BUS	1.00	\$710.70	100.00	\$0.00	Repair	X R
<b>Total</b>					<b>\$1,926.90</b>		<b>\$0.00</b>		

#### Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
<b>Total</b>									

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged parts during resurvey
- Parts prices are based on "no prejudice" basis
- Third party Surveyor's report is on "no prejudice" basis
- No illegal modification allowed
- Supplementary items must be surveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: