

INS. CASE OWNER:

Bernard Ler

CC4/AIG19017079/Uda3

LKK:
IDAC:

Surveyor:

MARCUS

DOI: 30/09/2019

Date / Time: 27/09/2019

Registered in Meriton: 27/09/2019

Pre-assign / CCU / FTE



Insured Vehicle No. : SKX 8772X

Claim No. : 6278988846SG

Name of Insured : CONNECT4CAR PTE LTD

Policy No. :

Insured Tel No. : HP:

Make / Model : TOYOTA ALTIS

Excess Sec II :SS D.O.A: 21/09/2019 04:45

Place of Accident : TAMPINES AVE 5 & AVE 2

Is driver the owner? (YES / NO) Nature of Accident :

If NO, Driver Name / Age : MIGAWATI BINTE JANTAN

OI GIA REPORT YES / NO ; TP GIA REPORT YES / NO

Driver Tel No. : +65-92389763 (V/L YES / NO)

Insured Liability : % Final ? Yes / No

FY 5018P

INSRS:
WSP: Erofia Motor
Tel:
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:

Date/ Time	FY 5018P - X	SKX 8772X - X	STAGE	DATE / PIC	
4/5/2020 - FILE PAPER TO HOME TO CLOSE	* Wt figures different in settlement amount (including Lon.)		Non-Reporting ltr (1st):		
			Non-Reporting ltr (2nd):		
			Non-Reporting ltr (Final):		
			Notification ltr (if non-pickup):		
			Call OI:		
			After call ltr to OI:		
			Documentation Check List: Handler	Typist	
			Notification ltr (if non-pickup)	☒	☐
			After call ltr to OI:	☒	☐
			Authorisation To Act:	☒	☐
			Release Voucher:	☒	☐
			Final Repair Bill:	☒	☐
			Car Rental Invoice:	☐	☐
			Towing Invoice:	☐	☐
			LTA / GIA :	☐	☐
Medical Bill:	☐	☐			
PIR:	☒	☐			
Mandate/Reject Instruction:	☐	☐			
LOD	☒	☐			
Payment Breakdown Form:					
Post-Repair Photos:	☐	☐			
Others:	☐	☐			

PRELIMINARY ADVICE	Date/Time:	Sent By:
--------------------	------------	----------

PRELIMINARY ADVICE		Date/Time:	Sent By:
FINALIZATION		Date/Time:	Confirm with:
Repair Cost:	SS	(days) Reduction:	%
FINAL SETTLEMENT		Date/Time: 4/3/2020	Confirm with: Lee See Tan
Final Liability:	% 100	(Agreed / Assessed) BOLA S/N No.:	NIL
Repair Cost:	SS 194.00	OR HIT TP MOTOR CYCLE	
Loss of Rental (LOR):	SS -	(days)	
Loss of Use (LOU):	SS 280.00	(5 20 x 14 days)	
Loss of Income (LOI):	SS -	(5 x days)	
LOR only ☐ LOU only ☒	LOR + LOU ☐ LOR + LOI ☐	[Tick only one]	
GIA/LTA Search:	SS -		
Medical:	SS -		
Disbursement:	SS -	(e.g. Tow/ Independent)	
Legal Cost:	SS -		
Total:	SS 474.00	Global Sum SS:	
FINAL PAYMENT		Date/Time:	Confirm with:
Payee 1:	SS 474.00	Name 1:	Erofia Motor Trading Pte Ltd
Payee 2: (Strike if N.A.)	SS	Name 2:	
Payee 3: (Strike if N.A.)	SS	Name 3:	

COPY SENT
5/3/20201) Claim status: Normal/Reject/Private Settle
2) Report Format: ☒
3) Survey fee: \$320

(08/11/12) wel

ASS. REC. BY: MARUS

REF:

ASSIGNMENT

From:

Date:

Veh No:

Yr Regn:

Estimated Cost:

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

Truck / Trailer or

To inspect Vehicle No:

Make:

c.c

at Workshop m/s

Colour:

A/C: Insured / Std / NI / NA

of

Sp. Reading

T/Radio: Insured / Std / NI / NA

Insured:

Eng/No:

Policy No.

C/No:

Claims No.

Gen. Cond: Good / Fair / Poor / Burnt

Sum insured:

Excess:

Steering: In order / Jammed / Leaked / Burnt or

(Client's Record)

Brake: In order / Jammed / Leaked / Burnt or

Make of Veh:

Mod: Nil / S/Rim / STD A/Rim or

(Policy Condition)

Tyre Size:

F:

R:

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days Res.: Yes or No

Lum Sum:

3 Val.: Yes or No

Front

R/Bal.

mm

Rear

R/Bal.

mm

L/Bal.

mm

L/Bal.

mm

D.O.A.

D.O.I.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

col 6-10-2019 15 day.
TOTAL LOSS

15/1/20 \$194 agreed.

MV : \$200

LTA : \$6

NV : \$194

Date/Time, File Pass to?

☐

Prel. Report

1)

☐

Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Weekend (\$

) \$ + RS \$

) Photos

) Others

TOTAL

Report Format :

Lump Sum / I.B.I: (\$)

(08/11/13) wef

ASS. REC. BY: Marcus

REF:

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rpt:

GIA / PR Seen:

Est. Repairs:

Lum Sum:

Consistent? : Yes or No

Consistent? : Yes or No

days Res.: Yes or No

% 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time

Action / Instruction

17AB
 on 6-10-2019 15-day
 TOTAL LOSS

Veh No:

Yr Regn:

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Colour:

Sp. Reading:

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal.

L/Bal.

D.O.A.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear &
 The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

1)

Date/Time, File Return to?

2)

☐

Preli. Report

☐

Final Report

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Weekend (\$

) S + RS. Si

) Photos

) Others

)

Report Format :

Lump Sum / I.B.I: (\$)

TOTAL

[> Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC
Owner ID: 114F

Vehicle Details

Vehicle No.: FY5018P
Vehicle to be Exported: No
Intended Deregistration Date: 30 Sep 2019
Vehicle Make: YAMAHA
Vehicle Model: YBR125
Primary Colour: Red
Manufacturing Year: 2004
Engine No.: JYM154FMI04405648
Chassis No.: LBPPCJLB440183728
Maximum Power Output: -
Open Market Value: \$1,277.00
Original Registration Date: 07 Oct 2004
First Registration Date: 07 Oct 2004
Transfer Count: 4
Actual ARF Paid: \$192.00

Intended PARF Rebate Details

PARF Eligibility: No
PARF Eligibility Expiry Date: -
PARF Rebate Amount: \$0.00

Intended COE Rebate Details

COE Expiry Date: 06 Oct 2019
COE Category: D - Motorcycle
COE Period(Years): 5
PQP Paid: \$2,160.00
COE Rebate Amount: \$6.00
Total Rebate Amount: \$6.00

Message

Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 30 Sep 2019

17079/d

PRE-REPAIR INSPECTION REQUEST – FY5018P vs SKX8772X (OI) on D.O.A.: 21/09/2019

From: Hor Yinnul
To: assignments@lkkauto.com; Admin A (admin-a@lkkauto.com)
Cc: Fong, Andy-SY; Chin, Lee-Ying; Abu Kassim, Noor Mariesa; Azlan, Syazairdina; Chan, Yoke Shi; Lim, Sheng Yang; Mithoosingh, Aashweenjeetkaur; Parthiban, Theerthan; Subramaniam, Divy
Sent: 18/09/2019 2:44:06 PM
Attachments: 27092019114303.pdf

Hi,

Please refer to the enclosed request from Roy & Partners.

Claim no : 6278988846SG003
Case Owner : Bernard Ler Ji Qian

If you have any queries/concerns, please let us know.
Kindly assist to assign **Marcus Chua** as Single Joint Expert as requested.

Thanks & Regards,

Hor Yin Rul (Viviane)
AIG
FNOL Adjuster I
Singapore FNOL | Claims Operations – Auto

Tel: 8001206556 | Ext: 1002208
Yinnul.Hor@aig.com | www.aig.sg

P: Simon
T: 2.43p.m
V: out
E: ✓

From: jiarong@roypartners.com.sg [mailto:jiarong@roypartners.com.sg]
Sent: Friday, September 27, 2019 12:30 PM
To: Hor, Yinnul
Cc: Fong, Andy-SY; Chin, Lee-Ying; Abu Kassim, Noor Mariesa; Azlan, Syazairdina; Chan, Yoke Shi; Lim, Sheng Yang; Mithoosingh, Aashweenjeetkaur; Parthiban, Theerthan; Subramaniam, Divyashini
Subject: RE: PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SKX8772X AND FY5018P ON 21/09/2019

Dear Sirs,

Our Client selects Marcus Chua from LKK as the Single Joint Expert for the pre-repair inspection

Regards,

Jia Rong

From: Hor, Yinnul
Sent: Fri, 27 Sep 2019 03:52:46 +0000
To: jiarong@roypartners.com.sg
Cc: Fong, Andy-SY; Chin, Lee-Ying; Abu Kassim, Noor Mariesa; Azlan, Syazairdina; Chan, Yoke Shi; Lim, Sheng Yang; Mithoosingh, Aashweenjeetkaur; Parthiban, Theerthan; Subramaniam, Divyashini
Subject: PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SKX8772X AND FY5018P ON 21/09/2019

Without Prejudice

Your Reference : MKR/103/9246/2019/as.jr
Our Reference : 6278988846SG003

Dear Sir/Madam,

We refer to your Notice of Accident of even date.

We intend to conduct a pre-repair survey of the damage to your client's/your customer's vehicle jointly with your client/your motor workshop. We propose to use one of the motor surveyors named in the attached list to conduct the joint pre-repair survey as a single joint expert:

Name of Surveyor	Company Name
AIG In House Surveyor	AIG Asia Pacific Insurance Pte Ltd
Lawrence Ng Chun Kee	Priority Services
Jeffrey Ong Leng Kiat	Priority Services
Jimmy Lee	Priority Services
EC Looi	Automobile Inspection Services Pte Ltd
Pang Kiah Keen (Frankie)	Formteam Adjusters Pte Ltd
Ng You Han	Formteam Adjusters Pte Ltd
Soon HanXin (Gary)	Formteam Adjusters Pte Ltd
Chow Bo Xiong	Formteam Adjusters Pte Ltd
Chua Soo Teck (Benjamin)	Formteam Adjusters Pte Ltd
Kalvin Ang	LKK Auto Consultants Pte Ltd
Xing Guo Qiang	LKK Auto Consultants Pte Ltd

Marcus Chua	LKK Auto Consultants Pte Ltd
Mohamad Taufikh	LKK Auto Consultants Pte Ltd
Adrian Ling	LKK Auto Consultants Pte Ltd
Mohammed Rasul	LKK Auto Consultants Pte Ltd
Kenneth Kong	LKK Auto Consultants Pte Ltd

Please let us know within two (2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert. You may select one or more of the listed motor surveyors. We will bear the cost of the pre-repair survey carried out by the single joint expert.

Thanks & Regards,

Hor Yin Ru (Viviane)
AIG
FNOL Adjuster I
Singapore FNOL | Claims Operations – Auto

Tel: 8001206556 | Ext: 1002208
Yim.Hor@aig.com | www.aig.sg

From: Chia Jia Rong [mailto:jiarong@roypartners.com.sg]
Sent: Friday, September 27, 2019 11:42 AM
To: Chan, Yoke Shi; Lim, Sheng Yang; Mithoosingh, Aashweenjeetkaur
Subject: [EXTERNAL] Pre Repair Inspection

This message is from an external sender; be cautious with links and attachments.

[Without Prejudice](#)
[Save as to cost](#)

Dear Sir,

Our Ref: MKR/103/9246/2019/as.jr
Your Ref: Your insured vehicle SKX 8772X

Dear Sirs,

CLAIMANT: RAZMAN BIN ABUL RAHIM
ROAD TRAFFIC ACCIDENT INVOLVING VEHICLE NOS. FY 5018P AND SKX 8772X ALONG TAMPINES AVE 5 AND TAMPINE AVE 2 ON 21.09.2019 AT ABOUT 0430 HOURS
We refer to the above matter.

We act for Razman bin Abdul Rahim, the owner of the motorbike No. **FY 5018P**.

We are instructed by our client to notify you of a road traffic accident on 21.09.2019 at about 0430 hours along Tampines Ave 5 involving our client's motorbike registration number **FY 5018P** and motor vehicle registration number **SKX 8772X** driven by your insured at the material time. A copy of the Singapore General Insurance report filed is enclosed.

As a result of the accident, our client's motorbike **FY 5018P** has been damaged. Before our client proceed to repair the damaged motor car, please let us know within **two (2) working days** of your receipt of this notice whether you would like to conduct a pre-repair survey of our client's motorbike **FY 5018P** at our client's repairer workshop, **M/s EROFIA MOTOR TRADING PTE LTD NO.1 KAKI BUKIT AVENUE 6 #02-62 AUTOBAY@Kaki Bukit Singapore 417883**. Your said surveyor may contact **Lee Lee** at 6752 7740 to arrange the said inspection. If we do not receive any reply from you within the stipulated timeline, our client shall proceed to repair the motor car without further reference to you.

With regards,

Chia Jia Rong
M/s Roy & Partners
133 New Bridge Road
#08-09
China Town Point
Singapore 059413
Tel : 6536 8466 Fax : 6536 1963
Email : jiarong@roypartners.com.sg

IMPORTANT NOTE: The information in this email is confidential and may also be privileged. If you are not the intended recipient, any use or dissemination of the information and any disclosure or copying of this email is unauthorized and strictly prohibited. If you have received this email in error, please notify the sender immediately. You should also delete and destroy all copies of it. Thank you.

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

View Received Message

This mail is associated with :

***FY5018P (6278988846SG)
[SKX8772X]**

TP

RAZMAN BIN ABDUL RAHIM

Sep 21 2019 4:00AM

[CONNECT4CAR PTE LTD]

Erofia Motor Trading Pte Ltd - (kaki Bukit)

[Reply](#) [Reply All](#) [Mark as Unread](#) [Print Message](#) [Delete Message](#) [Forward](#)

From AIG Asia Pacific Insurance Pte. Ltd. (Express) (AIG_SG_EXPRESS), sent on 14/02/2020 14:29 PM.

To LKK_HQ

Subject Alert - Adj Mandate Approved (S\$474.00) - FY5018P - Claim Handler: Ler, Bernard-JQ

Approved:474.00;Cost of Repairs 194 (Total loss value) Loss Use 280 (14days x \$20) Total 474

DOCUMENTS SUMMARY

There are no documents.

EROFIA MOTOR TRADING PTE LTD (201202259N)

1 Kaki Bukit Ave 6 #02-62
Singapore 417883
Tel: 67527740 Fax: 67528669
H/P: 90696165 (Mr Teo)

X
total loss

INVOICE

Number	Date	Page
FY5018P	15-Jan-20	1

YOUR REF:
VEHICLE NO: FY5018P
MAKE/MODEL: YAMAHA YBR125
NAME: AIG ASIA PACIFIC INSURANCE PTE LTD
ADDRESS: 78 SHENTON WAY #07-16
AIG BUILDING
SINGAPORE 079120

ACCIDENT INVOLVING SKX8772X AND FY5018P ON 21 SEPTEMBER 2019

TOTAL LOSS AS PER SURVEYOR'S RECOMMENDATION	S\$	194.00
LOSS OF USE (16DAYS X \$20.00/DAY) PRI & LOSS DA'	S\$	320.00

SUB-TOTAL: S\$ 514.00

SINGAPORE DOLLARS: FIVE HUNDRED AND FOURTEEN ONLY

TOTAL : S\$ 514.00

EROFIA MOTOR TRADING PTE LTD


.....

...CLAIM SUBFOLDER...(Pending for Survey Report)

Fastlane

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	23 Sep 2019 Edit Reg		27 Sep 2019 00:00 Edit Adj Rpt	S\$194.00 Edit Estimates	S\$194.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured: CONNECT4CAR PTE LTD , Co. Reg. No.: 201411459M									
Main Claimant: RAZMAN BIN ABDUL RAHIM , ID: S6802114F									
Vehicle Reg. No.:	FY5018P	Date of Loss:	21/09/2019 04:00 - :59 179 Months and 14 Days From LTA Reg Date (Man Yr)						
Claim Type:	TP / 6278988846SG	Policy/Cover Note No.:	(Comprehensive)						
Vehicle Reg. No. (Insured):	SKXB772X	Policy No. (Claimant):	5040756657-09						
Excess:									
Repairer:	Erofia Motor Trading Pte Ltd - (kaki Bukit) (HQ) 1 Kaki Bukit Avenue 6, #02-62 AutoBay @ Kaki Bukit, 417883 Kaki Bukit - Tel: 67527740 / 90696165								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Ler, Bernard-JQ] BernardJiQian.Ler@aig.com								
Claimant's Insurer:	NTUC Income Insurance Co-operative Ltd (HQ) - Tel:								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MARCUS CHUA] ... [Final Rpt due 08/10/2019]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
- AIG_SG_EXPRESS (14/02/2020): Alert - Adj Mandate Approved (S\$474.00) - FY5018P - Claim Handler: Ler, Bernard-JQ - AIG_SG_EXPRESS (13/02/2020): Alert - Adj Mandate Maintained - FY5018P - Claim Handler: Ler, Bernard-JQ									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*FY5018P (6278988846SG)
[SKX8772X]
TP
RAZMAN BIN ABDUL RAHIM
Sep 21 2019 4:00AM
[CONNECT4CAR PTE LTD]
Erofia Motor Trading Pte Ltd - (kaki Bukit)

Upload Documents			Upload Photos			Compose New Letter			Upload Video			Upload Audio			View View in Browser v		
Letters/Correspondences															1 per page v		☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)										Thumbnail		Print			
1	(Draft)	Third Party Express Settlement – Payment Breakdown										1	Edit				
Assessment Reports															1 per page v		☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)										Thumbnail		Print			
1	22/01/20 14:18	Adjuster Immediate Advice										1	Load HTM				
Photos/Images															3 per page v		☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)										Thumbnail		Print			
1	30/09/19 16:26	Chassis Number										1	Load JPG	☒			
2	30/09/19 16:27	Odometer Reading										1	Load JPG	☒			
3	30/09/19 16:27	General View										1	Load JPG	☒			
4	30/09/19 16:27	General View										1	Load JPG	☒			
5	30/09/19 16:27	General View										1	Load JPG	☒			
6	30/09/19 16:27	General View										1	Load JPG	☒			
7	30/09/19 16:27	General View										1	Load JPG	☒			
8	30/09/19 16:27	General View										1	Load JPG	☒			
9	30/09/19 16:27	General View										1	Load JPG	☒			
10	30/09/19 16:27	General View										1	Load JPG	☒			
11	30/09/19 16:27	General View										1	Load JPG	☒			
12	30/09/19 16:27	General View										1	Load JPG	☒			
13	30/09/19 16:27	General View										1	Load JPG	☒			
14	30/09/19 16:27	General View										1	Load JPG	☒			
15	30/09/19 16:27	General View										1	Load JPG	☒			
16	30/09/19 16:27	General View										1	Load JPG	☒			
17	30/09/19 16:27	General View										1	Load JPG	☒			
18	30/09/19 16:27	General View										1	Load JPG	☒			
19	30/09/19 16:27	General View										1	Load JPG	☒			
20	30/09/19 16:27	General View										1	Load JPG	☒			
21	30/09/19 16:27	General View										1	Load JPG	☒			
22	30/09/19 16:27	General View										1	Load JPG	☒			
23	30/09/19 16:27	General View										1	Load JPG	☒			
24	30/09/19 16:27	General View										1	Load JPG	☒			
25	30/09/19 16:27	General View										1	Load JPG	☒			
26	30/09/19 16:27	General View										1	Load JPG	☒			
27	30/09/19 16:27	General View										1	Load JPG	☒			
28	30/09/19 16:27	General View										1	Load JPG	☒			
29	30/09/19 16:27	General View										1	Load JPG	☒			
30	30/09/19 16:27	General View										1	Load JPG	☒			
31	30/09/19 16:27	General View										1	Load JPG	☒			
32	30/09/19 16:27	General View										1	Load JPG	☒			
33	30/09/19 16:27	General View										1	Load JPG	☒			
34	30/09/19 16:27	General View										1	Load JPG	☒			
35	30/09/19 16:27	General View										1	Load JPG	☒			
36	30/09/19 16:27	General View										1	Load JPG	☒			

Letters/Correspondences			1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
37	30/09/19 16:27	General View	 Load JPG	☒
38	30/09/19 16:27	General View	 Load JPG	☒
39	30/09/19 16:27	General View	 Load JPG	☒
Documentation			1 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	27/09/19 17:12	ACKNOWLEDGEMENT EMAIL TO AIG DD 27.09.2019	 Load PDF	
2	27/09/19 17:12	EMAIL FROM AIG DD 27.09.2019	 Load PDF	
3	27/09/19 17:12	TP GIA REPORT	 Load PDF	
4	22/01/20 12:56	LOD	 Load PDF	
5	22/01/20 12:56	DEREGISTRATION	 Load PDF	
6	22/01/20 13:00	PIR	 Load PDF	
7	14/02/20 14:39	COE Rebate	 Load PDF	
8	13/03/20 14:01	Release Voucher	 Load PDF	
9	13/03/20 14:01	AUTHORISATION TO ACT FORM	 Load PDF	
10	13/03/20 14:01	LETTER TO OI	 Load PDF	
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	30/09/19 14:33	OI GIA REPORT	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.			

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SKX8772X (Insd veh)	Model:	YAMAHA YBR125 124CC
	FY5018P (TP veh)		(M)
Date of Accident:	21/09/2019		

Global Sum Settlement	:	☐ Yes	☒ No
Repair Estimate	:	\$	0.00
Total Loss	:	\$	194.00
Loss of Use	:	\$	280.00
Rental (if any)	:	\$	0.00
LTA / GIA Search Fee	:	\$	0.00
Others:	:	\$	0.00
	:	\$	
Final Settlement Sum	:	\$	474.00

14.00 days at \$20.00 per day
days

Is Third Party Workshop GIA Registered? ☐ YES ☒ NO (Kindly indicate below)

A) For **Non GIA Registered Workshop:** Agreed Liability ____ 100 ____ (%)

B) For **GIA Registered Workshop:** BOLA Applicable: Yes/ No BOLA Scenario No: ____

BOLA Liability: ____ (%) Assessed Liability (*): ____ (%)

* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.

Remarks TOTAL LOSS

Payment Instruction: Payee's Breakdown			
1)	Erofia Motor Trading Pte Ltd	:	\$ 474.00
2)		:	\$

JOANNE LEE KHANG MIN

13 Mar
2020

LKK Auto Consultants Pte Ltd

Date

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report;
Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd (Co Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG19017079/UDA3Q2

Date: 13/03/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No:

Claimant

Vehicle No : FY5018P

Insured Vehicle No : SKX8772X

Date of Loss: 21/09/2019

Nature of Claim: TP

Claim No: 6278988846SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: FY5018P

Make & Model: YAMAHA YBR125, 124cc (M)

Engine No: JYM154FMI04405648

Reg. Date: 07/10/2004 (Man. Year: 2004)

Chassis No: LBPPCJLB440183728

Colour: Red

Odometer: 30679 km

Engine Capacity: 124 cc

Market Value/New Car

Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes

Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 80-90-18

Rear Tyre Size:

3.60-18

Front Left Side: FKR 5 mm

Rear Left Side:

FKR 5 mm

Front Right Side: 0 mm

Rear Right Side:

0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	0.00	0.00	0.00	
Approved Total (Overridden) (S\$)		194.00		
Nett Amount (S\$)	0.00	194.00	-194.00	
+ Loss of Use (14.0 x S\$20.00/day) (S\$)		280.00		
Nett Liability (S\$)		474.00		

INSPECTION

Date of Assignment: 27/09/2019

Date Inspected: 30/09/2019 Inspected At:

Erofia Motor Trading Pte Ltd - (kaki Bukit) (HQ)
 1 Kaki Bukit Avenue 6, #02-62
 AutoBay @ Kaki Bukit
 Singapore 417883

Estimated Period of Repair: 0.0 days

Adjuster: MARCUS CHUA

Manager: CHAN JIA LE

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

SPECIAL REMARKS

PLEASE BE INFORMED OWNER THAT THE VEHICLE NOT ECONOMICAL FOR REPAIR.

MARKET VALUE : \$200.00

LTA REIMBURSEMENT VALUE (RV) : \$6.00

NETT VALUE : \$194.00

IN VIEW OF THE ABOVE, THE VEHICLE IS UNECONOMICAL TO BE REPAIRED.

REPAIR DETAILS

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >