

Surveyor: Kalvin

ASSIGNMENT (Office)

From (Person): Dillen Senthilan So

of

TM1

Date/Time: 30.9.19 9.55 a.m

Estimated Cost: Bill to:

OD TP+WS/TP RES/OD RES/EVA/INV/MV/CS

To Inspect Vehicle No: SHC 1760Y

Insured:

SLV 4957E

at Workshop m/s ComfoAdulgro

Tel:

6248300

of 59 Ioyang Dore

Policy No: MP 000843

Claim No:

M1907589

Sum Insured:

Excess:

Make of Veh:

D.O.A. 27.9.19

(Client's Record)

CA / REV / REP. / REV 24 HRS

Date/Time: 30.9.19 10.36 a.m

Person Contacted:

Jumadi

H.O.D. Endorsement:

Vehicle: IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	SHC 1760Y - CSI FC1 18000008/Arbn2 DOD - 26/12/2017
	SLV 4957E-x

Surveyor: Kelvin

REF:

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspected Vehicle No: _____
 at Workshop m/s _____
 of _____
 Insured: _____
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
 repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____
 IDAC Accident Rpt: _____ Consistent?: Yes or No
 GIA / PR Seen: _____ Consistent?: Yes or No
 Est. Repairs: _____ days Res.: Yes or No
 Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SHC 1760 Y Yr Regn: 23 Aug, 2017
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or
 Make: Toyota Prius C.C. 1798
 Colour: Blue A/C: Insured / Std / NI / NA
 Sp. Reading: 282444 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: 570KDJF4603563762
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: In order / Jammed / Leaked / Burnt or
 Brake: In order / Jammed / Leaked / Burnt or
 Modi: Nil / S/Rim / STD A/Rim or
 Tyre Size: F: 195/65R15
 R: _____
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or Garanti
 Front 7 mm Rear 7 mm
 R/Bal. 7 mm L/Bal. 7 mm
 D.O.A. 27/9/19 D.O.I. 30/9/19
 Survey held at C DHE (Loyang)
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
O/S Front
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
3/10/19	Under PIP \$1990.68 / 2 days. Cred. 3004.19 (60%)
	Taka PIP

RECEIVED 03 OCT 2019

Date/Time, File Pass to?

☐ : Prel. Report
☒ : Final Report

1) 3/10 Typist

Date/Time, File Return to?

2)

Days Of Repair: 2Resurvey No. of Trip: 1Add Fee: ☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)Survey Fee: 250

Transportation: _____

Photos

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	27 Sep 2019 Sendback Est	27 Sep 2019 18:37 S\$4,994.87	30 Sep 2019 09:55 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	----------

CLAIM SUBFOLDER DETAILS

Insured:	SECTION CREDIT & MOTOR LEASING PTE LTD, Co. Reg. No.: 198703128Z		
Main Claimant:	CTPL		
Vehicle Reg. No.:	SHC1760Y	Date of Loss:	27/09/2019 14:00 - :59 [25 Months and 4 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / M1907589	Policy/Cover Note No.:	MF000843 (Comprehensive) Coverage: 15/10/2018 - 14/10/2019
Vehicle Reg. No. (Insured):	SLV4957E	Policy No. (Claimant):	
Repairer:	ComfortDelGro Engineering Pte Ltd (Loyang) 59 Loyang Drive, 508969 Loyang - Tel: 6214 8300		
Handling Insurer:	Tokio Marine Insurance Singapore Ltd (HQ) - Tel: 6221 6111 ... [Handled by Dillen Senthilan so Selvarajoo]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 09/10/2019]		

ASSOCIATED MAIL RECEIVED

There are no mail for this case.

View All

Compose Case Mail

ALL ASSOCIATED TASKS

Due Date	Priority	Type	Task Group	Subject	Handler	View All	Search Tasks	Create New Task	Complete
No results.						Assigned By	Completed On	Created On	Done?

OMFORDDELGRO ENGINEERING

member of COMFORTDELGRO

ComfortDelGro Engineering Pte Ltd

205 Braddell Road Singapore 578701
Mainline + 65 6383 8280 Facsimile + 65 6290 9755

Workshops

59 Loyang Drive Singapore 508959
383 Sin Ming Drive Singapore 575717
45 Pandan Road Singapore 609296
10 Ubi 2911 Singapore 600099

24 Senoko Loop Singapore 758156
7 Sungei Kadut Way Singapore 728791
501 Yehun Industrial Park A Singapore 768732

Date/Time: 27.09.2019 17:40 Page : 1

Team: ARC Repair TP(CLSO)1

JOB CARD

Sales Order:

JC NO.: 305336967

OMER:

COMFORT TRANSPORTATION PTE LTD

7010045

S

OMER NO.

383 SIN MING DRIVE

ESS

Singapore SINGAPORE 575717

65508755

(R)

(O)

(P)

JUNT CARD NO.

REGN NO.:

SHC1760Y

MILEAGE

MAKE:

TOYOTA

FUEL

E.....1/2.....F

MODEL

PRIUS HYBRID(G4)27.09.2019 15:45

DATE/TIME IN

YR OF MANU

23.08.2017

TARGET DATE

CHASSIS CODE

JTDKB3FU603563762

COMPLETION DATE/TIME

JOB DESCRIPTION


Accident Date: 27.09.2019

NATURE: 3P 27.09.19

S/NO

LABOR CODE

DESCRIPTION



KED & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

edgement Slip

Exit Pass

to.:

SHC1760Y

LIMITS

Vehicle No.:

SHC1760Y

Service Advisor

Signature/Date

Name of Service Advisor

Date

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	27/09/2019 16:38
Date Of Accident	27/09/2019 14:00
Exact Location Of Accident	ORCHARD LINK TWDS BIDEFORD RD B4 ORCHARD RD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHC1760Y
Insured/Policyholder	
Name Of Registered Owner	COMFORT TRANSPORTATION PTE LTD
Co Reg No	199303821R
Email Address	FLEETSAFETY@CDGTAXI.COM.SG
Mobile Phone No	
Alternative Phone No	OFFICE-65508768

Vehicle Particulars

Manufacturer	TOYOTA
Model	PRIUS HYBRID 4G

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category TAXI

Insurance Company

Name of Insurance Company	MS FIRST CAPITAL INSURANCE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	YES
Policy Number	D-18088936MFSH
Cover Note Number	

Driver

Name of Driver	TAN WEI SHEE
NRIC No	S7430521J
Date Of Birth	15/09/1974
Occupation	OUTDOOR
Date Of Driving Pass	01/03/2004
Driving Experience	15 YEARS AND 6 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-90933469
Fax Number	
Contact Number	
Email Address	ANDYTANBOY@GMAIL.COM

Address	BLK 669 WOODLANDS RING RD
	#09-361
Postcode	730669
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - TAXI DRIVER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	SIDE SWIPE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : -
	GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER ATTACHED

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	-
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLV4957E
Vehicle Make/Model/Colour	TOYOTA
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	HOFFER THOMAS WALTER
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	

Nature Of Damage

LH REAR

No. Of Passenger (Including Driver)

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

COMFORT TRANSPORTATION PTE LTD
CO. REG. NO. 190002221R

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name: Loke Wei Yiong
NRIC/FIN No.:

GIA/RIAC Sketch Plan Form V3

4. 9
3. 9

SKETCH PLAN

Orchard Lane
Tends Biddford
Road

A: SHC 1760 Y
B: SLV 4954 E



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 27/9/19 at about 14:00hrs, I was driving
at above said location with a female passenger onboard.
Shortly veh B cut into my lane, it left rear portion
hit & grazed onto the front right portion of my taxi.
Scene photo taken. No injury reported.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

COMFORT TRANSPORTATION PTE LTD
CO. REG. NO. 199303821R

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Loke Wei Yeng

ComfortDelGro Engineering Pte Ltd (Co.Reg.No:199506048W)
59 Loyang Drive
Singapore 508969
Tel: 6214 8300

TS

CP/P

Lkk-Kalvin

TP INSURER: Tokio Marine Insurance Singapore Ltd (HQ)
CTPL

Singapore

PARTICULARS OF CLAIM

Claim Type:	THIRD PARTY	Ref. No:	
Policy No:		Date of Loss:	27/09/2019
Vehicle Reg. No.:	SHC1760Y	Driveable?	NO
Party At Fault:	UNKNOWN		
Make/Model:	TOYOTA PRIUS, 1.8 HYBRID CVT (A)	Vehicle Reg. Date:	23/08/2017
Vehicle Colour:	BLUE	Gen Condition:	GOOD
Engine No:	2ZRS062502	Chassis No:	JTDKB3FU603563762
Odometer:	0 KM		
Paint Type:			
List Item Discount:	25.00 %		
Total Loss?	NO		
Est. Duration of Repair (day)	4		
Present Location:	COMFORTDELGRO ENGINEERING PTE LTD (LOYANG)		

COST OF CLAIMS	Amount
Parts	3,583.87
Miscellaneous Items	11.00
Labour	1,400.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (S\$)	4,994.87
+ GST 7.00% (S\$)	349.64
Nett Amount (S\$)	5,344.51

This claim is handled by: LIM TIEN SIONG

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS**Reference**

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 27 Sep 2019)

Parts: 144 TOYOTA PRIUS 1.8 HYBRID CVT (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: ComfortDelGro Engineering Pte Ltd/SHC1760Y/27/09/2019 18:37

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*FRT BUMPER <i>Rebored</i>	25.00	0.00	*490.50 FL
2	1		*FRT BUMPER SIDE BRKT RH <i>Rebored</i>	25.00	0.00	*77.00 FL
3	1		*FRT BUMPER RETAINER RH <i>Rebored</i>	25.00	0.00	*32.00 FL
4	1		*FRT FENDER RH <i>Rebored</i>	25.00	0.00	*933.10 FL
5	1		*FRT FENDER SHIELD RH <i>Rebored</i>	25.00	0.00	*198.50 FL
6	1		*HEADLAMP RH <i>Rebored</i>	25.00	0.00	*2,530.10 FL
7	1		*FRT WHEEL CAP RH <i>Rebored</i>	25.00	0.00	*175.80 FL
8	1		*FRT DAVANTI TYRES RH <i>Rebored</i>	0.00	0.00	*216.00 F
9	1		*FRT FENDER HYBRID RH <i>Rebored</i>	25.00	0.00	*53.50 FL

F=Franchise part. L=ListItemDisc.

Sub Total (S\$)

4,706.50

- List Item Discount on L Items (S\$)

1,122.63

Total Parts (S\$)

3,583.87

ComfortDelGro Engineering Pte Ltd/SHC1760Y/27/09/2019 18:37. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No Qty Particulars

Amount

Miscellaneous Items

1 1 OD/TP Case (Insurer)

11.00

Sub Total (S\$)

11.00

Estimates on Labour

No Particulars

Lab.Type

Amount

Labour Items

1 PANEL BEATING

New

~~700.00~~ 320

2 SPRAY PAINTING

New

~~500.00~~ 400

3 CHECK LIGHTING

New

~~40.00~~ X

4 TUFF KOTE

New

~~40.00~~ 20

5 WHEEL ALIGNMENT

New

~~120.00~~ X

Gross Labour Cost (S\$)

1,400.00

ComfortDelGro Engineering Pte Ltd/SHC1760Y/27/09/2019 18:37. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

Kalin 10000

30/9/19 1020L

2 Lp.

P/P

Before Paint photo

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Our Job Ref No : 305336967

Date : 02/10/19

ComfortDelGro Engineering Pte Ltd
59 Loyang Drive Singapore 508969
Fax: 6546 8156

FINALIZATION FORM

To : LKK

Fax :

Attn : KALVIN ANG

Vehicle Reg No. : SHC1760Y

Date of Accident : 27-Sep-19

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

1. The repair job shall bill to: TOKIO MARINE --- SLV4957E
2. The finalized amount shall be:

(a) Spare Parts after List discount	\$1,239.68
(b) Labour Charges	\$751.00
Total for Part-By-Part Repair Cost	\$1,990.68
(c.) Lumpsum Repair (if applicable)	
Total for Lumpsum repair cost after Less: 20%	
Final Lumpsum Repair cost	

3. Estimated normal period for repairs: 2 working days.

4. We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days

5. Thank you for your assistance.

We confirm the estimates and
finalized amountSignature : 

Name : LIM T S

Tel : 62148398

Fax : 65468156

Signature : 

Name : KALVIN

Date : 3/10/19

For Official Use Only

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid		NO		
3. Survey Fees	-----			
4. LTA Search Fee	\$7.49			
5. Medical Fees (on behalf of driver, if applicable)				
6. Overrun				

Remarks:

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE

Date: 01.10.2019

Time: 18:40:09

Page: 1

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305336967
REGN NO : SHC1760Y
MILEAGE : 0000000000
MAKE : TOYOTA
MODEL : PRIUS HYBRID(G4)
DATE OF REGN : 23.08.2017
DATE/TIME IN : 27.09.2019 15:45
ACCIDENT DATE : 27.09.2019

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001 04-01-0302-2292-A	FRT BUMPER	1	490.50	25.00	367.87
0002 04-01-0302-0573-A	FRT FENDER RH	1	933.10	25.00	699.82
0003 03-01-0302-2057-G	FRT WHEEL CAP RH	1	175.80	25.00	131.85
0004 04-01-0302-2297-G	FRT FENDER (HYBRID) RH	1	53.50	25.00	40.12

SUB-TOTAL : 1,239.66

JOB NATURE

0000 PB	PANEL BEATING	320.00
0001 SP	SPRAYPAINT CHARGE	400.00
0002 20-00	TUFF COAT ON AFFECTED PARTS.	20.00
0003 20-05	TP MERIMEN	11.00

SUB-TOTAL : 751.00

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE

Date: 01.10.2019

Time: 18:40:09

Page: 2

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305336967
REGN NO : SHC1760Y
MILEAGE : 0000000000
MAKE : TOYOTA
MODEL : PRIUS HYBRID(C
DATE OF REGN : 23.08.2017
DATE/TIME IN : 27.09.2019 15:45
ACCIDENT DATE : 27.09.2019

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

Limfs

TOTAL : 1,990.66

MVA NAME & SIGNATURE
DATE :

AUTHORISED : YES / NO
SURVEYOR NAME & SIGNATURE
DATE :

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	27 Sep 2019 Sendback Est	27 Sep 2019 18:37 S\$4,994.87	30 Sep 2019 09:55 Edit Adj Rpt	S\$1,990.67 Edit Estimates	S\$1,990.67 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS									
Insured:	SECTION CREDIT & MOTOR LEASING PTE LTD , Co. Reg. No.: 198703128Z								
Main Claimant:	CTPL								
Vehicle Reg. No.:	SHC1760Y	Date of Loss:	27/09/2019 14:00 - :59 [25 Months and 4 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / M1907589	Policy/Cover Note No.:	MF000843 (Comprehensive) Coverage: 15/10/2018 - 14/10/2019						
Vehicle Reg. No. (Insured):	SLV4957E	Policy No. (Claimant):							
		Excess:	S\$1,500.00						
Repairer:	ComfortDelGro Engineering Pte Ltd (Loyang) 59 Loyang Drive, 508969 Loyang - Tel: 6214 8300								
Handling Insurer:	Tokio Marine Insurance Singapore Ltd (HQ) - Tel: 6221 6111 ... [Handled by Dillen Senthilan so Selvarajoo]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KALVIN ANG WEI KUN] ... [Final Rpt due 09/10/2019]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

SHC1760Y (M1907589)
[SLV4957E]
TP
CTPL
Sep 27 2019 2:00PM
[SECTION CREDIT & MOTOR LEASING PTE LTD]
ComfortDelGro Engineering Pte Ltd

Upload Documents Upload Photos Compose New Letter

View View in Browser ▼

Assessment Reports				1 per page ▼	✓
No	Finalized On	ComfortDelGro Engineering Pte Ltd (Loyang)		Thumbnail	Print
1	27/09/19 18:37	Repairer Estimates	i	Load HTM	

Photos/Images				3 per page ▼	✓
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	01/10/19 08:18	General View	i	Load JPG	✓
2	01/10/19 08:18	General View	i	Load JPG	✓
3	01/10/19 08:18	General View	i	Load JPG	✓
4	01/10/19 08:18	General View	i	Load JPG	✓
5	01/10/19 08:18	General View	i	Load JPG	✓
6	01/10/19 08:18	General View	i	Load JPG	✓
7	01/10/19 08:18	General View	i	Load JPG	✓
8	01/10/19 08:18	General View	i	Load JPG	✓
9	01/10/19 08:18	General View	i	Load JPG	✓
10	01/10/19 08:18	General View	i	Load JPG	✓
11	01/10/19 08:18	General View	i	Load JPG	✓
12	01/10/19 08:18	General View	i	Load JPG	✓
13	01/10/19 08:18	General View	i	Load JPG	✓
14	01/10/19 08:18	General View	i	Load JPG	✓
15	01/10/19 08:18	General View	i	Load JPG	✓
16	01/10/19 08:18	General View	i	Load JPG	✓
17	01/10/19 08:18	General View	i	Load JPG	✓
18	01/10/19 08:18	General View	i	Load JPG	✓
19	01/10/19 08:18	General View	i	Load JPG	✓
20	01/10/19 08:18	General View	i	Load JPG	✓
21	01/10/19 08:18	General View	i	Load JPG	✓
22	01/10/19 08:18	General View	i	Load JPG	✓
23	01/10/19 08:18	General View	i	Load JPG	✓
24	01/10/19 08:18	General View	i	Load JPG	✓
25	01/10/19 08:18	General View	i	Load JPG	✓
26	01/10/19 08:18	General View	i	Load JPG	✓
27	01/10/19 08:18	General View	i	Load JPG	✓
28	01/10/19 08:18	General View	i	Load JPG	✓
29	01/10/19 08:18	General View	i	Load JPG	✓
30	02/10/19 08:39	Reinspection Photo	i	Load JPG	✓
31	02/10/19 08:39	Reinspection Photo	i	Load JPG	✓
32	02/10/19 08:39	Reinspection Photo	i	Load JPG	✓

Documentation				1 per page ▼	✓
No	Finalized On	ComfortDelGro Engineering Pte Ltd (Braddell)		Thumbnail	Print
1	07/10/19 14:05	LOD, Invoice, LOR, Mileage Record, LA, LTA Search Fee	i	Load PDF	
No	Finalized On	ComfortDelGro Engineering Pte Ltd (Loyang)		Thumbnail	Print
1	27/09/19 18:38	E-filed GIA report	i	Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST[Reset](#) [Save](#) [Print](#)

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Repairer ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/TMI19017119/K1TF3S2

Date: 08/10/2019

REFERENCE

Handling Insurer: Tokio Marine Insurance Singapore Ltd

Policy No: MF000843

Claimant Vehicle No : SHC1760Y

Insured Vehicle No : SLV4957E

Date of Loss: 27/09/2019

Nature of Claim: TP Claim No: M1907589

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SHC1760Y

Make & Model: TOYOTA PRIUS, 1.8 HYBRID CVT (A)

Engine No: 2ZRS062502

Reg. Date: 23/08/2017 (Man. Year: 2017)

Chassis No: JTDKB3FU603563762

Colour: Blue

Odometer: 282444 km

Engine Capacity: 1798 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Fair	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	Good

CONDITION OF TYRES

Front Tyre Size: 195/65R15

Rear Tyre Size: 195/65-R15

Front Left Side: Davanti 7 mm

Rear Left Side: Davanti 7 mm

Front Right Side: Davanti 7 mm

Rear Right Side: Davanti 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,583.87	1,239.67	2,344.20	65.41
Miscellaneous Items	11.00	11.00	0.00	0.00
Labour	1,400.00	740.00	660.00	47.14
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	4,994.87	1,990.67	3,004.20	60.15
+ GST 7.00/7.00% (S\$)	349.64	139.35	210.29	60.14
Nett Amount (S\$)	5,344.51	2,130.02	3,214.49	60.15

INSPECTION

Date of Assignment:	30/09/2019	Present Location:	ComfortDelGro Engineering Pte Ltd (Loyang)
Date Inspected:	30/09/2019	Inspected At:	ComfortDelGro Engineering Pte Ltd (Loyang) 59 Loyang Drive Singapore 508969
Estimated Period of Repair:	2.0 days		

Adjuster: KALVIN ANG WEI KUN

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

DIFFERENT BY 1 CENT. FINALIZE CONFIRMED AMOUNT \$1,990.68

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 08 Oct 2019)
Parts:	144	TOYOTA PRIUS 1.8 HYBRID CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SHC1760Y)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT BUMPER	Deformed	490.50 FL	*490.50 FL
2	1		*FRT BUMPER SIDE BRKT RH	Serviceable	77.00 FL	*- FL
3	1		*FRT BUMPER RETAINER RH	Serviceable	32.00 FL	*- FL
4	1		*FRT FENDER RH	Buckled	933.10 FL	*933.10 FL
5	1		*FRT FENDER SHIELD RH	Serviceable	198.50 FL	*- FL
6	1		*HEADLAMP RH	Serviceable	2,530.10 FL	*- FL
7	1		*FRT WHEEL CAP RH	Grazed	175.80 FL	*175.80 FL
8	1		*FRT DAVANTI TYRES RH	Serviceable	216.00 F	*- F
9	1		*FRT FENDER HYBRID RH	Necessary	53.50 FL	*53.50 FL
					Sub Total (\$\$)	4,706.50 1,652.90
					- List Item Discount on L Items 25.00/25.00% (\$\$)	1,122.63 413.23
					Total Parts (\$\$)	3,583.87 1,239.67

F=Franchise part. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
<u>Miscellaneous Items</u>				
1	1	OD/TP Case (Insurer)	11.00	11.00
Sub Total (S\$)			11.00	11.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING	New	700.00	320.00
2	SPRAY PAINTING	New	500.00	400.00
3	CHECK LIGHTING	New	40.00	0.00
4	TUFF KOTE	New	40.00	20.00
5	WHEEL ALIGNMENT	New	120.00	0.00
Gross Labour Cost (S\$)			1,400.00	740.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >