

22/06/2002

ASS. REC. BY:

REF:

CS3/III 19012672/Fy8302-1

Special Instruction:

Survivor: Ram

ASSIGNMENT (Office)

From (Person):

Gabriel Wee

of

III

Date/Time:

28/9/2019

18/7/19 @ 10:30am

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SMD 4827E

Insured:

SH 8944G

at Workshop m/s

AT performance

Tel:

9686 6219

of

160 Sin Ming Drive # 0718/17

Policy No:

Claim No:

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

13/07/2019

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement

Date/Time:

12:20pm @ 10/7/19

Person Contacted:

Alvin

Vehicle IN/OUT

Date/Time

Action/Instruction ( x ) Estimate

SMD 4827E - X

SH 8944G - CS/TMI/8020/44/14/16/2

28/9/19/2019

Dismantle: 19/7/2019 @ 3.50pm.

After repair: 23/7/2019 @ 4.08pm.

check with RAM. Submit \$2550. 4 working days 4/10/2019  
(Red \$3078.01, 54%)

9/10/19 File Pass to Typist

RECEIVED 09 OCT 2019

PRS

# ASSIGNMENT

Form: Date: 18/07/2019

Estimated Cost:

OD (TP) WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SMD 4827E

at Workshop n/s: AT Performance

at 160 Sin Ming Drive # 07-18 / 19

Insured: Autocity, 575722

Policy No.

Claims No.

Sum Insured: Excess:

(Client's Record)

Make of Veh: Mr. Alvin @ 9686 6219

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Report Consistent? Yes or No

GIA / PR Seen: Consistent? Yes or No

Est. Repairs: days Res: Yes or No

Lum Sum: % 3 Val: Yes or No

CA / REV / REP. / 24 HRS (wp)

Date: Person Contacted:

Vehicle: IN / OUT

Veh No: SMD 4827E Vi Regn: DEC 2013

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: BMW 316i CC 1598

Colour: WHITE A/C: Insured / Std / NI / NA

Sp. Reading: 115812 T/Radio: Insured / Std / NI / NA

Eng/No: -

C/No: WBA3A16070ND36166

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 245 / 40 R18

R: 245 / 40 R18

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal: 6 mm R/Bal: 6 mm

L/Bal: 6 mm L/Bal: 6 mm

D.O.A: 13/07/19 D.O.I: 18/07/19 0302pm

Survey held at: AT PERFORMANCE

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision

Date / Time	Action / Instruction
	Repair days: 3 days
	Range: \$2000 - \$3000
	MV: \$66000
	PV: \$53825
	NV: \$12000

Date/Time: File Pass to?

☐: Prel. Report

ii

☐: Final Report

Date/Time: File Return to?

iii

Days Of Repair:

Resurvey No. of Trip: 2

Add Fee: ☐ Site Insp (\$

☐ Interview (\$

☐ ... (\$

☐ ... (\$

Survey Fee:

Transportation

... (\$

... (\$

... (\$

... (\$

... (\$

20

11

131

PRS

**Nivitha (LKK Auto)**

---

**From:** Stanley Lai <stanley.lai@iii.com.sg>  
**Sent:** Saturday, 28 September 2019 12:07 PM  
**To:** 'sur@lkkauto.com'; Admin-D (LKKAuto)  
**Cc:** Mekavathanan Sarangapani; Pooi Chin Han Daniel  
**Subject:** III REF: MCT19070375 | REQUEST PAPER SURVEY TP VEH SMD4827E

Dear Sir/Mdm,

TP vehicle seems unscathed, please adjust cost of repairs - S\$4.5K accordingly.  
LOD uploaded and rights granted to you in Merimen.

**Accident Photo**



Thank you.

Warmest regards,  
Stanley Lai  
**Motor Claims Department**  
**India International Insurance Pte Ltd**  
64 Cecil Street #04-02 IOB Building  
Singapore 049711  
Tel: 6347 6100 Ext 206 Fax: 6224 4174  
**S&P 'A-' rated Company**



INDIA  
INTERNATIONAL  
INSURANCE  
SOUTH AFRICA  
INCORPORATED IN 1987

This email is intended solely for the person to whom it has been addressed. It may contain confidential and/or legally privileged information. If you are not the person for whom this e-mail was intended, or if this e-mail has reached you by mistake, please delete it immediately and inform us of the error and also be hereby notified that any use, distribution, transmission, printing, copying or dissemination of this information in any way or in any manner is strictly prohibited and may be unlawful. Internet communications may not be entirely secure or accurate as information could be intercepted, corrupted, lost, delayed or contain viruses. Therefore, we do not accept liability for any errors or omissions in the content of this message or any delay in delivery which may arise as a result of Internet transmission or any modification.

\*\*\*\*\*  
 \*\*\* TX REPORT \*\*\*  
 \*\*\*\*\*

TRANSMISSION OK

TX/RX NO 1834  
 RECIPIENT ADDRESS 65330313  
 DESTINATION ID  
 ST. TIME 24/09 10:50  
 TIME USE 00'28  
 PAGES SENT 2  
 RESULT OK



18/09 2019 11:57 FAX 63383536

HIN TAT

0001/0002

# HIN TAT AUGUSTINE & PARTNERS

UEN NO. 53130863D

*Associates of Solicitors Commissioners For Outlets Notaries Public*

20 UPPER CIRCULAR ROAD  
 #02-10/12 THE RIVERWALK  
 SINGAPORE 058416  
 TEL : (65) 6533 0212  
 FAX : (65) 6533 0313

(65) 6338 3536 (Direct Fax)  
 Service By Fax Not Accepted

WEBSITE: www.htapartners.com.sg  
 WRITER : GONG CHIN NAM (chinam@htapartners.com.sg)  
 SECRETARY : RUBY ONG (ruby@htapartners.com.sg)

In Association with:  
 Strohal Legal Group Pte Ltd  
 International Legal Consultants

Our Ref : TCL.GCN.ro.50449.19.at  
 Your Ref : SH 8944G

18 September 2019



Comfort Transportation Pte Ltd  
 383 Sin Ming Drive  
 GAS Building  
 Singapore 575717

By Certificate of Posting (w/o encl)  
 (for your information only)

India International Insurance Pte Ltd  
 64 Cecil Street  
 #05-00 IOB Building  
 Singapore 049711  
 Attn : Mr Daniel Pooi / Motor Claims Department

By Hand &amp; By Fax (w/o encl)

Dear Sirs,

ACCIDENT INVOLVING SMD 4827E & SH 8944G ALONG SERVICE ROAD OF BLOCK  
 813 JELlicoe ROAD ON 13 JULY 2019 @ 0930HRS

We act for Kong Hui Long Joleen, the owner of motor vehicle no. SMD 4827E, in relation to the  
 above-captioned road traffic accident.

We are instructed that you were the owner and/or the insurers of motor vehicle no. SH 8944G at the  
 material time. We are further instructed that the accident was caused by authorized driver and / or  
 your insured driver's negligence in the driving, control and/or management of your insured vehicle.  
 As a result of the accident, our client's vehicle was damaged and our client has been put to loss and  
 expense, particulars of which are as follows:

1. Cost of Repair

SMD 4827E

TPPD

PRESERVE

TPPI

PRESERVE

UNINSURED LOSS

PRESERVE

SUBRO

PRESERVE

LPPN

INVESTIGATION FEE

SURVEY FEES

LEGAL FEES

OTHERS

FRAUD CHECK

UPLOAD TO MERIMEN

GRANT RIGHTS

MCT/

1907 0375

101/DP  
(5K) 72

22

(261)

P.S.

# HIN TAT AUGUSTINE & PARTNERS

Advocates & Solicitors Commissioners For Oaths Notaries Public

UEN NO. 53130863D

20 UPPER CIRCULAR ROAD  
#02-10/12 THE RIVERWALK  
SINGAPORE 058416  
TEL : (65) 6533 0212  
FAX : (65) 6533 0313

WEBSITE: www.htapartners.com.sg  
WRITER : GONG CHIN NAM (chinnam@htapartners.com.sg)  
SECRETARY : RUBY ONG (ruby@htapartners.com.sg)

In Association with:  
Stroh Legal Group Pte Ltd  
International Legal Consultants

Our Ref : TCL.GCN.ro.50449.19.at  
Your Ref : SH 8944G

18 September 2019



2019 ✓

Comfort Transportation Pte Ltd  
383 Sin Ming Drive  
GAS Building  
Singapore 575717

By Certificate of Posting (w/o encl)  
(for your information only)

India International Insurance Pte Ltd  
64 Cecil Street  
#05-00 IOB Building  
Singapore 049711  
Attn : Mr Daniel Pooi / Motor Claims Department

By Hand & By Fax (w/o encl)

Our Ref: MT/19070375  
Name: Daniel  
Date: 20/9/19  
India International Insurance P.L.

Dear Sirs,

**ACCIDENT INVOLVING SMD 4827E & SH 8944G ALONG SERVICE ROAD OF BLOCK 813 JELlicoe ROAD ON 13 JULY 2019 @ 0930HRS**

We act for Kong Hui Long Joleen, the owner of motor vehicle no. SMD 4827E, in relation to the above-captioned road traffic accident.

We are instructed that you were the owner and/or the insurers of motor vehicle no. SH 8944G at the material time. We are further instructed that the accident was caused by authorized driver and / or your insured driver's negligence in the driving, control and/or management of your insured vehicle. As a result of the accident, our client's vehicle was damaged and our client has been put to loss and expense, particulars of which are as follows:

1. Cost of Repairs	S\$4,500.00
2. Rental Charges (6 days x \$150.00/day)	S\$ 900.00
3. Survey Report Fees	S\$ 512.00
4. LTA Search Fee	S\$ 7.49
5. Costs (inclusive of GST)	S\$ 749.00
6. Incidentals	S\$ 50.00
Total	<u>S\$6,718.49</u>

.../Page 2

TAN HIN TAT  
AUGUSTINE SOH KIENG YEOW  
SEAN LIM THIAN SIONG  
TANG CHI LOONG

WOO FOONG LIN  
TAN E-FANG  
CLAIRE THAM LI MEI

CAROLYN LIM MAY LEAN  
HO KIM FOONG  
SERENA GOH MAE LI  
GONG CHIN NAM  
MOHD ZIKRU B MOHD MUZAMMIL  
CHRISTINE CHUAH HUI FEN  
MARILYN HO SU FEN  
ANDREW PATRICK HILL  
THIAN RUI LING

CONSULTANTS: LIM KIA TONG  
JANET WEE-TAN

eLitigation

**HIN TAT AUGUSTINE & PARTNERS**

Page No. 2

Our Ref. TCL.GCN.ro.50449.19.at

Your Ref. SH 8944G

Date : 18 September 2019

The following supporting documents are enclosed herewith: -

1. Copy of Singapore Accident Statement by SMD 4827E;
2. Copy of Certificate of Insurance by ECICS Limited;
3. Copy of Final Repair Bill from A T Performance;
4. Copy of Rental Invoice and Rental Agreement from T5 Auto Pte. Ltd;
5. Copy of LTA search result of YP 1298X;
6. Copy of Survey Invoice & Survey Report from Premier Appraiser Services; and
7. **36 pcs of original** photographs of motor vehicle no. SMD 4827E.

Please note that you / your authorized driver and/or your insured driver should send to us an acknowledgement of receipt of this letter within **fourteen (14)** days of receipt of this letter, failing which our client will have no alternative but to commence proceedings against you / your authorized driver and/or your insured driver without further notice to you / your authorized driver and/or your insured driver.

Please note that if you / your authorized driver and/or insured driver have a counterclaim against our client arising out of the accident, you / your authorized driver and/or your insured driver are also required to send us a letter giving full particulars of the counterclaim together with all relevant supporting documents within **eight (8)** weeks of your receipt of this letter.

Please note that our client's claim is in respect of her property damage claim and is strictly without prejudice to the uninsured losses and/or injury claim (if any).

Yours faithfully,

  
**GONG CHIN NAM**

Enc.

cc: client

By fax

# HIN TAT AUGUSTINE & PARTNERS

Advocates & Solicitors Commissioners For Oaths Notaries Public

20 UPPER CIRCULAR ROAD  
#02-10/12 THE RIVERWALK  
SINGAPORE 058416  
TEL : (65) 6533 0212  
FAX : (65) 6533 0313

(65) 6338 3536 (Direct Fax)  
Service By Fax Not Accepted

WEBSITE: [www.htapartners.com.sg](http://www.htapartners.com.sg)  
WRITER : GONG CHIN NAM ([chinnam@htapartners.com.sg](mailto:chinnam@htapartners.com.sg))  
SECRETARY : RUBY ONG ([ruby@htapartners.com.sg](mailto:ruby@htapartners.com.sg))

In Association with  
*Strohal Legal Group Pte Ltd*  
International Legal Consultants

Our Ref : TCL.GCN.ro.50449.19.at  
Your Ref : SH 8944G

18 September 2019

Comfort Transportation Pte Ltd  
383 Sin Ming Drive  
GAS Building  
Singapore 575717

By Certificate of Posting (w/o encl)  
(for your information only)

India International Insurance Pte Ltd  
64 Cecil Street  
#05-00 IOB Building  
Singapore 049711  
Attn : Mr Daniel Pooi / Motor Claims Department

By Hand & By Fax (w/o encl)

Dear Sirs,

## ACCIDENT INVOLVING SMD 4827E & SH 8944G ALONG SERVICE ROAD OF BLOCK 813 JELlicoe ROAD ON 13 JULY 2019 @ 0930HRS

We act for Kong Hui Long Joleen, the owner of motor vehicle no. SMD 4827E, in relation to the above-captioned road traffic accident.

We are instructed that you were the owner and/or the insurers of motor vehicle no. SH 8944G at the material time. We are further instructed that the accident was caused by authorized driver and / or your insured driver's negligence in the driving, control and/or management of your insured vehicle. As a result of the accident, our client's vehicle was damaged and our client has been put to loss and expense, particulars of which are as follows:

1. Cost of Repairs	S\$4,500.00
2. Rental Charges (6 days x \$150.00/day)	S\$ 900.00
3. Survey Report Fees	S\$ 512.00
4. LTA Search Fee	S\$ 7.49
5. Costs (inclusive of GST)	S\$ 749.00
6. Incidentals	S\$ 50.00
Total	<u>S\$6,718.49</u>

.../Page 2

TAN HIN TAT  
AUGUSTINE SOH KIENG YEOW  
SEAN LIM THIAN SIONG  
TANG CHI LOONG

WOO FOONG LIN  
TAN E-FANG  
CLAIRE THAM LI MEI

CAROLYN LIM MAY LEAN  
HO KIM FOONG  
SERENA GOH MAE LI  
GONG CHIN NAM  
MOHD ZIKRI B MOHD MUZAMMIL  
CHRISTINE CHUAH HUI FEN  
MARILYN HO SU FEN  
ANDREW PATRICK HILL  
THIAN RUI LING

CONSULTANTS LIM KIA TONG  
JANET WEE-TAN

 eLitigation

**HIN TAT AUGUSTINE & PARTNERS**

Page No. 2

Our Ref. TCL.GCN.ro.50449.19.at

Your Ref. SH 8944G

Date : 18 September 2019

---

The following supporting documents are enclosed herewith: -

1. Copy of Singapore Accident Statement by SMD 4827E;
2. Copy of Certificate of Insurance by ECICS Limited;
3. Copy of Final Repair Bill from A T Performance;
4. Copy of Rental Invoice and Rental Agreement from T5 Auto Pte. Ltd;
5. Copy of LTA search result of YP 1298X;
6. Copy of Survey Invoice & Survey Report from Premier Appraiser Services; and
7. **36 pcs of original** photographs of motor vehicle no. SMD 4827E.

Please note that you / your authorized driver and/or your insured driver should send to us an acknowledgement of receipt of this letter within **fourteen (14)** days of receipt of this letter, failing which our client will have no alternative but to commence proceedings against you / your authorized driver and/or your insured driver without further notice to you / your authorized driver and/or your insured driver.

Please note that if you / your authorized driver and/or insured driver have a counterclaim against our client arising out of the accident, you / your authorized driver and/or your insured driver are also required to send us a letter giving full particulars of the counterclaim together with all relevant supporting documents within **eight (8)** weeks of your receipt of this letter.

Please note that our client's claim is in respect of her property damage claim and is strictly without prejudice to the uninsured losses and/or injury claim (if any).

Yours faithfully,



**GONG CHIN NAM**

Enc.

cc: client

By fax

# 0/

## Enquire Vehicle & Owner Information ( Vehicle No. SH8944G As At 13 Jul 2019 / 09:30:00 )

### Law Firm Search Details

Search Reason: Insurance claim in relation to traffic accident

Law Firm Case No.: GCN.RO.50449.19.AT

### Current Owner Details

Owner ID Type: Company

Owner ID: 199303821R

Owner Name: COMFORT TRANSPORTATION PTE LTD

Registered Address Type: Private Residential (Condo Apt or House) / Shopping / Office Complexes

Registered Block/House No.: 383

Registered Street Name: SIN MING DRIVE

Registered Unit No.: -

Registered Building Name: GAS BUILDING

Registered Postal Code: 575717

### Current Vehicle Details

Vehicle No.: SH8944G

Make Description/Model: TOYOTA / PRIUS SDR HATCHBACK (AUTO)

Insurance Company Name: INDIA INT'L INS PTE LTD

MLHM19092014 / Lai Hunt (Meng Kee) Motor Pte Ltd - 6in Ming  
 ENTRY DATE & TIME: 15/07/2019 11:54  
 SUBMITTED BY: Poh Kwec Chon

### SINGAPORE ACCIDENT STATEMENT

#### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

#### ACCIDENT STATEMENT

Date Of Report 15/07/2019 11:54  
 Date Of Accident 13/07/2019 09:30  
 Exact Location Of Accident SERVICE ROAD OF BLK 813 JELlicoe ROAD  
 Country/State of Loss SINGAPORE

#### DETAILS OF OWN VEHICLE

Vehicle Registration Number SMD4827E  
 Insured/Policyholder  
 Name Of Registered Owner KONG HUI LONG JOLEEN  
 NRIC No S8939097D  
 Email Address NOEMAIL  
 Mobile Phone No (LOCAL) +65-95164769  
 Alternative Phone No OTHERS-95164769  
 Vehicle Particulars  
 Manufacturer BMW  
 Model 316  
 Exact Purpose for which vehicle was being used at time of accident PRIVATE USE  
 Are you claiming under your own insurance policy for repair to your vehicle? NO  
 If No, Please state action to be taken THIRD PARTY  
 Vehicle Category PRIVATE CAR  
 Insurance Company  
 Name of Insurance Company ECICS LIMITED  
 Type Of Coverage COMPREHENSIVE  
 Fleet Policy NO  
 Policy Number MPC18A00289000  
 Cover Note Number  
 Driver  
 Name of Driver DOMINIC CHAN KWOK WING  
 NRIC No S8013579C  
 Date Of Birth 10/05/1980  
 Occupation INDOOR  
 Date Of Driving Pass 03/10/2018  
 Driving Experience 0 YEAR AND 9 MONTH  
 Gender MALE  
 Mobile Number (LOCAL) +65-98717422  
 Fax Number  
 Contact Number  
 EMail Address TO\_DOMINIC@HOTMAIL.COM

Address	BLK 35 LORONG TOA PAYOH
	#03-323
Postcode	310035
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	SPOUSE
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

**General Information of the Accident**

Type Of Accident	SIDE SWIPE
Weather Conditions	CLEAR
Road Surface	DRY

**Other Information**

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) Involved in the accident	2
Was any body injured in the Accident?	NO
Was any Injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

**Details of Police Action**

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

**Circumstances of Accident**

PLEASE REFER TO SKETCH PLAN.

**Attachment(s)**

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

**DETAILS OF OTHER VEHICLE PROPERTY 1**

Vehicle Registration Number	SH8944G
Vehicle Make/Model/Colour	TOYOTA
Details Of Properties	
Vehicle Category	TAXI
Name of Driver	
NRIC/Passport Number	
Contact Number	98153939
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

## Sketch Plan Pg. 1

## SKETCH PLAN

## IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My Insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my Insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all Insurer(s) who have insured vehicle(s) involved in this accident (all Insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims, (collectively the "Purposes")
- (b) all Insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the Information so collected under (d) above may be shared / disclosed:
  - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.


Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time: 15 JUL 2019

Reporting Centre Personnel's Signature  
Name:   
NRIC/FIN No.:

## Sketch Plan Pg. 2

## SKETCH PLAN



## DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

MY CAR WAS PARKED STATIONARY. A TAXI SH8944G THEN  
REVERSE AND HIT INTO MY CAR REAR RH SECTION

## DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature  
Date & Time:

(WARRIC Sketch/Plan Form, V3)

Driver's Signature  
(If driver is not the policyholder)  
Date & Time: 15 JUL 2019

Reporting Centre Personnel's Signature  
Name: POH KWEE  
NRIC/FIN No.: 8084033A



## CERTIFICATE OF INSURANCE

Motor Vehicles (Third-Party Risks Compensation) Act (Chapter 189)  
Motor Vehicles (Third-Party Risks and Compensation) Rules, 1960  
Road Transport Act, 1987 (Malaysia)  
Motor Vehicles (Third-Party Risks) Rules, 1959 (Malaysia)

**E-DRIVE AUTHORISED  
WORKSHOPS**

MZ300  
COMPREHENSIVE  
ORIGINAL

CERTIFICATE NO: MPC18A00289000  
Agency Name: Assure (Singapore) Pte Ltd  
Agency Code: A0000110

Chassis No: WBA3A16070NS36166  
Engine No: A708J543N13R16A

1. Index Mark and Registration Number of Vehicle: SMD4827E
2. Name of Policyholder: KONG HUI LONG, JOLEEN
3. Period of Insurance (both dates inclusive): 07 September 2019 to 19 December 2019

4. Persons or Classes of Persons entitled to drive

- a) The Policyholder and all Named Drivers declared under the policy
- b) Any other person who is driving on the Policyholder's order or with his permission.

Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.

5. Limitations as to use

Use for social, domestic and pleasure purposes and for the Policyholder's business. The policy does not cover use for hire or reward, tuition, driving test, race, pace-making, reliability trial, speed-testing, the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with the Motor Trade.

6. EXCESS APPLICABLE

WINDSCREEN	SGD 100.00
SECTION I - INSURED/NAMED DRIVER	SGD 150.00
ADDITIONAL EXCESS OTHER THAN NAMED DRIVERS:	
SECTION I - AGE <25, AGE >70 OR DRIVING EXP <2 YEARS OLD	SGD 3,000.00

7. Hire Purchase Company: TOKYO CENTURY LEASING (S) PTE LTD

Signed for and on behalf of ECICS Limited

\_\_\_\_\_  
AUTHORISED SIGNATORY

**Important Notice:**

- i) Policyholders are hereby warned that it shall be unlawful for any person to use or cause or permit any other person to use a motor vehicle without a valid insurance under the Act.
- ii) On the sale of a motor vehicle, Policyholders must surrender all insurance papers issued including the Certificate of Insurance and the Policy to the insurance company. If the Certificate of Insurance has been lost or destroyed, a Statutory Declaration to that effect must be made. Failure to comply with this obligation is an offence under the Motor Vehicles (Third Party Risks and Compensation) Act (Chapter 189).
- iii) The Certificate of Insurance and the Policy will cease to be valid once the motor vehicle has been sold or transferred.
- iv) The Payment Before Cover Warranty or Premium Payment Warranty found in the Policy must be complied with otherwise there would be no liability under the Policy and Certificate of Insurance.

FINAL REPAIR BILL  
REF.: TP/140120/159074827

## AT PERFORMANCE

160 SIN MING DRIVE #07-19 SIN MING  
AUTOCITY SINGAPORE 575722

TEL: 6453 5112

FAX: 6552 2061

Regn. No. 52983289E

Messrs.	Kong Hui Long Joleen	Date	31/07/19
---------	----------------------	------	----------

Vehicle No. SMD4827E BMW 316 1.6 AT

Quantity	Items/Descriptions	Prices
	Lump sum repair basis as recommended.	4,500.00
	SGD.: Four Thousand Five Hundred Only.	
Total:		\$4,500.00

# T5 AUTO PTE. LTD.

160 Sin Ming Drive #07-18 Sin Ming Autocity Singapore 575722  
Tel/Fax:68521588 Email Address: t5auto@singnet.com.sg  
Co Regn No. 201326853C

## INVOICE

Invoice To
Kong Hui Long Joleen Blk 35 Lor 5 Toa Payoh #03-323 Singapore 310035


Date 24/7/2019  
Invoice 12562  
Handled by Jeffrey96191115  
Referred By Alvin/96866219  
(AT PERFORMANCE)

S.No	Description	Amount
1	ONE UNIT SJY6175P, VOLSWAGEN TIGUAN. RENT FOR 06 DAYS RENTAL PERIOD: 18 JUL 2019 TO 24 JUL 2019 RENTAL FEE: \$150.00 X 06 DAYS  RENTAL AGREEMENT NO: 15161	900.00
Important Note: Hirer has to top up fuel to the same level as check out upon returning the vehicle. No refund will be given back for fuel left in the vehicle. Vehicle return during office hour only (9.00am - 5.00pm) No service on Public Holiday and Sunday.		<b>Total \$900.00</b>

All Cheque should be crossed and make payable to "T5 AUTO PTE. LTD."

For payment made via electronic transfer  
Bank:United Overseas Bank Limited  
Account No.:357-305-306-9  
Bank Code:7375  
Branch Code:018

Signed for and on behalf  
T5 Auto Pte. Ltd.

  
Authorised Signature

## T5 AUTO PTE LTD

## RENTAL AGREEMENT

BLK 13 SIN-MING INDUSTRIAL ESTATE SECTOR B #01-37 SINGAPORE 575657.  
TEL / FAX : +65 6852 1588 EMAIL : t5auto@singnet.com.sg  
Co. Regn. No.: 201326853C

NO. 15161

HIRER PARTICULAR		
NAME KONG HUI LONG JOLEEN	NRIC/ROC S8939097D	
ADDRESS BLK 35 LORONG 5 TOA PAYOH #03-323 S(310035)		
CONTACT (HP) 98917422	(OFFICE)	FAX

DRIVER'S PARTICULAR		
NAME Dominic Chan Kwok Wing	NRIC/PERMIT S8013579C	
ADDRESS 35 Toa Payoh Lr 5 #03-323 S(310035)		
DRIVING EXPERIENCE monthly	LICENSE NO. S8013579C	DOB 10/5/1980

VEHICLE & CHARGES			
VEHICLE NO S336175P	MAKE & MODEL	Volkswagen	
RENTAL PERIOD 06 Days	CHARGES \$150	DEPOSIT -	
DATE OUT 18 Jul 19	TIME 1030HRS	MILAGE 119456 Km	FUEL LEVEL 1/4

\* INTEREST OF LATE PAYMENT 1.5% PER MONTH

IMPORTANT NOTES: Restricted to Singapore use only.

No refund will be given for fuel left in vehicle.

Hirer is liable to pay first insurance Excess S\$ 3,500 = Section 1/11 in any accident plus lost of earnings while damaged vehicle is under repair. Hirer is liable for all Parking Fines and Traffic Violations.


Driver must be above 23 years with minimum 2 years driving experience.

Vehicle return during office hour only. No services on Public Holiday and Sunday.

- ☐ I/WE DECLARE THAT THE ABOVE PARTICULARS ARE TRUE AND CORRECT IN EVERY RESPECT AND
- ☐ I/WE HAVE READ AND UNDERSTOOD THE TERMS AND CONDITIONS OF THIS RENTAL AGREEMENT AND AGREE TO

  
COMPANY'S STAMP / HIRER'S SIGNATURE & DATE

INDICATE:  
D-DENTS  
S-SCRATCHES  
A-ACCIDENT



DATE IN 24 Jul 2019	TIME 1145HRS	MILAGE 119840 Km	FUEL LEVEL 1/4
CHECKED BY Liu Qian		DEPOSIT REFUND -	
REMARKS			

  
SIGNATURE OF HIRER / DRIVER

# PREMIER APPRAISER SERVICES

Insurance Loss Adjusters and Qualified Appraisers

16 Sin Ming Walk, #03-02 Singapore 575568

Tel: 6554-2269 Fax: 6685-1399

Regn. No: 52864369W

To Ms. Kong Hui Long Joleen  
c/o 160 Sin Ming Drive  
#07-18/19 Sin Ming Autocity  
Singapore 575722

INVOICE NO : **PT1907005**  
Our Ref : PT1907005-L  
Your Ref : -  
Date : 26th Jul 2019

	AMOUNT
VEHICLE REGISTRATION NO : SMD 4827 E	
VEHICLE MAKE/MODEL : BMW 316 1.6AT	
TO SERVICE RENDERED:-	
<input checked="" type="checkbox"/> CONSULTANT/APPRaiser FEES	\$ 340.00
<input checked="" type="checkbox"/> PHOTOGRAPHS	\$ 32.00
<input checked="" type="checkbox"/> TRANSPORT CHARGES	\$ 60.00
<input checked="" type="checkbox"/> RE-INSPECTION FEES	\$ 80.00
	<u>\$ 512.00</u>
DOLLARS :- FIVE HUNDRED & TWELVE ONLY	

E. & O. E.

  
for PREMIER APPRAISER SERVICES

# PREMIER APPRAISER SERVICES

Insurance Loss Adjusters and Qualified Appraisers  
16 Sin Ming Walk, #03-02 Singapore 575568  
Tel: 6554-2269 Fax: 6685-1399  
Regn. No: 52864369W

Our Ref : PT1907005-L  
Date : 26th Jul 2019

Ms. Kong Hui Long Joleen  
c/o 160 Sin Ming Drive  
#07-18/19 Sin Ming Autocity  
Singapore 575722

**WITHOUT PREJUDICE**

Dear Sir,

**Re: Third Party Claim / Workshop :- AT Performance**  
**Vehicle Regn. No. : SMD 4827 E**

We refer to your instruction to appraise the above-mentioned vehicle on 18th Jul 2019 .

A static inspection was carried out and our report is enclosed for your perusal. The estimated repair costs submitted by the repairer for **S\$ 7,426.30** as per our attached schedule have been scrutinized and revised by us against the actual damages found on the vehicle and we recommend the replacements and rectification accordingly.

The repairer has agreed to undertake the repairs at our adjusted amount of **S\$ 4,500.00 lump sum** corresponding to supply of parts, labour charges and spraypainting. However, we have not given instruction to authorize.


Under normal circumstances the estimated period of repairs is **FOUR ( 4 ) days**.  
Photographs of the damaged vehicle taken by us during our inspection are enclosed.

We are leaving the matter to you for a decision.

Please do not hesitate to contact us if you need any clarification.

Assuring you of our best services always.

Very truly yours  
**PREMIER APPRAISER SERVICES**

  
**LESLIE K C LIM CAE (UK), MIMI (UK)**  
MSAAA, Automotive Appraiser  
Dip.MTM. Automotive Engineer

# PREMIER APPRAISER SERVICES

## VEHICLE INSPECTION REPORT

To: Ms. Kong Hui Long Joleen  
c/o 160 Sin Ming Drive  
#07-18/19 Sin Ming Autocity  
Singapore 575722

Our Ref: PT1907005-L  
Policy No.:  
Claim No.:  
Sum Insured:  
Excess: T/P Claim  
Date: 26th Jul 2019

Assigned By: Ms. Kong Hui Long Joleen  
Date of Assignment: 18th Jul 2019  
Date of Accident: 13th Jul 2019  
Date of Inspection: 18th Jul 2019 Follow up inspections were also conducted.  
Name of Workshop: AT Performance  
Place of Inspection: 160 Sin Ming Drive #07-18/19 Sin Ming Autocity  
Singapore 575722

### PARTICULARS OF VEHICLE

Registration No.	: SMD 4827 E	Odometer/km	: 115812
Make/Model	: BMW 316 1.6AT	Chassis No.	: WBA3A16070NS36166
Type Of Body	: 4 Door Saloon	Engine No.	: A708J543N13B16A
Year of Manuf./Regn.	: 2013	Engine Cap.	: 1598 cc
Colour	: White	Carrying Cap.	: 4 Passengers

### PRE-ACCIDENT CONDITION (Static tests only)

Handbrake	: Serviceable	Body Work	: Good	Market Value	: N/A
Footbrake	: Serviceable	Paint Work	: Good	Scrap Value	: -
Steering	: Serviceable	Modifications	: None	Others	: -

### CONDITION OF TYRES

	Size	N/s - Tread Depth/Make	O/s - Tread Depth/Make
Front Tread	: 245/40 - R18	6mm - Goodyear	6mm - Goodyear
Rear Tread (inner)	:		
Rear Tread (outer)	: 245/40 - R18	6mm - Goodyear	6mm - Goodyear

*The above represent an estimated remaining life of the tyre treads in mm.*

### POINT OF IMPACT/GENERAL DESCRIPTION OF DAMAGES

The vehicle sustained an impact on the rear portion.

The boot lid, rear end panel, rear bumper, bumper reinforcement, reinforcement garnish were dented/ chafed/ distorted/ damaged.

For details of damages please refer to our schedule attached.

### REMARKS :

This survey was conducted strictly without prejudice.

*This report is confidential and is given for the use of clients and their agents and any disclosure or publication of it or parts thereof shall be the responsibility of such person and no liability shall be attached to us therefore.*

# PREMIER APPRAISER SERVICES

Our Ref : PT1907005-L

Vehicle No : SMD 4827 E

Qty	Parts Descriptions	Conditions	Repairer's Est.	Our Revised
LIST ITEMS:				
1	rear bumper	dented/distorted <i>DD</i>	S\$ 1,280.00	S\$ 1,280.00 ✓
1	rear bumper outer mldg - centre	damaged <i>xnn</i>	386.00	<del>386.00</del> <i>xnn</i>
2	rear bumper reflectors	fractured <i>cra</i>	110.00	<del>110.00</del> <i>\$55</i>
4	rear bumper parking sensors <i>@195</i>	damaged <i>SC</i>	1,340.00	<del>1,340.00</del> <i>\$55</i>
4	rear bumper parking sensor seals	damaged <i>rec</i>	100.00	<del>100.00</del> <i>\$50</i>
4	rear bumper parking sensor mtgs	damaged <i>XND</i>	140.00	<del>140.00</del> <i>?</i>
1	rear bumper tow cover	serviceable <i>xnn</i>	33.40	-
1	rear bumper reinforcement	dented/bent <i>xnn (repair)</i>	599.00	599.00 <i>xnn</i>
1	rear bumper reinforcement garnish	damaged <i>cra</i>	113.90	113.90 ✓
2	rear bumper side attachments	damaged <i>as</i>	110.00	110.00 ✓
2	rear bumper side retainers	damaged <i>rec</i>	97.00	97.00 ✓
1	rear bumper centre retainer	damaged <i>rec</i>	122.00	122.00 ✓
1	rear end panel	dented - repair <i>xnn (repair)</i>	597.00	-
1	rear end panel top trim	serviceable <i>xnn</i>	188.00	-
			S\$ 5,216.30	S\$ 2,247.94
LESS 0%			-	5% <i>12.31</i> 219.90
			5,216.30	<del>\$2135.51</del> 4,178.01
S/NETT ITEMS:				
12	rear bumper clips	necessary <i>rec</i>	60.00	60.00 <i>\$50</i>
4	rear end panel top trim clips	necessary <i>rec</i>	20.00	20.00 ✓
TOTAL S/PARTS			S\$ 5,296.30	S\$ 70 4,258.01
Labour charges to repair, panel beat and straighten damaged parts and replace the above-mentioned parts.			800.00	<del>\$400</del> 500.00
To replace reverse sensor.			120.00	60.00 <i>\$50</i>
To check wiring functions.			50.00	30.00 ✓
To putty, apply primer & spray-paint the affected areas.			1,100.00	750.00 <i>\$500</i>
To apply rust-proofing on repaired/replaced panels.			60.00	<del>\$990</del> 30.00 ✓
TOTAL			S\$ 7,426.30	S\$ 5,628.01

Note: The repairer has agreed to undertake the repairs at our adjusted amount of **S\$ 4,500.00 lump sum** corresponding to supply of parts, labour and spray painting charges.  
The estimated period of repairs is **FOUR (4) days**. Pursuant to your instruction we have **not** authorised repairs on your behalf.

*4S = \$2550.00 #* List Item: *\$2135.51*  
*net item: \$70*  
*Labour: \$990*  
*Total: \$3195.51*  
*4S 20%: \$2550.00 #*

PREMIER APPRAISER SERVICES

LESLIE K C LIM CAE (UK), MIMI (UK)  
MSAAA, Automotive Appraiser  
Dip.MFTM. Automotive Engineer




## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
INDIA INTERNATIONAL INSURANCE PL		Ref : CS3/III19012672/Fyf3e2-1	
64 CECIL STREET #05-02 IOB BUILDING SINGAPORE 049711		Date : 09-10-2019	
		Code : III2	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>			
Insured Veh.	SH 8944G	Veh. Inspected	SMD 4827E
Policy No.		Coverage (\$)	0.00
Claim No.	MCT19070375	Excess (\$)	0.00
Assign From	STANLEY LAI	Assign Date	28/09/2019
<b>2. Vehicle Particulars &amp; Condition</b>			
Make & Model	B.M.W. 316I	c.c	1598
Engine No.	HIDDEN	Year of Reg.	2013
Chassis No.	WBA3A16070NS36166	Colour	WHITE
Odometer	115812	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		
<b>3. Conditions of Tyres</b>			
	Size	Make	Balance
R/H Front Tyre	245/40 R18	GOODYEAR	6 mm
L/H Front Tyre	245/40 R18	GOODYEAR	6 mm
R/H Rear Tyre	245/40 R18	GOODYEAR	6 mm
L/H Rear Tyre	245/40 R18	GOODYEAR	6 mm
<b>4. Description of Damages</b>			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
<b>5. General Information</b>			
Accident Date	13/07/2019	Inspection Date	18/07/2019
Survey held at	160 SIN MING DRIVE #07-18/19		
Repairer	A T PERFORMANCE		
<b>5a. Remarks</b>			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
<b>5b. Estimate Days of Repair</b>			
ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days	



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

### ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMD 4827E

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b><u>REPLACEMENT OF PARTS</u></b>				
1	REAR BUMPER	DENTED	1,280.00	1,280.00
1	REAR BUMPER OUTER MLDG - CENTRE	NOT NECESSARY	386.00	-
2	REAR BUMPER REFLECTORS	N/S CRACKED	110.00	55.00
4	REAR BUMPER PARKING SENSORS	SHORT CIRCUIT (2PCS ONLY)	1,340.00	390.00
4	REAR BUMPER PARKING SENSOR SEALS	NECESSARY	100.00	80.00
4	REAR BUMPER PARKING SENSOR MTGS	NO DAMAGED	140.00	-
1	REAR BUMPER TOW COVER	NOT NECESSARY	33.40	-
1	REAR BUMPER REINFORCEMENT	TO REPAIR SEE LABOUR	599.00	-
1	REAR BUMPER REINFORCEMENT GARNISH	CRACKED	113.90	113.90
2	REAR BUMPER SIDE ATTACHMENTS	DISTORTED	110.00	110.00
2	REAR BUMPER SIDE RETAINERS	NECESSARY	97.00	97.00
1	REAR BUMPER CENTRE RETAINER	NECESSARY	122.00	122.00
1	REAR END PANEL	TO REPAIR SEE LABOUR	597.00	-
1	REAR END PANEL TOP TRIM	NOT NECESSARY	188.00	-
	LESS 5% DISCOUNT		-	-112.40
			5,216.30	2,135.50
<b><u>SPECIAL NETT ITEMS</u></b>				
12	REAR BUMPER CLIPS (SN)	NECESSARY	60.00	50.00
4	REAR END PANEL TOP TRIM CLIPS (SN)	NECESSARY	20.00	20.00
			80.00	70.00
<b><u>LABOUR</u></b>				
	LABOUR CHARGES TO REPAIR, PANEL BEAT AND STRAIGHTEN DAMAGED PARTS AND REPLACE THE ABOVE-MENTIONED PARTS. INCLUSIVE OF THE REPAIR OF REAR BUMPER REINFORCEMENT AND REAR END PANEL.		800.00	400.00
	TO REPLACE REVERSE SENSOR.		120.00	30.00
	TO CHECK WIRING FUNCTIONS.		50.00	30.00
	TO PUTTY, APPLY PRIMER & SPRAY-PAINT THE AFFECTED AREAS.		1,100.00	500.00

Report Ref No. CS3/III19012672/Fyf3e2-1



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO APPLY RUST-PROOFING ON REPAIRED / REPLACED PANELS.		60.00	30.00
			2,130.00	990.00
GRAND TOTAL			7,426.30	3,195.50
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				2,550.00

Report Ref No. CS3/III19012672/Fyf3e2-1

PARASURAM S/O SHANMUGAM

Asst. Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.