

## ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_  
 Estimated Cost: \_\_\_\_\_  
 OD / W / WS / TP RES / OD RES / EVA / INV / MV  
 To Inspect Vehicle No: SLV7660R  
 at Workshop m/s R.  
 of \_\_\_\_\_  
 Insured: GBA604/M  
 Policy No. MSD/VCT/18-001172  
 Claims No. MSC/V/19-001174  
 Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_  
 (Client's Record)  
 Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its  
 repair at the time of inspection.

Bal. or Market Value: 70

IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seen: ✓ Consistent? : Yes or NoEst. Repairs: 5 days Res.: Yes or NoLum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Veh No: SLV7660R Yr Regn: 1/18  
 Type: Car / Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or CAMake: Honda shuttle C.C. 1496Colour: Silver A/C: Insured / Std / NI / NASp. Reading: 41807 T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: GK81200569Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 185/60R15

R: \_\_\_\_\_

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front	Rear
R/Bal. <u>6</u> mm	R/Bal. <u>6</u> mm
L/Bal. <u>6</u> mm	L/Bal. <u>6</u> mm
D.O.A. <u>30/9/19</u>	D.O.I. <u>30/9/19</u>

Survey held at \_\_\_\_\_

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

1/10-2:49pm Sent email via email4/10/19 1/5 \$8200 confirmed with Mr. Ured: 11817-30 15910

Date/Time, File Pass to?

1) 8/10 Typist ☐ : Prel. Report☒ : Final Report

Date/Time, File Return to?

2) \_\_\_\_\_

Days Of Repair: 5

Resurvey No. of Trip: \_\_\_\_\_

Survey Fee: \_\_\_\_\_

Transportation: \_\_\_\_\_

Add Fee: ☐ : Site Insp (\$ \_\_\_\_\_) \$ + RS \$ \_\_\_\_\_☐ : Interview (\$ \_\_\_\_\_) Photos☐ : Tech. Invs (\$ \_\_\_\_\_) Others☐ : Weekend (\$ \_\_\_\_\_)

TOTAL

200

11

211

Report Format: TPLump Sum / I.B.I. (\$ 8200)

## Denise Tay (LKKAUTO)

---

**From:** Denise Tay (LKKAUTO)  
**Sent:** Tuesday, 1 October 2019 2:49 PM  
**To:** motorsurvey@sg.msig-asia.com  
**Cc:** SUR  
**Subject:** DIRECT SURVEY INSPECTION ON WORKSHOP - FASTECH AUTO PTE LTD, DOA: 30/9/2019, SLV 7600R (TP VEHICLE), GBA 6041M (OI VEHICLE)  
**Attachments:** SLV 7600R GIA.pdf

Dear Sir/Madam,

Please be informed that we had inspected the vehicle SLV 7600R at M/s: FASTECH AUTO PTE LTD, 1 KAKI BUKIT AVENUE 6 #01-46/48/50 AUTOBAY SINGAPORE 417883 on 30/9/2019

Enclosed herewith a copy of TP's GIA report and estimated cost of repair will forward to you shortly.

Meanwhile, kindly provide us the claim reference number for our necessary action.


Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: [sur@lkkauto.com](mailto:sur@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Post an Advertisement  
Sell it yourself! Advertise it at just  
**\$58 until it's SOLD!**

Post an AdAdvertiser LoginWays of Selling

Cerato Forte SX At \$14K, Mid December 2009.

Low Mileage, Good Smooth  
Ride. Best For COE Renewal,  
Regularly Serviced.  
Direct Owner - StarAd

click here to view  
our **PRISTINE USED CARS**  
at **GREAT PRICES**

Browse by Category

Sort by Date Posted








20 results/page

20 vehicles

Honda Shuttle

Advanced Search

Submit

	Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
Search Selection	Honda Shuttle		Any	Any	2018	Any	Any	Any	Available
	Honda Shuttle Hybrid 1.5A		\$78,000	\$8,690 /yr	28-May-2018	1,496 cc	-	Stationwagon	Available
	<b>Fuel Type:</b> Petrol-Electric Elegant Black, Low Fuel Consumption With Hybrid, One Owner Only, Low Maintenance Cost, Very Well Maintained, Easy Financing, Flexi... Prime Motor & Leasing Posted: 30-Sep-2019 Tags: 2018 Honda Shuttle, 2018 honda shuttle, Honda Shuttle, honda shuttle, Honda, Shuttle, shuttle, Used Honda								
	Honda Shuttle Hybrid 1.5A X		\$78,388	\$9,020 /yr	27-Feb-2018	1,496 cc	-	Stationwagon	Available
	Graded B by <b>STP</b> <b>Fuel Type:</b> Petrol-Electric Serviced By PI Workshop And Still Under Warranty. 1 Owner, x Model High Specs, Original Paintwork. In Beautiful Condition, Superb Fue... Posted: 30-Sep-2019 Tags: 2018 Honda Shuttle, 2018 honda shuttle, Honda Shuttle, honda shuttle, Honda, Shuttle, shuttle, Used Honda								
	Honda Shuttle Hybrid 1.5A		\$79,800	\$9,140 /yr	15-Mar-2018	1,496 cc	22,000 km	Stationwagon	Available
	<b>Fuel Type:</b> Petrol-Electric New Arrival! (1st Owner Unit!) Cheapest In Town! Hybrid Edition! (This Is Not A P/H Vehicle!) Best Selling Stationwagon! Genuine Low... Posted: 29-Sep-2019 Tags: 2018 Honda Shuttle, 2018 honda shuttle, Honda Shuttle, honda shuttle, Honda, Shuttle, shuttle, Used Honda								
	Honda Shuttle Hybrid 1.5A		\$76,500	\$8,900 /yr	11-Jan-2018	1,496 cc	-	Stationwagon	Available
	<b>Fuel Type:</b> Petrol-Electric Elegant White, Almost New Condition. Low Fuel Consumption With Hybrid, One Owner Only, Low Maintenance Cost, Very Well Maintaine... Prime Motor & Leasing Posted: 29-Sep-2019 Tags: 2018 Honda Shuttle, 2018 honda shuttle, Honda Shuttle, honda shuttle, Honda, Shuttle, shuttle, Used Honda								
<div>  <div> <div>Improve Car Response And Performance</div> <div>Honda Shuttle Nano Grounding Cables to improve fuel consumption &amp; RPM stability for a better driving experience</div> <div>More info about this product</div> </div> </div>									
	Honda Shuttle Hybrid 1.5A		\$78,888	\$8,850 /yr	18-May-2018	1,496 cc	10,000 km	Stationwagon	Available
	<b>Fuel Type:</b> Petrol-Electric Owned This Car With 95% Loan As Indicated, One Single Under Uterlise Unit, Extremely Low Mileage Clocked, Hybrid Systems Making T... Posted: 28-Sep-2019 Tags: 2018 Honda Shuttle, 2018 honda shuttle, Honda Shuttle, honda shuttle, Honda, Shuttle, shuttle, Used Honda								
	Honda Shuttle Hybrid 1.5A		\$83,999	\$9,540 /yr	13-Apr-2018	1,496 cc	5,117 km	Stationwagon	Available
	<b>Fuel Type:</b> Petrol-Electric No Gimmicks! Price Negotiable, Low Mileage Done 5117KM, 100% Beautiful Condition, Low Depreciation, Low Interest Rate, Most Worth... Posted: 28-Sep-2019 Tags: 2018 Honda Shuttle, 2018 honda shuttle, Honda Shuttle, honda shuttle, Honda, Shuttle, shuttle, Used Honda								

Compare

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type: Singapore NRIC

Owner ID: 428F

**Vehicle Details**

Vehicle No.: SLV7660R

Vehicle to be Exported: No

Intended Deregistration Date: 30 Sep 2019

Vehicle Make: HONDA

Vehicle Model: SHUTTLE 1.5G CVT

Primary Colour: Silver

Manufacturing Year: 2017

Engine No.: L15B5460682

Chassis No.: GK81200569

Maximum Power Output: 97.0 kW (130 bhp)

Open Market Value: \$19,287.00

Original Registration Date: 15 Jan 2018

First Registration Date: 15 Jan 2018

Transfer Count: 0

Actual ARF Paid: \$9,287.00

**Intended PARF Rebate Details**

PARF Eligibility: Yes

PARF Eligibility Expiry Date: 14 Jan 2028

PARF Rebate Amount: \$6,965.00

**Intended COE Rebate Details**

COE Expiry Date: 14 Jan 2028

COE Category: A - Car up to 1600cc &amp; 97kW (130bhp)

COE Period(Years): 10

QP Paid: \$42,339.00

COE Rebate Amount: \$35,089.00

**Total Rebate Amount: \$42,054.00**

The information contained herein is correct as at 30 Sep 2019

OK

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT	
Date Of Report	30/09/2019 10:50
Date Of Accident	30/09/2019 06:45
Exact Location Of Accident	ALONG BKE TWDS PIE
Country/State of Loss	SINGAPORE
DETAILS OF OWN VEHICLE	
Vehicle Registration Number	SLV7660R
<b>Insured/Policyholder</b>	
Name Of Registered Owner	TOH WEI TIONG
NRIC No	S8801428F
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-94370339
Alternative Phone No	OFFICE-94370339
<b>Vehicle Particulars</b>	
Manufacturer	HONDA
Model	SHUTTLE
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR
<b>Insurance Company</b>	
Name of Insurance Company	FWD SINGAPORE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	PNPV2019-00000162
Cover Note Number	
<b>Driver</b>	
Name of Driver	TOH WEI TIONG
NRIC No	S8801428F
Date Of Birth	20/01/1988
Occupation	INDOOR
Date Of Driving Pass	16/08/2012
Driving Experience	7 YEARS AND 1 MONTH
Gender	MALE
Mobile Number	(LOCAL) +65-94370339
Fax Number	
Contact Number	OFFICE-94370339
Email Address	NOEMAIL

Address	BLK 256C SUMANG WALK #11-633
Postcode	823256
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	CHAIN COLLISION
Weather Conditions	RAINING
Road Surface	WET

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	5
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

#### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

REFER TO STATEMENT.

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	WITH DRIVER
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GBA6041M
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

#### DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number	SLM4271Y
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

#### DETAILS OF OTHER VEHICLE PROPERTY 3

Vehicle Registration Number	SJK908E
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

#### DETAILS OF OTHER VEHICLE PROPERTY 4

Vehicle Registration Number	SLT4238H
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

#### DETAILS OF INJURED PERSON 1

Name	TOH WEI TIONG
Approximate Age	
Injuries Sustain	BODY
Injured person in which vehicle?	SLV7660R
Were seat belts worn?	YES
Was this injured conveyed to hospital by ambulance?	NO
Address	
Postcode	

### SKETCH PLAN

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorized Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers to the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:


- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
- (ii) investigating the accident and/or my claims;
- (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
- (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
- (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes").

- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be based outside of Singapore, for one or more of the above Purposes
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
- (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

Reporting Centre Personnel's Signature  
Name: \_\_\_\_\_  
NRIC/IDN No.: \_\_\_\_\_

# Accident Sketch Plan

## SKETCH PLAN



A - SLV7660R  
 B - GBA 6041M  
 C - SLM 4271Y  
 D - SJK 908E  
 E - SLT 4238H

## DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On the stated date and time, I was driving along  
 BKE toward PIE. Suddenly I felt an impact from behind  
 vehicle B hit on my rear portion. There were 5 cars  
 involved in an accident.

## DECLARATION

I/We declare the foregoing particulars are true in every respect.

  
 Policyholder's Signature  
 Date & Time:

  
 Driver's Signature  
 (If driver is not the policyholder)  
 Date & Time:

  
 Reporting Centre Personnel's Signature  
 Name:  
 NRIC/TIN No.:

# **FASTECH AUTO PTE LTD**

1 Kaki Bukit Ave 6 #01-48 Autobay

Singapore 417883

Tel No: 67452063 / 67467158 Fax No: 67458520

Tax Reg No : 20-0006262-D

SLV 7660R

not Authorized  
N/A  
30/9/19  
4/5 #8200  
54.

QTY	PARTICULAR
1 PCS	REAR WINDSCREEN MOULDING 136.40
1 PCS	TAILGATE 1195.20
1 PCS	TAILGATE OUTER GARNISH 455.20
1 PCS	TAILGATE 'H' LOGO 38.50
2 PCS	TAILGATE REFLECTORS @\$ 499.00 385 x 2 = 770
1 PCS	TAILGATE 'SHUTTLE' EMBLEM
1 PCS	TAILGATE INNER LOCK
1 PCS	TAILGATE INNER TRIM BOARD 345.50
1 SET	TAILGATE INNER TRIM BOARD CLIPS
2 PCS	TAILGATE DAMPERS @\$280.00
1 PCS	TAILGATE WEATHERSTRIP 288.20
1 PCS	TAILGATE wiper motor
1 PCS	REAR BUMPER 1150.00
2 PCS	REAR BUMPER SIDE COVERS @\$115.00
1 PCS	REAR BUMPER <del>sponge</del>
2 PCS	REAR BUMPER SIDE RETAINERS @\$85.00
1 SET	REAR BUMPER CLIPS
1 PCS	REAR END PANEL 487.40
1 PCS	REAR END PANEL TOP GARNISH 171.40
2 PCS	TAILLAMPS @750.00 288.40 x 2 = 1136.80
1 PCS	REAR FLOOR PANEL
1 PCS	REAR FLOOR PANEL TOP BOARD
2 PCS	REAR FENDER INNER TRIM BOARD 394.05 x 2 = 788.10
1 PCS	REAR window
1 PCS	REAR reverse camera 380.50

## **S.NETT**

1 SET	REAR BUMPER REVERSE SENSOR
1 PCS	REAR END PANEL SEALANT
1 PCS	REAR LICENCE PLATE W/HOLDER
1 PCS	REAR WINDSCREEN SEALANT

## **LABOUR CHARGES:**

TO CHECK WIRING	
TO DISMANTLE & REPLACING REVERSE SENSOR	
TO DISMANTLE & REFIX REAR WINDSCREEN	
TO DISMANTLE & REFIX TAILGATE MECHANISM	
TO DISMANTLE & REFIX SEAT CUSHION UPHOLSTREY	
TO SPRAY RUST PROOFING	

net	\$166.30 ✓
body	\$1,866.20 ✓
body	\$745.20 ✓
net	\$60.00 ✓
net	\$998.00 ✓
net	\$58.00 ✓
tail	\$299.50 ✓
body	\$766.20 ✓
net	\$50.00 ✓
11	\$560.00 X
tail	\$322.20 ✓
body	\$450.00 ✓
body	\$1,418.20 ✓
body	\$230.00 PC
tail	\$58.00 ✓
11	\$170.00 X
net	\$50.00 ✓
body	\$945.20 ✓
tail	\$311.20 ✓
cur/cne	\$1,500.00 ✓
net	\$1,450.00 X
11	\$820.00 X
body	\$788.10 ✓
body	\$1,125.00 ✓
body	\$850.00 ✓
	\$16,057.30

body	\$280.00 200
net	\$50.00 ✓
net	\$50.00 X
net	\$50.00 40

\$80.00	30
\$80.00	50
\$150.00	120
\$150.00	60
\$150.00	80
\$120.00	60

P-9168.20  
202  
733428

11	\$100.00	X
	\$1,200.00	800
	\$1,500.00	1080
TOTAL	\$20,017.30	

10284.51  
827

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/MSG19017136/UTF3N2

Date: 10/10/2019

## REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	MSD/VCT/18-001172
Claimant Vehicle No :	SLV7660R	Insured Vehicle No :	GBA6041M
Date of Loss:	30/09/2019	Nature of Claim:	TP
		Claim No:	MSC/V/19-001174

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No:	SLV7660R	Engine No:	L15B5460682
Make & Model:	HONDA SHUTTLE, 1.5 G CVT (A)	Chassis No:	GK81200569
Reg. Date:	15/01/2018 (Man. Year: 2017)	Odometer:	41907 km
Colour:	Silver		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

## CONDITION OF TYRES

Front Tyre Size:	185/60R15	Rear Tyre Size:	185/60R15
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

## COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	16,487.30	8,004.56	8,482.74	51.45
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,530.00	2,280.00	1,250.00	35.41
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (\$\$)</b>	<b>20,017.30</b>	<b>10,284.56</b>	<b>9,732.74</b>	<b>48.62</b>
<b>Approved Total (Overridden) (\$\$)</b>		<b>8,200.00</b>		
<b>(\$\$)</b>	20,017.30	8,200.00	11,817.30	59.04
<b>+ GST 7.00/7.00% (\$\$)</b>	1,401.21	574.00	827.21	59.04
<b>Nett Amount (\$\$)</b>	<b>21,418.51</b>	<b>8,774.00</b>	<b>12,644.51</b>	<b>59.04</b>

## INSPECTION

Date of Assignment:	01/10/2019	
Date Inspected:	30/09/2019	Inspected At:
		Fastech Auto Pte Ltd (HQ)
		1 Kaki Bukit Ave 6, #01-46/48/50
		Autobay
		Singapore 417883
Estimated Period of Repair:	5.0 days	

Adjuster: MARCUS CHUA

Manager: DENISE TAY KWEE CHENG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

## Reference

<b>Part Source:</b>	(Last Synchronised: 10 Oct 2019)		
<b>Parts:</b>	N/A	HONDA SHUTTLE 1.5 G CVT (A) (Model not available in database)	
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)	
<b>Print Code:</b>	(Unsubmitted, no print-code for SLV7660R)		
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page		
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.		

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR WINDSCREEN MOULDING	Necessary	166.30 F	*136.40 FL
2	1		*TAILGATE	Badly Dented	1,866.20 F	*1,195.20 FL
3	1		*TAILGATE OUTER GARNISH	Bent/Cracked	745.20 F	*455.20 FL
4	1		*TAILGATE H LOGO	Necessary	60.00 F	*38.50 FL
5	2		*TAILGATE REFLECTORS	Cracked	998.00 F	*770.00 FL
6	1		*TAILGATE SHUTTLE EMBLEM	Necessary	58.00 F	*58.00 FL
7	1		*TAILGATE INNER LOCK	Twisted/Bent	299.50 F	*299.50 FL
8	1		*TAILGATE INNER TRIM BOARD	Deformed/Cracked	766.20 F	*345.50 FL
9	1		*SET TAILGATE INNER TRIM BOARD CLIPS	Necessary	50.00 F	*50.00 FL
10	2		*TAILGATE DAMPERS	Not Necessary	560.00 F	*- FL
11	1		*TAILGATE WEATHERSTRIP	Twisted	322.20 F	*288.20 FL
12	1		*TAILGATE WIPER MOTOR	Bent/Jammed	450.00 F	*450.00 FL
13	1		*REAR BUMPER	Distorted	1,418.20 F	*1,150.00 FL
14	1		*REAR BUMPER SIDE COVERS	N/s Dented	230.00 F	*115.00 FL
15	1		*REAR BUMPER SPONGE	Torn	58.00 F	*58.00 FL
16	2		*REAR BUMPER SIDE RETAINERS	Not Necessary	170.00 F	*- FL
17	1		*SET REAR BUMPER CLIPS	Necessary	50.00 F	*50.00 FL
18	1		*REAR END PANEL	Badly Dented	945.20 F	*487.40 FL
19	1		*REAR END PANEL TOP GARNISH	Twisted	311.20 F	*171.40 FL
20	2		*TAILLAMPS	Cracked	1,500.00 F	*1,136.80 FL
21	1		*REAR FLOOR PANEL	Repair	1,450.00 F	*- FL
22	1		*REAR FLOOR PANEL TOP BOARD	Not Necessary	820.00 F	*- FL
23	2		*REAR FENDER INNER TRIM BOARD	Deformed/Cracked	788.10 F	*788.10 FL
24	1		*REAR WINDSCREEN	Shattered	1,125.00 F	*1,125.00 FL
25	1		*REAR REVERSE CAMERA	Shorted	850.00 FS	*380.00 FS
26	1		*SET REAR BUMPER REVERSE SENSOR	Shorted	280.00 FS	*200.00 FS
27	1		*REAR END PANEL SEALANT	Necessary	50.00 FS	*50.00 FS
28	1		*REAR LICENCE PLATE W/HOLDER	Serviceable	50.00 FS	*- FS
29	1		*REAR WINDSCREEN SEALANT	Necessary	50.00 FS	*40.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>16,487.30</b>	<b>9,838.20</b>
<b>- List Item Discount on L Items 0.00/20.00% (\$\$)</b>	<b>0.00</b>	<b>1,833.64</b>
<b>Total Parts (\$\$)</b>	<b>16,487.30</b>	<b>8,004.56</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO CHECK WIRING	New	80.00	30.00
2	TO DISMANTLE & REPLACING REVERSE SENSOR	New	80.00	50.00
3	TO DISMANTLE & REFIX REAR WINDSCREEN	New	150.00	120.00
4	TO DISMANTLE & REFIX TAILGATE MECHANISM	New	150.00	60.00
5	TO DISMANTLE & REFIX SEAT,CUSHION UPHOLSTERY	New	150.00	80.00
6	TO SPRAY RUST PROOFING	New	120.00	60.00
7	TO DISMANTLE & REFIX EXHAUST	New	100.00	0.00
8	LABOUR FOR PANEL BEATING & REPLACING PARTS	New	1,200.00	800.00
9	TO PUTTY & SPRAY PAINTING	New	1,500.00	1,080.00
<b>Gross Labour Cost (S\$)</b>			<b>3,530.00</b>	<b>2,280.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >