	Surveyor Marcus ASSIGNME	ENT (Office)
Mrinun	From (Person): Gnon Pau Loom of Si	mo Date/Time: 1.10.19 11.10 G.M
	Estimated Cost:	Bill to:
	To Inspect Vehicle No: SJ L 3906 K	Insured: SLA 8057L Tel: 44 L 5405
7	of 1 kgki Buki Ave 6 4101-46	Tel: 174 (5405
	Policy No: DHMTP VOIOU3/67	Claim No: CMT1) 190454 6
	Sum Insured:	Excess:
	Make of Veh:(Client's Record)	D.O.A. 28.9.19
	CA / REV / REP. / REV 24 HRS Date/Time: 1-10-19 11-15am Person Contacted:	Nancy Vehicle IN DUT
	Date/Time Action/Instruction (V) Estimate	
	03/10/19 @ 9,2000 Informed Gnot Pau Lo	oung, we are pending for estimate from w
	07/10/19@ 11.39an revised to Gards	pong, we are pending for estimate from no par loon vin merimen.

ASSIGNMENT Veh No: \$\frac{1}{3906k}\$ \text{Yr Regn:} \text{III of No:} \text{Truck / Trailer or } \text{Truck / Trailer or } \text{Veh No:} \text{Veh No:} \text{Veh No:} \text{Veh No:} \text{Truck / Trailer or } \text{Veh No:} Veh No			/	T	
ASSIGNMENT The property of th		REF:	Cual		
Veh No: SJL 39.06 K Yr Regit: 1/8 Imples Cost: Truck	SS. REC. BY: Marcus				
Date: Implied Cost: Truck Tr	9,	AS		-22	~ C
Truck Trailer or A Colour Card Card Colour Card Card Colour Card Card Colour Card Car	rom:	Date:		Yr Regn: / Lorry / Taxi / Prime Mover /	8
Impect Vehicle No: Workshop mis SJA 8087C Colour Sp. Reading IS259(Insured Std / NI NA ACC Insured Std	stimated Cost:	W. 100 ST. 100			
Interest Vehicle No. S.J. A. SOLY Colour Sp. Reading T. S.J. Sp. Reading T. S.J. Sp. Reading T. S.J. Sp. Sp. Reading T. S.J. Sp. S	DITA WS ITP RES I OD F	ES/EVA/INV/MV	- ,	c.c <i>(</i>	498
Sp. Reading 1829 Tritadio: Insured (Std / NI / NA Survey Res. Person Contacted: Std / REP 124 HRS Survey Res. Person Contacted: Std / Time Action / Instruction Action / Instru	Inspect Vehicle No:	57L 5906K	- Make: VOIZAL 2		
EngNo: Circle No. JMODE IDY 1901 2 80 4 8 Gen. Cont Good Fair Poor I Burnt Steering: Long Jammed J Leaked I Burnt or Brake: (Client's Record) alice of Veh: (Policy Condition) Remark: The veh had commenced its repair at the time of inspection. Sel. or Market Value: DAC Accident Rport: Consistent?: Yes or No GIA / PR Seen: Consistent?: Yes or No GIA / PR Seen: Consistent?: Yes or No CIA / REV / REP. / 2 4 HRS Vehicle: IN / OUT Date: Person Contacted: CA / REV / REP. / 2 4 HRS Vehicle: IN / OUT Date: Person Contacted: CA / REV / REP. / 2 4 HRS Vehicle: IN / OUT Date: Person Contacted: CA / REV / REP. / 2 4 HRS Vehicle: IN / OUT Date: Person Contacted: CA / REV / REP. / 2 4 HRS Vehicle: IN / OUT Date: Person Contacted: CA / REV / REP. / 2 4 HRS Vehicle: IN / OUT Date: Person Contacted: CA / REV / REP. / 2 4 HRS Vehicle: IN / OUT Date: Person Contacted: CA / REV / REP. / 2 4 HRS Vehicle: IN / OUT Date: Person Contacted: CA / REV / REP. / 2 4 HRS Vehicle: IN / OUT Date: Person Contacted: CA / REV / REP. / 2 4 HRS Vehicle: IN / OUT Date: Person Contacted: CA / REV / REP. / 2 4 HRS Vehicle: IN / OUT Date: Person Contacted: CA / REV / REP. / 2 4 HRS Vehicle: IN / OUT Date: Person Contacted: CA / REV / REP. / 2 4 HRS Vehicle: IN / OUT Date: Date: Person Contacted: CA / REV / REP. / 2 4 HRS Vehicle: IN / OUT Date: Date: Person Contacted: CA / REV / REP. / 2 4 HRS Vehicle: IN / OUT Date: Date: Person Contacted: CA / REV / REP. / 2 4 HRS Vehicle: IN / OUT Date: Date: Person Contacted: CA / REV / REP. / Rear / OIS / INIS / UIC / Rooftop or Receive held at Des. of Damages: Frt. / Rear / OIS / INIS / UIC / Rooftop or Receive held at Des. of Damages: Frt. / Rear / OIS / INIS / UIC / Rooftop or Receive held at Des. of Damages: Frt. / Rear / OIS / INIS / UIC / Rooftop or Receive held at Des. of Damages: Frt. / Rear / OIS / INIS / UIC / Rooftop or Receive held at Des. of Damages: Frt. / Rear / OIS / INIS / UIC / Rooftop or Receive held at De	Workshop m/s	4.		T/Radio: Insured / Std	INIINA
Consider the very large of the		C 0 0 27/	Maria 100 100 100 100 100 100 100 100 100 10	197	
Gen. Com/ Good/ Fair / Poor / Burnt Gen. Com/ Good/ Fair / Poor / Burnt Steering / Portal / Jammed / Leaked / Burnt or Brake: Inforder / Jammed / Leaked / Burnt or Modi: Nil (Signer / Stocked / Burnt or Robal / Stocked / Burnt or Modi: Nil (Signer / Stocked / Burnt or Robal / Stocked / Burnt or Modi: Nil (Signer / Stocked / Burnt or Robal / Stocked / Burnt or Modi: Nil (Signer / Stocked / Burn	sured:	374 SORAC	Ing/No.	10/10 12 00	16
Silent's Record) Itake of Vehr: College Condition Steeling Lyndra Jammed Leaked Burnt or Brake: Lyndra Jammed Leaked Burnt or Brake: Lyndra Jammed Leaked Burnt or Brake: Lyndra Jammed Leaked Burnt or Modi: Nil (Sign STD AlRim or Tyre Size: F: 20 S / 44 - 72 / 6 R:	olicy No.	1			49
College of Vah: Excess: Exce	laims No.	22 22 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1			
Colleging Record Colleging R	tum Insured:	Excess:	5		
Tyre Size: F: 20 \$ / 4 C	(Client's Record)			MA OUT-MAN COLUMN	W
(Policy Condition) Remark: The veh had commenced its repair at the time of inspection. Sell or Market Value: DAC Accident Rport: Consistent?: Yes or No GIA / PR Seen: Consistent?: Yes or No Est Repairs: 7 days Res.: Yes or No Lum Sum: 20 % 3 Val.: Yes or No Vehicle: IN / OUT Date: Person Contacted: Consistent?: Yes or No Lost / Time Action / Instruction L 7 A V3 Y Court Land Court L	Make of Veh:)	neluca	1,
(Policy Condition) Remark: The veh had commenced its repair at the time of inspection. Bal. or Market Value: DAC Accident Rport: Consistent?: Yes or No GIA / PR Seen: Consistent?: Yes or No GIA / PR Seen: Consistent?: Yes or No CA / REV / REP. / 24 HRS Date: Person Contacted: Person Co				15/4000	16
repair at the time of inspection. TOYO / YOKO or Front	(Policy Condition)				
Eront Front Fron		nonoda no		IZA / MIC / OHTSU / PIR / SC	J 1001 1
DAC Accident Rport: Consistent? : Yes or No GIA / PR Seen: Consistent? : Yes or No Est. Repeirs: 7 days Res.: Yes or No Lum Sum: 20 % 3 Val.: Yes or No CA / REV / REP. / 24 HRS Date: Person Contacted: Yes 2 Mc Date / Time Action / Instruction L / A V33 / Gov	repair at the time	of inspection.	TOYO/YOKO or		1 11
DAC Accident Rport: Consistent: 188 of No GIA / PR Seen: Consistent?: Yes or No Est. Repairs: 7 days Res.: Yes or No Lum Sum: 20 % 3 Val.: Yes or No CA / REV / REP. / 24 HRS Date: Person Contacted: Yes 2 Jul. Date / Time Action / Instruction L 7 A 1231/ Got 18 'III - 2013 ### CETIVED 0 7 OCT 2019 Date/Time, File Pass to? Date/Time, File Pass to? Date/Time, File Pass to? Date/Time, File Pass to? Add Fee: Site Insp (\$) s-RS_SI Interview (\$) Protos Report Format: MER-TP L/Bal. D.O.A. 28/9/19	Bal. or Market Value:	756.	Front 6		
GIA / PR Seen: Consistent?: Yes or No Est. Repairs: 7 days Res.: Yes or No Lum Sum: 20 % 3 Val.: Yes or No CA / REV / REP. / 24 HRS Date: Person Contacted: Yarg 2 Jul. Date / Time Action / Instruction L 7 A 1231/ Cou 12 (1-2013) Which is person? PRECEIVED 0 7 001 2019 RECEIVED 0 7 001 2019 Report Format: MER-P Add Fee: Site Insp (\$) protos Instruction Add Fee: Tech. Invs (\$) protos Instruction Add Fee: Tech. Invs (\$) the protos Instruction Add Fee: Tech. Invs (\$) the protos Instruction Add Fee: Tech. Invs (\$) the protos Instruction Add Fee: Tech. Invs (\$) the protos Instruction Construction Add Fee: Tech. Invs (\$) the protos Instruction Construction Construction Add Fee: Tech. Invs (\$) the protos Instruction Construction Add Fee: Tech. Invs (\$) the protos Instruction Construction Construction Construction Construction Add Fee: Site Insp (\$) protos Instruction Construction Co	IDAC Accident Rport:	Consistent?: Yes or No	R/Bal. mm	6	mm
Est. Repairs: 7 days Res.: Yes or No Lum Sum: 20. % 3 Val.: Yes or No CA / REV / REP. / 24 HRS Date: Person Contacted: Rys Lumb. Date / Time Action / Instruction L7A 1237 Cot 18: 11-2013 H/W/S 4/5 \$7800 Confiand wh Blan, (Red \$ 4773, 10, 68%) RECEIVED 0.7 OCT 2019 Describe, File Pass to? Preli. Report Potential, File Return to? Date / Time, File Pass to? Survey Fee: Transportation: Transportation: Add Fee: Stee Insp. (\$) _s+RS_\$! Report Format: MER-TP Lump Sum / J.B.1: (\$ 7800) Lum Sum: 20. 48/9/(8) Survey held at Described at		Consistent? : Yes or No	L/Bal. 6 mm	~ /	0/mm
Lum Sum: 20 % 3 Val.: Yes or No 1736 CA / REV / REP. / 24 HRS Date: Person Contacted: Person Contact		days Res.: Yes or No	D.O.A. 28/9/19	D.O.I. 30/	7/17
Description File Pass to? Description File Return to? Action / Instruction L7A 1237/ Cost 12023 Person Contacted: Cyrs 2 ml. The U/C / Chassis frame / Body Structure affected due to collision. The U/C / Chassis frame / Body Structure affected due to collision. RECEIVED 0.7 OCT 2019 Description File Pass to? 1) ON to Mark 1200 Structure affected due to collision. RECEIVED 0.7 OCT 2019 Description File Pass to? 1) ON to Mark 1200 Structure affected due to collision. RECEIVED 0.7 OCT 2019 Description File Pass to? 1) One Mark 1200 Structure affected due to collision. RECEIVED 0.7 OCT 2019 Description File Pass to? 1) One Mark 1200 Structure affected due to collision. RECEIVED 0.7 OCT 2019 Description File Pass to? 1) One Mark 1200 Structure affected due to collision. RECEIVED 0.7 OCT 2019 Description File Pass to? 1) One Mark 1200 Structure affected due to collision. Report Format 1200 Structure affected due to collision. Received Action / Chassis frame / Body Structure affected due to collision. Received Action / Chassis frame / Body Structure affected due to collision. Received Action / Chassis frame / Body Structure affected due to collision. Received Action / Chassis frame / Body Structure affected due to collision. Received Action / Chassis frame / Body Structure affected due to collision. Received Action / Chassis frame / Body Structure affected due to collision. Received Action / Chassis frame / Body Structure affected due to collision. Received Action / Chassis frame / Body Structure affected due to collision.		The state of the s	Survey held at		
Date: Person Contacted: Gyg 2ml. The U/C / Chassis frame / Body Structure affected due to collision. Date / Time		773C	Des. of Damages : Frt / Rear /	O/S / N/S / U/C / Rooftop	O OF
Date / Time Action / Instruction L 7 A 123 V Cox 26 · (1 - 2023	CA / REV / REP. /	Vehicle: IN /	OUT K	2e-	
L7A 1237 COL 26-11-2023	Date: Per	son Contacted: Que 2ml.	The U/C / Chassis frame /	Body Structure affected du	e to collision.
Plivis A/s \$7800 Confirmed who Ahn. (Red \$ 4773.70, 68%) RECEIVED 0 7 OCT 2019 Date/Time, File Pass to? Preli. Report Resurvey No. of Trip: 2 Survey Fee: Transportation: Transportation: Add Fee: Site Insp (\$)_\$ +RS_\$ Interview (\$) Procts Report Format: MER-P Lump Sum / LEN: (\$ 7800) Weekend (\$):	Date / Time Action /	Instruction			
DeterTime, File Pass to? 1) ON to Muser : Final Report DaterTime, File Pass to? 1) ON to Muser : Final Report DaterTime, File Return to? Add Fee: Site Insp (\$) S+RS_SI III Report Format : MERTP Lump Sum / I.B.I: (\$ 7800) : Weekend (\$):		2717 1231/ coe 12.1	1-1013		18 19
DeterTime, File Pass to? 1) ON to Muser : Final Report DaterTime, File Pass to? 1) ON to Muser : Final Report DaterTime, File Return to? Add Fee: Site Insp (\$) S+RS_SI III Report Format : MERTP Lump Sum / I.B.I: (\$ 7800) : Weekend (\$):	1/-/-	22 - 1	1 l. Alin 11	Red & 4773.10.	68%)
DeterTime, File Pass to? 1) ON to Muser : Final Report DaterTime, File Pass to? 1) ON to Muser : Final Report DaterTime, File Return to? Add Fee: Site Insp (\$) S+RS_SI III Report Format : MERTP Lump Sum / I.B.I: (\$ 7800) : Weekend (\$):	4/10/18 1/5	1800 CONTINUE	e was round		= 8 C ×
Date/Time, File Pass to? 1) ON to hum : Final Report Date/Time, File Return to? 2) Add Fee: : Site Insp (\$		and the second of the	2002 22 2 100		
ON 10 hum : Final Report Resurvey No. of Trip: 2 Survey Fee: Transportation: 450	- 1 - H - 18 18 17 1 1	RECI	E1VED 0.7 OCT 2019		
ON 10 hum : Final Report Resurvey No. of Trip: 2 Survey Fee: Transportation: 450	* ** ***				SETE E
ON 10 hum : Final Report Resurvey No. of Trip: 2 Survey Fee: Transportation: 450					
ON 10 hum : Final Report Resurvey No. of Trip: 2 Survey Fee: Transportation: 450	Burger Broken	T. Deall Dealed	Dave Of Rangir 2		
Date/Time, File Return to?	ON in has see			2/ Survey Fee: [
2) Add Fee: Site Insp (\$)_S+RS_SI 11 : Interview (\$) Photos Report Format : MER-TP : Tech. Invs (\$); Others Lump Sum / I.B.1: (\$ 7800) : Weekend (\$):	1) U 1 IU 1/1/1-17	: Final Report	Resulvey No. of Thp.	· · · · · ·	450
: Interview (\$) Photos Report Format : MER-TP : Tech. Invs (\$); Others Lump Sum / I.B.I.: (\$ 7800) : Weekend (\$);		Δd	d Fee: Site Insp. (\$	1	//
Report Format : MER-TP : Tech. Invs (\$); Others Lump Sum / L. (\$ 7800) : Weekend (\$);	2)	Au			
Lump Sum / L.B.1: (\$ 7800) : Weekend (\$):	Daniel Francis	MER-TP			
		100	and the same of th).	
	Lump Sum / 138.1: (3	7800	L. Weevallo V	TOTAL	41

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To:

Sompo Insurance Singapore Pte. Ltd.

50 Raffles Place

#05-01/06, Singapore Land Tower

Singapore 048623

From: LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25

Paya Ubi Industrial Park Singapore 408933

Attn:

GNOH PAU LOONG

Date:

07 Oct 2019

Preliminary Advice

Insured Vehicle No : SLA8057L

TP Vehicle No

: SJL3906K

Accident Date

: 28/09/2019

Make

Assignment Date

: 01/10/2019

: MAZDA 2

Date of Inspection : 30/09/2019

Est. Duration of Repair

: 7.00

Inspection At

: FASTECH AUTO PTE LTD (HQ) 1 KAKI BUKIT AVE 6, #01-46/48/50 AUTOBAY

SINGAPORE 417883

Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	24,523.10
Revised Amount	:S\$	9,757.88
Check Items (Estimated)	:S\$	0.00
Total	:S\$	9,757.88
Lump Sum Repair	:S\$	7,800.00

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

()	The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
()	The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
()	Other comments :

...CLAIM SUBFOLDER...(New Assignment)

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status	
Main	30 Sep 2019		01 Oct 2019 11:10 Assign	1112100101000			New Assi	500 (C)
	Main	Re	ference	Clai	m Details	Docume	ents	Show All
CLAIM S	UBFOLDER DET	TAILS	SECURITY AND ADDRESS OF	77		[Cre	eated by in	surer]
Insured:			LEE YEW, ID: S1					
Main Clair			ENG LIN, ID: S		te of Loss:	29//	9/2019 00:0	nn . +50
Vehicle R	And the second second		DJEDJOOK				D19MTPV01003167	
Claim Typ	eg. No. (Insured)		and the second s		Policy No. (Claimant):		401003	
venicle K	ey. No. (Insured)	JEAGO	372	Excess:				
Repairer:	8	Fasted	h Auto Pte Ltd (HQ) 1 Kaki Bul	cit Ave 6, #01-46/48/	50 Autobay, 417	883 Kaki Buk	kit - Tel: 6746540
Handling	Insurer:	63295	217]		1. (HQ) - Tel: 6461 6			
Adjuster:		LKK A	uto Consultants	Pte Ltd (HQ)	Tel: 6256-3561 [Final Rpt due	10/10/20	19]
Adj Asg. I	Remarks:	WS: N	ANCY 6746 5405					
ASSOCI	ATED MAIL REC	CEIVED				View A	II Con	npose Case Mail
There are	no mail for this	case.						
District Control								
E		-22-2			- 92	- 20		
ALL ASS	SOCIATED TASK	KS			View All Searc	th Tasks Cr	eate New Tas	sk Complete

Shiau Chan (LKKAuto)

From:

Do-Not-Reply <do-not-reply@merimen.com>

Sent:

Thursday, 3 October 2019 9:20 AM

To:

do-not-reply@merimen.com

Cc:

SUR

Subject:

TP VEHICLE SJL 3906K (YOUR REF: CMTD1904546)

This mail is associated with: *SJL3906K (CMTD1904546) [SLA8057L]

TP

TAN HENG LIN Sep 28 2019 12:00AM [LIEW LEE YEW] Fastech Auto Pte Ltd

Dear Pau Loong,

Please be informed that we have inspected the vehicle SJL 3906K on 30/09/2019.

We are pending for estimate from repairer.

Thanks & Regards,

Shiau Chan (Ms) LKK Auto Consultants Pte Ltd

This is an auto-generated email. Do not reply to this email.

Sent by: SHIAU CHAN (LKK Auto Consultants Pte Ltd)



This email has been checked for viruses by AVG antivirus software. www.avg.com

SGCARMART.COM

Login Sign up

New Cars

Used Cars

Sell My Car

Directory

Products

Insurance

Articles

Мар

Forum

Resources



mazda 2

Price Range

Depreciation V > 10 year(: V

Vehicle Type

Submit (

Advanced Search

Home » Used Cars » Bestauto Motoring » Mazda 2 HB 1.5A R (COE till 11/2022)

Mazda 2 HB 1.5A R (COE till 11/2022)

Overview	Financial	Insurance	Accessories	Similar	Research	Photos
Price	\$22,888	3				
Depreciation	\$7,220 /	уг	Reg Date		03-Apr-2008 (3yrs 2mths COE left)	
Mileage	N.A.		Manufact	ured	2008	
Road Tax	\$752 /yr		Transmis	sion	Auto	
Dereg Value	\$13,312	as of today (chang	ge) OMV		\$13,646	
COE	\$20,997		ARF		\$13,646	
Engine Cap	1,498 co	:	Power		77.0 kW (103 bhp)	

Curb Weight

1,041 kg

No. of Owners

Type of Vehicle

Hatchback

Features

Leather Seats, Factory Fitted Audio System, Reverse Sensors, Knockdown Rear Seats, Sports Rim, Solar Film. View specs of the Mazda 2 Hatchback (2007-2014)

Description

Just Arrived, Well Maintained, Sporty White, Buy With A Peace Of Mind As Car Is In Fantastic Condition, High Loan Available. \$0 Driveaway. High Trade In. Don't Miss It, Call Now.

Category

COE Car

Status

Available

Resources



Car Valuation - Free

Find out the market value of your existing car for free. Get started



Vehicle Evaluation

Afraid of lemons? Request to have this car evaluated professionally. Find out more

Posted on: 16-Sep-2019 | Last Updated on: 30-Sep-2019



Transfer Fee \$25

Down Payment

\$6,866 (change)

Maximum 70% Loan

1st Instalment

\$472

Based on 3.75% interest rate













Shortlist

Compare

Add note

Report Error

More Actions

Seller Information

Company

Bestauto Motoring

» dealer's pricelist

* 0 vehs sold | 6 vehs available

Address

» more Financial info

9004 Tampines Street 93 #02-104 Search cars nearby this location

Contact Person(s)

Ray Heng

AT

91691738 85859495

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	100 0100 <u>0</u>
Owner ID Type:	Singapore NRIC
Owner ID:	773E
Vehicle Details	
Vehicle No.:	SJL3906K
Vehicle to be Exported:	No
Intended Deregistration Date:	30 Sep 2019
Vehicle Make:	MAZDA
Vehicle Model:	MAZDA2 1.5 MT R
Primary Colour:	Grey
Manufacturing Year:	2008
Engine No.:	ZY512536
Chassis No.:	JM0DE10Y190128048
Maximum Power Output:	77.0 kW (103 bhp)
Open Market Value:	\$13,912.00
Original Registration Date:	26 Nov 2008
First Registration Date:	26 Nov 2008
Transfer Count:	1
Actual ARF Paid:	\$13,912.00
Intended PARF Rebate Details	
PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	•
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	25 Nov 2023
COE Category:	A - Car (1600cc & below)
COE Period(Years):	5
PQP Paid:	\$14,835.00
COE Rebate Amount:	\$12,321.00
Total Rebate Amount: Message	\$12,321.00
	vehicle cannot be further renewed. The vehicle
	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1

must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 30 Sep 2019

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- 6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available

aforesaid.	~ (1995) 1996 -
A College State St	ACCIDENT STATEMENT
Date Of Report	30/09/2019 13:30
Date Of Accident	28/09/2019 09:20
Exact Location Of Accident	ALONG PIE TOWARDS TUAS
Country/State of Loss	SINGAPORE
Control of the Contro	DETAILS OF OWN VEHICLE
Vehicle Registration Number	SJL3906K
Insured/Policyholder	
Name Of Registered Owner	TAN HENG LIN
NRIC No	S7715773E
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-97772922
Alternative Phone No	OTHERS-97772922
Vehicle Particulars	
Manufacturer	MAZDA
Model	MAZDA2 1.5 MT R
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE

Are you claiming under your own insurance policy

for repair to your vehicle?

If No, Please state action to be taken THIRD PARTY Vehicle Category PRIVATE CAR

Insurance Company

Name of Insurance Company

AXA INSURANCE PTE LTD

COMPREHENSIVE Type Of Coverage

Fleet Policy NO

GA415909/1 Policy Number

Cover Note Number

Driver

TAN HENG LIN Name of Driver NRIC No S7715773E Date Of Birth 07/06/1977 Occupation INDOOR Date Of Driving Pass 05/10/2006

12 YEARS AND 11 MONTHS **Driving Experience**

Gender **FEMALE**

Mobile Number (LOCAL) +65-97772922

Fax Number

Contact Number OTHERS-97772922

EMail Address NOEMAIL Address

20 MARIAM WALK SINGAPORE 507167

Postcode

Was driver an employee of the Insured's Company NO

If No, Relationship of the Driver with the Insured

Vehicle Registration Number of Driver's Own

Vehicle

OWNER

Insurance Company of Driver's Own Vehicle

General Information of the Accident

Type Of Accident

CHAIN COLLISION

Weather Conditions

CLEAR

Road Surface

DRY

Other Information

Was any foreign vehicle involved in this accident?

Foreign Vehicle Registration Number

JQT2246 (PRIVATE CAR)

Number of vehicles (including own vehicle)

involved in the accident

2

Was any body injured in the Accident?

YES

Was any injured conveyed to hospital by

ambulance?

NO

Was any other material or property damaged?

I have been approached by unknown person(s)

YES NO

soliciting/offering accident claims assistance.

2

Number of Passengers (Including Driver)

Passenger 1

NAME:

: CAITLIN LEE PUGSLEY

GENDER:

: FEMALE

Details of Police Action

Was the accident reported to the police?

YES

If Yes, Please state which Police Station

Police Station Address

Police Station Name

TRAFFIC POLICE DIVISION HQ - SINGAPORE CITY

ROAD: 10 UBI AVENUE 3, POSTCODE: 408865, COUNTRY:

SINGAPORE

Police Station Contact

TEL NO: 65470000 - FAX NO:

Was notice of intended Prosecution given?

NO

If Yes, against whom?

Circumstances of Accident

REFER TO SKETCH PLAN

Attachment(s)

Are accident photos available for attachment?

YES

Was there any video captured by Car Camera?

YES

Remarks/ Reasons:

VIDEO WITH OWNER

Was there any audio recorded?

NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number

JQT2246

Vehicle Make/Model/Colour

Details Of Properties

PRIVATE CAR

Vehicle Category Name of Driver

NRIC/Passport Number

Page 2 of 20

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number

SLA8057L

Vehicle Make/Model/Colour

NISSAN / SYLPHY 1.6 CVT ABS D/AIRBAG 2WD 4DR

Details Of Properties

Vehicle Category

PRIVATE CAR

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 3

Vehicle Registration Number

FBC6779H

Vehicle Make/Model/Colour

HONDA / CB4008J M

Details Of Properties

Vehicle Category

MOTORCYCLE

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
- The issue and acceptance of this form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- The report will be forwarded by the insurers of the GIA Records Management Centre established by the General insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:


- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature Date & Time: Driver's Signature (if driver is not the policyholder) Date & Time:

r) Name: ££aimr NRIC/FIN No.:

Reporting Centre Personnel's Signature

CW	E 7	עויייי	DI	8.5
36	е і		-	ALI D



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Res	ler.	to -	the	police	Report

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature

Date & Time:

Driver's Signature (If driver is not the policyholder)

Date & Time:

Reporting Centre Personnel's Signature Name: Su Kus Ar'

NRIC/FIN No.:

FASTECH AUTO PTE LTD

1 Kaki Bukit Ave 6 #01-48 Autobay

Singapore 417883

Tel No: 67452063 / 67467158 Fax No: 67458520

Tax Reg No : 20-0006262-D

53L3906K

Not Albert 1 1/5 = 7800 727.

eg ivo	: 20-0000202-12	22-21001		(-
Qty	Particular			Amount S\$
List Ite	em:			_
1PCS	REAR WINDSCREEN MOUI	DING 66.80	rec	\$110.80
	TAILGATE	1099.60	roll Do	\$1480.20
1PCS	TAILGATE INNER LOCK	242.77	00/slubs	\$392.10
1PCS	TAILGATE INNER TRIM BO	ARD	11	\$485.00 🗶
	TAILGATE INNER TRIM BO		11	\$50.00 ×
2PCS	TAILGATE REFLECTORS @	\$480.00	NY	\$960.00 🗶
	TAILGATE WEATHERSTRII	1015 3220	INI	\$220.00
	TAILGATE DAMPERS @\$3		11	\$600.00 X
	TAILGATE REAR LOGO	48.10	rec	\$80.00
	TAILGATE 'MAZDA'2 EME	0 /00	nu	\$35.00
1PCS	TAILGATE 'SKYACTIV' EM	BLEM	NF	\$48.00 💢
1PCS	TAILGATE REAR WIPER N	NOTOR	17	\$560.00
1PC	S REAR BUMPER	913.70	DUS	\$1280.00
1PC	S REAR BUMPER REINFOR		ser	\$385.00
	S REAR BUMPER SIDE RET		olsbert	\$90.00 100
	T REAR BUMPER CLIPS		w	\$50.00
	S REAR BUMPER LICENCE	DIATE LANADS @\$110.00	CN	\$220.00 le C
			and600	\$630.00
	S REAR END PANEL	415.50	,,,,,,	\$289.00
1PC	S REAR END PANEL TOP G		I.l.	— _
	S REAR FLOOR PANEL	1499.20	crapaes/su	\$1500.00
1PC	S REAR FLOOR PANEL TO	BOARD 486.20	Tim	\$685.00
1P0	S REAR FLOOR PANEL TO	OLS SPONGE	NF	\$320.00 🗸
2P(S TAILLAMPS @\$850.00	548.9542=1091.	EU cre	\$1700.00

20%

FASTECH AUTO PTE LTD

1 Kaki Bukit Ave 6 #01-48 Autobay

Singapore 417883

Tel No: 67452063 / 67467158 Fax No: 67458520

Tax Reg No: 20-0006262-D

1 ax				W-000-000-000-4
	Qty	Particular		Amount S\$
	List It	em:		2/
	2PCS	TAILLAMP HOUSING PANELS @\$330.00	· A	\$660.00
		REAR FENDERS @\$1150.00	1	\$2300.00 众
371.59 XV	2PCS	REAR FENDER INNER TRIM BOARDS @\$690.00	743.18 Al/Tui	\$1380.00
N(%)		REAR EXHAUST	Sel	\$665.00
50	2PCS	REAR EXHAUST MOUNTINGS @\$30.00	17	\$60.00 0
	1PCS	REAR EXHAUST HEAT SHIELD	111	\$118.00 0
	1PCS	REAR BUMPER SPLASH SHIELD O/S	200 11	\$60.00
	List	Item Total:	100	\$17,413.10
	Spec	ial Nett Item:	2/8/2	11-
	1PCS	S REAR WINDSCREEN SEALANT	ner	\$50.00 40
	1PC	REAR LICENCE PLATE W/HOLDER	cre	\$50.00 40
	1SE	T REAR REVERSE CAMERA	11	\$680.00 X
	1PC	S REAR END PANEL SEALANT	ne	\$50.00 _
	1SE	T REAR FLOOR PANEL INSULATOR	er,	\$300.00 /50
	1SE	T REAR BUMPER REVERSE SENSOR	shold	\$280.00 200
	Spe	cial Nett Total:		\$1,410.00
	, Lah	our Charge:		
	.1.1			\$80.00 30
		CHECK WIRING.		\$80.00 (2
		DISMANTLE & REPLACING REVERSE SENSOR.		\$150.00 / 20
		DISMANTLE & REFIX REAR WINDSCREEN.		190
	ТО	TRANSFER TAILGATE MECHANISM.		\$100.00 60

FASTECH AUTO PTE LTD

1 Kaki Bukit Ave 6 #01-48 Autobay

Singapore 417883

Tel No: 67452063 / 67467158 Fax No: 67458520

Tax Reg No: 20-0006262-D

La	bour	Cha	rge:
La	Doui	CHA	150

TO DISMANTLE & REPLACING REAR EXHAUST.	\$100.00 60
	\$100.00 ×
TO DISMANTLE & REFIX PETROL TANK.	2
TO DISMANTLE & REFIX SEAT, CUSHION UPHOLSTERY.	\$180.00 &
TO RESET & REPLACING REVERSE CAMERA.	\$280.00 😾
TO MOUNT VEHICLE ON CAR O-LINER.	\$380.00 🗶
TO SPRAY RUST PROOFING.	\$150.00 100
TO CONDUCT WHEEL ALIGNMENT.	\$100.00 🗴
LABOUR FOR PANEL BEATING, CUT, WELD, STRAIGHTEN & REPLACING PARTS.	120 -
	\$2000.00 1100
TO PUTTY & SPRAY PAINTING.	
Labour Charge Total:	\$5700.00

ESTIMATE PARTS AND LABOUR GRAND TOTAL \$24,523.10

JRK All to Consultants hence notify and the fallowing:

The second liter sprit publing

The second liter sprit publication is a second literature of the second l High bire-may liam(s) must be resurvoyed and its subsect to final approval from Insurance Company

9787-88

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No:

CS/SMO19017138/UQF3N2

Date:

09/10/2019

REFERENCE

Handling

Sompo Insurance Singapore Pte.

Policy No:

D19MTPV01003167

Insurer: Claimant

Insured Vehicle

No:

SLA8057L

Vehicle No: Date of Loss: SJL3906K 28/09/2019

Nature of Claim:

TP

Claim No:

CMTD1904546

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:

Colour:

SJL3906K

Make & Model:

MAZDA 2, 1.5 R (A)

Engine No:

ZY512536

Reg. Date:

26/11/2008 (Man. Year: 2008) Grey

Chassis No: Odometer:

JM0DE10Y190128048 182591 km

Engine Capacity:

1498 cc

Market Value/New Car Price:

N/A

Sum Insured (S\$):

Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Steering (Serviceable):

Yes Footbrake (Serviceable):

Yes

Handbrake (Serviceable): CONDITION OF TYRES

Yes Engine Modification:

No Pre-accident Condition:

205/45 R16

Front Tyre Size: Front Left Side:

Bridgestone 6 mm

205/45 R16

Rear Tyre Size:

Front Right Side:

Bridgestone 6 mm

Rear Left Side: Rear Right Side: Bridgestone 6 mm Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's 18,823.10	Adjuster's 6,877.88	Difference 11,945.22	Diff % 63.46
Parts Miscellaneous Items	0.00	0.00	0.00	
Labour Paintwork Labour	5,700.00 0.00	2,880.00 0.00	2,820.00 0.00	49.47
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$) Approved Total (Overridden) (S\$)	24,523.10	9,757.88 7,800.00	14,765.22	60.21
(S\$)	24,523.10	7,800.00	16,723.10	68.19
+ GST 7.00/7.00% (S\$)	1,716.62	546.00	1,170.62	68.19
Nett Amount (S\$)	26,239.72	8,346.00	17,893.72	68.19

INSPECTION

Date of Assignment:

01/10/2019

Date Inspected:

30/09/2019 Inspected At:

Nett Amount (S\$)

Fastech Auto Pte Ltd (HQ) 1 Kaki Bukit Ave 6, #01-46/48/50

Autobay

Singapore 417883

Estimated Period of Repair:

7.0 days

Adjuster: MARCUS CHUA

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 09 Oct 2019)

Parts: 143 MAZDA 2 1.5 R (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SJL3906K)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page

numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

lo.	Qty	Part No. Particulars	Condition	Repairer's	Amount
	1	*REAR WINDSCREEN MOULDING	Necessary	110.80 F	*66.80 FL
	1	*TAILGATE	Badly Dented	1,480.20 F	*1,099.60 FL
	1	*TAILGATE INNER LOCK	Dented/Shorted	392.10 F	*242.77 FL
	1	*TAILGATE INNER TRIM BOARD	Not Necessary	485.00 F	*-FL
	1	*SET TAILGATE INNER TRIM BOARD CLIPS	Not Necessary	50.00 F	*-FL
	2	*TAILGATE REFLECTORS	Not fitted	960.00 F	*-FL
9	1	*TAILGATE WEATHERSTRIP	Twisted	220.00 F	*111.80 FL
3	2	*TAILGATE DAMPERS	Not Necessary	600.00 F	*-FL
)	1	*TAILGATE REAR LOGO	Necessary	80.00 F	*48.50 FL
0	1	*TAILGATE MAZDA 2 EMBLEM	Necessary	35.00 F	*30.50 FL
11	1	*TAILGATE SKYACTIV EMBLEM	Not fitted	48.00 F	*-FL
12	1	*TAILGATE REAR WIPER MOTOR	Not Necessary	560.00 F	*-FL
13	1	*REAR BUMPER	Distorted	1,280.00 F	*913.70 FL
14	1	*REAR BUMPER REINFORCEMENT	Bent	385.00 F	*229.60 FL
15	1	*REAR BUMPER SIDE RETAINERS	O/s Bent	90.00 F	*45.00 FL
16	1	*SET REAR BUMPER CLIPS	Necessary	50.00 F	*50.00 FL
17	1	*REAR BUMPER LICENCE PLATE LAMPS (2 Pcs)	Cracked (1 Pc only)	220.00 F	*110.00 FL
18	1	*REAR END PANEL	Badly Dented	630.00 F	*415.50 FL
19	1	*REAR END PANEL TOP GARNISH	Twisted	289.00 F	*148.20 FL
20	1	*REAR FLOOR PANEL	Crumpled/Buckled	1,500.00 F	*1,499.20 FL
21	1	*REAR FLOOR PANEL TOP BOARD	Torn	685.00 F	*486.20 FL
22	1	*REAR FLOOR PANEL TOOLS SPONGE	Not fitted	320.00 F	*-FL
23	2	*TAILLAMPS	Cracked	1,700.00 F	*1,091.80 FL
24	2	*TAILLAMP HOUSING PANELS	Repair	660.00 F	*-FL
25	2	*REAR FENDERS	Repair	2,300.00 F	*-FL
26	2	*REAR FENDER INNER TRIM BOARDS	Deformed/Twisted	1,380.00 F	*743.18 FL
27	1	*REAR EXHAUST	Bent	665.00 F	*665.00 FL
28	2	*REAR EXHAUST MOUNTINGS	Not Necessary	60.00 F	*-FL
29	1	*REAR EXHAUST HEAT SHIELD	Not Necessary	118.00 F	*-FL
30	1	*REAR BUMPER SPLASH SHIELD O/S	Not Necessary	60.00 F	*-Fl
31	1	*REAR WINDSCREEN SEALANT	Necessary	50.00 FS	
32	1	*REAR LICENCE PLATE W/HOLDER	Cracked	50.00 FS	*40.00 FS
33	1	*SET REAR REVERSE CAMERA	Not Necessary	680.00 FS	*-F8
34	1	*REAR END PANEL SEALANT	Necessary	50.00 FS	*50.00 FS
35	1	*SET REAR FLOOR PANEL INSULATOR	Necessary	300.00 FS	*150.00 FS
36	1	*SET REAR BUMPER REVERSE SENSOR	Shorted	280.00 FS	*200.00 F
	ranchis	part. S=SpcNett. L=ListItemDisc.			
			Sub Total (S\$)	18,823,10	8,477.35
		- List Item Discount on L			1,599.47
			Total Parts (S\$)	18,823.10	6,877.88
_		Report was unsubmitted during	122284007010000	s (S\$)	s (S\$) 18,823.10

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended	l abour
RECUIIIIIIIIIIIIII	Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labo	our Items			20.00
1	TO CHECK WIRING	New	80.00	30.00
2	TO DISMANTLE & REPLACING REVERSE SENSOR	New	80.00	50.00
3	TO DISMANTLE & REFIX REAR WINDSCREEN	New	150.00	120.00
4	TO TRANSFER TAILGATE MECHANISM	New	100.00	60.00
5	TO DISMANTLE & REPLACING REAR EXHAUST	New	100.00	60.00
6	TO DISMANTLE & REFIX PETROL TANK	New	100.00	0.00
7	TO DISMANTLE & REFIX SEAT, CUSHION UPHOLSTERY	New	180.00	80.00
	TO RESET & REPLACING REVERSE CAMERA	New	280.00	0.00
8	TO MOUNT VEHICLE ON CAR O-LINER	New	380.00	0.00
9	TO SPRAY RUST PROOFING	New	150.00	100.00
10		New	100.00	0.00
11 12	TO CONDUCT WHEEL ALIGNMENT LABOUR FOR PANEL BEATING, CUT, WELD, STRAIGHTEN & REPLACING PARTS	17 SART 11	2,000.00	1,280.00
13	TO PUTTY & SPRAY PAINTING	New	2,000.00	1,100.00
	Gross Labou	r Cost (S\$)	5,700.00	2,880.00
_	Report was unsubmitted duri	ng this print-out.		

< END OF ESTIMATES >