

ASS. REC. BY:

REF:

TU

ASSIGNMENT

(-2022)

From:

Date:

30.9.2019

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

SGV 1455

at Workshop m/s

Tan him motor

of

1 Defu Lane 6

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

\$20K.

IDAC Accident Rpt:

Consistent?: Yes or No

GIA / PR Seen:

Consistent?: Yes or No

Est. Repairs:

7

days

Res.: Yes or No

Lum Sum:

20

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

m/s

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SGV1455

Yr Regn:

30 May 2007

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Honda stream

c.c

1799

Colour:

Red

A/C:

Insured / Std / NI / NA

Sp. Reading

258405

T/Radio:

Insured / Std / NI / NA

Eng/No:

RN61031108.

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD / A/Rim or

Tyre Size:

F:

225/45R17

R:

17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Linglong

Front

Rear

R/Bal.

S

mm

R/Bal.

3

mm

L/Bal.

S

mm

L/Bal.

3

mm

D.O.A.

D.O.I.

30-09-19

Survey held at

w/s

5:30pm

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

20/9

offered w/s \$4000 to repair.

Date/Time, File Pass to?

☐

Preli. Report

1)

Date/Time, File Return to?

☐

Final Report

2)

Rep. Format:

Lump Sum / L.B.C.

Days Of Repair:

Resurvey No. of Trip:

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Weekend (\$

Survey Fee:

Transportation:

S + RS. SI

Photos

Others

TOTAL