

ASS. REC. BY:

REF: CS/SMD 190 17164/R2y f3 e2

Special Instruction:

winin

Surveyor: Rasul ASSIGNMENT (Office)

From (Person): Agnes Chan Shu Hui of SMD Date/Time: 30.9.19 1453 PM

Estimated Cost: Bill to:

OD: TP/WS/TP RES/OD RES/EVA/INV/MV/CS

To Inspect Vehicle No: SLS 2504H Insured: FBQ 3416B

at Workshop m/s: Pegasus Engineering Tel: 65137748

of 74 Kian Teck Road

Policy No: D19MTM(01007812) Claim No: (MTD) 1904543

Sum Insured: Excess:

Make of Veh: D.O.A. 26.9.2019

(Client's Record) CA / REV / REP. / REV 24 HRS m.p. 1.10.2019

Date/Time: 30.9.19 2.56 PM Person Contacted: Yoyo H.O.D. Endorsement:

Vehicle: IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	SLS 2504H - X
	FBQ 3416B - X
10/10/19	Sent Preli by Merincen
18/11	Rasul confirmed final fig \$550p; 3 days with Vivian Pan. (Ref 2934, 80?)

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	27 Sep 2019		30 Sep 2019 14:53 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS		[Created by insurer]							
Insured:	GOKEDA SATHISH NAIDU, ID: S9332810H, Tel: +6587489074, Email: SHYROME093@GMAIL.COM								
Main Claimant:	GRAB RENTALS PTE LTD, Co. Reg. No.: 201617200G								
Vehicle Reg. No.:	SLS2504H	Date of Loss:	26/09/2019 12:00 - :59						
Claim Type:	TP / CMTD1904543	Policy/Cover Note No.:	D19MTMC01007812 (TP, Fire & Theft)						
Vehicle Reg. No. (Insured):	FBQ3416B	Policy No. (Claimant):	Excess:						
Repairer:	Pegasus Engineering & Trading Pte Ltd (Kian Teck) 74 Kian Teck Road, 628800 Pioneer - Tel: 65137751								
Handling Insurer:	Sompo Insurance Singapore Pte. Ltd. (HQ) - Tel: 6461 6555 ... [Handled by CHAN SHU HUI AGNES - 6329 5327]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 09/10/2019]								
Driver/Custodian (Insured):	GOKEDA SATHISH NAIDU (26 / Male), NRIC: S9332810H, Tel: +6587489074 Email: SHYROME093@GMAIL.COM								
Adj Asg. Remarks:	WS: 65137748 YOYO/ VEH CMG 7/10/19@10.30AM								
ASSOCIATED MAIL RECEIVED			View All	Compose Case Mail					
There are no mail for this case.									
ALL ASSOCIATED TASKS		View All	Search Tasks	Create New Task	Complete				
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: Sompoo Insurance Singapore Pte. Ltd.
50 Raffles Place
#05-01/06, Singapore Land Tower
Singapore 048623

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: CHAN SHU HUI AGNES

Date: 10 Oct 2019

Preliminary Advice

Insured Vehicle No	: FBQ3416B	Accident Date	: 26/09/2019
TP Vehicle No	: SLS2504H	Assignment Date	: 30/09/2019
Make	: MAZDA 3	Est. Duration of Repair	: 3.00
Date of Inspection	: 07/10/2019		
Inspection At	: PEGASUS ENGINEERING & TRADING PTE LTD (KIAN TECK) 74 KIAN TECK ROAD SINGAPORE 628800		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages n/s rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	3,484.00
Revised Amount	:S\$	550.00
Check Items (Estimated)	:S\$	0.00
Total	:S\$	0.00
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : THE ABOVE SURVEY WAS CONDUCTED ON A WITHOUT "PREJUDICE" BASIS

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	200G
Vehicle Details	
Vehicle No.:	SLS2504H
Vehicle to be Exported:	No
Intended Deregistration Date:	10 Jan 2020
Vehicle Make:	MAZDA
Vehicle Model:	MAZDA3 SEDAN 1.5 AT EU6
Primary Colour:	White
Manufacturing Year:	2017
Engine No.:	P520446804
Chassis No.:	JM6BN22A8H0154806
Maximum Power Output:	88.0 kW (118 bhp)
Open Market Value:	\$14,761.00
Original Registration Date:	15 Sep 2017
First Registration Date:	15 Sep 2017
Transfer Count:	1
Actual ARF Paid:	\$9,761.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	14 Sep 2027
PARF Rebate Amount:	\$7,320.00
Intended COE Rebate Details	
COE Expiry Date:	14 Sep 2027
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$44,002.00
COE Rebate Amount:	\$33,783.00
Total Rebate Amount:	\$41,103.00

The information contained herein is correct as at 10 Jan 2020

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	26/09/2019 15:09
Date Of Accident	26/09/2019 12:20
Exact Location Of Accident	EUNOS AVENUE 5
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLS2504H
Insured/Policyholder	
Name Of Registered Owner	GRAB RENTALS PTE LTD
Co Reg No	201617200G
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-83335956
Alternative Phone No	OFFICE-66550005

Vehicle Particulars

Manufacturer	MAZDA
Model	3
Exact Purpose for which vehicle was being used at time of accident	PRIVATE HIRE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE HIRE

Insurance Company

Name of Insurance Company	MSIG INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	YES
Policy Number	A29114756MKF
Cover Note Number	

Driver

Name of Driver	NG CHOON AIK, SIMON
NRIC No	S7703437D
Date Of Birth	24/01/1977
Occupation	OUTDOOR
Date Of Driving Pass	30/10/1998
Driving Experience	20 YEARS AND 10 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-83335956
Fax Number	
Contact Number	
EMail Address	NOEMAIL

Address	BLK 220B BEDOK CENTRAL #07-42
Postcode	462220
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	SIDE SWIPE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : UNKNOWN GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

ON 26 SEPTEMBER 2019 AT ABOUT 1220HRS, I WAS DRIVING MY VEHICLE SLS2504H ALONG EUNOS AVENUE 5, WAITING AT THE JUNCTION OF AVENUE 5 TO MAKE RIGHT TURN TO EUNOS ROAD 8. THERE VEHICLE FBQ3416B'S SIDE HELMET THAT WAS HANGING OUT OF THE BIKE'S RIGHT SIDE OF THE VEHICLE SIDE SWIPED MY LEFT BACK PORTION OF MY VEHICLE. NOBODY WAS INJURED. *MY VEHICLE WAS AT STATIONARY WAITING FOR THE GREEN LIGHT WHEN THE SIDE SWIPE HAPPENED.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	VIDEO WITH GRAB
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	FBQ3416B
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	MOTORCYCLE
Name of Driver	GOKEDA SATHISH NAIDU
NRIC/Passport Number	S9332810H
Contact Number	+6587489074
Address	

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE


1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:


- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:


 Driver's Signature
 (If driver is not the policyholder)
 Date & Time: 25/09/19
 1250WS


 Reporting Centre Personnel's Signature
 Name: Adlan Shah
 NRIC/FIN No.:

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT Eunos Avenue 5

On the 26/09/19 at about 1220hrs I was driving my Vehicle SLS2504H along Eunos Avenue 5, waiting at the junction of Avenue 5 to make a right turn to Eunos Road 8. There where Vehicle FBQ3416B Side helmet that was hanging out of the Bike right side of the Vehicle, that Side swipe my Left back portion of my Vehicle. Nobody was injured.

My Vehicle was at stationary waiting for the green light, when the Side swipe happen.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time: 25/09/19
1250hrs

Reporting Centre Personnel's Signature
Name: Adlan Shah
NRIC/FIN No.:



PEGASUS ENGINEERING & TRADING PTE LTD

GST / ROC COMPANY NO : 201101753C

Quotation

From : PEGASUS ENGINEERING & TRADING PTE LTD 74 KIAN TECK ROAD SINGAPORE 628800 Officer in Charge : YOYO TIAN Tel : Email :	Customer : GRAB RENTALS PTE LTD 18 SIN MING LANE #01-08 MIDVIEW CITY SINGAPORE 573960 Attn : Tel : Fax No. :
--	--

Quotation No. : QO19/10-1047	Quotation Date : 04/10/2019	Terms : 30 DAYS
Vehicle No. : SLS2504H	Chassis No. : JM6BN22A8H0154806	Third Party Insurer : SOMPO
Model : MAZDA 3	Date of Accident : 26/09/2019	
Remarks :		

ITEM	DESCRIPTION	Qty	UNIT PRICE	AMOUNT (SGD)
1	REAR BUMPER <i>repair</i>	1	1,075.0000	1,075.00
2	REAR BUMPER SIDE RETAINER LHS X	1	55.0000	55.00
3	REAR BUMPER CLIPS X	10	4.0000	40.00
4	REAR FENDER <i>repair</i>	1	1,185.0000	1,185.00
5	LESS 20%	1	-471.0000	-471.00
6	TO KNOCKING & PANEL BEAT	1	600.0000	<i>150</i> 600.00
7	TO PUTTY & SPRAY PAINT ON THE AFFECTED AREAS.	1	1,000.0000	<i>400</i> 1,000.00

Total = 550/-

*Same
Hp 90010068
3 days
P/P
07/10/19 @ 1220
Remy after repair*

Sub Total 3,484.00
GST(7.00%) 243.88
Total (SGD) 3,727.88

Please conduct the survey at
Pegasus Engineering @ 74 Kian Teck Road Singapore 628800



PEGASUS ENGINEERING & TRADING PTE LTD

GST / ROC COMPANY NO : 201101753C

Quotation

From :
PEGASUS ENGINEERING & TRADING PTE LTD 74 KIAN TECK ROAD SINGAPORE 628800
Officer in Charge : YOYO TIAN Tel : Email :

Customer :
GRAB RENTALS PTE LTD 18 SIN MING LANE #01-08 MIDVIEW CITY SINGAPORE 573960
Attn : Tel : Fax No. :

Quotation No. : QO19/10-1047	Quotation Date : 04/10/2019	Terms : 30 DAYS
Vehicle No. : SLS2504H	Chassis No. : JM6BN22A8H0154806	Third Party Insurer : SOMPO
Model : MAZDA 3	Date of Accident : 26/09/2019	
Remarks :		

ITEM	DESCRIPTION	Qty	UNIT PRICE	AMOUNT (SGD)
1	REAR BUMPER <i>repair</i>	1	1,075.0000	1,075.00
2	REAR BUMPER SIDE RETAINER LHS <i>X n</i>	1	55.0000	55.00
3	REAR BUMPER CLIPS <i>X n</i>	10	4.0000	40.00
4	REAR FENDER <i>repair</i>	1	1,185.0000	1,185.00
5	LESS 20%	1	-471.0000	-471.00
6	TO KNOCKING & PANEL BEAT	1	600.0000	<i>150</i> 600.00
7	TO PUTTY & SPRAY PAINT ON THE AFFECTED AREAS.	1	1,000.0000	<i>400</i> 1,000.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Rane
Hp 90010068
3 days
P/P
07/10/19 @ 1220
Revy after repair

Sub Total	3,484.00
GST(7.00%)	243.88
Total (SGD)	3,727.88

Please conduct the survey at
Pegasus Engineering @ 74 Kian Teck Road Singapore 628800

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	27 Sep 2019		30 Sep 2019 14:53 Edit Adj Rpt	S\$550.00 Edit Estimates	S\$550.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS		[Created by insurer]							
Insured:	GOKEDA SATHISH NAIDU, ID: S9332810H, Tel: +6587489074, Email: SHYROME093@GMAIL.COM								
Main Claimant:	GRAB RENTALS PTE LTD, Co. Reg. No.: 201617200G								
Vehicle Reg. No.:	SLS2504H	Date of Loss:	26/09/2019 12:00 - :59 [24 Months and 11 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / CMTD1904543	Policy/Cover Note No.:	D19MTMC01007812 (TP, Fire & Theft)						
Vehicle Reg. No. (Insured):	FBQ3416B	Policy No. (Claimant):							
		Excess:							
Repairer:	Pegasus Engineering & Trading Pte Ltd (Kian Teck) 74 Kian Teck Road, 628800 Pioneer - Tel: 65137751								
Handling Insurer:	Sompo Insurance Singapore Pte. Ltd. (HQ) - Tel: 6461 6555 ... [Handled by CHAN SHU HUI AGNES - 6329 5327]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD RASUL] ... [Final Rpt due 09/10/2019]								
Driver/Customer (Insured):	GOKEDA SATHISH NAIDU (26 / Male), NRIC: S9332810H, Tel: +6587489074 Email: SHYROME093@GMAIL.COM								
Adj Asg. Remarks:	WS: 65137748 YOYO/ VEH CMG 7/10/19@10.30AM								
ASSOCIATED MAIL RECEIVED			View All	Compose Case Mail					
There are no mail for this case.									
ALL ASSOCIATED TASKS			View All	Search Tasks					
			Create New Task	Complete					
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SLS2504H (CMTD1904543)**
[FBQ3416B]
TP
GRAB RENTALS PTE LTD
Sep 26 2019 12:00PM
[GOKEDA SATHISH NAIDU]
Pegasus Engineering & Trading Pte Ltd

Upload Documents		Upload Photos	Compose New Letter	View View in Browser v
Assessment Reports				1 per page v <input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail Print
1	10/10/19 11:24	Adjuster Immediate Advice	1	Load HTM <input type="checkbox"/>
Photos/Images				3 per page v <input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail Print
1	14/01/20 17:26	General View	1	Load JPG <input checked="" type="checkbox"/>
2	14/01/20 17:26	General View	1	Load JPG <input checked="" type="checkbox"/>
3	14/01/20 17:26	General View	1	Load JPG <input checked="" type="checkbox"/>
4	14/01/20 17:26	General View	1	Load JPG <input checked="" type="checkbox"/>
5	14/01/20 17:26	General View	1	Load JPG <input checked="" type="checkbox"/>
6	14/01/20 17:26	General View	1	Load JPG <input checked="" type="checkbox"/>
7	14/01/20 17:26	General View	1	Load JPG <input checked="" type="checkbox"/>
8	14/01/20 17:26	General View	1	Load JPG <input checked="" type="checkbox"/>
9	14/01/20 17:26	General View	1	Load JPG <input checked="" type="checkbox"/>
10	14/01/20 17:26	General View	1	Load JPG <input checked="" type="checkbox"/>
11	14/01/20 17:26	General View	1	Load JPG <input checked="" type="checkbox"/>
12	14/01/20 17:26	General View	1	Load JPG <input checked="" type="checkbox"/>
13	14/01/20 17:27	Reinspection Photo	1	Load JPG <input checked="" type="checkbox"/>
14	14/01/20 17:27	Reinspection Photo	1	Load JPG <input checked="" type="checkbox"/>
15	14/01/20 17:27	Reinspection Photo	1	Load JPG <input checked="" type="checkbox"/>
16	14/01/20 17:27	Reinspection Photo	1	Load JPG <input checked="" type="checkbox"/>
Documentation				1 per page v <input checked="" type="checkbox"/>
No	Finalized On	Sompo Insurance Singapore Pte. Ltd. (HQ)		Thumbnail Print
1	30/09/19 14:26	Pre-Repair Survey - SAS	1	Load PDF <input type="checkbox"/>
2	30/09/19 14:54	Pre-Repair Survey - AGREED LKK/Mohd Rasul	1	Load PDF <input type="checkbox"/>
3	07/01/20 08:43	Letter of Demand from Third Party	1	Load PDF <input type="checkbox"/>

Documents Checklist

DOCUMENTS CHECKLIST		Reset Save Print
There are no document checklists configured.		
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)		
<div style="border: 1px solid gray; width: 100%; height: 100%;"></div>		
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>		

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/SMO19017164/R1YF3E2**Date:** 14/01/2020REFERENCE

Handling Insurer:	Sompo Insurance Singapore Pte. Ltd.	Policy No:	D19MTMC01007812		
Claimant Vehicle No :	SLS2504H	Insured Vehicle No :	FBQ3416B		
Date of Loss:	26/09/2019	Nature of Claim:	TP	Claim No:	CMTD1904543

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLS2504H		Engine No:	P520446804
Make & Model:	MAZDA 3, 1.4 SEDAN 1.5L SP.6EAT (A)		Chassis No:	JM6BN22A8H0154806
Reg. Date:	15/09/2017 (Man. Year: 2017)		Odometer:	128718 km
Colour:	White			
Engine Capacity:	1496 cc			
Market Value/New Car Price:	N/A			
Sum Insured (S\$):	Market Value/New Car Price			

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/60 R16	Rear Tyre Size:	205/60 R16
Front Left Side:	Triangle 6 mm	Rear Left Side:	Triangle 6 mm
Front Right Side:	Triangle 6 mm	Rear Right Side:	Triangle 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,884.00	0.00	1,884.00	100.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,600.00	550.00	1,050.00	65.63
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	3,484.00	550.00	2,934.00	84.21
+ GST 7.00/7.00% (S\$)	243.88	38.50	205.38	84.21
Nett Amount (S\$)	3,727.88	588.50	3,139.38	84.21

INSPECTION

Date of Assignment:	30/09/2019	
Date Inspected:	07/10/2019	Inspected At: Pegasus Engineering & Trading Pte Ltd (Kian Teck) 74 Kian Teck Road Singapore 628800
Estimated Period of Repair:	3.0 days	

Adjuster: MOHD RASUL**Manager:** YVONNE WONG YIN CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference	
Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 14 Jan 2020)
Parts: 143	MAZDA 3 1.4 SEDAN 1.5L SP.6EAT (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SLS2504H)	
Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
1	1		*REAR BUMPER	Repair	1,075.00 FL	*- FL	
2	1		*REAR BUMPER SIDE RETAINER LHS	Not Necessary	55.00 FL	*- FL	
3	10		*REAR BUMPER CLIPS	Not Necessary	40.00 FL	*- FL	
4	1		*REAR FENDER	Repair	1,185.00 FL	*- FL	
					Sub Total (S\$)	2,355.00	0.00
					- List Item Discount on L Items 20.00/20.00% (S\$)	471.00	0.00
					Total Parts (S\$)	1,884.00	0.00

F=Franchise part. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO KNOCKING & PANEL BEAT	New	600.00	150.00
2	TO PUTTY & SPRAY PAINT ON THE AFFECTED AREAS	New	1,000.00	400.00
Gross Labour Cost (\$\$)			1,600.00	550.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >