

22/03/2002

ASS. REC. BY:

REF: CSI/PCI 1907192 / 0393 02

Special Instruction:

Surveyor: Marcus

ASSIGNMENT (Office)

From (Person): Joanny

of

PCI

Date/Time: 30.9.19 4.59 p.m.

Estimated Cost:

Bill to:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV/CS

To Inspect Vehicle No:

SGV 5085D

Insured:

SHC 3367 L

at Workshop m/s

Focus Auto

Tel:

68869097

of

NO 1 Kaki Bukit Ave 6 Building #02-50

Policy No:

Claim No:

D19006115MPSH

Sum Insured:

Excess:

Make of Veh:

D.O.A. 20.9.2019

(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

30.9.19 5.14 p.m.

Person Contacted:

Aidah

Vehicle: IN/OUT

Date/Time

Action/Instruction (✓) Estimate

SGV 5085E-X

SHC 3367 L - CSI/PCI/FOH 230/DVH n2

D.O.A - 03/11/2017

02/10/19

@ 16:47 pm revised PA to Joanne via email

(08/11/13) wef
ASS. REC. BY: Marcus

REF:

7011

ASSIGNMENT

From: _____ Date: _____
Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV
To Inspect Vehicle No: SGU 5050
at Workshop m/s locus
of _____
Insured: _____
Policy No. _____
Claims No. _____
Sum Insured: _____ Excess: _____
(Client's Record)
Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: 15%.

IDAC Accident Rpt: _____

GIA / PR Seen: _____

Est. Repairs: 2 days

Lum Sum: 20 %

CA / REV / REP. / 24 HRS

Date: _____

Person Contacted: _____

N/S	O/S

Veh No: SGU 5050 Yr Regn: 9 06
Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
Truck / Trailer or EA
Make: Toyota wish C.C. 1794
Colour: white A/C: Insured / Std / NI / NA
Sp. Reading: 194528 T/Radio: Insured / Std / NI / NA
Eng/No: 2NE 100 314047
C/No: _____
Gen. Cond: Good / Fair / Poor / Burnt
Steering: In order / Jammed / Leaked / Burnt or
Brake: In order / Jammed / Leaked / Burnt or
Modi: Nil / S/Rim / STD A/Rim or
Tyre Size: F: _____ R: 225/42R17
BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or 1113/018
Front 6 mm Rear 6 mm
R/Bal. 6 mm L/Bal. 6 mm
D.O.A. 20/9/19 D.O.I. 1/10/19
Survey held at _____
Des. of Damages: Fr / Rear / O/S / N/S / U/C / Rooftop or
n/s rear
The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

02 28.9.2021 LTA 11304 2hrs

4/10/19 1/5 \$1000 confirmed with Mr Wong
(\$ 1,252.10 Red - 56%)

MV - \$ 151K

LTA - \$ 11,304.00

Nett - \$ 3,696.00

RECEIVED 04 OCT 2019

Date/Time, File Pass to?

04/10/19
Typist

1)

Date/Time, File Return to?

2)

☐

: Preli. Report

☒

: Final Report

Days Of Repair: 2

Resurvey No. of Trip: 1

Survey Fee:

Transportation:

\$ + RS \$

Photos

Others

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

TOTAL

110
50
50
30
240

Report Format:

Lump Sum / I.B.I: (\$ 1,000/- 45)

MOTOR SURVEY ASSIGNMENT

Date	23-09-2019	Our Ref No.	D19006115MFSH
Accident Date	20-09-2019	Claim Type.	Third Party
Insured Vehicle	SHC3367L	Third Party Vehicle.	SGU5085E
Survey Location	NO 1 KAKI BUKIT AVE 6 AUTOBAY #02-50 AUTOBAY		
Contact Person.	AIDAH		
Contact No.	68869097/ 0	Fax No.	64819095
Survey Type	WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM TO BE AGREED:		
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD		
Contact Person	NA	Fax No.	68416315
Contact Number.	NA		

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	FOCUS AUTO PTE LTD	Attention.	NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No.	NA
Officer Incharge	JOANNEY		

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Re: SURVEY ASSESSMENT - D19006115MFSH/1

Shirley Hiew (LKK Auto)

Wed 2/10/2019 4:47 PM

To: 'Joanne Yong' <Joanneyong@msfirstcapital.com.sg>; 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>

Cc: SUR <sur@lkkauto.com>; assignments <assignments@lkkauto.com>

Dear Joanne,

Please be informed that we have inspected the vehicle SGU 5085D on 01/10/2019.

We are pending estimate from repairer.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto) <admin-d@lkkauto.com>

Sent: Monday, 30 September 2019 5:06 PM

To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>

Cc: 'Joanne Yong' <Joanneyong@msfirstcapital.com.sg>; SUR <sur@lkkauto.com>

Subject: RE: SURVEY ASSESSMENT - D19006115MFSH/1

Dear Sir/Madam,

Thank you for the assignment.

Please be informed that vehicle is not in the workshop, repairer will arrange.

Celine Fong

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: CWS Motor Claims [mailto:cwsmotorclaims@msfirstcapital.com.sg]

Sent: Monday, 30 September 2019 4:59 PM

To: ASSIGNMENTS@LKKAUTO.COM

Cc: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>; Joanne Yong <Joanneyong@msfirstcapital.com.sg>

Subject: PRI: SURVEY ASSESSMENT - D19006115MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

New Cars

Used Cars

Sell My Car

Directory

Products

Insurance

Articles

F



Loaded with delectably Sweetdeals!

Toyota Wish

Price Range ▼

Depreciation ▼

> 10 year(s) ▼

Vehicle Type ▼


[Home](#) » [Used Cars](#) » [Carway](#) » Toyota Wish 1.8A (COE till 05/2021)

Toyota Wish 1.8A (COE till 05/2021)

Overview

Financial

Insurance

Accessories

Similar

Research

Photos

Map



車之道

CARWAY
Your Satisfaction Is Our Success



Price

\$16,800

Depreciation ⓘ

\$10,360 /yr

Reg Date

17-May-2006
(1yr 7mths 14days COE left)

Mileage

155,000 km (11.6k /yr)

Manufactured ⓘ

2006

Road Tax ⓘ

\$1,264 /yr

Transmission

Auto

Dereg Value ⓘ

\$7,469 as of today (change)

OMV ⓘ

\$19,749

COE ⓘ

\$23,024

ARF ⓘ

\$21,724

Engine Cap

1,794 cc

Power

97.0 kW (130 bhp)

Curb Weight ⓘ

1,300 kg

No. of Owners ⓘ

2

Type of Vehicle

MPV

Features

1.8L 16 Valves VVT-i DOHC Engine, Smooth And Reliable Super 4 Speed ECT Steptronic Auto, Digital Auto Climate Control Aircon, Airbags, ABS, 7 Seaters. View specs of the Toyota Wish (2008-2009)

Accessories


New Leather Seats, Upgraded Sports Rims, Pioneer Audio Player, Reverse Sensors, Auto Retractable Side Mirrors, Tinted Films, Alarm Remote.

Description

1 Year In House Warranty, Full Loan Available, Free Servicing, Warranty NOT By 3rd Party Workshop, Price Stated Above Is Actual Selling Price, New Paintwork, Fully Refurbished, Accident Free, STA Or Vicom Are Welcome, Purchase With Official Certificate With A Peace Of Mind, Bank & In House Loan Available At Flexible Interest Rate, Free Grooming.

[Cal](#) [Compare](#)


Price Chart


[Click on the point to view](#)
[Shortlist](#)
[Com](#)
[Report Error](#)
[M](#)
[Seller Information](#)

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	636F
Vehicle Details	
Vehicle No.:	SGU5085D
Vehicle to be Exported:	No
Intended Deregistration Date:	02 Oct 2019
Vehicle Make:	TOYOTA
Vehicle Model:	WISH 1.8 A
Primary Colour:	White
Manufacturing Year:	2006
Engine No.:	1ZZ2616456
Chassis No.:	ZNE100314047
Maximum Power Output:	97.0 kW (130 bhp)
Open Market Value:	\$19,706.00
Original Registration Date:	29 Sep 2006
First Registration Date:	29 Sep 2006
Transfer Count:	2
Actual ARF Paid:	\$21,677.00
Intended PARF Rebate Details	
PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	28 Sep 2021
COE Category:	B - Car (1601cc & above)
COE Period(Years):	5
PQP Paid:	\$28,418.00
COE Rebate Amount:	\$11,304.00
Total Rebate Amount:	\$11,304.00
Message	
Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 02 Oct 2019

OK

FOCUS AUTO PTE LTD

NO. 1 KAKI BUKIT AVENUE 6 #02-48/50

AUTOBAY @ KAKI BUKIT SINGAPORE 417883

TEL: 6886 9097 FAX: 6886 9095 Email: claims@focusauto.com.sg

GST:200712509E RCB NO:201004495R

M/S :

not Authorised
2/10/19
1/5410001
2dy.

Estimate No: **EST0001010**

Date: 02 Oct 2019

Policy No:

Veh Reg No: **SGU5085D**

Make/Model: TOYOTA TOYOTA

ATTN: Motor Claim Department
WISH

Your Ref No: REETU KAUR

Claim Type: Third Party

Accident Date:

Chassis No: ZNE100314047

Engine No: 1ZZ2616454

Reg. Date:

Estimate Repair Cost to Vehicle No :SGU5085D

PAGE:1/1

Description

U/PriceQuantity List Price Amount
SS SS

List Price

1	Rear Tail Lamp <i>Scr 388.10</i>	408.20	1 PC	408.20	
2	Rear Bumper <i>2e/10.11 488.10</i>	889.20	1 PC	889.20	
3	Rear Bumper Side Retainer <i>17</i>	65.40	1 PC	65.40 X	
				1,362.80	
		Less 25%		340.70	1,022.10

Labour

4	Panel Beating	650.00	1 PC	650.00	<i>200</i>
5	Rust Proofing	50.00	1 PC	<i>17</i> 50.00 X	
6	To Remove & Replace Bumper Sensor	80.00	1 PC	80.00	<i>40</i>
7	Spray Painting	450.00	1 PC	450.00	<i>400</i>
				1,230.00	1,230.00
				Total	SS 2,252.10

TOTAL: SINGAPORE DOLLAR TWO THOUSAND TWO HUNDRED FIFTY TWO AND CENTS TEN ONLY

LKK Auto Consultants hence notify

the Repairer of the following:

- To be used before/after spray painting
- To be used on damaged part(s) during resurvey
- All estimates are subject to confirmation
- This estimate is on a "Without Prejudice" basis
- No part of the estimate is to be used
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

For FOCUS AUTO PTE LTD

AUTHORISED SIGNATURE

7-873.20
25%
6549
12949
103591



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
MS FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI19017192/Usf3n2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 07-10-2019	
		Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SHC 3367L	Veh. Inspected	SGU 5085D
Policy No.		Coverage (\$)	0.00
Claim No.	D19006115MFSH	Excess (\$)	0.00
Assign From	JOANNE YONG	Assign Date	30/09/2019
2. Vehicle Particulars & Condition			
Make & Model	TOYOTA WISH (A)	c.c	1794
Engine No.	HIDDEN	Year of Reg.	2006
Chassis No.	ZNE100314047	Colour	WHITE
Odometer	194528	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	225/45 ZR17	LING LONG	6 mm
L/H Front Tyre	225/45 ZR17	LING LONG	6 mm
R/H Rear Tyre	225/45 ZR17	LING LONG	6 mm
L/H Rear Tyre	225/45 ZR17	LING LONG	6 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE N/S REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	20/09/2019	Inspection Date	01/10/2019
Survey held at	FOCUS AUTO PTE LTD NO 1 KAKI BUKIT AVE 6 AUTOBAY #02-48 SINGAPORE 417883		
5a. Remarks			
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		2 Working Days	

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SGU 5085D

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	REAR TAIL LAMP	SCRATCHED	408.20	388.10
1	REAR BUMPER	DEFORMED / TORN	889.20	485.10
1	REAR BUMPER SIDE RETAINER	NOT NECESSARY	65.40	-
	LESS 25% DISCOUNT		-340.70	-218.30
			1,022.10	654.90
	<u>LABOUR</u>			
	PANEL BEATING.	NOT NECESSARY	650.00	200.00
	RUST PROOFING.		50.00	-
	TO REMOVE & REPLACE BUMPER SENSOR.		80.00	40.00
	SPRAY PAINTING.		450.00	400.00
			1,230.00	640.00
	GRAND TOTAL		2,252.10	1,294.90
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			1,000.00

Report Ref No. CS/FCI19017192/Usf3n2

MARKET VALUE: \$15,000.00 (EST)-LTA REIMBURSEMENT VALUE: \$11,304.00=NETT VALUE: \$3,696.00**CHUA KANG SENG**

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.