

ASS. REC. BY:

REF: CS/MSG/19017193/Kg-f3n2

Special Instruction:

Surveyor: KANUTH

ASSIGNMENT (Office)

From (Person): Crystal Lu

of NSI 9

Date/Time: 30.9.19 4.53pm

Estimated Cost:

Bill to:

OD ~~TP~~ WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SKZ 3582A

Insured: FBN 1543X

at Workshop m/s Chew Giron Motor

Tel: 64841626

of BIK 10 AMK Ind Pac 2A N1 5 #01-15

Policy No: MSD/VMS/19-402068

Claim No: MSC/V/19-001169

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 22.9.2019

CA / REV / REP. / REV 24 HRS

Date/Time: 30.9.19 5.00pm

Person Contacted:

Kelly

H.O.D. Endorsement:

Vehicle IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	SKZ 3582A - X
	FBN 1543X - Y
2/10-16/48	Revised via preli advise.
1/11	6/1 Pm @ 7k email & confirm (ref to 6152.75, 47%)

ACC. REC'D. BY: KennethREF: MSL9

ASSIGNMENT

From _____ Date: 1-10-2019

Estimated Cost: _____

OE / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SKZ 3582Aat Workshop n/s Chow Green Motorof BIC 10 Amc Ind Park 24 Ave 5 #01-15

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____

Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.Bal. or Market Value: 82K

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 10 days Res.: Yes or NoLum Sum: 20 % 3 Val. Yes or No

CA / REV / REP. / 24 HRS

imp

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SKZ 3582A Yr Regn: 03 11Type: Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toy Maz C.C. 1598Colour: m. Grey A/C: Insured / Std / NI / NASp. Reading: 217313 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: MRO53REE104112536Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 205/55R16

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal. 4 mmL/Bal. 4 mmD.O.A. 26/9/19

Rear

R/Bal. 2 mmL/Bal. 2 mmD.O.I. 1/10/19

Survey held at: _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear n/s

The U/C / Chassis frame / Body Structure affected due to collision.

4/11/2019

RECEIVED 5 NOV 2019

Date / Time Action / Instruction

Date/Time, File Pass to?

☐

Preli. Report

1) 04/11/2019 Mazda☐

Final Report

Date/Time, File Return to?

2) _____

Days Of Repair: 10Resurvey No. of Trip: 2

Add Fee:

☐

Site Insp (\$)

☐

Interview (\$)

☐

Tech. Invs (\$)

☐

Weekend (\$)

Rep. Formed: MER 1PComp. Sum. / P.C. 7000

Survey Fee: _____

Transportation: _____

S + PS: _____

Photos: _____

Other: _____

TOTAL

200

11

211

Note: This document has not been finalised.
LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933
Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Katherine Wong

Date: 02 Oct 2019

Preliminary Advice

Insured Vehicle No	: FBN1543X	Accident Date	: 26/09/2019
TP Vehicle No	: SKZ3582A	Assignment Date	: 01/10/2019
Make	: TOYOTA COROLLA ALTIS	Est. Duration of Repair	: 10.00
Date of Inspection	: 01/10/2019		
Inspection At	: CHEW GOON MOTOR (AMK) BLK 10 ANG MO KIO INDUSTRIAL PARK 2A, #01-15/16 & 17, AMK AUTOPOINT SINGAPORE 568047		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear n/s portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	13,152.25
Revised Amount	:S\$	9,206.90
Check Items (Estimated)	:S\$	1,243.75
Total	:S\$	10,450.62
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is economical/not economical for repair.
- (x) The above survey was conducted on a 'without prejudice' basis.

Nivitha (LKK Auto)

From: Crystal Lee <crystal_lee@sg.msig-asia.com>
Sent: Monday, 30 September 2019 4:53 PM
To: Admin-D (LKKAuto); assignments
Cc: Ong Zi Hui; Helene Phua
Subject: Survey Request - Manual Assigned

Our ref: SKZ3582A ; Your ref: FBN1543X Date of acc: 26.09.2019

Manual Assigned

Dear LKK,

Refer to the email below, please arrange survey the vehicle.

We'll assign via Merimen once we receive the assignment from Motor Team.

Please contact us ASAP if you cannot attend this assignment

Thank you & Best regards,
Crystal Lee
Admin Officer, Claims Services (In-House Survey)
D: +65 6594 2535 | F: +65 6643 1349 | crystal_lee@sg.msig-asia.com



MSIG

MSIG Insurance (Singapore) Pte Ltd 16 Raffles Quay, #24-01 Hong Leong Building, Singapore 048581 | T: +65 6220 9644 | F: +65 6225 6371 | Co. Reg. No. 200412212G | msig.com.sg



A Member of **MS&AD** INSURANCE GROUP

From: Motor Survey
Sent: Monday, 30 September, 2019 10:37 AM
To: Helene Phua <helene_phua@sg.msig-asia.com>; Eileen Ang <eileen_ang@sg.msig-asia.com>; Winnie Chua <pingping_chua@sg.msig-asia.com>
Subject: FW: Our ref: SKZ3582A ; Your ref: FBN1543X Date of acc: 26.09.2019

@ HP, for your necessary action.

@ EA, please create folder.

Thank you & Best regards,
Crystal Lee
Admin Officer, Claims Services (In-House Survey)
D: +65 6594 2535 | F: +65 6643 1349 | crystal_lee@sg.msig-asia.com



MSIG



A Member of **MS&AD** INSURANCE GROUP

From: Koh Lay Hoon
Sent: Monday, 30 September, 2019 9:31 AM
To: Motor Survey <motorsurvey@sg.msig-asia.com>
Subject: FW: Our ref: SKZ3582A ; Your ref: FBN1543X Date of acc: 26.09.2019

From: Chew Goon Motor(ad3) [<mailto:ad3@chewgoonmotor.com.sg>]
Sent: Saturday, September 28, 2019 12:31 PM
To: Claims <claims@sg.msig-asia.com>
Cc: Nor Azian Binte Noordin <NorAzian_Noordin@sg.msig-asia.com>; chewgoon@singnet.com.sg; Eric <eric@chewgoonmotor.com.sg>
Subject: Our ref: SKZ3582A ; Your ref: FBN1543X Date of acc: 26.09.2019

EXTERNAL EMAIL: Be careful when you click any links or open any attachment(s).

Dear Sir / Mdm,

Vehicle SKZ3582A is at our workshop, we have to arrange surveyor.
Could you provide us with a list of 10 surveyors name.

Please advise.

Thanks & Regards,
Kelly

Chew Goon Motor
Blk 10, Ang Mo Kio Ind Park 2A,
Ave 5 #01-15 , 16 & 17,
Ang Mo Kio Autopoint
Singapore 568047
Tel : 6484 1626
Fax : 6484 0465

Sent from Mail for Windows 10

CONFIDENTIALITY NOTICE

This e-mail (including any attachments) may contain information that is privileged or confidential. The sending of this e-mail to any person other than the intended recipient is not a waiver of the privilege or confidentiality that attaches to it. If you are not the intended recipient, please notify the sender immediately, delete the email and do not copy, distribute or disclose its contents.



AVIVA

Post an Advertisement
Sell it yourself! Advertise it at just
\$58 until it's SOLD!

Post an Ad

Advertiser Login

Ways of Selling

2011 Lexus CT200h Auto Premium AT \$36K Only



2 Owners, Low Mileage, Well
Maintained, Luxury Hatchback,
View By Appointment
Direct Owner - **Good**



Browse by Category

Sort by Date Posted

20 results/page

4 vehicles

toyota altis

Advanced Search

Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status	
Search Selection	toyota altis	Any	Any	2011	Any	Any	Available	
	Toyota Corolla Altis 1.6A	\$21,900	\$10,940 /yr	04-Jan-2011	1,598 cc	-	Sedan	Available
Will Trade With SUV Or Other Car.								SELECT OWNER
Posted: 29-Sep-2019 Tags: 2011 Toyota Corolla, 2011 toyota corolla, Toyota Corolla, toyota corolla, Toyota, Corolla, corolla, Used Toyota								
	Toyota Corolla Altis 1.6A	\$28,800	\$10,960 /yr	15-Sep-2011	1,598 cc	122,000 km	Sedan	Available
Well Maintained Unit, Reliable Ride, Drive Without Worries, Road Tax Until March 2020, Attractive Interest Rate Of 2.28% Available, Loan/Trade In Welcome, Contact Us For An Appointment Now!								
Posted: 20-Sep-2018 Tags: 2011 Toyota Corolla, 2011 toyota corolla, Toyota Corolla, toyota corolla, Toyota, Corolla, corolla, Used Toyota								
	Toyota Corolla Altis 1.6A	\$28,800	\$11,740 /yr	22-Jul-2011	1,598 cc	127,000 km	Sedan	Available
Very Well Maintained By Previous Owner, Excellent Condition, Accident-Free, Bank And In House Loan Available, Trade-In More Welcome, Powerful Engine And Smooth Transmission, Call Up For Viewing And Test Drive Now.								
Posted: 03-Sep-2019 Tags: 2011 Toyota Corolla, 2011 toyota corolla, Toyota Corolla, toyota corolla, Toyota, Corolla, corolla, Used Toyota								
	Toyota Corolla Altis 1.6A	\$24,800	\$12,200 /yr	24-Feb-2011	1,598 cc	138,200 km	Sedan	Available
First Owner Car! Well Maintained, Excellent Condition, Accident Free, Bank And In House Loan Available, Trade In Are Welcome, Powerful Engine And Smooth Transmission, Buy With Confidence! Call Us Now To Make An Appointment To Viewing.								PREMIUM AD
Posted: 22-Aug-2019 Tags: 2011 Toyota Corolla, 2011 toyota corolla, Toyota Corolla, toyota corolla, Toyota, Corolla, corolla, Used Toyota								

Save this search criteria, to get email alerts whenever a match is found.

Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
-------	-------	--------------	----------	---------	---------	----------	--------

For old advertisements, view Expired ads

20 results/page

[Home](#) | [New Cars](#) | [Used Cars](#) | [Sell My Car](#) | [Directory](#) | [Products](#) | [Insurance](#) | [Article](#) | [Forum](#) | [Resources](#)

sgCarMart is the number one car classifieds for parallel import cars, Toyota, Honda, Nissan, Mitsubishi & BMW. There are plenty of cars for sale, from vans, trucks, sedan cars, luxury cars, sports cars or stationwagons, SUV, MPV, hatchback, to CDE cars & OPC cars. You can also buy from a car auction, look up car loans, financial services, low mileage cars, car brands, carpark rates & car insurance. Find buy used toyota altis, toyota altis Singapore, used toyota altis Singapore, used toyota altis, used vehicles Singapore or even buy used toyota altis Singapore. We have new car dealers comprising parallel importers, authorised car dealers, and used car dealers on our site. Find new car price lists, new car launches and new car promotions. Visit our partner sites for job openings for Singapore jobs, real estate properties for sale, mover, car performance parts, car discussion, forum discussion, commercial vehicle leasing & CDE results.

All prices and other information displayed on sgCarMart.com are gathered from sources and based on algorithms that are believed by sgCarMart.com to be reliable, but no assurance can be given that this information is accurate, complete or current. sgCarMart.com does not assume any responsibility for errors or omissions or warrant the accuracy of this information.

Follow sgCarMart.com

[About Us](#) | [Careers](#) | [Contact Us](#) | [Sitemap](#) | [Terms of Service](#) | [Privacy Policy](#) | [Personal Data Protection Statement](#)

©2004-2019 sgCarMart. All rights reserved.

Complete

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type: Singapore NRIC
Owner ID: 977D

Vehicle Details

Vehicle No.: SKZ3582A
Vehicle to be Exported: No
Intended Deregistration Date: 27 Sep 2019
Vehicle Make: TOYOTA
Vehicle Model: COROLLA ALTIS 1.6 AUTO
Primary Colour: Silver
Manufacturing Year: 2011
Engine No.: 1ZR071097
Chassis No.: MR053REE104112536
Maximum Power Output: 90.0 kW (120 bhp)
Open Market Value: \$15,510.00
Original Registration Date: 07 Mar 2011
First Registration Date: 07 Mar 2011
Transfer Count: 3
Actual ARF Paid: \$15,510.00

Intended PARF Rebate Details

PARF Eligibility: Yes
PARF Eligibility Expiry Date: 06 Mar 2021
PARF Rebate Amount: \$8,530.00

Intended COE Rebate Details

COE Expiry Date: 06 Mar 2021
COE Category: A - Car (1600cc & below)
COE Period(Years): 10
QP Paid: \$42,999.00
COE Rebate Amount: \$6,173.00
Total Rebate Amount: \$14,703.00

The information contained herein is correct as at 27 Sep 2019

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	27/09/2019 13:44
Date Of Accident	26/09/2019 18:30
Exact Location Of Accident	ALONG PAN ISLAND EXPRESSWAY
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKZ3582A
Insured/Policyholder	
Name Of Registered Owner	NEO SIN GEE
NRIC No	S1478977D
Email Address	NEOTINGLING@GMAIL.COM
Mobile Phone No	(LOCAL) +65-81989307
Alternative Phone No	OTHERS-81989307

Vehicle Particulars

Manufacturer	TOYOTA
Model	COROLLA ALTIS 1.6 AUTO
Exact Purpose for which vehicle was being used at time of accident	PRIVATE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE HIRE

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5104517692
Cover Note Number	

Driver

Name of Driver	NEO SIN GEE
NRIC No	S1478977D
Date Of Birth	24/01/1961
Occupation	OUTDOOR
Date Of Driving Pass	27/02/1979
Driving Experience	40 YEARS AND 6 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-81989307
Fax Number	
Contact Number	OTHERS-81989307
Email Address	NEOTINGLING@GMAIL.COM

Address	BLK 345 YISHUN AVENUE 11 #10-165
Postcode	760345
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	CHAIN COLLISION
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	3
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	YES
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : UNKNOWN
	GENDER: : MALE

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	YISHUN NORTH NEIGHBOURHOOD POLICE CENTRE
Police Station Address	ROAD: 31 YISHUN CENTRAL , POSTCODE: 768827 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: 1800-8529999 - FAX NO: 68522299
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO ATTACHED POLICE REPORT NO: T20190926/2202.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	PASS TO TRAFFIC POLICE
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	FBN1543X
Vehicle Make/Model/Colour	(Honda CB 150R)
Details Of Properties	
Vehicle Category	MOTORCYCLE
Name of Driver	UNKNOWN
NRIC/Passport Number	
Contact Number	

Address
Postcode
Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number SJO8403K
Vehicle Make/Model/Colour
Details Of Properties
Vehicle Category PRIVATE CAR
Name of Driver NI ZHI WEI
NRIC/Passport Number
Contact Number 91993756
Address
Postcode
Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name UNKNOWN
Approximate Age
Injuries Sustain
Injured person in which vehicle? FBN1543X
Were seat belts worn?
Was this injured conveyed to hospital by ambulance? YES
Address
Postcode

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE


1. Please report correctly the details of the accident to speed up the claims process.
2. This form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

E. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/un be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated; or
 - (ii) for complying with requirements under any regulations, laws or court orders.


Policyholder's Signature
Date & Time:


Driver's Signature
(If driver is not the policyholder)
Date & Time:


Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Sketch Plan #2

SKETCH PLAN

P/E towards Chongli after Thomson Exit

A: SK235820

B: FBV1543X

C: SJQ8403K

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Refer to attached Police Report.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/PM No.:



Police Station Of Origin:
Yishun North N.P.C
31 Yishun Central SINGAPORE 768827
Tel No: 1800-8529999

Report No. T/20190926/2202

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 26/09/2019 23:18		Vide Report No.: E/20190926/0121		Station Diary No.: 250	
Informant's Particulars					
Name of Informant: NEO SIN GEE			Address: APT BLK 345 YISHUN AVENUE 11 #10-165 SINGAPORE 760345		
ID Type / ID No.: NRIC NO / S1478977D			Contact No.: Home/Office: 81989307 Mobile:		
Nationality: SINGAPORE CITIZEN			Email:		
Sex: Male	Age: 58	Date of Birth: 24/01/1961	Type of Informant: Driver		
Race: Chinese			Language:		Institution / School Name:
Occupation: GRAB DRIVER			Driving Licence Information: Class: 3 Date of Expiry:		

General Information of the Accident

Type of Accident:	Injury Conveyed By Ambulance	Drink Drive: No	Date/Time of Accident: 26/09/2019 18:30	Type of Location: Straight Road
Location: Along Road 1 PAN-ISLAND EXPRESSWAY				
Its along PIE towards Changi after the Thomson Exit				
Weather: Clear		Road Surface: Dry		Road Speed Limit:
Traffic Flow:		Traffic Control: Not Controlled		Traffic Volume: Heavy
Type of Collision: Between Moving Vehicles - Head To Rear				Anyone conveyed by ambulance: Yes

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
FBN1543X	Motorcycle					0
SJQ8403K	Car					0
SKZ3582A	Car	TOYOTA	COROLLA ALTIS 1.6 AUTO	Silver	Seriously Damaged	1

Details of Vehicle Insurance

Vehicle No.	Insurance Company	Insurance No.	Effective	Expiry Date
-------------	-------------------	---------------	-----------	-------------



Police Station Of Origin:
Yishun North N.P.C
31 Yishun Central SINGAPORE 768827
Tel No: 1800-8529999

Report No. T/20190926/2202

CONTINUATION OF REPORT

Details of Vehicle Insurance				
Vehicle No.	Insurance Company	Insurance No	Effective	Expiry Date
SKZ3582A	NTUC Income Insurance Co-Operative Limited	5104517692	11/10/2018	06/03/2020

Details of Person Involved			
Any Pedestrian Involved: No			
No. of Pedestrians Injured: NIL		Use of Pedestrian Crossing: NA	
Driver			
Name	NEO SIN GEE	ID No.	S1478977D
Related Vehicle	SKZ3582A (Car)	Contact No.	81989307
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: 3 Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

Brief Details.

On 26/09/2019 at about evening 6.30pm, I was driving along PIE towards Changi after the Thomson Exit. I was driving at the first lane and the road I was driving in was a 3 lane road. The traffic was quite heavy. I had a passenger with me. My vehicle is SKZ3582A. There was a motorbike, FBN1543X, behind me and he was riding quite fast. Suddenly he banged onto my vehicle rear on the left side and fell on the 2nd lane up front. The vehicle, SJQ8403K, which was travelling on the lane 2 had to suddenly brake. I called for ambulance. Certis cisco, ambulance and traffic police was at scene. No one was injured in my vehicle including me. However I am not sure of the extend of injuries for the rider. The rider was conveyed by ambulance. My car was quite badly damaged on the rear left. My rear windscreen had been cracked like a spider web, my brake light, and the back side light has been all damaged. My vehicle was also badly dented at the rear left. I managed to exchange contact number with the vehicle owner of SJQ8403K, his name is Ni Zhiwei and contact 91993756.



Police Station Of Origin:
Yishun North N.P.C
31 Yishun Central SINGAPORE 768827
Tel No: 1800-8529999

Report No. T/20190926/2202

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report:
L /
Sr Staff Sgt KAVITHA D/O MAGENDARAN

Signature Of Interpreter:
Not applicable

Officer In Charge Of Case:
TP / GIT /
Sr Staff Sgt MOHAMMED FEROZ BIN HUSSEIN
Contact No.: 65476206

Signature Of Informant:

Date/Time:
26/09/2019 23:18

Classification Of Case:

SN 085

Authentication Stamp
NP168



Signature:

Singapore Police Force

Certificate of Insurance

MOTOR VEHICLES (THIRD PARTY RISKS AND COMPENSATION) ACT (CHAPTER 189)
MOTOR VEHICLES (THIRD PARTY RISKS AND COMPENSATION) RULES, 1960
ROAD TRANSPORT ACT, 1987 (MALAYSIA)
MOTOR VEHICLES (THIRD PARTY RISKS) RULES, 1959 (MALAYSIA)

Certificate Number: 5104517692

Cover : drive CLASSIC

1. Index mark and Registration Number of Vehicle : **SKZ3582A**
Chassis Number : **MR053REE104112536**
2. Name of Policyholder : **NEO SIN GEE**
3. Effective Date of Insurance : **11 Oct 2018**
4. Expiry Date of Insurance : **10 Oct 2019**
5. Persons or Classes of Persons entitled to drive#
(a) The Policyholder.
(b) Any other person who is driving on the Policyholder's order or with his/her permission.
Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.
6. Limitations as to Use#
(a) Use for social domestic and pleasure purposes and in connection with the Policyholder's or Hirer's business.

This Policy does not cover

- (a) Use for racing, pace-making, reliability trial or speed-testing.
- (b) Use for the carriage of goods (other than samples) in connection with any trade or business.
- (c) Use for any purpose in connection with the Motor Trade.

Limitations rendered inoperative by Section 8 of the Motor Vehicle (Third Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

EXCESS (SECTION 1)	: \$2,000
EXCESS (SECTION 2)	: \$1,500
WINDSCREEN EXCESS	: \$100
ADDITIONAL EXCESS	: N/A
UNNAMED DRIVER EXCESS	: PLEASE REFER OVERLEAF
REPAIR AT OWNER'S PREFERRED WORKSHOP	: NO
INSURE WITH COE	: YES
NCD PROTECTION	: NO
TRANSPORT ALLOWANCE	: NO
EXCESS WAIVER	: NO
PRIMARY DRIVER	: NEO SIN GEE
NAMED DRIVER (1)	: N/A
NAMED DRIVER (2)	: N/A
HIRE PURCHASE COMPANY	: N/A
SUM INSURED	: MARKET VALUE OF INSURED VEHICLE AT TIME OF LOSS

I/We hereby Certify that the Policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia)

Agency : DICKSON INSURANCE AGENCY PTE. LTD. (00000573832)
Date of Issue : 11 Oct 2018 13:28 hrs

For NTUC INCOME INSURANCE CO-OPERATIVE LIMITED



Countersigned By:

Authorised Officer



Chief Executive

趙 源 摩 哆 Chew Goon Motor

Blk 10, Ang Mo Kio Industrial Park 2A, Avenue 5
#01-15, 16, 17 & #03-05, AMK Autopoint Singapore 568047
Tel: 6484 1626 (24Hrs) Fax: 6484 0465
Business Reg. No: 221880/00C GST Reg. No: MX-0486007-A0

Not Notion
2/10/19
10 days
870000 max
Assess After Paint

To: MSIG Insurance (S) Pte Ltd

Policy No: Third Party

Date: 30.09.2019

Accident Date : 26.09.2019

Specialised in Car Painting, Welding,
Panel-Beating and Insurance Claim.

ESTIMATE

承接汽车烧焊喷漆及
代理各种车辆赔偿

数量 Quantity	货 名 DESCRIPTION	单 价 Unit Price	银 Amount 额 \$ cts.
Estimate Cost of Repair "Toyota Altis" Reg. No. SKZ3582A Claiming Against Your Insured Veh. No. FBN1543X			
1pc	Boot		By 792.00 ✓
1pc	Boot Hinge LH		R 71.80 X
1pc	Boot Center Emblem		M 57.40
1pc	Boot Badge "1.6"		M 42.40
1pc	Boot Badge "VVTi"		M 40.90
1pc	Boot Badge "Dual"		M 78.00
1pc	Boot Badge "Corolla"		M 46.50
1pc	Boot Badge "Altis"		M 48.20
1pc	Boot Badge "Elegance"		M 102.00
1pc	Boot Outer Chrome Moulding		Red 185.00
1pc	Boot Lamp LH		Bro 185.00
1pc	Boot Lamp Gasket		Tn 62.00
1pc	Boot Lamp Wiring Harness - photo 2		CM 385.00
1pc	Boot Stopper LH		M 10.30
1pc	Boot Lock		M 106.00
1pc	Boot Lock Catch		R 32.00 X
1pc	Boot Weatherstrip		Dij/Rd 191.00 5000
1pc	Boot Trim Board		Sm 282.00 X
10pcs	Boot Trim Board Clips	3.80	M 38.00 X
1pc	Rear Bumper		Tn 495.00
10pcs	Rear Bumper Clips	3.80	M 38.00
1pc	Rear Bumper Sponge		CM 129.00
1pc	Rear Bumper Bracket LH		D 87.50
1pc	Rear Bumper Reflector LH		M 37.00
1pc	Rear Bumper Top Retainer LH		CM 79.00
1pc	Rear Bumper Corner Retainer LH		CM 110.00
1pc	Taillamp LH		Bro 386.00
1pc	Taillamp Gasket		M 55.00
1pc	Taillamp Panel		R 215.00
1pc	Rear Joint Panel (Taillamp-End Panel)		R 255.00
1pc	End Panel		R 607.00
1pc	End Panel Ganish		M 203.00
1pc	Rear Fender LH		Bro 1,418.00
1pc	Rear Fender Inner Panel		R 785.00 X
1pc	Rear Fender Trim Board		Deform 345.00
1pc	Rear Fender Lower Splash Shield		CM 195.00
		C/F	8,195.00

UKK Auto Consultants hence notify
the Repairer of the following:

- To relay/review before/after spray painting
- To display damaged part(s) during insurance survey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No legal mediation/claim involved
- Supplementary costs must be reviewed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

趙 源 摩 哆 Chew Goon Motor

Blk 10, Ang Mo Kio Industrial Park 2A, Avenue 5
#01-15, 16, 17 & #03-05, AMK Autopoint Singapore 568047
Tel: 6484 1626 (24Hrs) Fax: 6484 0465
Business Reg. No: 221880/00C GST Reg. No: MX-0486007-A0

To: MSIG Insurance (S) Pte Ltd

Policy No: Third Party

Date: 30.09.2019

Accident Date : 26.09.2019

Specialised in Car Painting, Welding,
Panel-Beating and Insurance Claim.

ESTIMATE

承接汽车烧焊喷漆及
代理各种车辆赔偿

数量 Quantity	货 名 DESCRIPTION	单 价 Unit Price	银 Amount 額 \$ cts.
Estimate Cost of Repair "Toyota Altis" Reg. No. SKZ3582A Claiming Against Your Insured Veh. No. FBN1543X			
		B/F	8,195.00
1pc	Rear Fender Lower Air Vent		<i>nu</i> 120.00 ✓
1pc	Rear Fender Inner Top Ganish		<i>ni / m</i> 155.00 ✓
1pc	Fuel Lid		<i>bu</i> 103.00 ✓
1pc	Fuel Lid Base Panel		<i>n</i> 320.00 ✗
1pc	Rear Door Inner Lock LH		<i>n</i> 285.00 ✗
1pc	Rear Door Weatherstrip		<i>su</i> 195.00 ✗
1pc	Rear Windscreen Glass		<i>Shatter</i> 550.00 ✓
1pc	Rear Speaker Board		<i>n</i> 180.00 ✗
1pc	Roof Panel Drip Moulding		<i>su</i> 168.00 ✗
			10,271.00
	Less 25%		2567.75
			7,703.25
1pc	Rear Bumper Reverse Sensor		<i>su</i> 280.00 SN ✗
2pcs	Fuel Lid Rivets	9.50	<i>nu</i> 19.00 SN ✗
1pc	Rear Windscreen Glass Sealant		<i>40 su</i> 50.00 SN ✓
1pc	Rear Windscreen Glass Fastener		<i>nu</i> 30 su 50.00 SN ✓
1pc	Rear Windscreen Glass 3M Solar Film		<i>nu</i> 180.00 SN ✓
1pc	Rear Windscreen Glass Decal (Private Hire)		<i>nu</i> 40.00 SN ✓
	To Conduct Rear Electrical Check, Replace Reverse Sensors, Module etc.		120.00 <i>For</i>
	To Dismantle / Transfer Boot Fittings / Ancillary Accessories		120.00 <i>60 100</i>
	To Dismantle / Refit Rear Windscreen Glass		160.00 <i>120</i>
	To Dismantle / Refit Roof Lining		150.00 } <i>120</i>
	To Dismantle / Refit Trunk Compartment Boards & Trims etc		80.00 }
	To Dismantle / Refit Fuel Tank Inlet Hoses & Piping		100.00 <i>60</i>
	To Supply Rear Body Panel Sealant		100.00 <i>60</i>
		C/F	9,152.25

趙 源 摩 哆 Chew Goon Motor

Blk 10, Ang Mo Kio Industrial Park 2A, Avenue 5
#01-15, 16, 17 & #03-05, AMK Autopoint Singapore 568047
Tel: 6484 1626 (24Hrs) Fax: 6484 0465
Business Reg. No: 221880/00C GST Reg. No: MX-0486007-A0

To: **MSIG Insurance (S) Pte Ltd**

Policy No: **Third Party**

Date: **30.09.2019**

Accident Date : 26.09.2019

Specialised in Car Painting, Welding,
Panel-Beating and Insurance Claim.

ESTIMATE

承接汽车烧焊喷漆及
代理各种车辆赔偿

数量 Quantity	货 名 DESCRIPTION	单 价 Unit Price	银 Amount 额 \$ cts.
	Estimate Cost of Repair "Toyota Altis" Reg. No. SKZ3582A Claiming Against Your Insured Veh. No. FBN1543X		
		B/F	9,152.25
	To Mount Vehicle on Car "O" Liner Chassis Alignment Equipment/ Workbench for Chassis Alignment to Facilitate Repair		<i>nn</i> 350.00 <i>X</i>
	To Perform Interior Of Glass Debris, Detailing etc		120.00 <i>301</i>
	To Conduct Computerize Wheel Alignment Test		<i>nn</i> 80.00 <i>X</i>
	To Apply Rust Proofing / Reseal Tuff Coating Treatment to Respray / Replaced / Repair Panel		150.00 <i>901</i>
	Labour Charge - Panel Beating, Repairing Rear Chassis Member, Inner Panel, Spare Tyre Panel, Rear N/S Door, Rear Speaker Panel etc. Cnt, Weld End Panel, Rear Fender, Inner Panel and Parts Replacement		<i>1400</i> 1,800.00
	To Respray Affected Areas		<i>1000</i> 1,500.00
		Total :	13,152.25

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG19017193/KQF3N2

Date: 06/11/2019

REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	MSD/VMS/19-402068
Claimant Vehicle No :	SKZ3582A	Insured Vehicle No :	FBN1543X
Date of Loss:	26/09/2019	Nature of Claim:	TP
		Claim No:	MSC/V/19-001169

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKZ3582A	Engine No:	1ZRX071097
Make & Model:	TOYOTA COROLLA ALTIS, 1.6 (A)	Chassis No:	MR053REE104112536
Reg. Date:	07/03/2011 (Man. Year: 2011)	Odometer:	217313 km
Colour:	Metallic Grey		
Engine Capacity:	1598 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/55R16	Rear Tyre Size:	205/55R16
Front Left Side:	Yokohama 4 mm	Rear Left Side:	Yokohama 2 mm
Front Right Side:	Yokohama 4 mm	Rear Right Side:	Yokohama 2 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	8,322.25	6,196.90	2,125.35	25.54
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,830.00	3,010.00	1,820.00	37.68
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	13,152.25	9,206.90	3,945.35	30.00
Approved Total (Overridden) (S\$)		7,000.00		
(S\$)	13,152.25	7,000.00	6,152.25	46.78
+ GST 7.00/7.00% (S\$)	920.66	490.00	430.66	46.78
Nett Amount (S\$)	14,072.91	7,490.00	6,582.91	46.78

INSPECTION

Date of Assignment:	01/10/2019	
Date Inspected:	01/10/2019	Inspected At: Chew Goon Motor (AMK) Blk 10 Ang Mo Kio Industrial Park 2A, #01-15/16 & 17, AMK Autopoint Singapore 568047
Estimated Period of Repair:	10.0 days	

Adjuster: KENNETH KONG

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 06 Nov 2019)
Parts:	143	TOYOTA COROLLA ALTIS 1.6 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKZ3582A)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOT	Bent	792.00 FL	*792.00 FL
2	1		*BOOT HINGE LH	Repair	71.80 FL	*- FL
3	1		*BOOT CENTER EMBLEM	Necessary	57.40 FL	*57.40 FL
4	1		*BOOT BADGE 1.6	Necessary	42.40 FL	*42.40 FL
5	1		*BOOT BADGE VVTI	Necessary	40.90 FL	*40.90 FL
6	1		*BOOT BADGE DUAL	Necessary	78.00 FL	*78.00 FL
7	1		*BOOT BADGE COROLLA	Necessary	46.50 FL	*46.50 FL
8	1		*BOOT BADGE ALTIS	Necessary	48.20 FL	*48.20 FL
9	1		*BOOT BADGE ELEGANCE	Necessary	102.00 FL	*102.00 FL
10	1		*BOOT OUTER CHROME MOULDING	Dented	185.00 FL	*185.00 FL
11	1		*BOOT LAMP LH	Broken	185.00 FL	*185.00 FL
12	1		*BOOT LAMP GASKET	Torn	62.00 FL	*62.00 FL
13	1		*BOOT LAMP WIRING HARNESS	Cracked	385.00 FL	*385.00 FL
14	1		*BOOT STOPPER LH	Missing	10.30 FL	*10.30 FL
15	1		*BOOT LOCK	Dented	106.00 FL	*106.00 FL
16	1		*BOOT LOCK CATCH	Repair	32.00 FL	*- FL
17	1		*BOOT TRIM BOARD	Serviceable	282.00 FL	*- FL
18	10		*BOOT TRIM BOARD CLIPS	Not Necessary	38.00 FL	*- FL
19	1		*REAR BUMPER	Torn	495.00 FL	*495.00 FL
20	10		*REAR BUMPER CLIPS	Necessary	38.00 FL	*38.00 FL
21	1		*REAR BUMPER SPONGE	Cracked	129.00 FL	*129.00 FL
22	1		*REAR BUMPER BRACKET LH	Distorted	87.50 FL	*87.50 FL
23	1		*REAR BUMPER REFLECTOR LH	Missing	37.00 FL	*37.00 FL
24	1		*REAR BUMPER TOP RETAINER LH	Cracked	79.00 FL	*79.00 FL
25	1		*REAR BUMPER CORNER RETAINER LH	Cracked	110.00 FL	*110.00 FL
26	1		*TAILLAMP LH	Broken	386.00 FL	*386.00 FL
27	1		*TAILLAMP GASKET	Necessary	55.00 FL	*55.00 FL
28	1		*TAILLAMP PANEL	Bent	215.00 FL	*215.00 FL
29	1		*REAR JOINT PANEL (TAILLAMP-END PANEL)	Bent	255.00 FL	*255.00 FL
30	1		*END PANEL	Bent	607.00 FL	*607.00 FL
31	1		*END PANEL GARNISH	Mtg Cracked	203.00 FL	*203.00 FL
32	1		*REAR FENDER LH	Buckled	1,418.00 FL	*1,418.00 FL
33	1		*REAR FENDER INNER PANEL	Repair	785.00 FL	*- FL
34	1		*REAR FENDER TRIM BOARD	Deformed	345.00 FL	*345.00 FL
35	1		*REAR FENDER LOWER SPLASH SHIELD	Cracked	195.00 FL	*195.00 FL
36	1		*REAR FENDER LOWER AIR VENT	Dented	120.00 FL	*120.00 FL
37	1		*REAR FENDER INNER TOP GARNISH	Distorted/Cut	155.00 FL	*155.00 FL
38	1		*FUEL LID	Buckled	103.00 FL	*103.00 FL
39	1		*FUEL LID BASE PANEL	Repair	320.00 FL	*- FL
40	1		*REAR DOOR INNER LOCK LH	Repair	285.00 FL	*- FL
41	1		*REAR DOOR WEATHERSTRIP	Serviceable	195.00 FL	*- FL
42	1		*REAR WINDSCREEN GLASS	Shattered	550.00 FL	*550.00 FL
43	1		*REAR SPEAKER BOARD	Repair	180.00 FL	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
44	1		*ROOF PANEL DRIP MOULDING	Serviceable	168.00 FL	*- FL
45	1		*BOOT WEATHERSTRIP (50%)	Distorted/Dented	191.00 FN	*95.50 F
46	1		*REAR BUMPER REVERSE SENSOR	Serviceable	280.00 FS	*- FS
47	2		*FUEL LID RIVETS	Necessary	19.00 FS	*19.00 FS
48	1		*REAR WINDSCREEN GLASS SEALANT	Necessary	50.00 FS	*40.00 FS
49	1		*REAR WINDSCREEN GLASS FASTENER	Necessary	50.00 FS	*30.00 FS
50	1		*REAR WINDSCREEN GLASS 3M SOLAR FILM	Necessary	180.00 FS	*180.00 FS
51	1		*REAR WINDSCREEN GLASS DECAL (PRIVATE HIRE)	Necessary	40.00 FS	*40.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc. N=NettItemDisc.

Sub Total (\$\$)	10,890.00	8,127.70
- List Item Discount on L Items 25.00/25.00% (\$\$)	2,520.00	1,930.80
- Nett Item Discount on N Items 25.00/0.00% (\$\$)	47.75	0.00
Total Parts (\$\$)	8,322.25	6,196.90

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CONDUCT REAR ELECTRICAL CHECK,REPLACE REVERSE SENSORS,MODULE ETC	New	120.00	70.00
2	TO DISMANTLE/TRANSFER BOOT FITTINGS/ANCILLARY ACCESSORIES	New	120.00	60.00
3	TO DISMANTLE/REFIT REAR WINDSCREEN GLASS	New	160.00	120.00
4	TO DISMANTLE/REFIT ROOF LINING }	New	150.00	120.00
5	TO DISMANTLE/REFIT TRUNK COMPARTMENT BOARDS & TRIMS ETC)	New	80.00	0.00
6	TO DISMANTLE/REFIT FUEL TANK INLET HOSES & PIPING	New	100.00	60.00
7	TO SUPPLY REAR BODY PANEL SEALANT	New	100.00	60.00
8	TO MOUNT VEHICLE ON CAR O LINER CHASSIS ALIGNMENT EQUIPMENT/WORKBENCH FOR CHASSIS ALIGNMENT TO FACILITATE REPAIR	New	350.00	0.00
9	TO PERFORM INTERIOR OF GLASS DEBIS,DETAILING ETC	New	120.00	30.00
10	TO CONDUCT COMPUTERIZE WHEEL ALIGNMENT TEST	New	80.00	0.00
11	TO APPLY RUST PROOFING/RESEAL TUFF COATING TREATMENT TO RESPRAY/REPLACED/REPAIR PANEL	New	150.00	90.00
12	LABOUR CHARGE-PANEL BEATING,REPAIRING REAR CHASSIS MEMBER,INNER PANEL,SPARE TYRE PANEL,REAR N/S DOOR,REAR SPEAKER PANEL ETC.CNT,WELD END PANEL,REAR FENDER,INNER PANEL AND PARTS REPLACEMENT	New	1,800.00	1,400.00
13	TO RESPRAY AFFECTED AREAS	New	1,500.00	1,000.00
Gross Labour Cost (S\$)			4,830.00	3,010.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >