

EM-1 AUTO PTE LTD

BLK 8 SIN MING INDUSTRIAL ESTATE SECTOR C

#01-68 SINGAPORE 575643

Contact Number: 6452 3298 (O) 9666 6556 (H/P) 6457 5776 (F)

Email Address: em1autopteid@gmail.com

COMPANY / GST REG NO : 201316380R

Vehicle Number : SKZ 176J
Vehicle Model : HONDA VEZEL
Accident Date : 26.09.2019
Original Reg Date : 05.01.2016

Date : 30.09.2019
Chassis : RU31115657
TP Ins. : **AIG**

ESTIMATE

1	1 pc	Tailgate			1,685.50
2	1 pc	Tailgate Outer Garnish	NN	X	290.00
3	1 set	Tailgate Outer Garnish Clip	NN	X	40.00
4	1 pc	Tailgate Badge		NA	56.00
5	1 pc	Tailgate Emblem VEZEL		NA	80.00
6	1 pc	Tailgate Emblem HYBRID		NA	96.20
7	2 pcs	Tailgate Lamps	285.00	NA	570.00
8	2 pcs	Tailgate Lamp Inner Sealer	38.00	NA	76.00
9	2 pcs	Tailgate Lamp Clips	25.00	NA	50.00
10	1 pc	Tailgate Inner Trim		NA	325.00
11	1 set	Tailgate Inner Trim Clips		NA	30.00
12	1 pc	Tailgate Inner Lock		NA	340.30
13	1 pc	Tailgate Auto Lock Actuator	NN	X	172.20
14	1 pc	Tailgate Lock Catch	NN	X	56.00
15	1 pc	Tailgate Weatherstrip		NA	196.80
16	1 pc	Rear Windscreen Moulding		NA	128.00
17	1 pc	Rear Windscreen Inner Seal		NA	60.00
18	1 pc	Rear Bumper		NA	1,185.00
19	2 pcs	Rear Bumper Side Retainers LH-RH	NN		46.00 92.00
20	2 pcs	Rear Bumper Attachment Retainers LH-RH	NN		42.00 84.00
21	1 set	Rear Bumper Clips		30mm	50.00
22	2 pcs	Rear Bumper Side Pad LH-RH	NN	NA	289.50 579.00
23	1 pc	Rear Bumper Lower Cover		NA	196.00
24	1 set	Rear Bumper Lower Cover Clip		NA	30.00
25	1 pc	Spare Tyre Panel Top Board	NN	X	381.00
26	1 pc	Spare Tyre Panel Top Tool Tray		NA	351.00
27	2 pcs	Taillamps	680.00	NA	1,360.00
28	2 pcs	Taillamps Inner Sealer	38.00	NA	76.00
29	2 sets	Taillamps Clips	25.00	NA	50.00
30	1 pc	End Panel		NA	695.50
31	1 pc	End Panel Top Trim		NA	176.00
32	1 set	End Panel Top Trim Clips		NA	30.00

C/D

9,587.50

PRELIMINARY
FINALIZATION
Repair Cost
FINAL SETTLEMENT
Final Liability
Repair Cost
Loss of Rental (LOR)
Loss of Use (LOU)
Loss of Income (LOI)
LOR only
GIA/LTA Search
Medical
Disbursement
Legal Cost
Total:
FINAL PAYMENT
Payee 1:
Payee 2: (Strike if N/A)
Payee 3: (Strike if N/A)
KCK
A310

KCK
A310

EM-1 AUTO PTE LTD

BLK 8 SIN MING INDUSTRIAL ESTATE SECTOR C
#01-68 SINGAPORE 575643
Contact Number: 6452 3298 (O) 9666 6556 (H/P) 6457 5776 (F)
Email Address: em1autopteind@gmail.com
COMPANY / OCT REG NO : 2011183808

Vehicle No : SKZ 176J

B/F

9,587.50

1	1 pc	Alarm Sensor Speaker		Exp	150.00
2	1 pc	Rear Key Antenna Sensor	NN	7	175.00
3	2 pcs	Rear Fender Inner Trim	NN	335.00	x 670.00
4	1 set	Rear Fender Inner Trim Clip	NN	x	30.00
					10,612.50
Less 20%					2,122.50
					8,490.00

Special Nett

1	1 pc	Rear Windscreen Sealant	Pass		60.00
2	1 set	Body Panel Joint Sealant	NEC	40	120.00
3	1 set	Rear Camera	NN	x	450.00
4	1 set	Reverse Sensor	2.00	250.00	

Labour charge

Panel Beating	600	1,000.00
Spray painting	200	1,000.00
Check Wiring	30	50.00
Anti rust	30	100.00
Remove and install rear winscreen.	120	140.00
Remove and install tailgate parts.	60	90.00
Remove and install carpet and seat.	60	120.00
Remove and install rear exhaust.		x 120.00
Remove and install reverse camera	30	120.00
Remove and install reverse sensor	30	90.00

12,200.00

Less 20% 2,440.00

Lump sum 9,760.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Taufik 9745149
- WP

01/10/19 @ 12pm

Lump sum

Resurvey after repair

5 days

taufik@lkkauto.com
sur@lkkauto.com

EM-1 AUTO PTE LTD

BLK 8 SIN MING INDUSTRIAL ESTATE SECTOR C
#01-68 SINGAPORE 575643

Contact Number: 6452 3298 (O) 9666 6556 (H/P) 6457 5776 (F)

Email Address: em1autopteltd@gmail.com
COMPANY / GST REG. NO: 201316380R

Your Vehicle: SLM6578A (3rd Party Vehicle)
Our Vehicle: SKZ 176J

Date: 30.09.2019

M/s AIG Asia Pacific Insurance Pte Ltd
AIG Building
78 Shenton Way
#07-16
Singapore 079120

By email :
ClaimsDocManagement@aig.com

Dear Sir/Madam,

ACCIDENT INVOLVING SKZ 176J & SLM6578A ON 26/9/2019

We refer to the above matter.

I hereby give you 2 days' notice to conduct a pre-repair inspection of vehicle SKZ 176J
at my premises.

Vehicle to be survey as follow :

Yours faithfully

Chia

160 Sin Ming Drive
#65-21 Sing Ming Autocity
Singapore 575722

PIC - Mr Chua @ 96666556