

INSURANCE

INS. CASE OWNER:

Shervini

CC 4

/III 1901

7283

Ugbo

LKK:
IDAC:

Surveyor:

MARCUS

DOI:

ASSIGNMENT

2/10/19

Date / Time:

20/11/19

Registered in Merimen:

1/10/19

Pre-assign / CCU / FTE



Insured Vehicle No.:

SMC 3032C

Name of Insured:

LTPU

Insured Tel No.:

HP:

Claim No.:

Policy No.:

Make / Model:

Place of Accident:

Excess Sec II :\$5

D.O.A.:

30/11/19

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age: ABBAHOM (HAW BEEN NO AL)

Driver Tel No.:

(VL: YES / NO)

OI GIA REPORT: YES / NO : TP GIA REPORT: YES / NO

Insured Liability:

Final ? Yes / No

SMK 85890



INSRS:
WSP:
Tel:
Liability:
RMKS:

JMK



INSRS:
WSP:
Tel:
Liability:
RMKS:



INSRS:
WSP:
Tel:
Liability:
RMKS:



INSRS:
WSP:
Tel:
Liability:
RMKS:

Date/ Time		STAGE	DATE/ PIC
2/10	- liability unclear send TP	Non-Reporting 1st (1st):	
	REQ AMF from OI & TP	Non-Reporting 1st (2nd):	
3/10	- seek III instruction to reject or	Non-Reporting 1st (Final):	
	settle @ 50/50. If simple lane road	Notification 1st (if non-pickup):	
	try to overtake OI when it	Call OI:	
	attempting to park vehicle. TP should	After call 1st to OI:	
	wait patiently for OI to complete	Documentation Check List: Handler Typist	
	parking.	Notification 1st (if non-pickup):	
8/10	- Pichon email send TP.	After call 1st to OI:	
	To submit WP report. File pass Admin	Authorisation To Act:	
	to close.	Release Voucher:	
		Final Repair Bill:	
		Car Rental Invoice:	
		Towing Invoice:	
		LTA / GIA:	
		Medical Bill:	
		PIR:	
		Mandate/Reject Instruction:	
		LOD:	
		Payment Breakdown Form:	
		Post-Repair Photos:	
		Others:	

PRELIMINARY ADVICE		Date/Time:	Sent By:	Confirm with:	Confirm by:	Post-Repair Photos:		
FINALIZATION		Date/Time:		Confirm with:	Confirm by:	Others:		
Repair Cost:	LIS	\$5 17501-	(3 days)	Reduction:	91348 - 96 % 44	Email	<input type="checkbox"/>	Call <input type="checkbox"/>
FINAL SETTLEMENT		Date/Time:		Confirm with:		Email	<input type="checkbox"/>	Call <input type="checkbox"/>
Final Liability:	%	(Agreed / Assessed) BOLA S/N No. :			If NO or B 28, Ass. Lia :			
Repair Cost:	\$5				COPY SENT 10/10/29			
Loss of Rental (LOR):	\$5	(days)						
Loss of Use (LOU):	\$5	(5 x days)						
Loss of Income (LOI):	\$5	(5 x days)						
LOR only <input type="checkbox"/>	LOU only <input type="checkbox"/>	LOR + LOU <input type="checkbox"/>	LOR + LO <input type="checkbox"/>	(Tick only one)				
GIA/LTA Search	\$5							
Medical:	\$5				1) Claim status: Normal/Reject/Private Settle			
Disbursement:	\$5	(e.g. Tow/ Independent)			2) Report Format: WP #2501-			
Legal Cost	\$5				3) Survey fee:			
Total:	\$5	Global Sum \$5:						
FINAL PAYMENT		Date/Time:		Confirm with:		Email	<input type="checkbox"/>	Call <input type="checkbox"/>
Payee 1:	\$5	Name 1:						
Payee 2: (Strike if N.A.)	\$5	Name 2:						
Payee 3: (Strike if N.A.)	\$5	Name 3:						

COPY SENT
10/10/19

ASS. REC. BY:

REF: TH

9

ASSIGNMENT

From:

Date

1-10-2019

Estimated Cost:

OD TP / WS / TP RES / OD RES / EVA / INV / MVTo inspect Vehicle No: SMK 859ADat Workshop m/s Joo Hak Keeat BK 2007 Ubi road 1 #01-406

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh: AAK 10,000.00

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Report: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 3 days Res.: Yes or NoLum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

"rup"

Vehicle: IN / OUT

Date: Person Contacted:

Veh No:

SMK 859AD

Yr Regn:

419Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

CA

Make:

Honda Shuttlec.c. 1496

Colour:

Grey

A/C: Insured / Std / NI / NA

Sp. Reading

21008

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

GK 82001222Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F: 205/50 R16

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal.

S

mm

Rear

R/Bal.

S

mm

L/Bal.

S

mm

L/Bal.

S

mm

D.O.A.

30/9/19

D.O.I.

2/10/19

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop orO/S body.

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

3/10/19 3-4
4/5 & 1750 confirmed with Sherry

(red: \$1348.96 / 44%)

Date/Time, File Pass to?

1)

Date/Time, File Return to?

2)

Rep. Format:

Lump Sum / T.B. /

☐ : Prel. Report☐ : Final Report

Days Of Repair:

Resurvey No. of Trip:

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Weekend (\$

Survey Fee:

Transportation:

S + RS: \$

Photos

Others

TOTAL

ATTN: MOTOR CLAIMS DEPARTMENT
 OWNER:
 TP INSURER: India International Insurance Singapore
 POLICY NO: 5108970168
 REFERENCE: TP CLAIM
 DOA: 30/09/2019

REPAIR ESTIMATE

Est. No. : E19090007
 Date : 30/09/2019
 Vehicle Num. : SMK8589D
 Make/Model : HONDA SHUTTLE 1.5G
 CVT
 Chassis/Eng# : GK82001222
 Yr. of Manu : 2018

No	Description	Qty	U/P	Amt
Section: LIST ITEMS				
1	RH Front Door	1.00	757.20	757.20
2	RH Rear Door	1.00	703.40	703.40
3	RH Side Skirting	1.00	363.10	363.10

Amt S\$ 1,823.70

Discount (20.00%) S\$ 364.74

Subtotal S\$ 1,458.96

Section: LABOUR

4	To Panel Beat The Necessary Damaged Parts	1.00	600.00	600.00
5	To Dismantle and Reinstall Door Components	1.00	160.00	160.00
6	To Sand Down, Putty and Spray Paint on Necessary Damaged Part	1.00	880.00	880.00

Amt S\$ 1,640.00

Discount (0.00%) S\$ 0.00

Subtotal S\$ 1,640.00

not added
 2/s #1750/
 3 Aug.
 2/10/19
 The pt. H.K. rep. i

7,1460.6
 202
 1168.48
 2158.48
 1750.78

LKK Auto Consultants hence notify the Member of the following:
 • To ensure proper water spray painting
 • To ensure damaged part(s) during assembly
 • To ensure correct fitment of the part(s)
 • To ensure correct fitment of the part(s)
 • To ensure correct fitment of the part(s)
 • To ensure correct fitment of the part(s)
 • To ensure correct fitment of the part(s)
 • To ensure correct fitment of the part(s)

Administered by Provider

Signature

Date



Joo Hak Kee Auto Pte. Ltd.

LIST ITEMS Subtotal S\$ 1,458.96
 LABOUR Subtotal S\$ 1,640.00
 Total S\$ 3,098.96

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type: Singapore NRIC

Owner ID: 085B

Vehicle Details

Vehicle No.: SMK8589D

Vehicle to be Exported: No

Intended Deregistration Date: 02 Oct 2019

Vehicle Make: HONDA

Vehicle Model: SHUTTLE 1.5G CVT

Primary Colour: Grey

Manufacturing Year: 2018

Engine No.: L15B6001514

Chassis No.: GK82001222

Maximum Power Output: 97.0 kW (130 bhp)

Open Market Value: \$18,070.00

Original Registration Date: 26 Apr 2019

First Registration Date: 26 Apr 2019

Transfer Count: 0

Actual ARF Paid: \$8,070.00

Intended PARF Rebate Details

PARF Eligibility: Yes

PARF Eligibility Expiry Date: 25 Apr 2029

PARF Rebate Amount: \$6,052.00

Intended COE Rebate Details

COE Expiry Date: 25 Apr 2029

COE Category: A - Car up to 1600cc & 97kW (130bhp)

COE Period(Years): 10

QP Paid: \$29,159.00

COE Rebate Amount: \$27,887.00

Total Rebate Amount: \$33,939.00

The information contained herein is correct as at 02 Oct 2019

OK

Summer Lee (LKK Auto)

From: Motor Claim - III <motorclaim@iii.com.sg>
Sent: Monday, 30 September, 2019 3:43 PM
To: shimin poh; 'sur@lkkauto.com'; Admin-D (LKKAuto)
Cc: Kelvin Teo; Sherini Pillai
Subject: RE: NEW THIRD PARTY DIRECT SETTLEMENT VEH NO : SMK8589D DOA : 30/09/2019
Attachments: SAS REPORT.PDF

Dear Sir / Mdm,

Please conduct a survey on TP vehicle SMK8589D and let us have your report urgently.

This claim will be handled by Ms Sherini.

*Kindly upload this survey request email to merimen.

Thank You.

Best Regards,
Gabriel Wee



64 Cecil Street, #05 - IOB Building
Singapore 049711
Tel: 6347 6100, Ext - 248

From: shimin poh [mailto:shimin@jhk.com.sg]
Sent: 30 September, 2019 1:57 PM
To: Motor Claim - III <motorclaim@iii.com.sg>
Cc: Kelvin Teo <kelvin@jhk.com.sg>
Subject: Re: NEW THIRD PARTY DIRECT SETTLEMENT VEH NO : SMK8589D DOA : 30/09/2019

Dear Gabriel:

We choose LKK, please note car will be in on 2/10/2019 after 10am no waiting.

Thank You !
Bridget Poh (Shimin)
Joo Hak Kee Auto Pte Ltd
Blk 3007 Ubi Road 1
#01-406 Singapore 408701
Office: 67431913

On Mon, Sep 30, 2019 at 1:52 PM Motor Claim - III <motorclaim@iii.com.sg> wrote:

P: Shi min

T: 3.50pm

V: Out

E: ✓

Dear Sir / Mdm,

We acknowledge receipt of your email.

We propose using one of the following motor surveyors:

- LKK Auto Consultants Pte Ltd
- Vicom Assessment Centre Pte Ltd

Please notify us within 02 days of receipt of this letter for surveyor agreed on or if you have any objections to the above list.

Best Regards,

Gabriel Wee



64 Cecil Street, #05 - IOB Building

Singapore 049711

Tel: 6347 6100, Ext - 248

From: shimin poh [mailto:shimin@jhk.com.sg]

Sent: 30 September, 2019 1:11 PM

To: Motor Claim - III <motorclaim@iii.com.sg>

Cc: Kelvin Teo <kelvin@jhk.com.sg>

Subject: NEW THIRD PARTY DIRECT SETTLEMENT VEH NO : SMK8589D DOA : 30/09/2019

Dear Sir/Mdm,

Kindly arrange pre-repair survey for the above and if possible would like to do direct settlement.

Please provide us your list of surveyors for our selection.

Attached is the accident report for your reference and we're currently in the midst of preparing the estimate.

Thank you and hope to hear from you soon.

Thank You !

Bridget Poh (Shimin)

Joo Hak Kee Auto Pte Ltd

Blk 3007 Ubi Road 1

#01-406 Singapore 408701

Office: 67431913

Kindly note that by submitting this claim to us, you are deemed to have agreed to us collecting, using, disclosing and processing your personal data, sharing your personal data with our service providers (located both inside and outside Singapore) and/or with other insurers in the general insurance industry, including the General Insurance Association of Singapore. This enables us to ensure proper processing, handling and/or dealing with your claim, which includes investigating the said claim, and complying with applicable laws. If you do not agree to the same, kindly let us know immediately.

DISCLAIMER:

This email is intended solely for the person to whom it has been addressed.

It may contain confidential and/or legally privileged information.

If you are not the person for whom this e-mail was intended, or if this e-mail has reached you by mistake, please delete it immediately and inform us of the error and also be hereby notified that any use, distribution, transmission, printing, copying or dissemination of this information in any way or in any manner is strictly prohibited and may be unlawful. Internet communications may not be entirely secure or accurate as information could be intercepted, corrupted, lost, delayed or contain viruses.

Therefore, we do not accept liability for any errors or omissions in the content of this message or any delay in delivery which may arise as a result of Internet transmission or any modification.

Print this email only if it is absolutely necessary and help in preservation of environment.

India International Insurance Pte Ltd.

Registration No. 198703792-K

Kindly note that by submitting this claim to us, you are deemed to have agreed to us collecting, using, disclosing and processing your personal data, sharing your personal data with our service providers (located both inside and outside Singapore) and/or with other insurers in the general insurance industry, including the General Insurance Association of Singapore. This enables us to ensure proper processing, handling and/or dealing with your claim, which includes investigating the said claim, and complying with applicable laws. If you do not agree to the same, kindly let us know immediately.

DISCLAIMER:

This email is intended solely for the person to whom it has been addressed.

It may contain confidential and/or legally privileged information.

If you are not the person for whom this e-mail was intended, or if this e-mail has reached you by mistake, please delete it immediately and inform us of the error and also be hereby notified that any use, distribution, transmission, printing, copying or dissemination of this information in any way or in any manner is strictly prohibited and may be unlawful. Internet communications may not be entirely secure or accurate as information could be intercepted, corrupted, lost, delayed or contain viruses.

Therefore, we do not accept liability for any errors or omissions in the content of this message or any delay in delivery which may arise as a result of Internet transmission or any modification.

Print this email only if it is absolutely necessary and help in preservation of environment.

India International Insurance Pte Ltd.

Registration No. 198703792-K

Cecilia Chong (LKK Auto)

From: Sherini Pillai <sherini@iii.com.sg>
Sent: Thursday, 3 October 2019 4:27 PM
To: Cecilia Chong (LKK Auto)
Subject: RE: YOUR REF: SHC 3032C (OUR REF: CC4/III19017283/gb3) *** ACCIDENT INVOLVING SHC 3032C (OI) & SMK 8589D (TP) ON 30/09/2019 ***

Hi Cecilia,

Please reject 1st & then proceed to settle up to 50%.

Best Regards,

Sherini Pillai

Motor Claims Department



64 Cecil Street, #04/#05 IOB Building, Singapore 049711
☎ 6347 6128 Fax: 6224 4174
Company Registration No. 198703792K

From: Cecilia Chong (LKK Auto) [mailto:CeciliaChong@lkkauto.com]
Sent: Thursday, October 03, 2019 4:04 PM
To: Sherini Pillai <sherini@iii.com.sg>
Subject: YOUR REF: SHC 3032C (OUR REF: CC4/III19017283/gb3) *** ACCIDENT INVOLVING SHC 3032C (OI) & SMK 8589D (TP) ON 30/09/2019 ***

Dear Sherini,

Kindly refer to attached for the TP AVF.

Please upload into merimen.

We are in the view that OI is not fully liable for this.

As you can see from the AVF is a single lane road, TP should wait for OI to reverse and parked into lot in order to move off.

However, TP fail to do so, but try to overtake OIV when OI has not complete his parking.

We are in the view of rejecting TP claim, otherwise to settle at 50/50. Kindly let us have your instruction. Thanks

Best Regards,

Cecilia Chong | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6749-4274 | email: CeciliaChong@lkkauto.com | fax: 6741-4108

This email is intended solely for the person to whom it has been addressed. It may contain confidential and/or legally privileged information. If you are not the person for whom this e-mail was intended, or if this e-mail has reached you by mistake, please delete it immediately and inform us of the error and also be hereby notified that any use, distribution, transmission, printing, copying or dissemination of this information in any way or in any manner is strictly prohibited and may be unlawful. Internet communications may not be entirely secure or accurate as information could be intercepted, corrupted, lost, delayed or contain viruses. Therefore, we do not accept liability for any errors or omissions in the content of this message or any delay in delivery which may arise as a result of Internet transmission or any modification.

Cecilia Chong (LKK Auto)

From: Cecilia Chong (LKK Auto)
Sent: Thursday, 3 October 2019 5:05 PM
To: shimin poh
Subject: RE: NEW THIRD PARTY DIRECT SETTLEMENT VEH NO : SMK8589D DOA : 30/09/2019

Your Ref: **SMK 8589D**
Our Ref: CC4/III19017283/gb3

Without Prejudice

Dear Sirs/Madam,

ACCIDENT INVOLVING SHC 3032C (III) & SMK 8589D ON 30/09/2019

We refer to the above matter.

Base on your client Video Footage, We have reviewed the matter and we are of the view that our driver is not liable for the accident. It is a single lane road, and your client saw that Our Insured driver is attempting to park his vehicle therefore your client slow down and stop his vehicle, however, your client did not wait for Our Insured driver to complete his parking but trying to proceed to overtake Our Insured driver vehicle.

In view of the above, we have our principal instruction to deny liability and unable to look into your client's matter.

Thank you.

Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement.

Best Regards,

Cecilia Chong | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6749-4274 | email: CeciliaChong@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Auto
Consultants
Pte Ltd

Save the Earth. Print only when necessary.

From: shimin poh [mailto:shimin@jhk.com.sg]
Sent: Thursday, 3 October 2019 2:23 PM
To: Cecilia Chong (LKK Auto) <CeciliaChong@lkkauto.com>
Subject: Re: NEW THIRD PARTY DIRECT SETTLEMENT VEH NO : SMK8589D DOA : 30/09/2019

Dear Cecilia:

Please refer to the attached video footage. hope it helps.

Cecilia Chong (LKK Auto)

From: shimin poh <shimin@jhk.com.sg>
Sent: Tuesday, 8 October 2019 10:28 AM
To: Cecilia Chong (LKK Auto)
Subject: Re: NEW THIRD PARTY DIRECT SETTLEMENT VEH NO : SMK8589D DOA : 30/09/2019

Dear Cecilia:

We have informed our client and we will withdraw our claim on our side.

Thank You !
Bridget Poh (Shimin)
Joo Hak Kee Auto Pte Ltd
Blk 3007 Ubi Road 1
#01-406 Singapore 408701
Office: 67431913

On Thu, Oct 3, 2019 at 5:05 PM Cecilia Chong (LKK Auto) <CeciliaChong@lkkauto.com> wrote:

Your Ref: **SMK 8589D** Without Prejudice

Our Ref: CC4/III19017283/gb3

Dear Sirs/Madam,

ACCIDENT INVOLVING SHC 3032C (III) & SMK 8589D ON 30/09/2019

We refer to the above matter.

Base on your client Video Footage, We have reviewed the matter and we are of the view that our driver is not liable for the accident. It is a single lane road, and your client saw that Our Insured driver is attempting to park his vehicle therefore your client slow down and stop his vehicle, however, your client did not wait for Our Insured driver to complete his parking but trying to proceed to overtake Our Insured driver vehicle.

In view of the above, we have our principal instruction to deny liability and unable to look into your client's matter.

...CLAIM SUBFOLDER...(Pending for Survey Report)

WP

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	11 Oct 2019 16:37 Edit Reg		30 Sep 2019 00:00 Edit Adj Rpt	\$51,750.00 Edit Estimates	\$51,750.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured:	COMFORT TRANSPORTATION PTE LTD, Co. Reg. No.: -								
Main Claimant:	HO HENG CHIP, ID: S0598085B								
Vehicle Reg. No.:	SMK8589D	Date of Loss:	30/09/2019 09:00 - :59 [5 Months and 4 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP	Policy/Cover Note No.:							
Vehicle Reg. No. (Insured):	SHC3032C	Policy No. (Claimant):	5108970168						
		Excess:							
Repairer:	Joo Hak Kee Auto Pte Ltd (HQ) Blk 3007 Ubi Road 1, #01-406, 408701 Ubi - Tel: 67431913								
Handling Insurer:	India International Insurance Pte Ltd (HQ) - Tel: 63476100 ... [Handled by Sherini Pillai]								
Claimant's Insurer:	NTUC Income Insurance Co-operative Ltd (HQ) - Tel:								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MARCUS CHUA] ... [Final Rpt due 10/10/2019]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
<ul style="list-style-type: none"> III_SG (09/10/2019): Alert - Adj Mandate Approved (\$50.00) - SMK8589D - Claim Handler: Sherini Pillai III_SG (03/10/2019): Alert - Adj Mandate Maintained - SMK8589D - Claim Handler: Sherini Pillai 									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SMK8589D
[SHC3032C]
TP
HO HENG CHIP
Sep 30 2019 9:00AM
[COMFORT TRANSPORTATION PTE LTD]
Joo Hak Kee Auto Pte Ltd

Upload Documents

Upload Photos

Compose New Letter

View

View in Browser

Video

1 per page

No	Finalized On	India International Insurance Pte Ltd (HQ)	Thumbnail	Print
1	03/10/19 13:50	Video - OID	Load MP4	<input type="checkbox"/>
2	03/10/19 16:27	Video - TP	Load MP4	<input type="checkbox"/>

Photos/Images

3 per page

No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	08/10/19 15:37	General View	Load JPG	<input checked="" type="checkbox"/>
2	08/10/19 15:37	General View	Load JPG	<input checked="" type="checkbox"/>
3	08/10/19 15:37	General View	Load JPG	<input checked="" type="checkbox"/>
4	08/10/19 15:37	General View	Load JPG	<input checked="" type="checkbox"/>
5	08/10/19 15:37	General View	Load JPG	<input checked="" type="checkbox"/>
6	08/10/19 15:37	General View	Load JPG	<input checked="" type="checkbox"/>
7	08/10/19 15:37	General View	Load JPG	<input checked="" type="checkbox"/>
8	08/10/19 15:37	General View	Load JPG	<input checked="" type="checkbox"/>
9	08/10/19 15:37	General View	Load JPG	<input checked="" type="checkbox"/>
10	08/10/19 15:37	General View	Load JPG	<input checked="" type="checkbox"/>
11	08/10/19 15:37	General View	Load JPG	<input checked="" type="checkbox"/>
12	08/10/19 15:37	General View	Load JPG	<input checked="" type="checkbox"/>
13	08/10/19 15:37	General View	Load JPG	<input checked="" type="checkbox"/>
14	08/10/19 15:37	General View	Load JPG	<input checked="" type="checkbox"/>
15	08/10/19 15:37	General View	Load JPG	<input checked="" type="checkbox"/>
16	08/10/19 15:37	General View	Load JPG	<input checked="" type="checkbox"/>
17	08/10/19 15:37	General View	Load JPG	<input checked="" type="checkbox"/>
18	08/10/19 15:37	General View	Load JPG	<input checked="" type="checkbox"/>
19	08/10/19 15:37	General View	Load JPG	<input checked="" type="checkbox"/>
20	08/10/19 15:37	General View	Load JPG	<input checked="" type="checkbox"/>
21	08/10/19 15:37	General View	Load JPG	<input checked="" type="checkbox"/>
22	08/10/19 15:37	General View	Load JPG	<input checked="" type="checkbox"/>
23	08/10/19 15:37	General View	Load JPG	<input checked="" type="checkbox"/>
24	08/10/19 15:37	General View	Load JPG	<input checked="" type="checkbox"/>
25	08/10/19 15:37	General View	Load JPG	<input checked="" type="checkbox"/>
26	08/10/19 15:37	General View	Load JPG	<input checked="" type="checkbox"/>
27	08/10/19 15:37	General View	Load JPG	<input checked="" type="checkbox"/>
28	08/10/19 15:37	General View	Load JPG	<input checked="" type="checkbox"/>
29	08/10/19 15:37	General View	Load JPG	<input checked="" type="checkbox"/>
30	08/10/19 15:37	General View	Load JPG	<input checked="" type="checkbox"/>
31	08/10/19 15:37	General View	Load JPG	<input checked="" type="checkbox"/>
32	08/10/19 15:37	General View	Load JPG	<input checked="" type="checkbox"/>

Documentation

1 per page

No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	01/10/19 16:29	EMAIL FROM III DD 30092019	Load PDF	<input type="checkbox"/>
2	01/10/19 16:29	TP GIA REPORT	Load PDF	<input type="checkbox"/>
3	03/10/19 17:28	TP ESTIMATE- MARKED	Load PDF	<input type="checkbox"/>
4	08/10/19 15:34	EMAIL FROM TP	Load PDF	<input type="checkbox"/>
5	08/10/19 15:34	REJECTION EMAIL TO TP	Load PDF	<input type="checkbox"/>

Video			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	India International Insurance Pte Ltd (HQ)		Thumbnail Print
No	Finalized On	India International Insurance Pte Ltd (HQ)		Thumbnail Print
1	02/10/19 08:38	Singapore Accident Statement		Load PDF

Documents Checklist

DOCUMENTS CHECKLIST		Reset	Save	Print
There are no document checklists configured.				
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>				
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>				

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/III19017283/UGB3Q2

Date: 14/10/2019

REFERENCE

Handling Insurer: India International Insurance Pte Ltd

Policy No:

Claimant Vehicle No : SMK8589D

Insured Vehicle No : SHC3032C

Date of Loss: 30/09/2019

Nature of Claim: TP

Claim No: N/A

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SMK8589D

Make & Model: HONDA SHUTTLE, 1.5 (A)

Engine No: L15B6001514

Reg. Date: 26/04/2019 (Man. Year: 2018)

Chassis No: GK82001222

Colour: Grey

Odometer: 21008 km

Engine Capacity: 1496 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes Footbrake (Serviceable):

Yes

Handbrake (Serviceable): Yes Engine Modification:

No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/50 R16

Rear Tyre Size: 205/50 R16

Front Left Side: Goodyear 8 mm

Rear Left Side: Goodyear 8 mm

Front Right Side: Goodyear 8 mm

Rear Right Side: Goodyear 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,458.96	1,168.48	290.48	19.91
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,640.00	1,020.00	620.00	37.80
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	3,098.96	2,188.48	910.48	29.38
Approved Total (Overridden) (S\$)		1,750.00		
(S\$)	3,098.96	1,750.00	1,348.96	43.53
+ GST 7.00/7.00% (S\$)	216.93	122.50	94.43	43.53
Nett Amount (S\$)	3,315.89	1,872.50	1,443.39	43.53

INSPECTION

Date of Assignment: 30/09/2019

Date Inspected: 02/10/2019 Inspected At:

Joo Hak Kee Auto Pte Ltd (HQ)
Blk 3007 Ubi Road 1, #01-406
Singapore 408701

Estimated Period of Repair: 3.0 days

Adjuster: MARCUS CHUA

Manager: Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 11 Oct 2019)	
Parts:	N/A	HONDA SHUTTLE 1.5 (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMK8589D)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*RH FRONT DOOR	Badly Dented	757.20 FL	*757.20 FL
2	1		*RH REAR DOOR	Badly Dented	703.40 FL	*703.40 FL
3	1		*RH SIDE SKIRTING	Repair	363.10 FL	*- FL
					Sub Total (S\$)	1,823.70
					- List Item Discount on L Items 20.00/20.00% (S\$)	292.12
					Total Parts (S\$)	1,458.96

F=Franchise part, L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO PANEL BEAT THE NECESSARY DAMAGED PARTS	New	600.00	300.00
2	TO DISMANTLE AND REINSTALL DOOR COMPONENTS	New	160.00	120.00
3	TO SAND DOWN ,PUTTY AND SPRAY PAINT ON NECESSARY DAMAGED PART	New	880.00	600.00
Gross Labour Cost (S\$)			1,640.00	1,020.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >