

源摩哆廠

GUAN MOTOR WORKS

Business Regn. No: 08102600E

176 Sin Ming Drive #02-03 Sin Ming Autocare Singapore 575721 Tel: 6453 6111 Fax: 6453 8292 H/P: 9742 6003

REPAIR ESTIMATE FOR SKW5336Y

No.	Qty	List Items
1	1	Rear bumper
2	1	Rear bumper LH reflector
3	1	Rear bumper LH inner side bracket
4	2	Rear bumper side retainer
5	2	Rear bumper corner retainer
6	1 set	Rear bumper clips
7	1	Rear boot lid
8	1	Rear boot outer handle garnish
9	1	Rear boot centre "TOYOTA" logo
10	1	Rear boot LH "VIOS" emblem
11	1	Rear boot RH "E" emblem
12	1	Rear boot top lock
13	1	Rear boot lower lock catch
14	1	Rear boot weatherstrip
15	1	LH taillamp panel
16	2	Taillamp
17	1	Rear end panel
18	1	Rear end panel top garnish

\$	Bu	451.60	✓
\$	Sn	92.90	X
\$	Bu	56.30	✓
\$	al/di	171.20	✓
\$		86.00	?
\$	mu	30.00	✓
\$	Bu	589.10	✓
\$	way	175.00	✓
\$	mu	48.10	✓
\$	mu	55.60	✓
\$	mu	45.30	✓
\$	nd	121.35	✓
\$	R	41.40	X
\$	Sn	176.80	X
\$		128.50	?
\$	Cal/cm	655.20	✓
\$		575.00	?
\$		211.40	?
\$		3,710.75	
Less 25%		\$ 927.69	
Total :		\$ 2,783.06	

Special Nett Items

19	1 set	Reverse sensors
20	1 set	Rear end panel sealant

\$	250.00	?
\$	50.00	?
Total :	\$ 300.00	

Labour

1	Labour Charges for remove/refit, cutting/welding and replacement of damages.
2	To putty and spray Spray Paintings charges.
3	To check wirings and lightings.
4	To remove, refit reverses sensors.
5	To remove, refit rear boot lid fittings.
6	To remove, refit rear upholstery and attachments.
7	To supply and apply anti rust treatment

\$	1,000.00	?
\$	1,000.00	600
\$	40.00	200
\$	80.00	500
\$	80.00	500
\$	120.00	800
\$	80.00	?
Total :	\$ 2,400.00	

Total Parts and Labour : \$ 5,483.06

LKK Auto Consultants hence notify the Repairer of the following

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Not Notarised
1/1/2008 & ?
Mingy After Paint
4-5 days

INS. CASE OWNER:

SHERINI

CC4/III19017304/R1ga3

LKK:

IDAC:

ASSIGNMENT

Surveyor:

RASUL

DOI:

Date / Time : 01.10.19

Registered in Merimen: 01.10.19

Pre-assign / CCU / FTE



Insured Vehicle No. : SHA 4822T

Claim No. :

Name of Insured : COMFORT TRANSPORTATION PTE LTD

Policy No. : MCOM0015

Insured Tel No. : HP:

Make / Model : HYUNDAI IONIQ HYBRID

Excess Sec II :S\$

D.O.A : 26/09/2019 18:30

Place of Accident : STEVENS RD AND DRAYCOTT PARK

Is driver the owner? (YES / NO) Nature of Accident :

If NO, Driver Name / Age : YEE YEW CHIANG

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Driver Tel No. : +65-96791093 (V/L: YES / NO)

Insured Liability : % Final ? Yes / No

SLG 5160J

INSRS:
WSP: HIN LUNG
Tel: WORKSHOP
Liability :
RMKS:INSRS:
WSP:
Tel :
Liability :
RMKS:INSRS:
WSP:
Tel :
Liability :
RMKS:INSRS:
WSP:
Tel :
Liability :
RMKS:

Date/ Time		
	SLG 5160J - NBA/CTI19000258/Y; DOA: 04.01.19	STAGE
	SHA 4822T - NBA/CTI19017026/Y; DOA : 26.09.19	DATE / PIC
	- CC4/III18001614/Apb3q2; DOA: 11.01.18	Non-Reporting ltr (1st):
	- CS/GAI17024674/K1qbn2; DOA: 22.12.17	Non-Reporting ltr (2nd):
		Non-Reporting ltr (Final):
		Notification ltr (if non-pickup):
		Call OI:
		After call ltr to OI:
		Documentation Check List: Handler Typist
		Notification ltr (if non-pickup) ☐ ☐
		After call ltr to OI: ☐ ☐
		Authorisation To Act: ☐ ☐
		Release Voucher: ☐ ☐
		Final Repair Bill: ☐ ☐
		Car Rental Invoice: ☐ ☐
		Towing Invoice ☐ ☐
		LTA / GIA : ☐ ☐
		Medical Bill: ☐ ☐
		PIR: ☐ ☐
		Mandate/Reject Instruction: ☐ ☐
		LOD ☐ ☐
		Payment Breakdown Form: ☐ ☐
		Post-Repair Photos: ☐ ☐
		Others: ☐ ☐

PRELIMINARY ADVICE		Date/Time:	Sent By:	
FINALIZATION		Date/Time:	Confirm with:	Confirm by:
Repair Cost:	S\$	(days) Reduction:	%	Email ☐ Call ☐
FINAL SETTLEMENT		Date/Time:	Confirm with	Email ☐ Call ☐
Final Liability:	%	(Agreed / Assessed) BOLA S/N No. :		
Repair Cost:	S\$			
Loss of Rental (LOR):	S\$	(days)		
Loss of Use (LOU):	S\$	(\$ x days)		
Loss of Income (LOI):	S\$	(\$ x days)		
LOR only ☐	LOU only ☐	LOR + LOU ☐	LOR + LOI ☐	[Tick only one]
GIA/LTA Search	S\$			
Medical:	S\$			
Disbursement:	S\$	(e.g. Tow/ Independent)		
Legal Cost	S\$			
Total:	S\$	Global Sum S\$:		
FINAL PAYMENT		Date/Time:	Confirm with:	Email ☐ Call ☐
Payee 1:	S\$	Name 1:		
Payee 2: (Strike if N.A.)	S\$	Name 2:		
Payee 3: (Strike if N.A.)	S\$	Name 3:		

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

[> Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	193E
Vehicle Details	
Vehicle No.:	SLG5160J
Vehicle to be Exported:	Yes
Intended Deregistration Date:	30 Sep 2019
Vehicle Make:	B.M.W.
Vehicle Model:	316i 1.6 AT D/AB 4DR ABS HID
Primary Colour:	Black
Manufacturing Year:	2013
Engine No.:	A645J464N13B16A
Chassis No.:	WBA3A12030J720428
Maximum Power Output:	100.0 kW (134 bhp)
Open Market Value:	\$33,029.00
Original Registration Date:	17 May 2013
First Registration Date:	17 May 2013
Transfer Count:	1
Actual ARF Paid:	\$28,241.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	16 May 2023
PARF Rebate Amount:	\$18,356.00
Intended COE Rebate Details	
COE Expiry Date:	16 May 2023
COE Category:	A - Car (1600cc & below)
COE Period(Years):	10
QP Paid:	\$62,497.00
COE Rebate Amount:	\$22,663.00
Total Rebate Amount:	\$41,019.00

The information contained herein is correct as at 30 Sep 2019

OK

57,000
41,019

18,981