

ASSIGNMENT

Surveyor:

LEE HOCK ANN

DOI: 01/10/2019

Date / Time : 01.10.19

Registered in Meriton: 01.10.19

Fr sign / CCU / FTE



Insured Vehicle No. : SH 9525B

Claim No. :

Name of Insured : COMFORT TRANSPORTATION PTE LTD

Policy No. :

Insured Tel No. : HP:

Make / Model : HYUNDAI SONATA

Excess Sec II : \$5

D.O.A : 19/09/2019 20:00

Place of Accident : HOLLAND AVE TWDS HOLLAND RD

Is driver the owner? (YES / NO)

Nature of Accident :

If NO, Driver Name / Age : KANG TECK KIM

OI GIA REPORT: YES / NO : TP GIA REPORT: YES / NO

Driver Tel No. : +65-98814376

(V/L: YES / NO)

Insured Liability : % Final ? Yes / No

FBD 2402R



INSRS: KARZ WORKS

Tel :

Liability :

RMKS:



INSRS:

WSP:

Tel :

Liability :

RMKS:



INSRS:

WSP:

Tel :

Liability :

RMKS:



INSRS:

WSP:

Tel :

Liability :

RMKS:

Date/ Time

FBD 2402R } NA/INC19016753/z4; DOA: 19/9/19
SH 9525B } - CC3/III15017943/Rhv3q2; DOA: 17/10/15

* Total loss claim

9/10 - Liability approved. Liability clearance send

TP - Rm car to TP (pending WD)
10/10 - LOD in, file past R type report.

12/10 - Pending mandate approval.

14/10 - off G/S \$1200 (pending acceptance).

14/10 - To reject off, counter propose G/S \$2300.

14/10 - off G/S \$1890 (pending acceptance).

16/10 - settle @ G/S \$1890, DV send (pending DV)

16/10 - DV in, file past Rm to close.

STAGE DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OE

After call ltr to OE:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OE:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice

LTA / GIA :

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost: 116 SS 1650.00 (4 days) Reduction: \$1590.00 @ 88

Email ☐ Call ☐

FINAL SETTLEMENT

Date/Time:

Confirm with:

Email ☒ Call ☐

Final Liability: % 100 (Agreed / Assessed) BOLA S/N No.: 11A

If NO for B 28, Ann. Lia :

Repair Cost: SS 1650.00 (415 instruction)

Loss of Rental (LOR): SS - (1 days)

Loss of Use (LOU): SS 210.00 (530' x 7 days)

Loss of Income (LOI): SS - (5 x days)

LOR only ☐ LOU only ☐ LOR + LOU ☐ LOR + LOI ☐ [Tick only one]

GIA/LTA Search SS 376.45

Medical:

Disbursement:

Legal Cost:

(e.g. Tow/ Independent)

1) Claim status: Normal/Reject/Private Settle

2) Report Format: TP

3) Survey fee: \$500/-

Total: SS 1896.45

Global Sum SS: 1890.00

FINAL PAYMENT

Date/Time:

Confirm with:

Email ☒ Call ☐

Payee 1: SS 1890.00

Name 1: KARZ WORKS Pte Ltd

Payee 2: (Strike if N.A.)

Name 2:

Payee 3: (Strike if N.A.)

Name 3:

COPY SENT
30/11/2020

H.A.N.V

III

ASSIGNMENT

Date: 1.10.2019

Vehicle No: FBD 2402R

Type: M. Car (M. Cycle) Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or

Make: DERBI TERRA 125 cc 125

Colour: Red / Black A/C: Insured / Std / Nil / NA

Sp. Reading: N/A to chub. short T/Radio: Insured / Std / Nil / NA

Eng. No:

C/Nr: UTHTS1A1A8H411130

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 100/90/18 R: 130/80/17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front: PIRELLI Rear: SCARION

4 mm R/Sal 4 mm

U/Sal mm L/Sal mm

D.O.A: 17/9/19 D.O.L: 1/10/19

Survey held at: KARZ WORKS

Dist. of Damages: Fnt / Rear / O/S / N/S / UIC / Roof/Top or

The UIC / Chassis frame / Body Structure affected due to collision.

Policy No:

Claims No:

Sum Insured: Excess:

(Client's Record)

Make of Vch:

(Policy Condition)

Remark: The vch had commenced its repair at the time of inspection.

Est. or Market Value:

ICAC Accident Report: Consistent? : Yes or No

GA / PR. Sect: Consistent? : Yes or No

Est. Repair: 4 days Res.: Yes or No

Lum Sum: 20. % 3 Val. Yes or No

CA / REV / REP. : 24 HRS "up"

Date: Person Contacted: Vehicle: IN / OUT

N/S	O/S

Date / Time	Action / Instruction
1/10/2019	* FBD 2402R vehicle workshop / charge person (Corren) updated Requisite work
MU - 3200	(Red - \$11590/88/-) Repair back vehicle, Ready to
PV - 1555	know Limit repair \$1600 &
NV - 1600	

* 4 repair days + 2 PRS + 1 Sat + 1 Sun = 8 days.

Site Time Fee Paid: ☐ Prell. Report ☐ Final Report

Days Of Repair:

Resurvey No. of Trip:

Survey Fee: ☐ \$ 45.00

Add Fee: ☐ Site Insp. \$ ☐ Interview \$ ☐ Tech. Insp. \$ ☐ Roadside \$

Place: ☐ Date: ☐

KARZ WORKS PTE LTD
53 UBI AVENUE 1 #01-23, PAYA UBI INDUSTRIAL PARK
SINGAPORE 408934
(TEL) 6 8 4 4 5 9 3 4 (FAX) 6 8 4 4 2 4 7 4 - (E-MAIL) KARZWORKSSG@GMAIL.COM

INDIA INTERNATIONAL INSURANCE

REPAIR PERFORMANCE INVOICE

Vehicle number FBD2402R
Make / Model DERBI TERRA
Chassis number VTHTS1A1A8H411130
Accident date 19.09.19
Reference KK1909-40

LKK Auto Consultants hence notify the Repairer of the following:
• To resurvey before/after spray painting
• To display damaged part(s) during resurvey
• Parts prices are subject to confirmation
• Third party survey is on a "Without Prejudice" basis
• No illegal modification(s) is allowed
• Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Qty	Particulars	Unit Price - SGD	
PARTS REPLACEMENT - LIST ITEMS			
1 SET	HANDLEBAR GUARD R/H only ✓ SCR	100.00	400.00
1	FRONT FENDER R/H only ✓ CRN	180.00	50 ✓
1 SET	WING MIRROR ✓ SCR → (R/H only)	100.00	40 ✓
1	WINDSCREEN ✓ CRA	200.00	60 ✓
1	RH SIDE FAIRING ✓ CRA	280.00	60 ✓
1	RH REAR FAIRING X R SVC	350.00	
1	FRONT FAIRING X SVC	350.00	
1	ENGINE FAN WITH COVER ✓ cut	800.00	230 ✓
1	ENGINE FAN WITH COVER (SMALL) ✓ CRA	200.00	
1	RADIATOR X SVC	500.00	
1	RADIATOR PIPE ✓ CRA	300.00	50 ✓
1	EXHAUST FRONT COVER R/H ✓ mis	250.00	50 ✓
1	SEAT ✓ on	350.00	100 ✓
1	PILLION FOOTREST ✓ at	100.00	40 ✓
1	PILLION FOOTREST BRACKET X R SCR	80.00	
1	FRONT FOOTREST ✓ at	150.00	50 ✓
1	FRONT FOOTREST BRACKET X R side	80.00	
1	SWING ARM X SVC	550.00	
1	HANDLE BAR X R SVC	450.00	
1 SET	FRONT FORK X R SVC	550.00	
1	STARTER SWITCH ✓ mis	200.00	60 ✓
1 SET	REAR SIGNAL LAMP R/H only ✓ SCR	80.00	30 ✓
1	EXHAUST PIPE ✓ cut	500.00	150 ✓
1	ENGINE COOLING FAN X SVC	200.00	
		7200.00	
	Less 10%	720.00	
	Subtotal	6480.00	
	Balance C/F	6480.00	
PARTS REPLACEMENT - SPECIAL NETT ITEMS			
	Balance B/F	6480.00	
1	REAR CARPLATE ✓ SCR	50.00	20
1	FRONT CARPLATE ✓ RCR	50.00	20
1	REAR BOX ✓ at	1000.00	300 ✓
1	TYRE R X	500.00	
1	HANDLE BAR (METAL PIECE) X SVC	80.00	
1	REAR EXHAUST COVER ✓ CRA	120.00	30 ✓
1	FRONT EXHAUST ✓ CRN (Rear)	1200.00	250 ✓
1	REAR EXHAUST X RPT	1200.00	
	Subtotal	4200.00	
	Balance C/F	4200.00	
S/No	LABOUR AND MISCELLANEOUS CHARGES		
	Balance B/F	10680.00	
1	REPLACE, REALIGN AND ADJUST ABOVE DAMAGE PARTS AND CHECK WIRING AND LIGHTING SYSTEM	800.00	1320 ✓
2	TO REMOVE/REFIT, REPLACE SWING ARM	380.00	
3	TO REMOVE/REFIT, REPLACE FRONT FORK	380.00	
4	SPRAY PAINTING	500.00	100 ✓
5	REMOVE AND RESTICK STICKER	500.00	50 ✓
	Subtotal	2560.00	
	Grand total	13240.00	

Signature: _____
Date: 19/10/19

5.35pm
Hock Ann
85311883
without pitance
resurvey after paint
worky day - to be formal
TP
Hock ANN @ LKK Auto.com
4 day
limit repair
\$1600

parts = 1070
less = 100%
963
spent = 620
1960 = 470
2053
4/5 less 20%
Total 1642.40
4/5 net = 41650

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC
Owner ID: 076B

Vehicle Details

Vehicle No.: FBD2402R
Vehicle to be Exported: No
Intended Deregistration Date: 01 Oct 2019
Vehicle Make: DERBI
Vehicle Model: TERRA 125
Primary Colour: Red
Secondary Colour: Black
Manufacturing Year: 2008
Engine No.: M541M5409
Chassis No.: VTHTS1A1A8H411130
Maximum Power Output: -
Open Market Value: \$5,206.00
Original Registration Date: 18 Dec 2008
First Registration Date: 18 Dec 2008
Transfer Count: 2
Actual ARF Paid: \$781.00

Intended PARF Rebate Details

PARF Eligibility: No
PARF Eligibility Expiry Date: -
PARF Rebate Amount: \$0.00

Intended COE Rebate Details

COE Expiry Date: 17 Dec 2023
COE Category: D - Motorcycle
COE Period(Years): 5
PQP Paid: \$1,847.00
COE Rebate Amount: \$1,555.00
Total Rebate Amount: \$1,555.00

Message

Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 01 Oct 2019

OK

MV 3200
PV 1555
NV 1600

Enquire Vehicle Transfer Fee

Vehicle Details

Vehicle No.
FBD2402R

Make / Model
DERBI / TERRA 125

Vehicle Type :
P00 - Passenger Motorcycle/Autocycle/Moped

Vehicle Attachment 1 :
No Attachment

Vehicle Scheme :
Normal

Chassis No. :
VTHTS1A1A8H411130

Propellant :
Petrol

Engine No. :
M541M5409

Motor No. :
-

Engine Capacity :
125 cc

Power Rating :
-

Maximum Power Output :
-

[Back to OneMotoring](#)

Enquire Road Tax Expiry Date

Review Details

Vehicle No.
FBD2402R

Vehicle Make/Model
DERBI / TERRA 125

Road Tax Expiry Date :
17 Dec 2019

The information contained herein is correct as at 01 Oct 2019 / 15:32.

Save as PDF

OK →

Print

Maximum Laden Weight :

310 kg

Unladen Weight :

119 kg

Year Of Manufacture :

2008

Original Registration Date :

18 Dec 2008

Lifespan Expiry Date :

-

COE Category :

D - Motorcycle

PQP Paid :

\$1,847.00

COE Expiry Date :

17 Dec 2023

Road Tax Expiry Date :

17 Dec 2019

PARF Eligibility Expiry Date :

-

Inspection Due Date :

17 Dec 2019

Intended Transfer Date :

01 Oct 2019

CO2 Emission :

-

CEV/VES Rebate Utilised Amount :

-

CO Emission :

-

HC Emission :

-

NOx Emission :

-

PM Emission :

Advertisement

[Home](#) > [Motorbikes](#) > [Motorbikes for Sale](#) > [Class 2B](#)

Advertisement



amy.hamzah.7

★★★★★ 20

Sold

S\$2,500

Share

70

Derbi Terra 125

Woodlands

Meetup

Used

COE ends Nov 2020

Condition 8/10

Outlook 6/10

Don't see a lot of these on the road

Selling cheap as the outlook needs a little work

Can be really nice and eye-catching if you spend a

little effort on it, I don't have the time anymore =(

If not, it serves as a good workhorse for another more than 3 years

Just changed a number of items

- radiator and fan

- carburetor

- chain slider

- air filter

- spark plug, etc

PM for more info

Full cash. Negotiable.

2 years ago in Class 2B

Meet-up

Woodlands

Listed by amy.hamzah.7



Very Responsive



Hock Ann (LKK Auto)

From: Hock Ann (LKK Auto)
Sent: Wednesday, 2 October, 2019 1:34 PM
To: Darren
Cc: Cecilia Chong (LKK Auto)
Subject: FBD 2402R

'WITHOUT PREJUDICE'
SAVE AS TO COSTS

Dear darran,

Good day, regarding vehicle FBD 2402R derbi terra 125 motorcycle wan advice your have

Nv limit repair cost to repair , don.t exceed over ~~(2k)~~ do . please reply update back asap

116/c

Thanks.

Best Regards,

Hock Ann | Assistant Automotive Assessor

LKK Auto Consultants

Phone: 6741 3061 | Email: HockAnn@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

SATISFACTION OF REPAIRED VEHICLE

I/We, Collins Tan, owner/driver of vehicle No. FB22402X declare that the repairs of my/our vehicle has been completed and to my/our satisfaction.

I/We agree that I/we hereby irrevocable absolutely accept the settlement amount and the liability from the third party on the repair costs and/or rental and/or loss of use which are final and that the sum of amount are to be released and payment to the workshop for such repairs in respect of the damages caused in the accident.

I/We further acknowledge that any settlement the workshop may reach on my/our behalf is on a without prejudice and without admission of liability basis insofar as the driver/owner/insurers of the other vehicle/s concerned.

I/We acknowledge that the Discharge Voucher applies only to my/our property damage and will not affect any of the personal injuries claim(s) involved and/or uninsured losses claim in a later date. Further the settlement terms herein should not be used as an evidence to prejudice to any personal injuries claim(s) involved and/or other uninsured losses claim arising of the subject matter in the action.

Dated this 5 day of December (month) 20 19 (year)
@ 15 hrs 45 mins

Tan
Name and Signature

12305/19

Summer Lee (LKK Auto)

From: Motor Claim - III <motorclaim@iii.com.sg>
Sent: Tuesday, 1 October, 2019 9:35 AM
To: Darren; 'sur@lkkauto.com'; Admin-D (LKKAuto)
Cc: Manivel Priyadarshini
Subject: RE: OUR REF : KK1909-45 // YOUR REF : SH9525B ACCIDENT INVOLVINGSH9525B AND FBD2402R
Attachments: GIA REPORT.PDF

Dear Sir / Mdm,

Please conduct a survey on TP vehicle FBD2402R and let us have your report urgently.

This claim will be handled by Ms Priya.

*Kindly upload this survey request email to merimen.

Thank You.

Best Regards,
Gabriel Wee



64 Cecil Street; #05 - IOB Building
Singapore 049711
Tel: 6347 6100, Ext - 248

P. Darren

T: 5.34pm

v: In

E: ✓

From: Darren [mailto:karzworks.sg@gmail.com]
Sent: 01 October, 2019 9:19 AM
To: Motor Claim - III <motorclaim@iii.com.sg>
Subject: RE: OUR REF : KK1909-45 // YOUR REF : SH9525B ACCIDENT INVOLVINGSH9525B AND FBD2402R

Hi Gabriel,

Please appoint LKK

Darren
Karz Works Pte Ltd
53 Ubi Avenue 1
#01-23 Paya Ubi Industrial Park
Singapore 408934
Tel: 68442475
Fax: 68442474

From: Motor Claim - III
Sent: Tuesday, 1 October 2019 9:23 AM

To: karzworks

Subject: RE: OUR REF : KK1909-45 // YOUR REF : SH9525B ACCIDENT INVOLVING SH9525B AND FBD2402R

Dear Sir / Mdm,

We acknowledge receipt of your email.

We propose using one of the following motor surveyors:

- LKK Auto Consultants Pte Ltd
- Vicom Assessment Centre Pte Ltd

Please notify us within 02 days of receipt of this letter for surveyor agreed on or if you have any objections to the above list.

Best Regards,
Gabriel Wee



64 Cecil Street; #05 - IOB Building
Singapore 049711
Tel: 6347 6100, Ext – 248

From: karzworks [<mailto:karzworks.sg@gmail.com>]

Sent: 30 September, 2019 5:26 PM

To: Motor Claim - III <motorclaim@iii.com.sg>

Cc: karzworks <KARZWORKS.SG@gmail.com>

Subject: OUR REF : KK1909-45 // YOUR REF : SH9525B ACCIDENT INVOLVING SH9525B AND FBD2402R

WITHOUT PREJUDICE

OUR REF : KK1909-45

YOUR REF : SH9525B

Dear Sir / Madam,
PRE-REPAIR INSPECTION FOR FBD2402R
ACCIDENT INVOLVING SH9525B AND FBD2402R ON 19.09.2019.

We refer to the above matter and enclosed herewith our client's GIA report and notification of Pre-repair inspection for your attention.

We also enclosed herewith the State Court of the Republic of Singapore Practice Direction-Amendment No. 1 of 2016 of Pre-repair Inspection for your attention.

Regards,
Shu Shan
KARZ WORKS PTE LTD

53 Ubi Avenue 1

#01-23 Paya Ubi Industrial Park

Singapore 408934

Tel: 6844 5938

Fax: 6844 2474

Kindly note that by submitting this claim to us, you are deemed to have agreed to us collecting, using, disclosing and processing your personal data, sharing your personal data with our service providers (located both inside and outside Singapore) and/or with other insurers in the general insurance industry, including the General Insurance Association of Singapore. This enables us to ensure proper processing, handling and/or dealing with your claim, which includes investigating the said claim, and complying with applicable laws. If you do not agree to the same, kindly let us know immediately.

DISCLAIMER:

This email is intended solely for the person to whom it has been addressed.

It may contain confidential and/or legally privileged information.

If you are not the person for whom this e-mail was intended, or if this e-mail has reached you by mistake, please delete it immediately and inform us of the error and also be hereby notified that any use, distribution, transmission, printing, copying or dissemination of this information in any way or in any manner is strictly prohibited and may be unlawful. Internet communications may not be entirely secure or accurate as information could be intercepted, corrupted, lost, delayed or contain viruses.

Therefore, we do not accept liability for any errors or omissions in the content of this message or any delay in delivery which may arise as a result of Internet transmission or any modification.

Print this email only if it is absolutely necessary and help in preservation of environment.

India International Insurance Pte Ltd.

Registration No. 198703792-K

Kindly note that by submitting this claim to us, you are deemed to have agreed to us collecting, using, disclosing and processing your personal data, sharing your personal data with our service providers (located both inside and outside Singapore) and/or with other insurers in the general insurance industry, including the General Insurance Association of Singapore. This enables us to ensure proper processing, handling and/or dealing with your claim, which includes investigating the said claim, and complying with applicable laws. If you do not agree to the same, kindly let us know immediately.

DISCLAIMER:

This email is intended solely for the person to whom it has been addressed.

It may contain confidential and/or legally privileged information.

If you are not the person for whom this e-mail was intended, or if this e-mail has reached you by mistake, please delete it immediately and inform us of the error and also be hereby notified that any use, distribution, transmission, printing, copying or dissemination of this information in any way or in any manner is strictly prohibited and may be unlawful. Internet communications may not be entirely secure or accurate as information could be intercepted, corrupted, lost, delayed or contain viruses.

Therefore, we do not accept liability for any errors or omissions in the content of this message or any delay in delivery which may arise as a result of Internet transmission or any modification.

Print this email only if it is absolutely necessary and help in preservation of environment.

India International Insurance Pte Ltd.

Registration No. 198703792-K

Print Received Message

This mail is associated with :

***FBD2402R (MCT19090478)**

[SH9525B]

TP

TEE YUE TONG

Sep 19 2019 8:00PM

[COMFORT TRANSPORTATION PTE LTD]

Karz Work Solutions

From India International Insurance Pte Ltd (HQ) (III_SG), sent on 05/02/2020 12:11 PM.
To LKK_HQ
Subject Alert - Adj Mandate Maintained - FBD2402R - Claim Handler: Priya

Maintained: please try to negotiate LOU for 6-7 days.

Print Received Message

This mail is associated with :

***FBD2402R (MCT19090478)**
[SH9525B]

TP

TEE YUE TONG

Sep 19 2019 8:00PM

[COMFORT TRANSPORTATION PTE LTD]

Karz Work Solutions

From India International Insurance Pte Ltd (HQ) (III_SG), sent on 26/02/2020 16:11 PM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$1896.45) - FBD2402R - Claim Handler: Priya

Approved:1896.45:Please request TP WS to raise Tax Invoice for Cost of repairs in III's name

...CLAIM SUBFOLDER...(Pending for Survey Report)
Direct Settlement

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	01 Oct 2019 Edit Reg		01 Oct 2019 00:00 Edit Adj Rpt	\$51,650.00 Edit Estimates	\$51,650.00 View Rpt		Pending for Survey Report Cancel Case

MainReferenceClaim DetailsDocumentsShow All

CLAIM SUBFOLDER DETAILS

[Created by adjuster]

Insured:

COMFORT TRANSPORTATION PTE LTD, Co. Reg. No.: 199303821R

Main Claimant:

TEE YUE TONG, ID: 593160768

Vehicle Reg. No.:

FBD2402R

Date of Loss:

19/09/2019 20:00 - :59
[129 Months and 1 Days From LTA Reg Date (Man Yr)]

Claim Type:

TP / MCT19090478

Policy/Cover Note No.:

MCOM0015

Vehicle Reg. No. (Insured):

5H9525B

Policy No. (Claimant):

5108566413

Excess:

Repairer:

Karz Work Pte Ltd (HQ) 53 Ubi Avenue 1 #01-23 Paya Ubi Ind. Park, 408934 Ubi - Tel: 68442475

Handling Insurer:

India International Insurance Pte Ltd (HQ) - Tel: 63476100 ... [Handled by Priya]

Claimant's Insurer:

NTUC Income Insurance Co-operative Ltd (HQ) - Tel:

Adjuster:

LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by LEE HOCK ANN] ... [Final Rpt due 10/10/2019]

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

- III_SG (26/02/2020): Alert - Adj Mandate Approved (\$1896.45) - FBD2402R - Claim Handler: Priya
- III_SG (05/02/2020): Alert - Adj Mandate Maintained - FBD2402R - Claim Handler: Priya
- III_SG (03/02/2020): Alert - Adj Mandate Maintained - FBD2402R - Claim Handler: Priya
- III_SG (08/10/2019): Alert - Adj Mandate Approved (\$0.00) - FBD2402R - Claim Handler: Priya

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)












































Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

























































Claim Documents

























































*FBD2402R (MCT19090478)
[SH9525B]
TP
TEE YUE TONG
Sep 19 2019 8:00PM
[COMFORT TRANSPORTATION PTE LTD]
Karz Work Pte Ltd

Upload Documents | Upload Photos | Compose New Letter

View View in Browser

Photos/Images			3 per page	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	04/10/19 09:55	Chassis Number	 Load JPG	<input checked="" type="checkbox"/>
2	04/10/19 09:56	Odometer Reading	 Load JPG	<input checked="" type="checkbox"/>
3	04/10/19 09:56	General View	 Load JPG	<input checked="" type="checkbox"/>
4	04/10/19 09:56	General View	 Load JPG	<input checked="" type="checkbox"/>
5	04/10/19 09:56	General View	 Load JPG	<input checked="" type="checkbox"/>
6	04/10/19 09:56	General View	 Load JPG	<input checked="" type="checkbox"/>
7	04/10/19 09:56	General View	 Load JPG	<input checked="" type="checkbox"/>
8	04/10/19 09:56	General View	 Load JPG	<input checked="" type="checkbox"/>
9	04/10/19 09:56	General View	 Load JPG	<input checked="" type="checkbox"/>
10	04/10/19 09:56	General View	 Load JPG	<input checked="" type="checkbox"/>
11	04/10/19 09:56	General View	 Load JPG	<input checked="" type="checkbox"/>
12	04/10/19 09:56	General View	 Load JPG	<input checked="" type="checkbox"/>
13	04/10/19 09:57	General View	 Load JPG	<input checked="" type="checkbox"/>
14	04/10/19 09:57	General View	 Load JPG	<input checked="" type="checkbox"/>
15	04/10/19 09:57	General View	 Load JPG	<input checked="" type="checkbox"/>
16	04/10/19 09:57	General View	 Load JPG	<input checked="" type="checkbox"/>
17	04/10/19 09:57	General View	 Load JPG	<input checked="" type="checkbox"/>
18	04/10/19 09:57	General View	 Load JPG	<input checked="" type="checkbox"/>
19	04/10/19 09:57	General View	 Load JPG	<input checked="" type="checkbox"/>
20	04/10/19 09:57	General View	 Load JPG	<input checked="" type="checkbox"/>
21	04/10/19 09:57	General View	 Load JPG	<input checked="" type="checkbox"/>
22	04/10/19 09:57	General View	 Load JPG	<input checked="" type="checkbox"/>
23	04/10/19 09:57	General View	 Load JPG	<input checked="" type="checkbox"/>
24	04/10/19 09:57	General View	 Load JPG	<input checked="" type="checkbox"/>
25	04/10/19 09:57	General View	 Load JPG	<input checked="" type="checkbox"/>
26	04/10/19 09:57	General View	 Load JPG	<input checked="" type="checkbox"/>
27	04/10/19 09:57	General View	 Load JPG	<input checked="" type="checkbox"/>
28	04/10/19 09:57	General View	 Load JPG	<input checked="" type="checkbox"/>
29	04/10/19 09:57	General View	 Load JPG	<input checked="" type="checkbox"/>
30	04/10/19 09:57	General View	 Load JPG	<input checked="" type="checkbox"/>
31	04/10/19 09:57	General View	 Load JPG	<input checked="" type="checkbox"/>
32	04/10/19 09:57	General View	 Load JPG	<input checked="" type="checkbox"/>
33	04/10/19 09:57	General View	 Load JPG	<input checked="" type="checkbox"/>
34	04/10/19 09:57	General View	 Load JPG	<input checked="" type="checkbox"/>
35	04/10/19 09:57	General View	 Load JPG	<input checked="" type="checkbox"/>
36	04/10/19 09:57	General View	 Load JPG	<input checked="" type="checkbox"/>
37	04/10/19 09:57	General View	 Load JPG	<input checked="" type="checkbox"/>
38	04/10/19 09:57	General View	 Load JPG	<input checked="" type="checkbox"/>
39	04/10/19 09:57	General View	 Load JPG	<input checked="" type="checkbox"/>
40	04/10/19 09:57	General View	 Load JPG	<input checked="" type="checkbox"/>
41	04/10/19 09:57	General View	 Load JPG	<input checked="" type="checkbox"/>
42	04/10/19 09:57	General View	 Load JPG	<input checked="" type="checkbox"/>
43	04/10/19 09:57	General View	 Load JPG	<input checked="" type="checkbox"/>

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
44	04/10/19 09:57	General View	 Load JPG	<input checked="" type="checkbox"/>
45	04/10/19 09:57	General View	 Load JPG	<input checked="" type="checkbox"/>
46	04/10/19 09:57	General View	 Load JPG	<input checked="" type="checkbox"/>
47	04/10/19 09:57	General View	 Load JPG	<input checked="" type="checkbox"/>
48	04/10/19 09:57	General View	 Load JPG	<input checked="" type="checkbox"/>
49	04/10/19 09:57	General View	 Load JPG	<input checked="" type="checkbox"/>
50	04/10/19 09:57	General View	 Load JPG	<input checked="" type="checkbox"/>
51	04/10/19 09:57	General View	 Load JPG	<input checked="" type="checkbox"/>
52	04/10/19 09:57	General View	 Load JPG	<input checked="" type="checkbox"/>
53	04/10/19 09:58	General View	 Load JPG	<input checked="" type="checkbox"/>
54	04/10/19 09:58	General View	 Load JPG	<input checked="" type="checkbox"/>
55	04/10/19 09:58	General View	 Load JPG	<input checked="" type="checkbox"/>
56	04/10/19 09:58	General View	 Load JPG	<input checked="" type="checkbox"/>
57	04/10/19 09:58	General View	 Load JPG	<input checked="" type="checkbox"/>
58	04/10/19 09:58	General View	 Load JPG	<input checked="" type="checkbox"/>
59	04/10/19 09:58	General View	 Load JPG	<input checked="" type="checkbox"/>
60	04/10/19 09:58	General View	 Load JPG	<input checked="" type="checkbox"/>
61	04/10/19 09:58	General View	 Load JPG	<input checked="" type="checkbox"/>
62	04/10/19 09:58	General View	 Load JPG	<input checked="" type="checkbox"/>
63	04/10/19 09:58	General View	 Load JPG	<input checked="" type="checkbox"/>
64	04/10/19 09:58	General View	 Load JPG	<input checked="" type="checkbox"/>
65	04/10/19 09:58	General View	 Load JPG	<input checked="" type="checkbox"/>
66	04/10/19 09:58	General View	 Load JPG	<input checked="" type="checkbox"/>
67	04/10/19 09:58	General View	 Load JPG	<input checked="" type="checkbox"/>
68	04/10/19 09:58	General View	 Load JPG	<input checked="" type="checkbox"/>
69	04/10/19 09:58	General View	 Load JPG	<input checked="" type="checkbox"/>
70	04/10/19 09:58	General View	 Load JPG	<input checked="" type="checkbox"/>
71	04/10/19 09:58	General View	 Load JPG	<input checked="" type="checkbox"/>
72	04/10/19 09:58	General View	 Load JPG	<input checked="" type="checkbox"/>
73	04/10/19 09:58	General View	 Load JPG	<input checked="" type="checkbox"/>
74	04/10/19 09:58	General View	 Load JPG	<input checked="" type="checkbox"/>
75	04/10/19 09:58	General View	 Load JPG	<input checked="" type="checkbox"/>
76	04/10/19 09:58	General View	 Load JPG	<input checked="" type="checkbox"/>
77	04/10/19 09:58	General View	 Load JPG	<input checked="" type="checkbox"/>
78	04/10/19 09:58	General View	 Load JPG	<input checked="" type="checkbox"/>
79	04/10/19 09:58	General View	 Load JPG	<input checked="" type="checkbox"/>
80	04/10/19 09:58	General View	 Load JPG	<input checked="" type="checkbox"/>
81	04/10/19 09:58	General View	 Load JPG	<input checked="" type="checkbox"/>
82	04/10/19 09:58	General View	 Load JPG	<input checked="" type="checkbox"/>
83	04/10/19 09:58	General View	 Load JPG	<input checked="" type="checkbox"/>
84	04/10/19 09:58	General View	 Load JPG	<input checked="" type="checkbox"/>
85	04/10/19 09:58	General View	 Load JPG	<input checked="" type="checkbox"/>
86	04/10/19 09:58	General View	 Load JPG	<input checked="" type="checkbox"/>
87	04/10/19 09:58	General View	 Load JPG	<input checked="" type="checkbox"/>
88	04/10/19 09:58	General View	 Load JPG	<input checked="" type="checkbox"/>
89	04/10/19 09:58	General View	 Load JPG	<input checked="" type="checkbox"/>
90	04/10/19 09:58	General View	 Load JPG	<input checked="" type="checkbox"/>
91	04/10/19 09:58	General View	 Load JPG	<input checked="" type="checkbox"/>
92	04/10/19 09:58	General View	 Load JPG	<input checked="" type="checkbox"/>
93	04/10/19 09:59	General View	 Load JPG	<input checked="" type="checkbox"/>
94	04/10/19 09:59	General View	 Load JPG	<input checked="" type="checkbox"/>
95	04/10/19 09:59	General View	 Load JPG	<input checked="" type="checkbox"/>
96	04/10/19 09:59	General View	 Load JPG	<input checked="" type="checkbox"/>
97	04/10/19 09:59	General View	 Load JPG	<input checked="" type="checkbox"/>
98	04/10/19 09:59	General View	 Load JPG	<input checked="" type="checkbox"/>
99	04/10/19 09:59	General View	 Load JPG	<input checked="" type="checkbox"/>

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
100	04/10/19 09:59	General View	 Load JPG	<input checked="" type="checkbox"/>
101	04/10/19 09:59	General View	 Load JPG	<input checked="" type="checkbox"/>
102	04/10/19 09:59	General View	 Load JPG	<input checked="" type="checkbox"/>
103	04/10/19 09:59	General View	 Load JPG	<input checked="" type="checkbox"/>
104	04/10/19 09:59	General View	 Load JPG	<input checked="" type="checkbox"/>
105	04/10/19 09:59	General View	 Load JPG	<input checked="" type="checkbox"/>
106	04/10/19 09:59	General View	 Load JPG	<input checked="" type="checkbox"/>
107	04/10/19 09:59	General View	 Load JPG	<input checked="" type="checkbox"/>
108	04/10/19 09:59	General View	 Load JPG	<input checked="" type="checkbox"/>
109	04/10/19 09:59	General View	 Load JPG	<input checked="" type="checkbox"/>
110	04/10/19 09:59	General View	 Load JPG	<input checked="" type="checkbox"/>
111	04/10/19 09:59	General View	 Load JPG	<input checked="" type="checkbox"/>
112	04/10/19 09:59	General View	 Load JPG	<input checked="" type="checkbox"/>
113	04/10/19 09:59	General View	 Load JPG	<input checked="" type="checkbox"/>
114	18/10/19 09:30	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
115	18/10/19 09:30	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
116	18/10/19 09:30	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
117	18/10/19 09:30	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
118	18/10/19 09:30	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
119	18/10/19 09:30	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
120	18/10/19 09:30	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
121	18/10/19 09:30	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
122	18/10/19 09:30	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
123	18/10/19 09:30	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
124	18/10/19 09:30	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
125	18/10/19 09:30	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
126	18/10/19 09:30	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
127	18/10/19 09:30	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
128	18/10/19 09:30	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
129	18/10/19 09:30	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
130	18/10/19 09:30	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
131	18/10/19 09:30	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
132	18/10/19 09:30	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
133	18/10/19 09:30	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
134	18/10/19 09:30	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
135	18/10/19 09:30	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
136	18/10/19 09:30	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
137	18/10/19 09:30	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
138	18/10/19 09:30	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
139	18/10/19 09:30	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
140	18/10/19 09:30	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
141	18/10/19 09:30	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
142	18/10/19 09:30	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
143	18/10/19 09:30	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
144	18/10/19 09:30	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
145	18/10/19 09:30	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
146	18/10/19 09:30	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
147	18/10/19 09:30	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
148	18/10/19 09:30	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
149	18/10/19 09:30	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
150	18/10/19 09:30	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
151	18/10/19 09:30	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
152	18/10/19 09:30	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
153	18/10/19 09:30	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
154	18/10/19 09:30	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
155	18/10/19 09:30	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail Print
156	18/10/19 09:30	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
157	18/10/19 09:30	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
158	18/10/19 09:30	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
159	18/10/19 09:30	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
160	18/10/19 09:30	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
161	18/10/19 09:30	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail Print
1	01/10/19 20:28	EMAIL FROM III DD 01.10.19		Load PDF
2	01/10/19 20:28	TP GIA REPORT		Load PDF
3	08/10/19 11:24	TP ESTIMATE - MARKED		Load PDF
4	20/12/19 13:12	LOD AND OTHER DOCUMENTS		Load PDF
5	20/01/20 13:43	GIA SEARCH		Load PDF
6	20/01/20 13:43	LTA SEARCH		Load PDF
7	20/01/20 13:43	LOD		Load PDF
8	31/03/20 10:31	WORKSHOP INVOICE		Load PDF
9	31/03/20 10:31	AUTHORISATION TO ACT FORM		Load PDF
10	31/03/20 10:31	DISCHARGE VOUCHER		Load PDF
No	Finalized On	India International Insurance Pte Ltd (HQ)		Thumbnail Print
1	02/10/19 08:32	Singapore Accident Statement		Load PDF

Documents Checklist

DOCUMENTS CHECKLIST

ResetSavePrint

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To:

☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199807198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/III19017305/HGA3Q2
Date: 31/03/2020

REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: MCOM0015
Claimant Vehicle No : FBD2402R Insured Vehicle No : SH9525B
Date of Loss: 19/09/2019 Nature of Claim: TP Claim No: MCT19090478

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: FBD2402R Engine No: M541M5409
Make & Model: DERBI TERRA, 125cc (M) Chassis No: VTHTS1A1A8H411130
Reg. Date: 18/12/2008 (Man. Year: 2008) Odometer: 0 km
Colour: Red/Black
Engine Capacity: 125 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 100/90/18 Rear Tyre Size: 130/80/17
Front Left Side: Pirelli 4 mm Rear Left Side: Scorpion 4 mm
Front Right Side: 0 mm Rear Right Side: 0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	10,680.00	1,583.00	9,097.00	85.18
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,560.00	470.00	2,090.00	81.64
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	13,240.00	2,053.00	11,187.00	84.49
Approved Total (Overridden) (S\$)		1,650.00		
Nett Amount (S\$)	13,240.00	1,650.00	11,590.00	87.54
+ Loss of Use (7.0 x S\$30.00/day) (S\$)		210.00		
+ Doc/Search Fee (S\$)		36.45		
Nett Liability (S\$)		1,896.45		
Global Sum Settlement (S\$)		1,890.00		

INSPECTION

Date of Assignment: 01/10/2019
Date Inspected: 01/10/2019 Inspected At: 53 UBI AVE 1 #01-23 PAYA UBI
Repaired: Karz Work Pte Ltd
Estimated Period of Repair: 4.0 days

Adjuster: LEE HOCK ANN

Manager: Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 20 Jan 2020)	
Parts:	N/A	DERBI TERRA 125cc (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for FBD2402R)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*HANDLEBAR GUARD (1 PCS ONLY)	O/S Scratched	400.00 FL	*100.00 FL
2	1		*FRONT FENDER	O/S Crumpled	180.00 FL	*50.00 FL
3	1		*WING MIRROR (1 PCS ONLY)	O/S Scratched	100.00 FL	*40.00 FL
4	1		*WINDSCREEN	Cracked	200.00 FL	*60.00 FL
5	1		*RH SIDE FAIRING	Cracked	280.00 FL	*60.00 FL
6	1		*RH REAR FAIRING	Serviceable	350.00 FL	*- FL
7	1		*FRONT FAIRING	Serviceable	350.00 FL	*- FL
8	1		*ENGINE FAN WITH COVER }	Cut	800.00 FL	*230.00 FL
9	1		*ENGINE FAN WITH COVER (SMALL) }	Cracked	200.00 FL	*- FL
10	1		*RADIATOR	Serviceable	500.00 FL	*- FL
11	1		*RADIATOR PIPE	Cracked	300.00 FL	*50.00 FL
12	1		*EXHAUST FRONT COVER RH	Missing	250.00 FL	*50.00 FL
13	1		*SEAT	Damaged	350.00 FL	*100.00 FL
14	1		*PILLION FOOTREST	Bent	100.00 FL	*40.00 FL
15	1		*PILLION FOOTREST BRACKET	Repair	80.00 FL	*- FL
16	1		*FRONT FOOTREST	Bent	150.00 FL	*50.00 FL
17	1		*FRONT FOOTREST BRACKET	Repair	80.00 FL	*- FL
18	1		*SWING ARM	Serviceable	550.00 FL	*- FL
19	1		*HANDLE BAR	Serviceable	450.00 FL	*- FL
20	1		*SET FRONT FORK	Serviceable	550.00 FL	*- FL
21	1		*STATER SWITCH	Missing	200.00 FL	*60.00 FL
22	1		*REAR SIGNAL LAMP (1 PCS ONLY)	O/S Scratched	80.00 FL	*30.00 FL
23	1		*EXHAUST PIPE	Cut	500.00 FL	*150.00 FL
24	1		*ENGINE COOLING FAN	Serviceable	200.00 FL	*- FL
25	1		*REAR CARPLATE	Scratched	50.00 FS	*20.00 FS
26	1		*FRONT CARPLATE	Necessary	50.00 FS	*20.00 FS
27	1		*REAR BOX	Bent	1,000.00 FS	*300.00 FS
28	1		*TYRE	Repair	500.00 FS	*- FS
29	1		*HANDLE BAR (METAL PIECE)	Serviceable	80.00 FS	*- FS
30	1		*REAR EXHAUST COVER	Cracked	120.00 FS	*30.00 FS
31	1		*REAR EXHAUST	Crumpled	1,200.00 FS	*250.00 FS
32	1		*REAR EXHAUST	Repeated	1,200.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	11,400.00	1,690.00
- List Item Discount on L Items 10.00/10.00% (S\$)	720.00	107.00
Total Parts (S\$)	10,680.00	1,583.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	REPLACE ,REALIGN AND ADJUST ABOVE DAMAGE PARTS AND CHECK WIRING AND LIGHTING SYSTEM }	New	800.00	320.00
2	TO REMOVE/REFIT ,REPLACE SWING ARM }	New	380.00	0.00
3	TO REMOVE/REFIT ,REPLACE FRONT FORK	New	380.00	0.00
4	SPRAY PAINTING	New	500.00	100.00
5	REMOVE AND RESTICK STICKER	New	500.00	50.00
Gross Labour Cost (S\$)			2,560.00	470.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >