

ASS. REC. BY:

REF: CS/TM119017306/K/vf3e2

Special Instruction:

Supervisor: Calvin

ASSIGNMENT (Office)

From (Person): Francis Ng Kwai Kay of TM2

Date/Time: 1.10.19 19.09p.m

Estimated Cost: \_\_\_\_\_ Bill to: \_\_\_\_\_

OD TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SHD 687A D

Insured: SKR 8057J

at Workshop m/s Comfortfulgro Engineering  
of 59 loyang brve

Tel: 6214 8300

Policy No: MW002810

Claim No: M1907657

Sum Insured: \_\_\_\_\_

Excess: \_\_\_\_\_

Make of Veh:  
(Client's Record)

D.O.A. 27.9.19

CA / REV / REP. / REV 24 HRS <sup>mp</sup>

H.O.D. Endorsement: \_\_\_\_\_

Date/Time: 1.10.19 8.48a.m

Person Contacted: Jumadi

Vehicle IN / OUT

Date/Time	Action/Instruction ( <input checked="" type="checkbox"/> ) Estimate
	SHB 687A D - x
	SKR 8057J - x
<u>7/10/19</u>	<u>Send preli revised via merimen</u>



...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	01 Oct 2019 11:42 <a href="#">Sendback Est</a>	01 Oct 2019 11:48 <b>S\$5,932.80</b>	01 Oct 2019 19:09 <a href="#">Assign</a>				<b>New Assignment</b> <a href="#">Cancel Case</a>

<a href="#">Main</a>	<a href="#">Reference</a>	<a href="#">Claim Details</a>	<a href="#">Documents</a>	<a href="#">Show All</a>
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

CLAIM SUBFOLDER DETAILS									
Insured:	MSP TRACTORS PTE. LTD., Co. Reg. No.: 201005832C								
Main Claimant:	COMFORT TRANSPORTATION PTE LTD, Co. Reg. No.: 199303821R								
Vehicle Reg. No.:	SHD6878D	Date of Loss:	27/09/2019 17:00 - :59 [47 Months and 19 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / M1907657	Policy/Cover Note No.:	MU002810 (Comprehensive) Coverage: 10/03/2019 - 09/03/2020						
Vehicle Reg. No. (Insured):	SKR8057J	Policy No. (Claimant):	D-18088936MFSH						
		Excess:	S\$0.00						
Repairer:	ComfortDelGro Engineering Pte Ltd (Loyang) 59 Loyang Drive, 508969 Loyang - Tel: 6214 8300								
Handling Insurer:	Tokio Marine Insurance Singapore Ltd (HQ) - Tel: 6221 6111 ... [Handled by Ng Kwai Kay Francis]								
Claimant's Insurer:	MS First Capital Insurance Ltd (HQ) - Tel: 62222311								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 10/10/2019]								
<b>ASSOCIATED MAIL RECEIVED</b>		<a href="#">View All</a>	<a href="#">Compose Case Mail</a>						
There are no mail for this case.									
<b>ALL ASSOCIATED TASKS</b>									
<a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a>									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

<b>To:</b> Tokio Marine Insurance Singapore Ltd 20 McCallum Street #09-01 Tokio Marine Centre Singapore 069046	<b>From:</b> LKK Auto Consultants Pte Ltd 51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933
---	--

**Attn:** Ng Kwai Kay Francis **Date:** 07 Oct 2019

### Preliminary Advice

Insured Vehicle No	: SKR8057J	Accident Date	: 27/09/2019
TP Vehicle No	: SHD6878D	Assignment Date	: 01/10/2019
Make	: HYUNDAI I40	Est. Duration of Repair	: 3
Date of Inspection	: 1/10/2019		
Inspection At	: COMFORTDELGRO ENRINEERING PTE LTD		

#### Point of Impact / General Description of Damages

The vehicle sustained impact / damages n/s body and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	6,205.92
Revised Amount	:S\$	1,500.00 (lump sum)
Check Items (Estimated)	:S\$	0.00
<b>Total</b>	<b>:S\$</b>	<b>1,500.00</b>

Lump Sum Repair :S\$

#### Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	
COE / PARF Rebate	:S\$	
Salvage Value	:S\$	
Margin for Repair	:S\$	

#### Remarks

The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.

The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

Other comments : The above survey was conducted on a 'Without Prejudice' basis.

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	30/09/2019 12:09
Date Of Accident	27/09/2019 17:35
Exact Location Of Accident	ANG MO KIO AVE 6 TWDS LENTOR AVE AFTER ANG MO KIO
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHD6878D
<b>Insured/Policyholder</b>	
Name Of Registered Owner	COMFORT TRANSPORTATION PTE LTD
Co Reg No	199303821R
Email Address	FLEETSAFETY@CDGTAXI.COM.SG
Mobile Phone No	
Alternative Phone No	OFFICE-65508768

### Vehicle Particulars

Manufacturer	HYUNDAI
Model	I40
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI

### Insurance Company

Name of Insurance Company	MS FIRST CAPITAL INSURANCE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	YES
Policy Number	D-18088936MFSH
Cover Note Number	

### Driver

Name of Driver	TAN SWEE KHENG
NRIC No	S1261062I
Date Of Birth	22/09/1957
Occupation	OUTDOOR
Date Of Driving Pass	18/11/1977
Driving Experience	41 YEARS AND 10 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96798678
Fax Number	
Contact Number	
EMail Address	VICTAN8@YAHOO.COM.SG

Address	BLK 224 BISHAN STREET 23 #07-129
Postcode	570224
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - TAXI DRIVER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	SIDE SWIPE
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	3
Passenger 1	NAME: : - GENDER: : FEMALE
Passenger 2	NAME: : - GENDER: : FEMALE

#### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

REFER ATTACHED

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	-
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SKR8057J
Vehicle Make/Model/Colour	TOYOTA
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	UNKNOWN
NRIC/Passport Number	
Contact Number	
Address	

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

RH FRONT

**IMPORTANT NOTICE**

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

COMFORT TRANSPORTATION PTE LTD  
CO. REG. NO. 199303621R

Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

*[Signature]* 30/9/19  
Loke Wai Yiang



SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 27/9/19 at about 17:35 hrs, I was driving at above said location with 3 passengers onboard. I switched on signal light to alert other road user of my intention then filtering to middle lane after I ensured traffic is clear. When I changed to middle lane, Veh B suddenly come out from extreme left lane. As a result, Veh B front right portion collided onto my taxi left front portion. No injury reported in this accident.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

COMFORT TRANSPORTATION PTE LTD  
CO. REG. NO. 199303821R

Policyholder's Signature  
Date & Time:

  
Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

 30/9/19  
Reporting Centre Personnel's Signature  
Name: Loke Wai Yiang  
NRIC/FIN No.:

A member of COMFORTDELGRO

Date/Time: 01.10.2019 10:28 Page : 1


Team: <b>ARC Repair TP(CLS0)1</b>	<b>JOB CARD</b>	Sales Order:	JC NO.: <b>305337664</b>
CUSTOMER <b>COMFORT TRANSPORTATION PTE LTD</b> 7010045 <b>383 SIN MING DRIVE</b> Singapore SINGAPORE 575717 65508755	<i>VARs</i>	REGN NO.: <b>SHD6878D</b>	MILEAGE
(R) (P)	(O)	MAKE: <b>HYUNDAI</b>	FUEL E.....1/2.....F
COUNT CARD NO.		MODEL <b>I-40</b>	DATE/TIME IN <b>01.10.2019 09:55</b>
		YR OF MANU <b>08.10.2015</b>	TARGET DATE
	<i>(C)</i>	CHASSIS CODE <b>KMHLB41UMGU078398</b>	COMPLETION DATE/TIME:

JOB DESCRIPTION

Accident Date: 27.09.2019  
NATURE: 3P 27.09.2019 ( C )

S/NO	LABOR CODE	DESCRIPTION
------	------------	-------------

*TOKIO - Left front*



CKED & PASSED OUT BY: \_\_\_\_\_

SERVICE ADVISOR	CUSTOMER'S SIGNATURE
-----------------	----------------------

Acknowledgement Slip No.: <b>SHD6878D</b> Signature/Date: _____ returned to Service Reception upon collection	LARRY Signature/Date: _____	Exit Pass Vehicle No.: <b>SHD6878D</b> Name of Service Advisor: _____ Date: _____ To be kept by Security Guard
--	--------------------------------	--

# ComfortDelGro Engineering Pte Ltd (Co.Reg.No:199506048W)

59 Loyang Drive  
Singapore 508969  
Tel: 6214 8300

**TP INSURER: Tokio Marine Insurance Singapore Ltd (HQ)**  
**COMFORT TRANSPORTATION PTE LTD**

Singapore

**Claimant**  
**Insurer: MS First Capital Insurance Ltd**

## PARTICULARS OF CLAIM

Claim Type:	THIRD PARTY	Ref. No:	
Policy No:		Date of Loss:	29/09/2019
Vehicle Reg. No.:	<b>SHD6878D</b>	Driveable?	YES
Party At Fault:	UNKNOWN		
Driver (TP):	TAN SWEE KHENG		

Make/Model:	HYUNDAI I40, 1.7 D CRDI (A)	Vehicle Reg. Date:	08/10/2015
Vehicle Colour:	BLUE	Gen Condition:	GOOD
Engine No:	D4DFDU546159	Chassis No:	KMHLB41UMGU078398
Odometer:	1 KM		

Paint Type:

List Item Discount: 20.00 %

Total Loss? **NO**

Est. Duration of Repair (day) 4

Description of Accident/Loss: REFER POLICE REPORT NO: T/20190930/2004

Present Location: COMFORTDELGRO ENGINEERING PTE LTD (LOYANG)

## COST OF CLAIMS

	Amount
Parts	3,851.80
Miscellaneous Items	11.00
Labour	2,070.00
Paintwork Labour	0.00
Towing	6205.92
<b>Gross Total (S\$)</b>	<b>5,932.80</b>

+ GST 7.00% (S\$) 415.30

Nett Amount (S\$) 6,348.10

**This claim is handled by: NG NYUK PHIN**

*Generated using Merimen e-Claims Internet Estimation & Adjusting System*

**REPAIR DETAILS****Reference****Part Source:** MRM-SG Version: 1.0 (Last Synchronised: 01 Oct 2019)**Parts:** 143 HYUNDAI I40 1.7 D CRDi (A) (Catalogue:Merimen Singapore 1.0)**Labour:** Repairer's (Price-denominated Standard List)**Print Code:** ComfortDelGro Engineering Pte Ltd/SHD6878D/01/10/2019 11:48**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk \*.**Estimates on Parts**

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount	
1	1		*FRONT BUMPER <i>x succ</i>	20.00	0.00	*1,052.20 FL	
2	1		*FRONT BUMPER SIDE BRACKET - LH <i>x succ</i>	20.00	0.00	*24.60 FL	
3	1		*FRONT BUMPER TOP BRACKET - LH <i>x succ</i>	20.00	0.00	*22.40 FL	
4	10		*FRONT BUMPER CLIPS <i>x 10</i>	20.00	0.00	*22.00 FL	
5	1		*SIDE MIRROR - LH <i>x succ</i>	20.00	0.00	*670.00 FL	
6	1		*FRONT FENDER - LH <i>1 Bkbl</i>	20.00	0.00	*566.30 FL	
7	1		*FRONT WHEEL COVER - LH <i>1 Bkbl</i>	20.00	0.00	*107.10 FL	
8	1		*FRONT DOOR - LH <i>x 14/17</i>	20.00	0.00	*2,256.40 FL	
9	1		*FRONT DOOR COMFORT STICKER - LH <i>1 succ</i>	0	0.00	*75.00 FS	
						F=Franchise part. S=SpcNett. L=ListItemDisc.	
						<i>Rocker panel harness (LH) x 14/17</i>	
						Sub Total (S\$)	4,796.00
						- List Item Discount on L Items (S\$)	944.20
						Total Parts (S\$)	3,851.80

ComfortDelGro Engineering Pte Ltd/SHD6878D/01/10/2019 11:48. Not valid without Reference section.  
Generated using Merimen e-Claims IEAS

# Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
<b>Miscellaneous Items</b>			
1	1	OD/TP Case (Insurer)	11.00 ✓
<b>Sub Total (S\$)</b>			<b>11.00</b>

# Estimates on Labour

No	Particulars	Lab.Type	Amount
<b>Labour Items</b>			
1	PANEL BEATING	New	<del>1,120.00</del> <sup>420</sup>
2	SPRAY PAINTING	New	<del>600.00</del> <sup>600</sup>
3	TUFF KOTE	New	<del>80.00</del> <sup>50</sup>
4	WIRING CHARGE	New	<del>50.00</del> <sup>x</sup>
5	TRANSFER OF DOOR	New	<del>120.00</del> <sup>120</sup>
6	FRONT WHEEL ALIGNMENT	New	<del>100.00</del> <sup>x</sup>
<b>Gross Labour Cost (S\$)</b>			<b>2,070.00</b>

ComfortDelGro Engineering Pte Ltd/SHD6878D/01/10/2019 11:48. Not valid without Reference section.  
 Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

*Kalin 16/1/19*  
*1/10/19 1200h*  
*3 days*  
*4/5*  
*Allen Repair pte*

...hence notify  
 ...following:  
 ...painting  
 ...resurvey  
 ...prejudice' basis  
 ...and  
 ...Company  
 Acknowledged by:  
 Signature:  
 Date:

Our Job Ref No : 305337664

Date : 4. Oct. 2019

ComfortDelGro Engineering Pte Ltd  
59 Loyang Drive Singapore 508969  
Fax: 6546 8156

**FINALIZATION FORM**

To : LKK

Fax :

Attn : KALVIN

Vehicle Reg No. : SHD6878D

Date of Accident: 27. Sep. 2019

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

1. The repair job shall bill to: TOKIO SKR8057J

2. The finalized amount shall be:

(a) Spare Parts after List discount \_\_\_\_\_

(b) Labour Charges \_\_\_\_\_

**Total for Part-By-Part Repair Cost** \_\_\_\_\_

(c.) Lumpsum Repair (if applicable)

Total for Lumpsum repair cost after Less: \_\_\_\_\_

**Final Lumpsum Repair cost** \$1,500.00

3. Estimated normal period for repairs: 3 working days.

4. **We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days**

5. Thank you for your assistance.

We confirm the estimates and finalized amount

Signature : 

Name : Larry Ng

Tel : 6214 8316

Fax : 6546 8156

Signature : 

Name : Kalvin

Date : 7/10/19

**For Official Use Only**

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid				
3. Survey Fees				
4. LTA Search Fee	\$7.49			
5. Medical Fees (on behalf of driver, if applicable)				
6 Overrun				

Remarks:

\_\_\_\_\_

\_\_\_\_\_

# ComfortDelGro Engineering Pte Ltd (Co.Reg.No:199506048W)

59 Loyang Drive  
Singapore 508969  
Tel: 6214 8300

## (SUPPLEMENTARY)

**TP INSURER: Tokio Marine Insurance Singapore Ltd (HQ)**  
**MSP TRACTORS PTE. LTD.**

Singapore

**Claimant**  
**Insurer: MS First Capital Insurance Ltd**

### PARTICULARS OF CLAIM

Claim Type:	THIRD PARTY	Ref. No:	
Policy No:	MU002810	Date of Loss:	27/09/2019
Vehicle Reg. No.:	<b>SHD6878D</b>	Driveable?	YES
Party At Fault:	UNKNOWN		
Driver (TP):	TAN SWEE KHENG		
Make/Model:	HYUNDAI I40, 1.7 D CRDI (A)	Vehicle Reg. Date:	08/10/2015
Vehicle Colour:	BLUE	Gen Condition:	GOOD
Engine No:	D4DFDU546159	Chassis No:	KMHLB41UMGU078398
Odometer:	1 KM		
Paint Type:			
List Item Discount:	20.00 %		
Total Loss?	<b>NO</b>		
Est. Duration of Repair (day)	4		
Description of Accident/Loss	REFER POLICE REPORT NO: T/20190930/2004		
Present Location:	COMFORTDELGRO ENGINEERING PTE LTD (LOYANG)		

COST OF CLAIMS	Amount
Parts	273.12
Miscellaneous Items	0.00
Labour	0.00
Paintwork Labour	0.00

Towing

0.00

<b>Gross Total (S\$)</b>	<b>273.12</b>
<b>+ GST 7.00% (S\$)</b>	<b>19.12</b>
<b>Nett Amount (S\$)</b>	<b>292.24</b>
<b>+ Previous Estimates (S\$)</b>	<b>6,348.10</b>
<b>Claim Total (S\$)</b>	<b>6,640.34</b>

*Generated using Merimen e-Claims Internet Estimation & Adjusting System*

**REPAIR DETAILS****Reference****Part Source:** MRM-SG Version: 1.0 (Last Synchronised: 04 Oct 2019)**Parts:** 143 HYUNDAI I40 1.7 D CRDi (A) (Catalogue:Merimen Singapore 1.0)**Labour:** Repairer's (Price-denominated Standard List)**Print Code:** **ComfortDelGro Engineering Pte Ltd/SHD6878D/04/10/2019 14:33****Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk \*.**Estimates on Parts**

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*ROCKER COVER GARNISH - LH <i>ca</i>	20.00	0.00	*341.40 FL
						F=Franchise part. L=ListItemDisc.
						<b>Sub Total (S\$)</b>
						<b>341.40</b>
						<b>- List Item Discount on L Items (S\$)</b>
						<b>68.28</b>
						<b>Total Parts (S\$)</b>
						<b>273.12</b>

**ComfortDelGro Engineering Pte Ltd/SHD6878D/04/10/2019 14:33. Not valid without Reference section.**  
Generated using **Merimen e-Claims IEAS**



**...CLAIM SUBFOLDER...(Pending for Survey Report)**

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	01 Oct 2019 11:42 <a href="#">Sendback Est</a>	01 Oct 2019 11:48 <b>S\$5,932.80</b>	01 Oct 2019 19:09 <a href="#">Edit Adj Rpt</a>	<b>S\$1,500.00</b> <a href="#">Edit Estimates</a>	<b>S\$1,500.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>
Supp #1	04 Oct 2019 14:32	04 Oct 2019 14:33 <b>S\$273.12</b>	04 Oct 2019 14:33			(Combined)	<b>Combined with Main</b> <a href="#">Uncombine Suppl.</a>

Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b>									
Insured:	<b>MSP TRACTORS PTE. LTD.,</b> Co. Reg. No.: 201005832C								
Main Claimant:	<b>COMFORT TRANSPORTATION PTE LTD,</b> Co. Reg. No.: 199303821R								
Vehicle Reg. No.:	<b>SHD6878D</b>	Date of Loss:	27/09/2019 17:00 - :59 [47 Months and 19 Days From LTA Reg Date (Man Yr)]						
Claim Type:	<b>TP / M1907657</b>	Policy/Cover Note No.:	MU002810 (Comprehensive) Coverage: 10/03/2019 - 09/03/2020						
Vehicle Reg. No. (Insured):	<b>SKR8057J</b>	Policy No. (Claimant):	D-18088936MFSH						
		Excess:	S\$0.00						
Repairer:	<b>ComfortDelGro Engineering Pte Ltd (Loyang)</b> 59 Loyang Drive, 508969 Loyang - Tel: 6214 8300								
Handling Insurer:	<b>Tokio Marine Insurance Singapore Ltd (HQ)</b> - Tel: 6221 6111 ... [Handled by <b>Ng Kwai Kay Francis</b> ]								
Claimant's Insurer:	<b>MS First Capital Insurance Ltd (HQ)</b> - Tel: 62222311								
Adjuster:	<b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>KALVIN ANG WEI KUN</b> ] ... [Final Rpt due 10/10/2019]								
<b>ASSOCIATED MAIL RECEIVED</b> <a href="#">View All</a> <a href="#">Compose Case Mail</a>									
There are no mail for this case.									
<b>ALL ASSOCIATED TASKS</b> <a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a>									
<b>Due Date</b>	<b>Priority</b>	<b>Type</b>	<b>Task Group</b>	<b>Subject</b>	<b>Handler</b>	<b>Assigned By</b>	<b>Completed On</b>	<b>Created On</b>	<b>Done?</b>
No results.									

## Claim Documents

SHD6878D (M1907657)  
[SKR8057J]  
TP  
COMFORT TRANSPORTATION PTE LTD  
Sep 27 2019 5:00PM  
[MSP TRACTORS PTE. LTD.]  
ComfortDelGro Engineering Pte Ltd

Upload Documents			Upload Photos			Compose New Letter			View	View in Browser
<b>Assessment Reports</b>									1 per page	<input checked="" type="checkbox"/>
No	Finalized On	ComfortDelGro Engineering Pte Ltd (Loyang)		Thumbnail	Print					
1	30/09/19 12:45	<b>Accident Statement</b>		Load HTM						
2	30/09/19 12:58	<b>Accident Statement Addm. #1</b>		Load HTM						
3	30/09/19 12:59	<b>Accident Statement Addm. #2</b>		Load HTM						
4	30/09/19 13:05	<b>Addendum Sheet</b>		Load TIF						
5	30/09/19 13:05	<b>Accident Statement Addm. #3</b>		Load HTM						
6	01/10/19 11:48	<b>Repairer Estimates</b>		Load HTM						
7	04/10/19 14:33	<b>Repairer Estimates Suppl. #1</b>		Load HTM						
No	Finalized On	Tokio Marine Insurance Singapore Ltd (HQ)		Thumbnail	Print					
1	01/10/19 12:25	<b>Accident Statement</b> <small>From: SC - Reg. No: SKR8057J, Claimant: MSP TRACTORS PTE. LTD</small>		Load HTM						
2	01/10/19 19:09	<b>Accident Statement</b> <small>From: SC - Reg. No: SKR8057J, Claimant: MSP TRACTORS PTE. LTD</small>		Load HTM						
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print					
1	07/10/19 10:17	<b>Adjuster Immediate Advice</b>		Load HTM						
<b>Photos/Images</b>									3 per page	<input checked="" type="checkbox"/>
No	Finalized On	ComfortDelGro Engineering Pte Ltd (Loyang)		Thumbnail	Print					
1	30/09/19 13:05	<b>Accident Photo</b> <small>[Linked Accident Report Documents]</small>		Load JPG	<input checked="" type="checkbox"/>					
2	30/09/19 13:05	<b>Accident Photo</b> <small>[Linked Accident Report Documents]</small>		Load JPG	<input checked="" type="checkbox"/>					
3	30/09/19 13:05	<b>Accident Photo</b> <small>[Linked Accident Report Documents]</small>		Load JPG	<input checked="" type="checkbox"/>					
4	30/09/19 13:05	<b>Accident Photo</b> <small>[Linked Accident Report Documents]</small>		Load JPG	<input checked="" type="checkbox"/>					
5	30/09/19 13:05	<b>Accident Photo</b> <small>[Linked Accident Report Documents]</small>		Load JPG	<input checked="" type="checkbox"/>					
6	30/09/19 13:05	<b>Accident Photo</b> <small>[Linked Accident Report Documents]</small>		Load JPG	<input checked="" type="checkbox"/>					
7	30/09/19 13:05	<b>SCENE</b> <small>[Linked Accident Report Documents]</small>		Load JPG	<input checked="" type="checkbox"/>					
8	30/09/19 13:05	<b>SCENE</b> <small>[Linked Accident Report Documents]</small>		Load JPG	<input checked="" type="checkbox"/>					
9	30/09/19 13:05	<b>SCENE</b> <small>[Linked Accident Report Documents]</small>		Load JPG	<input checked="" type="checkbox"/>					
10	30/09/19 13:05	<b>SCENE</b> <small>[Linked Accident Report Documents]</small>		Load JPG	<input checked="" type="checkbox"/>					
11	30/09/19 13:05	<b>SCENE</b> <small>[Linked Accident Report Documents]</small>		Load JPG	<input checked="" type="checkbox"/>					
12	30/09/19 13:05	<b>SCENE</b> <small>[Linked Accident Report Documents]</small>		Load JPG	<input checked="" type="checkbox"/>					
13	30/09/19 13:05	<b>SCENE</b> <small>[Linked Accident Report Documents]</small>		Load JPG	<input checked="" type="checkbox"/>					
14	30/09/19 13:05	<b>SCENE</b> <small>[Linked Accident Report Documents]</small>		Load JPG	<input checked="" type="checkbox"/>					
15	30/09/19 13:05	<b>SCENE</b> <small>[Linked Accident Report Documents]</small>		Load JPG	<input checked="" type="checkbox"/>					
16	30/09/19 13:05	<b>SCENE</b> <small>[Linked Accident Report Documents]</small>		Load JPG	<input checked="" type="checkbox"/>					
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print					
1	03/10/19 07:57	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>					
2	03/10/19 07:57	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>					
3	03/10/19 07:57	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>					
4	03/10/19 07:57	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>					
5	03/10/19 07:57	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>					
6	03/10/19 07:57	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>					
7	03/10/19 07:57	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>					

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	ComfortDelGro Engineering Pte Ltd (Loyang)	Thumbnail	Print
8	03/10/19 07:57	General View	Load JPG	<input checked="" type="checkbox"/>
9	03/10/19 07:57	General View	Load JPG	<input checked="" type="checkbox"/>
10	03/10/19 07:57	General View	Load JPG	<input checked="" type="checkbox"/>
11	03/10/19 07:57	General View	Load JPG	<input checked="" type="checkbox"/>
12	03/10/19 07:57	General View	Load JPG	<input checked="" type="checkbox"/>
13	03/10/19 07:57	General View	Load JPG	<input checked="" type="checkbox"/>
14	03/10/19 07:57	General View	Load JPG	<input checked="" type="checkbox"/>
15	03/10/19 07:57	General View	Load JPG	<input checked="" type="checkbox"/>
16	03/10/19 07:57	General View	Load JPG	<input checked="" type="checkbox"/>
17	03/10/19 07:57	General View	Load JPG	<input checked="" type="checkbox"/>
18	03/10/19 07:57	General View	Load JPG	<input checked="" type="checkbox"/>
19	03/10/19 07:57	General View	Load JPG	<input checked="" type="checkbox"/>
20	03/10/19 07:57	General View	Load JPG	<input checked="" type="checkbox"/>
21	03/10/19 07:57	General View	Load JPG	<input checked="" type="checkbox"/>
22	03/10/19 07:57	General View	Load JPG	<input checked="" type="checkbox"/>
23	03/10/19 07:57	General View	Load JPG	<input checked="" type="checkbox"/>
24	03/10/19 07:57	General View	Load JPG	<input checked="" type="checkbox"/>
25	03/10/19 07:57	General View	Load JPG	<input checked="" type="checkbox"/>
26	03/10/19 07:57	General View	Load JPG	<input checked="" type="checkbox"/>
27	03/10/19 07:57	General View	Load JPG	<input checked="" type="checkbox"/>
28	04/10/19 07:59	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
29	04/10/19 07:59	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
30	04/10/19 07:59	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
31	04/10/19 07:59	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
32	04/10/19 07:59	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
33	04/10/19 07:59	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	11/10/19 15:03	Supplementary	Load PDF	

### Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
<b>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</b> <div style="border: 1px solid black; height: 40px; width: 100%;"></div>			
<b>Show Remarks To:</b> <input type="checkbox"/> Repairer <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

### VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CS/TMI19017306/K1VF3E2

**Date:** 11/10/2019

#### REFERENCE

Handling Insurer: Tokio Marine Insurance Singapore Ltd	Policy No:	MU002810
<b>Claimant</b>		
<b>Vehicle No :</b> SHD6878D	<b>Insured Vehicle No :</b>	SKR8057J
Date of Loss: 27/09/2019	Nature of Claim:	TP Claim No: M1907657

#### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SHD6878D</b>	Engine No:	D4DFDU546159
Make & Model:	HYUNDAI I40, 1.7 D CRDi (A)	Chassis No:	KMHLB41UMGU078398
Reg. Date:	08/10/2015 (Man. Year: 2015)	Odometer:	681218 km
Colour:	Blue		
Engine Capacity:	1685 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

#### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	Good

#### CONDITION OF TYRES

Front Tyre Size:	205/60R16	Rear Tyre Size:	205/60R16
Front Left Side:	West Lake 7 mm	Rear Left Side:	West Lake 7 mm
Front Right Side:	West Lake 7 mm	Rear Right Side:	West Lake 7 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,124.92	886.84	3,238.08	78.50
Miscellaneous Items	11.00	11.00	0.00	0.00
Labour	2,070.00	1,070.00	1,000.00	48.31
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>6,205.92</b>	<b>1,967.84</b>	<b>4,238.08</b>	<b>68.29</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>1,500.00</b>		
(S\$)	6,205.92	1,500.00	4,705.92	75.83
<b>+ GST 7.00/7.00% (S\$)</b>	<b>434.42</b>	<b>105.00</b>	<b>329.42</b>	<b>75.83</b>
<b>Nett Amount (S\$)</b>	<b>6,640.34</b>	<b>1,605.00</b>	<b>5,035.34</b>	<b>75.83</b>

#### INSPECTION

Date of Assignment:	01/10/2019 Present Location:	ComfortDelGro Engineering Pte Ltd (Loyang)
Date Inspected:	01/10/2019 Inspected At:	ComfortDelGro Engineering Pte Ltd (Loyang) 59 Loyang Drive Singapore 508969
Estimated Period of Repair:	3.0 days	

**Adjuster:** KALVIN ANG WEI KUN

**Manager:** VERON CHEN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

**REPAIR DETAILS**

Reference	
<b>Part Source:</b> MRM-SG	Version: 1.0 (Last Synchronised: 11 Oct 2019)
<b>Parts:</b> 143	HYUNDAI I40 1.7 D CRDi (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b> Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SHD6878D)
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
<b>Further Info:</b> Items/values not in reference catalogue are prefixed with an asterisk *.	

**Recommended Parts**

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Serviceable	1,052.20 FL	*- FL
2	1		*FRONT BUMPER SIDE BRACKET - LH	Serviceable	24.60 FL	*- FL
3	1		*FRONT BUMPER TOP BRACKET - LH	Serviceable	22.40 FL	*- FL
4	10		*FRONT BUMPER CLIPS	Not Necessary	22.00 FL	*- FL
5	1		*SIDE MIRROR - LH	Serviceable	670.00 FL	*- FL
6	1		*FRONT FENDER - LH	Buckled	566.30 FL	*566.30 FL
7	1		*FRONT WHEEL COVER - LH	Grazed	107.10 FL	*107.10 FL
8	1		*FRONT DOOR - LH	Repair	2,256.40 FL	*- FL
9	1		*FRONT DOOR COMFORT STICKER - LH	Necessary	75.00 FS	*75.00 FS
<b>Supplementary #1</b>						
10	1		*ROCKER COVER GARNISH - LH	Cracked	341.40 FL	*341.40 FL
<b>Sub Total (\$\$)</b>					<b>5,137.40</b>	<b>1,089.80</b>
<b>- List Item Discount on L Items 20.00/20.00% (\$\$)</b>					<b>1,012.48</b>	<b>202.96</b>
<b>Total Parts (\$\$)</b>					<b>4,124.92</b>	<b>886.84</b>

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

### Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
<b>Miscellaneous Items</b>				
1	1	OD/TP Case (Insurer)	11.00	11.00
<b>Sub Total (\$\$)</b>			<b>11.00</b>	<b>11.00</b>

### Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	PANEL BEATING	New	1,120.00	420.00
2	SPRAY PAINTING	New	600.00	600.00
3	TUFF KOTE	New	80.00	50.00
4	WIRING CHARGE	New	50.00	0.00
5	TRANSFER OF DOOR	New	120.00	0.00
6	FRONT WHEEL ALIGNMENT	New	100.00	0.00
<b>Gross Labour Cost (\$\$)</b>			<b>2,070.00</b>	<b>1,070.00</b>

Report was unsubmitted during this print-out.

**< END OF ESTIMATES >**