

Surveyor

REF: C/TPD19017318/N

Special Instruction

ASSIGNMENT (Office)

Date/Time: 24/9/2019

From (Person): Kamaliyah Kamis

SPF

Bill to:

Estimated Cost:

Estimated Cost: _____
 OD/TP/WS/TP RES / OD RES / EVA / INV / MV / CS

Insured:

To inspect Vehicle No: JRT4220

Tel:

at Workshop m/a

of

Policy No: MHASPE 06000025858

Claim No. _____

TP	IP	47559	2010
----	----	-------	------

Excess:

D.O.A. 8172016

Sum insured:

Make of Veh: _____
(Client's Remark)

H.O.D. Endorsement:

CA / REV / REP. / REV 24 HRS

Vehicle IN/OUT

Date/Time:

Person Contacted:

Date/Time	Action/Instruction ()	Estimate
-----------	------------------------	----------

IRTH220-X

Date/Time

Mechanical Inspection Report Request

Kamaliah KAMIS (SPF) <Kamaliah_KAMIS@spf.gov.sg>

Tue 24/9/2019 12:13 PM

To: Shervin Beh (LKA Auto) <ShervinBeh@lkaauto.com>; Naz (LKA Auto) <Naz@lkaauto.com>

Cc: Bryan FR CHEUNG (SPF) <Bryan_FR_CHEUNG@spf.gov.sg>; Shahul Nizam SAMARRI (SPF) <Shahul_Nizam_SAMARRI@spf.gov.sg>; David DY YAP (SPF) <David_DY_YAP@spf.gov.sg>

Dear Sir,

May I seek your assistance to perform a detailed mechanical inspection of the following 3 vehicles on an urgent basis as the vehicles below are required to be returned to their respective owners ASAP:

a) Case IAFP-09-20190924 - Mechanical Inspection of Police Motor Car, QX297H (TP/IP/54567/2019)

On 30 August 2019 (Friday) sometime before 4.45 pm, the police motor car, QX297H (B1), was travelling straight along Bishan St 2 towards the direction of Marymount Rd on lane 2 of the 2-lanes road and was on his way to Tanglin Div. At this juncture, a grey motor car (A1) that was travelling directly ahead of B1, was seen making a left turn into Raffles Institution. Upon seeing that, B1 JID from Tanglin Division, GIS 5) applied brake to slow down but to no avail, B1 claimed that the brakes were ineffective and this caused the police motor car to collide into the rear of A1. There was no injury reported for this accident however B1 claimed that there was a mechanical fault on his police motor car.

Vehicles to be inspected: QX297D - Driver (Potential Defendant)

ID In-Charge: IO Kamaliah

b) Case IAFP-09-20190924 - Mechanical Inspection of Motorcycle, JRT422Q (TP/IP/47559/2019)

On 31/07/2019 (Wednesday) at 5.44 pm, Serious RTA, involving 2 Malaysian motorcycles along BKE (Woodlands Checkpoint) before the viaduct L/P 523. B1: Motorcycle, JRT422Q, (Yamaha/Red). B1 was riding on Lane 2 of the 4-lane expressway along BKE towards Woodlands Checkpoint, B1 was heading upwards the viaduct towards Woodlands Checkpoint when he noticed another Malaysian motorcycle ahead of him - on the same lane and in stationary position - joining the queue. B1 was applying his brakes when he claimed, he had experience malfunction to the rear brakes and the rear brakes were not working. As such, B1 was not able to slow down his motorcycle which resulted in a collision with the rear right portion of the front motorcycle.

Vehicles to be inspected: JRT422Q - Rider (Potential Defendant)

ID In-Charge: IO Shahul Nizam

c) Case IAFP-09-20190924 - Mechanical Inspection of Motor Car, SGT680B (TP/IP/58341/2019)

On 16 September 2019 at about 1530hours along Woodlands Avenue 9 at the junction of North Coast Avenue, motor car, SGT680B, that was driven by a tester (accompanied by a qualified tester) was travelling along Woodlands Avenue 9 towards Woodlands Avenue 5 and had made a right turn towards North Coast Avenue on green traffic light. Testee was negotiating the right turn and was about 1/3 into the turn when the tester noticed the motorcycle coming fast from the opposite direction. The tester had warned the testee to not cross over but there was no response from the testee. The tester then pulled the hand brakes followed by applying the foot brake which resulted in the motorcar coming a complete stop. Thereafter, the motorcyclist came from the opposite direction on the left lane and collided onto the front left wheel. Both the tester and testee did not indicate any mechanical faults during the test. However, Commander had directed to send the motorcar for inspection and to particularly inspect the hand brakes and foot brakes. The motorcar belongs to a private instructor and thus I would like to seek your understanding in expediting this mechanical inspection so that we can get concurrence to return the motorcar upon receipt of the mechanical report.

Vehicles to be inspected: SGT680B - Driver (Potential Defendant)

ID In-Charge: IO David Yap

2. Thank you Sirs.

cc: Bryan, Fyp
IO Shahul Nizam & IO David Yap, as requested by you & Fyp

Best regards,

Kamaliah Kamis (SPF)
Senior Investigation Officer / 4 and Accident Investigation Team
Traffic Police Department / Singapore Police Force
MOB: 8327 0425 / FAX: (83) 8347 8322



HOME TEAM
TRANSFORMATION 2025
One Home, One Team
Building Our Future Together

WARNING: This document contains information that may be exempt from disclosure under the provisions of the Freedom of Information Act. It is to be controlled and its disclosure to the public is restricted. It is to be stored and handled in accordance with the provisions of the Information Security Act. It is to be destroyed when it is no longer required for official use.