



Your Ref : C10004143/JM

Date: 04th Oct 2019

Our Ref : CS/AGI19017324/Dvd3e2

M/s Auto & General Insurance (Singapore) Pte Ltd
(Budget Direct Insurance)
190 Clemenceau Avenue #03-01
Singapore Shopping Centre
Singapore 239924
(The Motor Claims Department)

Dear Sirs/Madam,

**AUTOMOBILE INSPECTION REPORT OF ACCIDENT VEHICLE SLM 4329R
ACCIDENT ON 29/09/2019**

Instruction was received to inspect the vehicle Reg. No. SLM 4329R. The inspection was conducted on 01/10/2019 at the premises of Ah Lim Motor Company, No 10, Ang Mo Kio Industrial Park 2A, #01-09 AMK Autopoint, Singapore 568047.

The following vehicle information was recorded:


Registration Number	: SLM 4329R
Make/Model	: Jaguar X-TYPE 2.0SE
Year of Registration	: 2007
Body Colour	: Grey
Chassis Number	: SAJAG51N08YJ29636
Engine Capacity	: 2099 cc
Speedometer Reading	: Not Available

The vehicle caught fire. (Details see photographs enclosed)

In view of this, we are of the opinion that it would be **uneconomical** to proceed with the repairs due to extensive repair cost and recommend it to be written off as **"Total Loss"**.

Market Value	S\$	63,000.00(est)
Less: LTA Reimbursement Value (RV)	(S\$	40,659.00)
Nett Liability	S\$	22,341.00

Vehicle Inspected By:



ANG BRYAN TANI

Automotive Assessor / Investigator



K.K.LAU

*MSc(Eng M), B Eng(Hons), Peng(UK),
MASME(USA), B Bus(Aust), MBA(UK),
IEng(UK), MIE(mech), MinstAEA, MFIEA,
MIRTE, MIMI, MSAE, MCIAd, AM, NIJAAR(USA),
AM CATARI(CAN), M.MATA(USA), M.MdATA(USA),
Licensed Appraiser*

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability or responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.