

22/03/2002

ASS. REC. BY:

REF:

CS/AGI19017328/Btd3^{sz}

Special Instructions:

Surveyor: Mr. Kim

ASSIGNMENT (Office)

From (Person): Jay Rabilla of AGIDate/Time: 2/10/19 @ 12:10pm

Estimated Cost: _____ Bill to: _____

OD ☒ TP WS / TP RES / OD RES / EVA / INV / MV / CSTo Inspect Vehicle No: SLX 150GInsured: SKF 8197B

at Workshop m/s

Team AutoproTel: 6258 1955of 160 Sin Ming Drive # 01-14

Policy No: _____

Claim No: C10004014 / KY

Sum Insured: _____

Excess: _____

Make of Veh: _____

D.O.A. 12/09/2019

(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement: _____

Date/Time: 12:17pm 2/10/19Person Contacted: peachVehicle ☒ IN ☐ OUT

Date/Time	Action/Instruction (✓) Estimate	
	SLX 150G - NBA/AGI19016227/Y	DOT: 12/09/2019
	SKF 8197B - NBA/AGI19016227/Y	DOT: 12/09/2019

REF: AGI

ASSIGNMENT

From: Date: 31/10/19

Estimated Cost:

OD ☒ TP ☐ WS ☐ TP RES ☐ OD RES ☐ EVA ☐ INV ☐ MVTo inspect Vehicle No: SLX 150G
at Workshop m/s Team Autopro
of 60 Sin Ming Drive # 01-14
Insured:

Policy No:

Claims No:


Sum Insured:

Excess:

(Client's Record)

Make of Veh: 2pm (waiting)

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 4 days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS ^{up}

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No: SLX 150G Yr Regn: 20/3/2018

Type: ☒ M. Car / ☐ M. Cycle / ☐ Bus / ☐ Van / ☐ Lorry / ☐ Taxi / ☐ Prime Mover /

Truck / Trailer or

Make: Kia Cerato K3 C.C 1531

Colour: White A/C: Insured / Std / NI / NA

Sp. Reading: 26302 T/Radio: Insured / Std / NI / NA

Eng/No: GAFGHH690869

C/No: KNAFZ411MJ5760948

Gen. Cond: Good / Fair / Poor / Burnt

Steering: ☒ In order / ☐ Jammed / ☐ Leaked / ☐ Burnt orBrake: ☒ In order / ☐ Jammed / ☐ Leaked / ☐ Burnt orModi: Nil / ☒ S/Rim / ☐ STD A/Rim or

Tyre Size: F: 215/45R17

R: 215/45R17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or NEXEN

Front

Rear

R/Bal. 6 mm R/Bal. 6 mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A. 12/09/2019 D.O.I. 3/10/19

Survey held at: Team Autopro

Des. of Damages: Frt / ☒ Rear / ☐ O/S / ☐ N/S / ☐ U/C / ☐ Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	Range 3,000/- - 4,000/- (Red: 6350.40, 69%)
	Lm, PLS see my remarks RECEIVED 07 NOV 2019
	HS 2,800/- Term 1/10/19 ✓
	MV 69,000/- Finalized with W/S @
	PV 42,646/- \$2800/- with 4 days repair
	NV 26,354/- on 6/11/19 @ 1000 hrs Term line 4/10/19

Date/Time, File Pass to?

☐ : Preli. Report

Days Of Repair: 4

1) 7/11 Typist

☐ : Final Report

Resurvey No. of Trip: 1

Date/Time, File Return to?

2)

Add Fee: ☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech. Insp (\$)☐ : T/NAF/STW (\$)

Survey Fee: 250

Transportation:

S+PS \$

Phone:

Other:

TOTAL

Report Format: Tp

Lum Sum / L.B. (\$)

2800/-

Nivitha (LKK Auto)

From: Ivy Ratilla <ivy.r@budgetdirect.com.sg>
Sent: Wednesday, 2 October 2019 12:10 PM
To: Admin-D (LKKAuto)
Cc: SUR; Justin Wong
Subject: TPPD Survey: Claim ref:C10004014/KY || OI- SKF8197B (Blue) TP- SLX150G || Est: \$23467.54 || Team Autopro
Attachments: PRS 150 SKF8197B.pdf

Hi Team,

We would like to arrange for TP survey for SLX150G.

Please confirm. Thank you.

Regards,

Ivy Ratilla
Executive, Claims Admin

T +65 6540 2185
F +65 6725 0853
E ivy.r@budgetdirect.com.sg



Customer Care +65 6221 2111
Claims +65 6221 2199
Claims (Int.) +65 6540 2199

190 Clemenceau Avenue, #03-01
Singapore Shopping Centre
Singapore
239924
budgetdirect.com.sg

auto  general

Auto & General Insurance (Singapore) Pte. Limited (Co. Reg. No. 201626103G) trading as **Budget Direct Insurance**.

This email is sent by Auto & General (SEA) Services Pte. Limited or a related body corporate (Auto & General) and is for the intended addressee. The views expressed in this email and attachments (email) reflect the views of the stated author but may not reflect views of Auto & General. This email is confidential and subject to copyright. It may be privileged. If you are not the intended addressee, confidentiality and privilege have not been waived and any use, interference with, or disclosure of this email is unauthorised.

This email is sent by Auto & General (SEA) Services Pte. Limited or a related body corporate (Auto & General) and is for the intended addressee. The views expressed in this email and attachments (email) reflect the views of the stated author but may not reflect views of Auto & General. This email is confidential and subject to copyright. It may

be privileged. If you are not the intended addressee, confidentiality and privilege have not been waived and any use, interference with, or disclosure of this email is unauthorised.

From: TeamAutoPro North <teamautopl@gmail.com>

Sent: Wednesday, 2 October 2019 10:49 AM

To: Claims <claims@budgetdirect.com.sg>

Subject: 2 Days Notice: SLX 150 G (Our Ref) and SKF 8197 B (Your Ref) Dated 12th September 2019

Dear Sir/Madam,

Road Traffic Accident Involving SLX 150 G (Our Ref) and SKF 8197 B (Your Ref)

Dated 12th September 2019, Time around 10:40HRS

@ ALONG UBI AVE 1

We represent our client; KOH SHAO YEN, to notify you of the aforesaid road traffic accident involving our client's vehicle registration number: SLX 150 G and your insured's vehicle registration number: SKF 8197 B.

For efficiency purpose, we are agreeable with the appointment of **Mr Lim - LKK** as the SJE for subject claim. Please let us know within **2 working days** from today your agreeing to the above otherwise kindly send us your list of at least **ten (10) motor surveyors, via email to the following personnel:-**

Contact Person	Eric Lee	8269 9999
Email Address	teamautopl@gmail.com	
Survey Address	160 Sin Ming Dr, #01-14 Singapore 575722	

Thank you for your attention to this email and we look forward to your earliest reply.

--
The above settlement is in respect of our client for damage pertaining to his motor vehicle and shall not prejudice our client's claim in respect of damages and consequential loss in relation to his personal injuries.

Cheers,

Peach

Team AutoPro Pte Ltd

Tel: 6258 1955

Fax: 6258 1956

(Newly Shifted) Main Office: 160 Sin Ming Dr, #02-12 Sin Ming AutoCity Singapore 575722
Workshop/Survey Venue: 160 Sin Ming Dr, #01-14 Sin Ming AutoCity Singapore 575722

This email is sent by Auto & General (SEA) Services Pte. Limited or a related body corporate (Auto & General) and is for the intended addressee. The views expressed in this email and attachments (email) reflect the views of the stated author but may not reflect views of Auto & General. This email is confidential and subject to copyright. It may be privileged. If you are not the intended addressee, confidentiality and privilege have not been waived and any use, interference with, or disclosure of this email is unauthorised.



BY FAX : 6725-0853

Email : Claims@budgetdirect.com.sg

02nd October 2019

Auto & General Insurance (Singapore) Pte Limited

Attn : Motor Claim Department

Dear Sir/Madam,

Road Traffic Accident Involving SLX 150 G (Our Ref) and SKF 8197 B (Your Ref)

Dated 12th September 2019, Time around 10:40HRS

@ ALONG UBI AVE 1

We represent our client; KOH SHAO YEN, to notify you of the aforesaid road traffic accident involving our client's vehicle registration number: SLX 150 G and your insured's vehicle registration number: SKF 8197 B. Enclosed herewith a copy of the Singapore Accident Statement / Traffic Police Report filed for your reference.

We hereby give you **NOTICE** that we are claiming against SKF 8197 B for damages, costs and disbursements as a result of the aforesaid road traffic accident.

Please let us know within 2 working days from today, your insured's and your intention to conduct a pre-repair survey on our client's vehicle, along with your list of at least ten (10) motor surveyors.

If we do not receive any reply from you within the stipulated timeline, we shall proceed to appoint our own surveyor and proceed with the necessary repair for our client's vehicle without further reference to your insured or you.

If we do not receive any reply from you within the stipulated timeline, we shall proceed to appoint our own surveyor and proceed with the necessary repair for our client's vehicle without further reference to your insured or you.

Contact Person	Eric Lee	8269 9999
Email Address	teamautopl@gmail.com	
Survey Address	160 Sin Ming Dr, #01-14 Sin Ming AutoCity Singapore 575722	

Kindly cc a copy of this letter to your insured for his/her acknowledgement.

Authorized Signatory



Team AutoPro Pte Ltd Co Reg No: 201811621K

160 Sin Ming Drive #02 -12 Sin Ming Autocity Singapore 575722
Tel: 6258-1955 Fax: 6258-1956 Email: teamautooffice@gmail.com / teamautopl@gmail.com

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	13/09/2019 12:06
Date Of Accident	12/09/2019 10:40
Exact Location Of Accident	ALONG UBI AVENUE 1
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLX150G
Insured/Policyholder	
Name Of Registered Owner	KOH SHAO YEN (XU XIAOYAN)
NRIC No	S7526667G
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-93809788
Alternative Phone No	OTHERS-93809788

Vehicle Particulars

Manufacturer	KIA
Model	CERATO K3-1.6 SUNROOF (A)
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	1800027599-01
Cover Note Number	


Driver

Name of Driver	TAN TEE GUAN
NRIC No	S8202359C
Date Of Birth	14/01/1982
Occupation	INDOOR
Date Of Driving Pass	24/05/2002
Driving Experience	17 YEARS AND 3 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-93809788
Fax Number	
Contact Number	OTHERS-93809788
Email Address	NOEMAIL

Sketch Plan #2

SKETCH PLAN

Along with Arhant



V-A) SLX1506

V-B) SKF 8197B

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On the stated date and time, I vehicle 'A' SLX1506 was travelling on the stated venue. I was travelling straight in my lane. the vehicle in front stop hence I slowed down and came to a complete stop. suddenly vehicle 'B' collided against my stationary vehicle rear portion.

DECLARATION

I/We declare the foregoing particulars are true in every respect

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Person's Signature
Name
NRIC/IN No:

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	667G
Vehicle Details	
Vehicle No.:	SLX150G
Vehicle to be Exported:	No
Intended Deregistration Date:	04 Oct 2019
Vehicle Make:	KIA
Vehicle Model:	CERATO K3 1.6A SUNROOF
Primary Colour:	White
Manufacturing Year:	2017
Engine No.:	G4FGHH690869
Chassis No.:	KNAFZ411MJ5760948
Maximum Power Output:	95.3 kW (127 bhp)
Open Market Value:	\$15,355.00
Original Registration Date:	20 Mar 2018
First Registration Date:	20 Mar 2018
Transfer Count:	0
Actual ARF Paid:	\$15,355.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	19 Mar 2028
PARF Rebate Amount:	\$11,516.00
Intended COE Rebate Details	
COE Expiry Date:	19 Mar 2028
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$36,810.00
COE Rebate Amount:	\$31,130.00
Total Rebate Amount:	\$42,646.00

The information contained herein is correct as at 04 Oct 2019

OK

MV 69,000/2
PV 42,646/2
NV 26,354/2

TGum lin
4/10/19

Posted: 26-Sep-2019 Tags: 2018 Kia Cerato, 2018 kia cerato, Kia Cerato, kia cerato, Kia, Cerato, cerato, Used Kia

**Kia Cerato K3 1.6A Sunroof (OPC)**

N.A

28-Feb-2018

1,591 cc

Sedan

SOLD

Selling On Behalf Of Direct Owner To Private Buyer By SgCarConsign.

Posted: 19-Aug-2019 Tags: 2018 Kia Cerato, 2018 kia cerato, Kia Cerato, kia cerato, Kia, Cerato, cerato, Used Kia

**Kia Cerato K3 1.6A Sunroof**

N.A

20-Mar-2018

1,591 cc

Sedan

SOLD

Rare Sunroof Unit. 1 Careful Owner Relocating. Urgent Sale Required. Still Smells Like A New Car. High Trade In And Flexible Financing Schemes Available. Call Us Today For A Viewing Or Discussion.

CONFIRMED

Posted: 01-Aug-2019 Tags: 2018 Kia Cerato, 2018 kia cerato, Kia Cerato, kia cerato, Kia, Cerato, cerato, Used Kia

**Kia Cerato K3 1.6A SX Sunroof**

\$69,800

\$7,330 /yr

26-Mar-2018

1,591 cc

24,000 km

Sedan

Available

Low Depreciation! Fully Agent Maintained By C&C. Still Under Agent's Warranty. Only 1 Previous Owner! SX Model With Bodykit With A Stylish Look Equipped With Paddle Shifters. Powerful, Smooth Yet Fuel Efficient. Flexible Loan Packages Available With Attractive Interes...

AL Autocar Pte Ltd

PREMIUM ED

Posted: 19-Sep-2019 Tags: 2018 Kia Cerato, 2018 kia cerato, Kia Cerato, kia cerato, Kia, Cerato, cerato, Used Kia

**Transform the look of your car**

Think your used car needs a fresh face? You can consider changing the colour. Find your preferred workshop providing the best quality car spray paint service here.

Find out more!

**Kia Cerato K3 1.6A Sunroof (OPC)**

N.A

26-Apr-2018

1,591 cc

Sedan

SOLD

Car In Mint Condition. Highest Specs (SX) Model. Just Serviced At C&C On 3rd Aug 2019. Agent Warranty Till Apr 2023. Interested Parties Please Call Now For Viewing.

DIRECT OWNER

Posted: 04-Aug-2019 Tags: 2018 Kia Cerato, 2018 kia cerato, Kia Cerato, kia cerato, Kia, Cerato, cerato, Used Kia

**Kia Cerato K3 1.6A Sunroof**

N.A

04-May-2018

1,591 cc

Sedan

SOLD

Very Well Maintained By The Owner! So Well Maintained That It Looks Better Than When Collection Of Car! Call To Arrange Appointment For Viewing. Call For More Flexible Loan Available, Price Negotiable, All Offers Considered, Make It Yours Today.

Cars & Yachts Pte Ltd

Posted: 14-Aug-2019 Tags: 2018 Kia Cerato, 2018 kia cerato, Kia Cerato, kia cerato, Kia, Cerato, cerato, Used Kia

**Kia Cerato K3 1.6A**

\$68,000

\$7,160 /yr

22-May-2018

1,591 cc

15,854 km

Sedan

Available

1 Owner, Sports Rims, Leather Seats, Rear Air Condition, Functions Steering, Cruise Control, Touch Screen LCD Audio System, Bluetooth, Reverse Camera And Sensors. Full Agent Maintained With Agent Warranty Till April 2023 For Peace Of Mind Plus 10 Years Engine Warra...

Posted: 26-Sep-2019 Tags: 2018 Kia Cerato, 2018 kia cerato, Kia Cerato, kia cerato, Kia, Cerato, cerato, Used Kia

**Kia Cerato K3 1.6A SX Sunroof**

\$72,000

\$7,430 /yr

28-May-2018

1,591 cc

20,000 km

Sedan

Available

Sports (SX) Version, Fully Stock. Sporty Ride In Gravity Blue With Sunroof, 17" Sports Rims, Paddle Shifters. Fully Serviced By C&C, Still Under Warranty. Genuine Mileage, Good Condition. Road Tax Paid Till Nov 19. Nice 3 Digit Plate.

Posted: 27-Sep-2019 Tags: 2018 Kia Cerato, 2018 kia cerato, Kia Cerato, kia cerato, Kia, Cerato, cerato, Used Kia

**Kia Cerato Forte 1.6A EX**

N.A

14-Sep-2018

1,591 cc

Sedan

SOLD

1 Careful Owner! Newest Facelift Agent Maintained Unit! Cheapest Depreciation In The Car Market! Showroom Condition! Original KIA Paint! 5 Years Comprehensive C&C Warranty, 10 Years Engine Warranty! 100% Loan Approval! Loan Up To 90%! Banks/In-House Loan...

PREMIUM ED

Posted: 27-Jul-2019 Tags: 2018 Kia Cerato, 2018 kia cerato, Kia Cerato, kia cerato, Kia, Cerato, cerato, Used Kia

**Kia Cerato 1.6A EX (OPC)**

N.A

01-Oct-2018

1,591 cc

Sedan

SOLD

With Normal Plate Conversion Selling At \$73,800! 1 Careful Owner! Latest Facelifted Model! Fully Agent Maintained Unit! Cheapest Depreciation With Lowest Mileage Done! Like New Condition With 5 Years Comprehensive C&C Warranty & 10 Years Engine Warranty! 1... Creative Auto

Posted: 29-Jul-2019 Tags: 2018 Kia Cerato, 2018 kia cerato, Kia Cerato, kia cerato, Kia, Cerato, cerato, Used Kia

**Kia Cerato Forte 1.6A SX**

N.A

30-Oct-2018

1,591 cc

Sedan

SOLDGraded A by **STP**

w Monthly From \$6xx Only! Wait No Further! 1 And Only Newest Facelifted Kia Cerato Forte In The Market! Still In New Condition! Low Depreciation Yet Good Fuel Consumption At 14km/L! Full Agent Unit Maintained By Cycle & Carriage Still Under Warranty Till 10/2023! A...

PREMIUM EDSelect used cars to **Compare** or **Add to Alert****Shortlist [1]**

Add to Shortlist

Compare Now

Clear All

Kia Cerato K3 1.6A SX Sunroof
26-Mar-2018

To compare cars, select from the search results.

To compare cars, select from the search results.

To compare cars, select from the search results.

Date of Recurvey: _____

After-PAINT
After-PAINT

Year: _____

Contacts: _____

Year: _____

Chassis No: _____

*** AGREED Cost Of Repair and Repair Day/s with SJE ***

Amount: _____

Working Day: _____

Nos.	PARTS	Qty	Unit S\$	TOTAL S\$
1	BOOTLID	1	\$ 747.00	\$ 747.00
2	BOOTLID LOGO	1	\$ 62.00	\$ 62.00
3	BOOTLID EMBLEM 'CERATO'	1	\$ 58.00	\$ 40.00
4	BOOTLID EMBLEM 'K3'	1	\$ 58.00	\$ 36.70
5	REAR BUMPER	1	\$ 601.00	\$ 601.00
6	REAR BUMPER SIDE RETAINER	2	\$ 64.00	\$ 128.00
7	REAR BUMPER REINFORCEMENT	1	\$ 360.00	\$ 360.00
8	REAR BUMPER REINFORCEMENT BRACKET	2	\$ 122.30	\$ 244.60
9	REAR BUMPER SPONGE	1	\$ 187.00	\$ 187.00
10	REAR BUMPER REVERSE SENSORS	2	\$ 200.00	\$ 400.00
11	REAR BUMPER LOWER SKIRT	1	\$ 389.00	\$ 389.00
12	REAR BUMPER DIFFUSER	1	\$ 258.00	\$ 258.00
13	REAR BUMPER REFLECTOR	2	\$ 46.00	\$ 92.00
14	REAR BUMPER STAY	5	\$ 58.00	\$ 290.00
15	REAR END PANEL	1	\$ 282.00	\$ 282.00
16	REAR END PANEL TOP GARNISH	1	\$ 56.00	\$ 56.00
17	TAIL LAMP	2	\$ 526.00	\$ 1,052.00
18	TAIL LAMP INNER SPONGE	2	\$ 60.00	\$ 120.00
19	TAIL LAMP PANEL	2	\$ 330.00	\$ 660.00
20	TAIL LAMP LOWER BRACKET	2	\$ 92.00	\$ 184.00

Parts Sub Total: \$ 2491.30 6,896.00

DISC

10%

\$ 249.13 689.60

PARTS TOTAL: \$ 2242.17 6,206.40

Nos.	SPECIAL NETT	Qty	Unit S\$	TOTAL S\$
1	TAIL LAMP INNER SPONGE CLIPS	2	\$ 50.00	\$ 100.00
2	REAR BUMPER CLIPS	10	\$ 5.00	\$ 50.00
3	Sundries	1	\$ 50.00	\$ 50.00
SPECIAL NETT TOTAL:				\$ 30.00 200.00

Nos.	LABOUR	S\$
1	PANEL BEATING	\$ 600.00 1,200.00
2	RUST PROOFING	\$ 30.00 150.00
3	SPRAY PAINTING	\$ 600.00 1,200.00
4	CHECK WIRING	\$ 30.00 100.00
5	RESET & RE-PROGRAM FAULT CODE	\$ 100.00 100.00
LABOUR TOTAL:		\$ 1260.00 2,750.00

PARTS TOTAL: \$ 2242.17 6,206.40

SPECIAL NETT TOTAL: \$ 30.00 200.00

LABOUR TOTAL: \$ 1260.00 2,750.00

GRAND TOTAL: \$ 3532.17 9,156.40

@ 20% 706.43

2825.74

4/5 2800/2

Resurvey 31/10/19 TGM Lin
1610 hrs
Repair days 4
Lump sum repair



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AUTO & GENERAL INSURANCE (S) PL

Ref : CS/AGI19017328/Btd3s2

(BUDGET DIRECT INSURANCE)

190 CLEMENCEAU AVENUE #03-01

SINGAPORE SHOPPING CENTRES SINGAPORE

239924

Date : 12-11-2019



Code : AGI

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SKF 8197B	Veh. Inspected	SLX 150G
Policy No.		Coverage (\$)	0.00
Claim No.	C10004014/KY	Excess (\$)	0.00
Assign From	IVY RATILLA	Assign Date	02/10/2019

2. Vehicle Particulars & Condition

Make & Model	KIA CERATO K3	c.c	1591
Engine No.	HIDDEN	Year of Reg.	2018
Chassis No.	KNAFZ411MJ5760948	Colour	WHITE
Odometer	26302	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	FAIR		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	215/45 R17	NEXEN	6 mm
L/H Front Tyre	215/45 R17	NEXEN	6 mm
R/H Rear Tyre	215/45 R17	NEXEN	6 mm
L/H Rear Tyre	215/45 R17	NEXEN	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	12/09/2019	Inspection Date	03/10/2019
Survey held at	160 SIN MING DRIVE #01-14 SINGAPORE 575722		
Repairer	TEAM AUTOPRO PTE LTD		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **4 Working Days**



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLX 150G

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	BOOTLID	TO REPAIR SEE LABOUR	747.00	-
1	BOOTLID LOGO	NECESSARY	62.00	62.00
1	BOOTLID EMBLEM 'CERATO'	NECESSARY	58.00	40.00
1	BOOTLID EMBLEM 'K3'	NECESSARY	58.00	36.70
1	REAR BUMPER	CUT	601.00	601.00
2	REAR BUMPER SIDE RETAINER @ \$64.00	NECESSARY	128.00	128.00
1	REAR BUMPER REINFORCEMENT	BROKEN	360.00	360.00
2	REAR BUMPER REINFORCEMENT BRACKET @ \$224.00	BENT	448.00	244.60
1	REAR BUMPER SPONGE	NOT APPLICABLE	187.00	-
4	REAR BUMPER REVERSE SENSORS @ \$200.00	DISLODGE / CUT 2PCS ONLY	800.00	200.00
1	REAR BUMPER LOWER SKIRT	BROKEN	389.00	389.00
1	REAR BUMPER DIFFUSER	NOT APPLICABLE	258.00	-
2	REAR BUMPER REFLECTOR @ \$78.00	BROKEN	156.00	92.00
5	REAR BUMPER STAY @ \$58.00	NO DAMAGE	290.00	-
1	REAR END PANEL	DENTED	282.00	282.00
1	REAR END PANEL TOP GARNISH	DENTED	56.00	56.00
2	TAIL LAMP @ \$526.00	NO DAMAGE	1,052.00	-
2	TAIL LAMP INNER SPONGE @ \$60.00	NOT APPLICABLE	120.00	-
2	TAIL LAMP PANEL @ \$330.00	NO DAMAGE	660.00	-
2	TAIL LAMP LOWER BRACKET @ \$92.00	NO DAMAGE	184.00	-
	LESS 10% DISCOUNT		-689.60	-249.13
			6,206.40	2,242.17
SPECIAL NETT ITEMS				
2	TAIL LAMP INNER SPONGE CLIPS @ \$50.00 (SN)	NOT APPLICABLE	100.00	-
10	REAR BUMPER CLIPS @ \$5.00 (SN)	NECESSARY	50.00	30.00
1	SUNDRIES (SN)	NOT APPLICABLE	50.00	-
			200.00	30.00
LABOUR				
	PANEL BEATING. INCLUSIVE OF THE REPAIR OF BOOTLID.		1,200.00	600.00
	RUST PROOFING.		150.00	30.00
	SPRAY PAINTING.		1,200.00	600.00

Report Ref No. CS/AGI19017328/Btd3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	CHECK WIRING.	NOT APPLICABLE	100.00	30.00
	RESET & RE-PROGRAM FAULT CODE.		100.00	-
			2,750.00	1,260.00
GRAND TOTAL			9,156.40	3,532.17
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				2,800.00

Report Ref No. CS/AGI19017328/Btd3s2

LIM TEOW GUAN

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report in whole or in part, does so at his or her own risk.