

22/03/2001

ASS. REC. BY:

REF:

CS3/MG19017343/TICD302

Special Instructions:

Surveyor: Taufik

ASSIGNMENT (Office)

From (Person):

meihan

Partikiban Theethan

MG

Date/Time: 2/10/19 @ 12.50pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLS1204

Insured:

SKP 99869

at Workshop m/s

MTM Performance

Tel:

92210404

of

42 Joh Guan Rd East #01-78

Policy No:

Claim No: 7622 958690SG

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

28/09/2019

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

1:49pm @ 2/10/19

Person Contacted:

Gwin

Vehicle ☒ IN ☐ OUT

Date/Time	Action/Instruction (X) Estimate
	SLS1204 - X
	SKP 99869 - X
	Dismantle: 3/10/2019
	After repair: 17/10/2019

Tangkh

ALG

From: \_\_\_\_\_ Date: \_\_\_\_\_  
Estimated Cost: \_\_\_\_\_  
OD / TP / WS / TP RES / OD RES / EVA / INV / MV  
To: (Select Vehicle No)  
at Work Shop no:  
of:  
Insured:  
Policy No:  
Claims No:  
Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_  
(Client's Record)  
Make of Veh:  
  
(Policy Condition)  
Remark: The veh had commenced its repair at the time of inspection.  
  
Bal. or Market Value:  
IDAC Accident Report: \_\_\_\_\_ Consistent? : Yes or No  
GIA / PE Seen: \_\_\_\_\_ Consistent? : Yes or No  
Est. Repairs: \_\_\_\_\_ days Res: Yes or No  
Lump Sum: \_\_\_\_\_ % 3 Val: Yes or No  
CA / REV / REP. / 24 HRS. 'PRS'  
Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_  
Vehicle: IN / OUT

N/S	O/S

SL5/204 2017 Sep.  
Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /  
Truck / Trailer or  
Make: Honda Vezel Hybrid 1496  
Colour: Grey A/C Insured / Std / NI / NA  
Sp. Reading: 166079 T/Radio: Insured / Std / NI / NA  
Eng/No: R43128520  
C/No:  
Gen. Cond: Good / Fair / Poor / Burnt  
Steering: In order / Jammed / Leaked / Burnt or  
Brake: In order / Jammed / Leaked / Burnt or  
Mod: Nil / S/Rim / STD A/Rim or  
Tyre Size: F: 215/60R16  
R:  
BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
TOYO / YOKO or Westlake  
Front: \_\_\_\_\_ Rear: \_\_\_\_\_  
R/Bal. 6 mm R/Bal. 6 mm  
L/Bal. 6 mm L/Bal. 6 mm  
D.O.A. D.O.I 2/10/19 2345  
Survey held at MTM  
Des. of Damages: Frl / Rear / O/S / N/S / U/C / Rooftop or  
The U/C / Chassis frame / Body Structure affected due to collision

Date / Time Action / Instruction  
No GIA DAR- puts only.

RECEIVED 18 NOV 2019

Enter Time File Pass to? ☐ : Preli. Report  
n ☐ : Final Report  
Date/Time File Return to?  
Add Fee: ☐ Site Insp. (\$) ☐ Interview (\$) ☐ Photo (\$\$) ☐ Workshop (\$\$)  
Days Of Repair: 9  
Resurvey No. of Trip: 2  
Survey Fee: 180  
Transportation: 11  
Report Format: DAR  
Lump Sum / LB: 191

## ...CLAIM SUBFOLDER...(Pending for Survey Report)

### CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	01 Oct 2019 <a href="#">Edit Reg</a>		02 Oct 2019 00:00 <a href="#">Edit Adj Rpt</a>				<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	<a href="#">Show All</a>					
<b>CLAIM SUBFOLDER DETAILS</b> <span style="float: right;">[Created by adjuster]</span>									
Insured: <b>ALLSWELL LEASING &amp; LIMOUSINE PTE LTD,</b> Co. Reg. No.: 201432541Z									
Main Claimant: <b>VFM PTE. LTD.</b>									
Vehicle Reg. No.:	<b>SLS120U</b>	Date of Loss:	28/09/2019 00:00 - :59						
Claim Type:	<b>TP / 7622958690SG</b>	Policy/Cover Note No.:	(Comprehensive)						
Vehicle Reg. No. (Insured):	<b>SKP9986G</b>	Policy No. (Claimant):							
		Excess:							
Repairer: <b>Mtm Performance Auto Pte Ltd ( )</b> 48 TOH GUAN ROAD EAST #01-115 ENTERPRISE HUB, 608586 Jurong East - Tel:									
Handling Insurer: <b>AIG Asia Pacific Insurance Pte. Ltd. (Express)</b> - Tel: 65-6419-3000 ... [Handled by <b>Ler, Bernard-JQ</b> ] BernardJlQian.Ler@aig.com									
Adjuster: <b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>MOHD TAUFIKH BIN HAMID</b> ] ... <b>[Final Rpt due 11/10/2019]</b>									
<b>ASSOCIATED MAIL RECEIVED</b>				<a href="#">View All</a> <a href="#">Compose Case Mail</a>					
<ul style="list-style-type: none"> <li>AIG_SG (03/10/2019): <b>TP GIA report</b></li> </ul>									
<b>ALL ASSOCIATED TASKS</b> <span style="float: right;"> <a href="#">View All</a>   <a href="#">Search Tasks</a>   <a href="#">Create New Task</a>   <a href="#">Complete</a> </span>									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

**PRE-REPAIR INSPECTION REQUEST – SLS120U vs SKP9986G on 28/09/2019**

From: Parthiban, Theerthan  
To: assignments@lkkauto.com, Admin A  
Cc: Fong, Andy-SY, Chin, Lee-Ying, Abu Kassim, Noor Mariesa, Azlan, Syazairdina, Chan, Yoke Shi, Hor, Yinnul, Lim, Sheng Yang, Mithoosingh, Aashweenjeetkaur, Parthiban, Theerthan, Subram  
Sent: 10/2/2019 12:50:13 PM

Hi,

Please refer to the enclosed request from **MTM Performance Auto Pte Ltd**.

Claim no : 7622958690SG003  
Case Owner : BERNARD JI QIAN LER

If you have any queries/concerns, please let us know.  
*Kindly assist to assign **Mohamad Taufikh** as Single Joint Expert as requested.*

Thank you.

Regards,

Theerthan R Parthiban (Troy)  
AIG  
Senior Claims Examiner, Auto  
Singapore Claims Operations | AIG Shared Services

Tel: 8001206556 Ext: 1002217  
[Theerthan.Parthiban@aig.com](mailto:Theerthan.Parthiban@aig.com) | [www.aig.com.sg](http://www.aig.com.sg)

**IMPORTANT NOTICE:**

*The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by AIG for any loss or damage arising in any way from its use.*

---

**From:** [fujimotorsports@hotmail.com](mailto:fujimotorsports@hotmail.com)  
**Sent:** Wednesday, October 2, 2019 11:25:06 AM (UTC+08:00) Kuala Lumpur, Singapore  
**To:** Hor, Yinnul  
**Subject:** RE: PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SKP9986G AND SLS120U ON 28/09/2019

Hi

We would like Taufikh from LKK for this PRS.

Please contact the undersigned urgently as vehicle is already in our workshop

Thank you

Erwin Ho  
m. 92210404

MTM Performance Auto Pte Ltd  
42 Toh Guan Road East, #01-78 Enterprise Hub, Singapore 608583

---

**From:** Hor, Yinnul  
**Sent:** Tue, 1 Oct 2019 08:10:01 +0000  
**To:** [fujimotorsports@hotmail.com](mailto:fujimotorsports@hotmail.com)  
**Cc:** Fong, Andy-SY, Chin, Lee-Ying, Abu Kassim, Noor Mariesa, Azlan, Syazairdina, Chan, Yoke Shi, Lim, Sheng Yang, Mithoosingh, Aashweenjeetkaur, Parthiban, Theerthan, Subramaniam, Divyashni  
**Subject:** PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SKP9986G AND SLS120U ON 28/09/2019

Without Prejudice

Your Reference : SLS120U  
Our Reference : 7622958690SG003

Dear Sir/Madam,

We refer to your Notice of Accident of even date.

We intend to conduct a pre-repair survey of the damage to your client's/your customer's vehicle jointly with your client/your motor workshop. We propose to use one of the motor surveyors named in the attached list to conduct the joint pre-repair survey as a single joint expert:

Name of Surveyor	Company Name
AIG In House Surveyor	AIG Asia Pacific Insurance Pte Ltd
Lawrence Ng Chun Kee	Priority Services
Jeffrey Ong Leng Kiat	Priority Services

Jimmy' Lee	Priority Services
EC Looi	Automobile Inspection Services Pte Ltd
Pang Kiah Keen (Frankie)	Formteam Adjusters Pte Ltd
Ng Yoo Han	Formteam Adjusters Pte Ltd
Soon HanXin (Gary)	Formteam Adjusters Pte Ltd
Chow Bo Xiong	Formteam Adjusters Pte Ltd
Chua Soo Teck (Benjamin)	Formteam Adjusters Pte Ltd
Kalvin Ang	LKK Auto Consultants Pte Ltd
Xing Guo Qiang	LKK Auto Consultants Pte Ltd
Marcus Chua	LKK Auto Consultants Pte Ltd
Mohamad Taufikh	LKK Auto Consultants Pte Ltd
Adrian Ling	LKK Auto Consultants Pte Ltd
Mohammed Rasul	LKK Auto Consultants Pte Ltd
Kenneth Kong	LKK Auto Consultants Pte Ltd

Please let us know within two (2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert. You may select one or more of the listed motor surveyors. We will bear the cost of the pre-repair survey carried out by the single joint expert.

Thanks & Regards,

Hor Yin Rui (Viviane)  
AIG  
FNOL Adjuster I  
Singapore FNOL | Claims Operations – Auto

Tel: 8001206556 | Ext: 1002208  
[Yinnui.Hor@aig.com](mailto:Yinnui.Hor@aig.com) | [www.aig.sg](http://www.aig.sg)

---

**From:** Erwin Ho [<mailto:Fujimotorsports@hotmail.com>]  
**Sent:** Tuesday, October 01, 2019 3:49 PM  
**To:** ClaimsDocManagement  
**Subject:** [EXTERNAL] Request for Pre Repairs Survey

This message is from an external sender; be cautious with links and attachments.

Dear Motor Claims Department

We are requesting for a PRS to our client's vehicle SL5120U damaged by your Insured's SKP9986G on 28/9/2019 along Yio Chu Kang Road.

Please contact the undersigned for the surey.

Thank you  
Erwin Ho  
m.92210404  
MTM Performance Auto Pte Ltd

**IMPORTANT NOTICE:**

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

**IMPORTANT NOTICE:**

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

[> Back to OneMotoring](#)

## Enquire PARF/COE Rebate for Registered Vehicle

<b>Vehicle Owner Particulars</b>	
Owner ID Type:	Company
Owner ID:	773K
<b>Vehicle Details</b>	
Vehicle No.:	SLS120U
Vehicle to be Exported:	No
Intended Deregistration Date:	04 Oct 2019
Vehicle Make:	HONDA
Vehicle Model:	VEZEL HYBRID 1.5X AUTO
Primary Colour:	Black
Manufacturing Year:	2017
Engine No.:	LEB5951537
Chassis No.:	RU31251520
Maximum Power Output:	112.0 kW (150 bhp)
Open Market Value:	\$25,051.00
Original Registration Date:	04 Sep 2017
First Registration Date:	04 Sep 2017
Transfer Count:	0
Actual ARF Paid:	\$5,000.00
<b>Intended PARF Rebate Details</b>	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	03 Sep 2027
PARF Rebate Amount:	\$3,750.00
<b>Intended COE Rebate Details</b>	
COE Expiry Date:	03 Sep 2027
COE Category:	E - Open - all except motorcycle
COE Period(Years):	10
QP Paid:	\$50,101.00
COE Rebate Amount:	\$39,572.00
<b>Total Rebate Amount:</b>	<b>\$43,322.00</b>

The information contained herein is correct as at 04 Oct 2019

OK

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	28/09/2019 13:06
Date Of Accident	28/09/2019 01:15
Exact Location Of Accident	YIO CHU KANG ROAD
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLS120U
<b>Insured/Policyholder</b>	
Name Of Registered Owner	VFM PTE. LTD.
Co Reg No	201523773K
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-98508991
Alternative Phone No	OFFICE-98508991

### Vehicle Particulars

Manufacturer	HONDA
Model	VEZEL-1.5 S (A)
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE HIRE

### Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5076629069-03 (CLASSIC)
Cover Note Number	

### Driver

Name of Driver	TAN YU CHAI
NRIC No	S7181380J
Date Of Birth	06/11/1971
Occupation	OUTDOOR
Date Of Driving Pass	03/10/1995
Driving Experience	23 YEARS AND 11 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-98508991
Fax Number	
Contact Number	OFFICE-98508991
EEmail Address	NOEMAIL

Address 137 LORONG AH SOO  
#01-528  
Postcode S530137  
Was driver an employee of the Insured's Company NO  
If No, Relationship of the Driver with the Insured OTHER - RENTAL  
Vehicle Registration Number of Driver's Own Vehicle -  
-  
Insurance Company of Driver's Own Vehicle -  
-

#### General Information of the Accident

Type Of Accident SIDE SWIPE  
Weather Conditions CLEAR  
Road Surface DRY

#### Other Information

Was any foreign vehicle involved in this accident? NO  
Number of vehicles (including own vehicle) involved in the accident 2  
Was any body injured in the Accident? NO  
Was any injured conveyed to hospital by ambulance? NO  
Was any other material or property damaged? YES  
I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO  
Number of Passengers (Including Driver) 2  
Passenger 1  
NAME: : -  
GENDER: : MALE

#### Details of Police Action

Was the accident reported to the police? YES  
If Yes, Please state which Police Station  
Police Station Name HOUGANG NEIGHBOURHOOD POLICE POST  
Police Station Address ROAD: BLK 357 HOUGANG AVENUE 7 #01-805 , POSTCODE: 530357 , COUNTRY: SINGAPORE  
Police Station Contact TEL NO: 1800-2869999 - FAX NO: 63822066  
Was notice of intended Prosecution given? NO  
If Yes, against whom?

#### Circumstances of Accident

PLEASE SEE ATTACHED POLICE REPORT

#### Attachment(s)

Are accident photos available for attachment? YES  
Was there any video captured by Car Camera? YES  
Remarks/ Reasons: SENT TO INSURANCE  
Was there any audio recorded? NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SKP9986G  
Vehicle Make/Model/Colour SALOON  
Details Of Properties  
Vehicle Category PRIVATE CAR  
Name of Driver  
NRIC/Passport Number



Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

**SKETCH PLAN**

**IMPORTANT NOTICE**

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by Interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

**IDAC BUKIT BATOK (VAC)**  
511 Bukit Batok Street 23  
Singapore 659545  
Tel: 6560 3312 Fax: 6569 0722  
Email: vacbb@singnet.com.sg

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:



Condition (CON)

(01) Bent (2) Dented (3) Distorted (4) Cracked (5) Cut (6) Scratched  
(07) Deformed (08) Shifted (09) Buckled (10) Broken (11) Necessary (12) Missing  
(13) Torn (14) Unconfirmed (15) Not Working

MOTOR CAR (RH)

ACTION (AC)

(1) Replace (✓) (2) Repair (X) (3) Check (?)  
(4) Not Consistent (NC)

Aug 2005

Right Portion

Vehicle No:

SLS1204

NAC	INC	Item	CON	AC	Qty
1316	995327	Frt RH Door	bt	✓	
1317	991654	Frt RH Door Protector			
1318	991601	Frt RH Door Hinge			
1319	991685	Frt RH Door Wing Mirror	?		
1320	991583	Frt RH Door Garnish			
1321	991639	Frt RH Door Glass Outer Moulding			
1322	991588	Frt RH Door Glass Inner Moulding			
1323	991584	Frt RH Door Glass			
1324	991595	Frt RH Door Glass Regulator	bt	✓	
1325	991596	Frt RH Door Glass Regulator Motor	?		
1326	991662	Frt RH Door Rubber	tn	✓	
1327	991636	Frt RH Door Outer Handle			
1328	991607	Frt RH Door Inner Handle			
1329	991625	Frt RH Door Lock w/Key			
1330	991624	Frt RH Door Lock			
1331	991562	Frt RH Door Central Lock			
1332	991675	Frt RH Door Switch			
1333	991617	Frt RH Door Inner Trim Board	de	✓	
1334	991568	Frt RH Door Checker			
1335	991575	Frt RH Door Felt			
1336	991688	Frt RH Door Wire Harness			
1337	991683	Frt RH Door Window Glass Pillar			
1338	991640	Frt RH Door Outer Pillar			
1339	991613	Frt RH Door Inner Pillar			
1340	991646	Frt RH Door Pillar Inner Garnish			
1341	990554	Centre Pillar RH	bt	✓	
1342	990543	Centre Inner Pillar RH			
1343	990518	Centre Pillar Upper Garnish RH			
1344	990565	Centre Pillar Lower Garnish RH			
1345	991670	Frt RH Door Step Garnish			
1346	994058	Rocker Panel RH	bt	✓	
1347	994049	Rocker Panel Inner Panel RH			
1348	994047	Rocker Panel Garnish RH	mis	✓	
1349	994055	Rocker Panel Outer Side Skirt RH			
1401	991300	Frt Bumper			
1402	991325	Frt Bumper Bracket			
1403	991462	Frt Bumper Side Retainer			
1404	991433	Frt Bumper Reinforcement			
1405	991468	Frt Bumper Sponge			
1406	991427	Frt Bumper Protector			
1407	991301	Frt Bumper Moulding			
1408	991407	Frt Bumper Lower Spoiler			
1409	991821	Frt RH Headlamp Assy			
1410	995089	Frt RH Side Lamp			
1411	995071	Frt RH Fender	bt	✓	
1412	991744	Frt RH Fender Lamp emblem	nee	✓	
1413	991752	Frt RH Fender Protector inner shield	?		
		Frt RH fender wheel arch garnish	cut	✓	
		Frt RH Rim	cut	✓	
		Frt RH knuckle arm	?		
		Frt RH knuckle arm bearing	?		
		Frt Lower arm	?		

NAC	INC	Item	CON	AC	Qty
1350	993201	Rear RH Door	bt	✓	
1351	993284	Rear RH Door Protector			
1352	995307	Rear RH Door Hinge	bt	✓	
1353	993228	Rear RH Door Garnish			
1354	993278	Rear RH Door Glass Outer Moulding			
1355	993231	Rear RH Door Glass Inner Moulding			
1356	993229	Rear RH Door Glass			
1357	993289	Rear RH Door Glass Regulator	?		
1358	993240	Rear RH Door Glass Regulator Motor			
1359	993294	Rear RH Door Rubber	tn	✓	
1360	993276	Rear RH Door Outer Handle			
1361	993251	Rear RH Door Inner Handle			
1362	993261	Rear RH Door Lock			
1363	993256	Rear RH Door Inner Trim Board	?		
1364	993218	Rear RH Door Checker			
1365	993230	Rear RH Door Glass Channel			
1366	993242	Rear RH Door Glass Triangle Garnish			
1367	993285	Rear RH Door 1/4 Glass			
1368	993288	Rear RH Door 1/4 Glass Rubber			
1369	993287	Rear RH Door 1/4 Glass Pillar			
1370	993306	Rear RH Door Step Garnish			
1371	993309	Rear RH Door Switch			
1372	994070	Roof Top Panel			
1373	994098	Roof Top Moulding			
1374	994085	Roof Top Air-bag			
1375	994084	Roof Top Air-bag Sensor			
1376	994083	Roof Top Air-bag Control Unit			
1377	992958	Rear Bumper			
1378	992976	Rear Bumper Bracket			
1379	993068	Rear Bumper Side Retainer			
1380	993045	Rear Bumper Reinforcement			
1381	993077	Rear Bumper Sponge			
1382	993040	Rear Bumper Protector			
1383	993026	Rear Bumper Moulding			
1384	993023	Rear Bumper Lower Spoiler			
1385	995116	Rear RH Taillamp			
1386	993456	Rear RH Fender			
1387	993450	Rear RH Fender Protector			
1388	990247	Sticker			
		Rear RH fender wheel arch garnish cut		✓	
		9 days			

No of Items:

Assessor:

### ...CLAIM SUBFOLDER...(Pending for Survey Report)




















CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	01 Oct 2019 <a href="#">Edit Reg</a>		02 Oct 2019 00:00 <a href="#">Edit Adj Rpt</a>	<b>\$0.00</b> <a href="#">Edit Estimates</a>	<b>\$0.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b> <span style="float: right;">[Created by adjuster]</span>									
Insured: <b>ALLSWELL LEASING &amp; LIMOUSINE PTE LTD</b> , Co. Reg. No.: 201432541Z									
Main Claimant: <b>VFM PTE. LTD.</b>									
Vehicle Reg. No.: <b>SLS120U</b>		Date of Loss: 28/09/2019 00:00 - :59 [24 Months and 24 Days From LTA Reg Date (Man Yr)]							
Claim Type: <b>TP / 7622958690SG</b>		Policy/Cover Note No.: (Comprehensive)							
Vehicle Reg. No. (Insured): <b>SKP9986G</b>		Policy No. (Claimant):							
		Excess:							
Repairer: <b>Mtm Performance Auto Pte Ltd ( )</b> 48 TOH GUAN ROAD EAST #01-115 ENTERPRISE HUB, 608586 Jurong East - Tel:									
Handling Insurer: <b>AIG Asia Pacific Insurance Pte. Ltd. (Express)</b> - Tel: 65-6419-3000 ... [Handled by <b>Ler, Bernard-JQ</b> ]									
Adjuster: <b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>MOHD TAUFIKH BIN HAMID</b> ] ... [Final Rpt due 11/10/2019]									
<b>ASSOCIATED MAIL RECEIVED</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Compose Case Mail</a></span>									
<ul style="list-style-type: none"> <li>AIG_SG (03/10/2019): <b>TP GIA report</b></li> </ul>									
<b>ALL ASSOCIATED TASKS</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a></span>									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Claim Documents

\*SLS120U (7622958690SG)  
 [SKP9986G]  
 TP  
 VFM PTE. LTD.  
 Sep 28 2019 12:00AM  
 [ALLSWELL LEASING & LIMOUSINE PTE LTD]  
 Mtm Performance Auto Pte Ltd

Upload Documents			Upload Photos			Compose New Letter			Upload Video			Upload Audio			View		View in Browser	
Photos/Images															3 per page		<input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)														Thumbnail	Print	
1	07/10/19 09:42	General View														Load JPG	<input checked="" type="checkbox"/>	
2	07/10/19 09:42	General View														Load JPG	<input checked="" type="checkbox"/>	
3	07/10/19 09:42	General View														Load JPG	<input checked="" type="checkbox"/>	
4	07/10/19 09:42	General View														Load JPG	<input checked="" type="checkbox"/>	
5	07/10/19 09:42	General View														Load JPG	<input checked="" type="checkbox"/>	
6	07/10/19 09:42	General View														Load JPG	<input checked="" type="checkbox"/>	
7	07/10/19 09:42	General View														Load JPG	<input checked="" type="checkbox"/>	
8	07/10/19 09:42	General View														Load JPG	<input checked="" type="checkbox"/>	
9	07/10/19 09:42	General View														Load JPG	<input checked="" type="checkbox"/>	
10	07/10/19 09:42	General View														Load JPG	<input checked="" type="checkbox"/>	
11	07/10/19 09:42	General View														Load JPG	<input checked="" type="checkbox"/>	
12	07/10/19 09:42	General View														Load JPG	<input checked="" type="checkbox"/>	
13	07/10/19 09:42	General View														Load JPG	<input checked="" type="checkbox"/>	
14	07/10/19 09:42	General View														Load JPG	<input checked="" type="checkbox"/>	
15	07/10/19 09:42	General View														Load JPG	<input checked="" type="checkbox"/>	
16	07/10/19 09:42	General View														Load JPG	<input checked="" type="checkbox"/>	
17	07/10/19 09:42	General View														Load JPG	<input checked="" type="checkbox"/>	
18	07/10/19 09:42	General View														Load JPG	<input checked="" type="checkbox"/>	
19	07/10/19 09:42	General View														Load JPG	<input checked="" type="checkbox"/>	
20	07/10/19 09:42	General View														Load JPG	<input checked="" type="checkbox"/>	
21	07/10/19 09:42	General View														Load JPG	<input checked="" type="checkbox"/>	
22	07/10/19 09:42	General View														Load JPG	<input checked="" type="checkbox"/>	
23	07/10/19 09:42	General View														Load JPG	<input checked="" type="checkbox"/>	
24	07/10/19 09:42	General View														Load JPG	<input checked="" type="checkbox"/>	
25	07/10/19 09:42	General View														Load JPG	<input checked="" type="checkbox"/>	
26	07/10/19 09:42	General View														Load JPG	<input checked="" type="checkbox"/>	
27	07/10/19 09:42	General View														Load JPG	<input checked="" type="checkbox"/>	
28	07/10/19 09:42	General View														Load JPG	<input checked="" type="checkbox"/>	
29	07/10/19 09:42	General View														Load JPG	<input checked="" type="checkbox"/>	
30	07/10/19 09:42	General View														Load JPG	<input checked="" type="checkbox"/>	
31	07/10/19 09:42	General View														Load JPG	<input checked="" type="checkbox"/>	
32	15/11/19 18:19	Photographs of Damaged Parts														Load JPG	<input checked="" type="checkbox"/>	
33	15/11/19 18:19	Photographs of Damaged Parts														Load JPG	<input checked="" type="checkbox"/>	
34	15/11/19 18:19	Photographs of Damaged Parts														Load JPG	<input checked="" type="checkbox"/>	
35	15/11/19 18:19	Photographs of Damaged Parts														Load JPG	<input checked="" type="checkbox"/>	
36	15/11/19 18:19	Photographs of Damaged Parts														Load JPG	<input checked="" type="checkbox"/>	
37	15/11/19 18:19	Photographs of Damaged Parts														Load JPG	<input checked="" type="checkbox"/>	
38	15/11/19 18:19	Photographs of Damaged Parts														Load JPG	<input checked="" type="checkbox"/>	
39	15/11/19 18:19	Photographs of Damaged Parts														Load JPG	<input checked="" type="checkbox"/>	
40	15/11/19 18:19	Photographs of Damaged Parts														Load JPG	<input checked="" type="checkbox"/>	
41	15/11/19 18:19	Photographs of Damaged Parts														Load JPG	<input checked="" type="checkbox"/>	
42	15/11/19 18:19	Photographs of Damaged Parts														Load JPG	<input checked="" type="checkbox"/>	
43	15/11/19 18:19	Photographs of Damaged Parts														Load JPG	<input checked="" type="checkbox"/>	

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
44	15/11/19 18:19	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
45	15/11/19 18:19	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
46	15/11/19 18:19	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
47	15/11/19 18:19	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
48	15/11/19 18:19	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
49	15/11/19 18:19	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
50	15/11/19 18:19	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
51	15/11/19 18:19	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
52	15/11/19 18:19	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
53	15/11/19 18:19	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
54	15/11/19 18:19	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
55	15/11/19 18:19	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
56	15/11/19 18:19	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
57	15/11/19 18:19	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
58	15/11/19 18:19	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
59	15/11/19 18:19	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
60	15/11/19 18:19	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
61	15/11/19 18:19	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	03/10/19 10:35	OI GIA REPORT	 Load PDF	

## Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
<b>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</b> <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			
<b>Show Remarks To:</b> <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			



# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG19017343/T1CD3E2

Date: 19/11/2019

### REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No:

#### Claimant

Vehicle No : SLS120U

Insured Vehicle No : SKP9986G

Date of Loss: 28/09/2019

Nature of Claim: TP

Claim No: 7622958690SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLS120U

Make &amp; Model: HONDA VEZEL, 1.5 HYBRID X (A)

Engine No: LEB5951537

Reg. Date: 04/09/2017 (Man. Year: 2017)

Chassis No: RU31251520

Colour: Grey

Odometer: 166079 km

Engine Capacity: 1496 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes

Engine Modification:

No

Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size: 215/60 R16

Rear Tyre Size:

215/60 R16

Front Left Side: West Lake 6 mm

Rear Left Side:

West Lake 6 mm

Front Right Side: West Lake 6 mm

Rear Right Side:

West Lake 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Nett Amount (S\$)</b>	<b>0.00</b>	<b>0.00</b>	<b>0.00</b>	

### INSPECTION

Date of Assignment: 02/10/2019

Date Inspected: 02/10/2019 Inspected At:

42 TOH GUAN ROAD EAST #01-78

Repairer : Mtm Performance Auto Pte Ltd

Estimated Period of Repair: 9.0 days

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.



## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT RH DOOR	Bent	0.00 F	*- F
2	1		*FRT RH DOOR WING MIRROR	* Check	0.00 F	*- F
3	1		*FRT RH DOOR GLASS REGULATOR	Bent	0.00 F	*- F
4	1		*FRT RH DOOR GLASS REGULATOR MOTOR	* Check	0.00 F	*- F
5	1		*FRT RH DOOR RUBBER	Torn	0.00 F	*- F
6	1		*FRT RH DOOR INNER TRIM BOARD	Deformed	0.00 F	*- F
7	1		*CENTRE PILLAR RH	Bent	0.00 F	*- F
8	1		*ROCKER PANEL RH	Bent	0.00 F	*- F
9	1		*ROCKER PANEL GARNISH RH	Missing	0.00 F	*- F
10	1		*FRT RH FENDER	Bent	0.00 F	*- F
11	1		*FRT RH FENDER EMBLEM	Necessary	0.00 F	*- F
12	1		*FRT RH FENDER INNER SHIELD	* Check	0.00 F	*- F
13	1		*FRT RH FENDER WHEEL ARCH GARNISH	Cut	0.00 F	*- F
14	1		*FRT RH RIM	Cut	0.00 F	*- F
15	1		*FRT RH KNUCKLE ARM	* Check	0.00 F	*- F
16	1		*FRT RH KNUCKLE ARM BEARING	* Check	0.00 F	*- F
17	1		*FRT LOWER ARM	* Check	0.00 F	*- F
18	1		*REAR RH DOOR	Bent	0.00 F	*- F
19	1		*REAR RH DOOR HINGE	Bent	0.00 F	*- F
20	1		*REAR RH DOOR GLASS REGULATOR	* Check	0.00 F	*- F
21	1		*REAR RH DOOR RUBBER	Torn	0.00 F	*- F
22	1		*REAR RH DOOR INNER TRIM BOARD	* Check	0.00 F	*- F
23	1		*REAR RH FENDER WHEEL ARCH GARNISH	Cut	0.00 F	*- F
Total Parts (\$\$)					0.00	0.00

F=Franchise part.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.
---

< END OF ESTIMATES >