

Surveyor

REF: CSI/SPF 19017357/ T19d3⁵²

Special Instruction:

ASSIGNMENT (Office)

From (Person): Hafizul Fahren of SPF Date/Time: 2/10/2019

\$ 9612.60

Estimated Cost: Bill to:

Third Parties:

Claimant:

Surveyor:

Workshop: Cycle & Carriage Industries

OD/TP Re-inspection Evaluation

To Inspect Vehicle No: SLA 5152P Insured: QX 790A

at Workshop m/s Cycle & Carriage Ind. Tel: 91217717

of 188 Pender Road

Policy No: Claim No: AEMD/105/009/2019/080

Sum Insured: Excess:

Make of Veh: D.O.A. 01/07/2019

(Client's Record)

H.O.D. Endorsement/Date:

Date/Time: Person Contacted: Vehicle IN / OUT

Date/Time: Confirmed with Final Fig days (Red \$ / %; Original days)

Date/Time: 07/10/19 Submit Final Fig 9612.60, 5 days (Red \$ 0/10 %; Original days)

Date/Time	Action/Instruction
	SLA 5152P-X QX 790A - CSI/SPF 17007927/Sph 3f2 DOA: 13/1/2017
2/10/19	Requested for survey report and both parties GJA Report. But SPF said they only have TP GJA.
	Repair cost fair and reasonable. \$8812.60, 5 days
	* type report first as need awaiting Mr Lau to counter sign on fair & reasonable.

Do Not Finalise

Para(1) : Parts found not replaced (To highlight R or UB, LR, Etc)

Para(2) : Comments on consistency of damages (Parts Not Consistent : NC)

RECEIVED 08 OCT 2019

Para(3) : Nett Value

Market Value :
Salvage Value :
Nett Value :

Inspected/
Evaluated by:

Fee Charged:
Basic & Add
Transport
Photos
Others
Total

Date:

- 1) Date/Time File Pass to
- 2) Date/Time File Return to
- 3) Date/Time File Pass to
- 4) Date/Time File Return to
- 5) Date/Time File Pass to
- 6) Date/Time File Return to