

[illegible]

ASS. REC. BY: Adrian.

REF:

FWD

ASSIGNMENT

From:

Date:

2/10/2019

Estimated Cost:

OD ☒ TP ☒ WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

SJZ 4047J

at Workshop m/s

Advance Auto

of

23 Kaki Bukit Ave 4 #04-01

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rpt:

Consistent?: Yes or No

GIA / PR Seen:

Consistent?: Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SJZ4047J.

Yr Regn:

2010 / NovType: ☒ M. Car / ☒ M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Volkswagen Scirocco. c.c 1390

Colour

White.A/C: Insured / Std / NI / NA

Sp. Reading

184358T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

WVW ZZZ132BV 015214Gen. Cond: ☒ Good / Fair / Poor / BurntSteering: ☒ In order / Jammed / Leaked / Burnt orBrake: ☒ In order / Jammed / Leaked / Burnt orModi: Nil / S/Km / STD A/Rim or

Tyre Size:

F:

225/40R18

R:

225/40R18.

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Newton.

Front

Rear

R/Bal.

06

mm

R/Bal.

06

mm

L/Bal.

06

mm

L/Bal.

06

mm

D.O.A.

D.O.I.

02/10/19.

Survey held at

Advance.Des. of Damages: Frt ☒ Rear ☒ O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

TP FWD.MV: 23KPV: 17.2KNett: 5.8K

Date/Time, File Pass to?



Preli. Report

1)



Final Report

Date/Time, File Return to?

2)

Report Format:

Lump Sum / LBJ: (\$

Days Of Repair:

Resurvey No. of Trip:

Add Fee:



Site Insp

(\$



Interview

(\$



Tech. Invs

(\$



Weekend

(\$

Survey Fee:

Transportation:

S + RS. SI

Photos

Others

TOTAL