

ASS. REC. BY:

REF: es/CTI/19017372 / Bsd306 Special Instruction:Surveyor: Mr KimASSIGNMENT (Office)From (Person): Tan Kah Kong of CTI Date/Time: 2/10/19 @ 3:36pm

Estimated Cost: _____ Bill to: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CSTo Inspect Vehicle No: GBB 5113R Insured: GBG 9066Rat Workshop m/s Team Autopro Tel: 6258 1955of 160 Sin Ming Drive #01-14Policy No: _____ Claim No: SNM19D204611

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. 01/10/2019
(Client's Record)

CA / REV / REP. / REV 24 HRS

3/10/19
H.O.D. Endorsement: _____Date/Time: 4:33pm @ 2/10/19 Person Contacted: Peach Vehicle IN OUT

Date/Time	Action/Instruction (✓) Estimate	
	<u>GBB 5113R - NBA / LPC / 19017367 / y</u>	<u>Est. 1/10/2019</u>
	<u>GBG 9066R - NBA / LPC / 19017367 / y</u>	<u>Est. 1/10/2019</u>

ASSIGNMENT

From:

Date:

31/10/2019

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

GBB 5113R

at Workshop m/s

Team Autopro

of

160 Sin Ming Drive # 01-14

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:


(Client's Record)

Make of Veh:

Vehicle In

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

7

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS up

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

GBB 5133R

Yr Regn: 13/5/2009

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toyota Dyna 150

C.C. 2982

Colour:

Silver

A/C: Insured / Std / NI / NA

Sp. Reading

170149

T/Radio: Insured / Std / NI / NA

Eng/No:

1KD1924892

C/No:

JTFAT35Y70K200560

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F: 195R/15

R: 195R/15

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

AUSTONE

Front

Rear

R/Bal.

5

mm

R/Bal.

5

mm

L/Bal.

5

mm

L/Bal.

5

mm

D.O.A.

2/10/2019

D.O.I.

3/10/19

Survey held at

Team Autopro

Des. of Damages: Frt / Rear / O/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	Range 6,000/- - 7,000/- Lim
	Finalized with w/s on Wed, 8:39 pm
	Pls see my remarks.
	@ L/S 3058/- with 7 days repair days Team
	L/S 3050/- Team Autopro 7/10/19
	Cd 18,977.16 Red - 86 %
	MV 22,000/-
	PV 12,818/-
	NV 16,182/-
	9/10/2019
	7/10
	Team Autopro
	3/10/19

RECEIVED 24 OCT 2019

Date/Time, File Pass to?

24/10/19



Preli. Report

1)

Typist



Final Report

Date/Time, File Return to?

2)

Days Of Repair:

67 hrs

Resurvey No. of Trip:

1

Survey Fee:

220

Transportation:

3 x RS. \$1

Photos

Others

TOTAL

220

Add Fee:



Site Insp (\$)



Interview (\$)



Tech. Invs (\$)



Weekend (\$)

Report Format:

Lump Sum / L.E. / 3.050/- 45

Nivitha (LKK Auto)

From: Tan Kah Leong <KahLeong.Tan@sg.cntaiping.com>
Sent: Wednesday, 2 October 2019 3:36 PM
To: TeamAutoPro North; assignments
Subject: RE: OUR REF: SNM19D204611-GBG9066R-TKL - 2 Days Notice: GBB 5113 R (Our Ref) and GBG 9066 R (Your Ref) Dated 01st October 2019
Attachments: PRS.pdf

WITHOUT PREJUDICE

Dear Sirs,

We refer to your email dated 01.10.2019.

We will be assigning M/s LKK Auto Consultants to survey your client's vehicle on a without prejudice basis.

Aside to LKK,

Please refer to the email below & proceed to survey the third party vehicle.

Thank you.

Regards

Tan Kah Leong
Assistant Executive
Claims Department

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road #15-00 Springleaf Tower Singapore 079909
DID: (65) 6389 6193 | F: (65) 6222 1033

W: www.sg.cntaiping.com | **FB:** www.facebook.com/chinataipingsg/

Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.

From: Claims Dept of CTI
Sent: Wednesday, October 2, 2019 9:05 AM
To: Tan Kah Leong <KahLeong.Tan@sg.cntaiping.com>; Alfred Toh <alfred.toh@sg.cntaiping.com>; Chee So Chow <sochow.chee@sg.cntaiping.com>; TeamAutoPro North <teamautopl@gmail.com>
Subject: OUR REF: SNM19D204611-GBG9066R-TKL - 2 Days Notice: GBB 5113 R (Our Ref) and GBG 9066 R (Your Ref) Dated 01st October 2019

Dear Kah Leong,

Please conduct PRS for GBB5113R.

Note : officer in charge – Kah Leong 63896193.

Regards,

Claims Department

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #15-00 Springleaf Tower Singapore 079909

T: (65) 63896116 | F: (65) 62247175

W: www.sg.cntaiping.com | FB: www.facebook.com/chinataipingsg/ | WeChat: 太平獅城 Taiping SG

Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.

From: TeamAutoPro North [<mailto:teamautopl@gmail.com>]

Sent: Tuesday, October 01, 2019 10:54 AM

To: Claims Dept of CTI

Subject: 2 Days Notice: GBB 5113 R (Our Ref) and GBG 9066 R (Your Ref) Dated 01st October 2019

Dear Sir/Madam,

Road Traffic Accident Involving GBB 5113 R (Our Ref) and GBG 9066 R (Your Ref)

Dated 01st October 2019, Time around 0850hrs

@ Marymount Road

We represent our client; BUDGET AIRCONDITIONING PTE LTD, to notify you of the aforesaid road traffic accident involving our client's vehicle registration number: GBB 5113 R and your insured's vehicle registration number: GBG 9066 R

For efficiency purpose, we are agreeable with the appointment of **Mr Lim - LKK** as the SJE for subject claim. Please let us know within **2 working days** from today your agreeing to the above otherwise kindly send us your list of at least **ten (10) motor surveyors, via email to the following personnel:-**

Contact Person	Eric Lee	8269 9999
Email Address	teamautopl@gmail.com	
Survey Address	160 Sin Ming Dr, #01-14 Singapore 575722	

Thank you for your attention to this email and we look forward to your earliest reply.

--

The above settlement is in respect of our client for damage pertaining to his motor vehicle and shall not prejudice our client's claim in respect of damages and consequential loss in relation to his personal injuries.

Cheers,

Peach

Team AutoPro Pte Ltd

Tel: 6258 1955

Fax: 6258 1956

(Newly Shifted) Main Office: 160 Sin Ming Dr, #02-12 Sin Ming AutoCity Singapore 575722

Workshop/Survey Venue: 160 Sin Ming Dr, #01-14 Sin Ming AutoCity Singapore 575722

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	123Z
Vehicle Details	
Vehicle No.:	GBB5113R
Vehicle to be Exported:	No
Intended Deregistration Date:	03 Oct 2019
Vehicle Make:	TOYOTA
Vehicle Model:	DYNA 150 MANUAL 3SEATER
Primary Colour:	Silver
Manufacturing Year:	2009
Engine No.:	1KD1924892
Chassis No.:	JTFAT35Y70K200560
Maximum Power Output:	-
Open Market Value:	\$24,970.00
Original Registration Date:	13 May 2009
First Registration Date:	13 May 2009
Transfer Count:	3
Actual ARF Paid:	\$1,249.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	12 May 2024
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	5
PQP Paid:	\$13,910.00
COE Rebate Amount:	\$12,818.00
Total Rebate Amount:	\$12,818.00
Message	
Please note that all future COE renewals for this vehicle can only be for a 5-year period, subject to the statutory lifespan (if applicable) of the vehicle.	

The information contained herein is correct as at 03 Oct 2019

OK

Dep 6,330/41

MV 29,000/2

PV 12,818/2

NV 16182/2

TG Lim
3/10/19



PUT YOUR PRICE ON LUXURY

THE VOLVO RANGE FROM \$115,000 (EXCLUDES COE).
Name your COE price, or top up \$30,000 for guaranteed COE.



Post an Advertisement

Sell it yourself! Advertise it at just
\$58 until it's SOLD!

[Post an Ad](#)
[Advertiser Login](#)
[Ways of Selling](#)

New 5 Years Renewal Coe Toyota Vios 1.5A



2.88% P.A \$0 Down, \$0 Admin,
Monthly Frm \$438, Sta "B" 2 Yrs
Warranty Engine
StarAd

**VALUE FOR MONEY
VALUE FOR TIME
A PEACE OF MIND**

HOTLINE: 6741 9997 [view our cars](#)

Browse by Category ▼

« Back (1 2 3 4 5) Next »

Sort by Reg. Date ▼

20 results/page ▼

92 vehicles

Toyota Dyna

Advanced Search:

	Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
Search Selection	Toyota Dyna		Any	Any	2009	Any	Any	Any	All
	Toyota Dyna	150 3.0M (COE till 05/2029)	\$47,800	\$4,950 /yr	01-Jun-2009	2,982 cc	-	Truck	Available
Fuel Type: Diesel Well Kept By One Careful Owner. Loan/Trade In Available. Call Now. Don't Miss. Posted: 26-Aug-2019 Tags: 2009 Toyota Dyna, 2009 toyota dyna, Toyota Dyna, toyota dyna, Toyota, Dyna, dyna, Used Toyota									
	Toyota Dyna	150 3.0M (COE till 04/2024)	\$24,800	\$5,420 /yr	01-Jun-2009	2,982 cc	-	Truck	Available
Fuel Type: Diesel ABWIN (1994) Pte Ltd Posted: 24-Aug-2019 Tags: 2009 Toyota Dyna, 2009 toyota dyna, Toyota Dyna, toyota dyna, Toyota, Dyna, dyna, Used Toyota									
	Toyota Dyna	150 3.0M (COE till 05/2024)	-	N.A	28-May-2009	2,982 cc	-	Truck	SOLD
Fuel Type: Diesel 1 Owner Only! New Paint! 6.5 Feet Box With 2 Sliding And 2 Swing Doors! Well Maintained By Previous Owner! Reliable Workhorse Ideal For Carrying Light To Heavy Goods! Fuel Efficient And Low Maintenance! Insurance And Loan Available For Your One Stop Convenience!... Net Link Partners Pte Ltd Posted: 21-Aug-2019 Tags: 2009 Toyota Dyna, 2009 toyota dyna, Toyota Dyna, toyota dyna, Toyota, Dyna, dyna, Used Toyota									
	Toyota Dyna	150 3.0M (COE till 05/2024)	\$25,800	\$5,550 /yr	27-May-2009	2,982 cc	-	Truck	Available
Fuel Type: Diesel 100% Loan! 1 Owner! 3 Days Hand Over! Best Selling Lorry With Box! New Paintwork And Servicing Done! Ready For Immediate Delivery! High Loan! High Trade In! Call Now! Door Viewing Are Possible! Net Link Partners Pte Ltd Posted: 30-Sep-2019 Tags: 2009 Toyota Dyna, 2009 toyota dyna, Toyota Dyna, toyota dyna, Toyota, Dyna, dyna, Used Toyota									
	Toyota Dyna	150 3.0M (COE till 05/2024)	\$29,588	\$6,390 /yr	20-May-2009	2,982 cc	-	Truck	Available
Fuel Type: Diesel Posted: 05-Sep-2019 Tags: 2009 Toyota Dyna, 2009 toyota dyna, Toyota Dyna, toyota dyna, Toyota, Dyna, dyna, Used Toyota									
	Toyota Dyna	150 3.0M (COE till 05/2024)	-	N.A	20-May-2009	2,982 cc	-	Truck	SOLD
Fuel Type: Diesel 3 Months Warranty! Come With LTA Approved Canopy And Can Carry Up To 13 Person Workers! Free 6 Months Road Tax! Fast And Easy Approval For You, 100% In House Loan At Low Interest Available! Call For Viewing And Test Drive Now For Believe! Call Now For Appoi... KSL Automotive Pte Ltd Posted: 07-Aug-2019 Tags: 2009 Toyota Dyna, 2009 toyota dyna, Toyota Dyna, toyota dyna, Toyota, Dyna, dyna, Used Toyota									

[Compare](#)

Email: sm@idac.com.sg

Tel no: 6555 6888 Fax no: 6454 3279

Personal Particulars of Owner & Driver (Vehicle A)

Date of Accident: 01/10/2019 (dd/mm/yy) Time of Accident: 08 : 50 (24-HR-FORMAT)
Vehicle No. : GBB 5113 R Vehicle Make & Model: TOYOTA DYNA 150 MANUAL 3SEATER
Exact location of Accident: MARYMOUNT ROAD
Policyholder's Name / IC No. : BUDGET AIRCONDITIONING PTE LTD 201624123Z
Driver's Name / IC No. : MURUGESAN MUTHARASAN G2183952W (As Above) ☐
Driver's Contact No. : 8459 9631 Company Contact No: 9323 2444
Driver's Address: 18 Roberts lane, #03-01 Singapore
Insurance Company: NTUC Email address (if any): _____

Relationship between Owner & Driver: EMPLOYEE

or Others specify: _____

What do you wish to claim? (Please TICK one only)

☐ Own Insurance / ☒ Other Vehicle (The one you want to claim against) / ☐ Reporting (For Record Purpose)

**Exact purpose for which the vehicle
Was being used at time of accident?**

☐ Private use / ☒ Work purpose

Occupation (nature of job) ☐ Indoor/ ☒ Outdoor

No. of Passengers (Including Driver): 01

Passenger Name : _____
Passenger Name : _____

Gender : _____
Gender : _____

Weather condition & Road conditions? (On the day of accident)

☒ Clear & Dry / ☐ Raining & Wet / ☐ After-Rain & Wet / ☐ Drizzling & Wet / Others: _____

Was there any video captured by your Car Camera? ☐ Yes / ☒ No

Any Injuries: ☐ Yes / ☒ No (If YES) Injured Person's Name: _____

Injuries Sustain: _____ Injured Person in Which Vehicle: _____

Police Report filed: ☐ Yes / ☒ No (If YES) Which Police Station: _____

The Other Party(s) Details:

1. Driver's Name / IC No: _____ Vehicle No: GBG 9066 R

Driver's Contact No: _____ Insurance Company (If any): _____

2. Driver's Name / IC No: _____ Vehicle No: _____


Driver's Contact No: _____ Insurance Company (If any): _____

*Independent Witness (If Any): _____ Contact No: _____

Preferred Workshop Name: _____ Contact No: _____

*If no proper documents are produced, IDAC should not file the report. Information will be discarded after one week.

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On the stated date and time, I vehicle 'A' GBB5113R was travelling on the stated venue. I was travelling straight in my lane, suddenly vehicle 'B' from the right cut into my lane had collided against my entire vehicle right portion. Later we went to the side of the road and vehicle 'B' explained that he was avoiding a car in front of him, hence he swerve towards my lane. Later I noticed my vehicle entire right portion was damaged due to this accident.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

M. Mytharasan

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	02/10/2019 15:00
Date Of Accident	01/10/2019 08:50
Exact Location Of Accident	ALONG MARYMOUNT ROAD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	GBB5113R
Insured/Policyholder	
Name Of Registered Owner	BUDGET AIRCONDITIONING PTE LTD
Co Reg No	201624123Z
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-93232444
Alternative Phone No	OFFICE-84599631

Vehicle Particulars

Manufacturer	TOYOTA
Model	DYNA 150 MANUAL 3SEATER-3.0 D (M)
Exact Purpose for which vehicle was being used at time of accident	WORKING PURPOSES
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	COMMERCIAL VEHICLE

Insurance Company

Name of Insurance Company	LONPAC INSURANCE BHD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	NO
Policy Number	Z19VC05003528
Cover Note Number	

Driver

Name of Driver	MURUGESAN MUTHARASAN
NRIC No	G2183952W
Date Of Birth	07/05/1993
Occupation	OUTDOOR
Date Of Driving Pass	10/09/2019
Driving Experience	0 YEAR AND 0 MONTH
Gender	MALE
Mobile Number	(LOCAL) +65-93232444
Fax Number	
Contact Number	OTHERS-84599631
Email Address	NOEMAIL

Address	18 ROBERT LANE #03-01
Postcode	218297
Was driver an employee of the Insured's Company	YES
If No, Relationship of the Driver with the Insured	
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	SIDE SWIPE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

PLEASE REFER TO SKETCH PLAN

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GBG9066R
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes, and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:




Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Sketch Plan #2

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On the stated date and time, I vehicle 'A' GBB5113R was travelling on the stated venue. I was travelling straight in my lane, suddenly vehicle 'B' from the right cut into my lane had collided against my entire vehicle right portion. Later we went to the side of the road and vehicle 'B' explained that he was avoiding a car in front of him, hence he swerve towards my lane. Later I noticed my vehicle entire right portion was damaged due to this accident.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:



Driver's Signature
(If driver is not the policyholder)
Date & Time:

M. Mytharasan

Reporting Centre Person's Signature
Name:
NRIC/FIN No.:

08/04/2018
Kishor Kumar

Accident Photo



Team AutoPro Pte Ltd 160 Sin Ming Dr, #02-12 Sin Ming AutoCity Singapore 575722

Tel: 8269-9999 Email: estimate.tap@gmail.com / teamautopl@gmail.com

SJE : _____ Mr T G LIM _____
 Date of Survey : _____
 Date of ReSurvey: _____ After-Paint: _____
 Contacts : _____

Vehicle Nos : **GBB 5113 R**
 Made : Toyota
 Model : Dyna
 Chassis No : _____

*** AGREED Cost Of Repair and Repair Day/s with SJE ***

Amount: _____

Working Day: _____

Nos.	PARTS	Qty	Unit S\$	TOTAL S\$
1	Front door rh	1	\$ 1,208.10	\$ 1,208.10
2	Front door hinge rh	2	\$ 74.00	\$ 148.00
3	Front door check pin rh	1	\$ 184.50	\$ 184.50
4	Front door weatherstrip rh	1	\$ 325.00	\$ 325.00
5	Front door outer moulding rh	1	\$ 168.00	\$ 168.00
6	Front door regulator motor rh	1	\$ 157.00	\$ 157.00
7	Front door regulator gear rh	1	\$ 89.00	\$ 89.00
8	Front door channel rh	1	\$ 106.00	\$ 106.00
9	Front door inner lock rh	1	\$ 236.80	\$ 236.80
10	Front door inner lock motor rh	1	\$ 189.00	\$ 189.00
11	Front door outer handle rh	1	\$ 89.00	\$ 89.00
12	Front floor panel	1	\$ 480.10	\$ 480.10
13	Front door glass rh	1	\$ 254.00	\$ 254.00
14	Front door glass run rubber rh	1	\$ 165.00	\$ 165.00
15	Front door pillar rh	1	\$ 435.10	\$ 435.10
16	Front wheel arch garnish rh	1	\$ 95.00	\$ 95.00
17	Front cabin coloumn	1	\$ 1,021.00	\$ 1,021.00
18	Front cabin coloumn bush	1	\$ 328.10	\$ 328.10
19	Front cabin mounting	2	\$ 109.10	\$ 218.20
20	Front cabin pillar	1	\$ 678.00	\$ 678.00
21	Front cabin lock	1	\$ 260.00	\$ 260.00
22	Front cabin air vent	1	\$ 85.30	\$ 85.30
23	Rear mudguard RH	1	\$ 283.40	\$ 283.40
24	Side gate	2	\$ 2,552.90	\$ 5,105.80
25	Side gate lock front	2	\$ 155.90	\$ 311.80
26	Side gate lock rear	2	\$ 105.00	\$ 210.00
27	Side gate rail	1	\$ 815.00	\$ 815.00
28	Rear gate	1	\$ 1,816.70	\$ 1,816.70
29	Right side gate hinges	2	\$ 45.00	\$ 90.00
30	Rear gate latch lock	1	\$ 106.50	\$ 106.50
31	Rear gate side lock lever	2	\$ 55.60	\$ 111.20
32	Rear gate stopper bracket	1	\$ 186.70	\$ 186.70
33	Rear gate reflector	1	\$ 28.50	\$ 28.50
34	Coolant tank	1	\$ 156.00	\$ 156.00
35	Fuel tank	1	\$ 345.00	\$ 345.00
36	Emblem Toyota D4D	1	\$ 105.60	\$ 105.60

Parts Sub Total : \$2821.46 17,070.20

20% 25% Discount \$ 705.37 3,414.04

PARTS TOTAL : \$ 2116.10 13,656.16

DD ✓
 NDMX
 JM ✓ XND
 BT ✓ XND
 NAX
 NDMX
 NAX
 BR ✓ XND
 SVCX
 SUT ✓ XND
 NECU ✓ XND
 DD ✓ XND
 RX
 SVCX
 SVCX
 SVCX
 DD ✓ XND
 NAX XND
 RX
 SVCX
 SVCX
 DD ✓
 RX
 NDMX
 BT ✓
 DD ✓
 SVCX
 BT ✓
 BR ✓
 SVC
 NEC ✓
 2821.46

Nos.	SPECIAL NETT	Qty	Unit S\$	TOTAL S\$
1	Front door inner board clips Rh	1	\$ 50.00	\$ 30.00 50.00
2	Front door inner pillar cover clips Rh	3	\$ 7.00	\$ 21.00
3	Front door LTA sticker	1	\$ 40.00	\$ 20.00 40.00
4	Rear canopy	1	\$ 2,800.00	\$ -2,800.00
5	Cabin rear panel glass moulding	1	\$ 100.00	\$ 100.00
6				\$ -
SPECIAL NETT TOTAL :				\$ 71.00 3,011.00

NEV ✓
NECV ✓
NECV ✓
SVC X
SVC X

Nos.	LABOUR	S\$
1	Panel beating	\$ 1000.00 2,000.00
2	Spray painting	\$ 200.00 2,000.00
3	Apply putty and anti-corrosion to affected areas	\$ 60.00 250.00
4	Check wiring	\$ 30.00 100.00
5	R&R upholstery to facilitate repair	\$ 30.00 150.00
6	R&R door mechanism to new door	\$ 80.00 150.00
7	R&R cabin assy	\$ 50.00 100.00
8	R&R door component	\$ - 80.00
9	R&R Rear flat bed	\$ 250.00
10	R&R Rear gate component	\$ 80.00
11	R&R Rear canopy	\$ 200.00
12		
LABOUR TOTAL :		\$ 1670.00 5,360.00

800.00 ✓
600
500 700.00 ✓
X
X
NDM

TTCim lin
Survey on 3/10/19
1430 hrs
Lump sum repair
7/10/19

PARTS TOTAL : \$ 13,656.16
SPECIAL NETT TOTAL : \$ 3,011.00
LABOUR TOTAL : \$ 5,360.00
GRAND TOTAL : \$ 22,027.16

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Resurvey on 4/10/19
TTCim lin
1610 hrs
Repair days 7

Parts 2116.10
SN 71.00
Labour 1670.00
3857.10
@ 20% 714.42
3085.68

L/S 3050/2

• **TG Lim (LKK Auto)**

From: Team Auto <tap.finalization@gmail.com>
Sent: Wednesday, 23 October, 2019 8:39 PM
To: TG Lim (LKK Auto)
Subject: Re: SLU1663C - FINALIZE AMOUNT AND AFTER PAINT
Attachments: WhatsApp Image 2019-09-24 at 10.11.07 AM.jpeg; WhatsApp Image 2019-09-24 at 10.12.11 AM.jpeg; WhatsApp Image 2019-09-24 at 10.11.23 AM.jpeg; WhatsApp Image 2019-09-24 at 10.11.45 AM.jpeg; WhatsApp Image 2019-09-24 at 10.10.59 AM.jpeg; WhatsApp Image 2019-09-24 at 10.12.50 AM.jpeg; WhatsApp Image 2019-09-24 at 10.13.13 AM.jpeg; WhatsApp Image 2019-09-24 at 10.13.02 AM.jpeg; 20191012_140719_resized.jpg; 20191012_140726_resized.jpg; 20191012_140717_resized.jpg; 20191012_140728.jpg; 20191012_140711_resized.jpg; 20191012_140738_resized.jpg; 20191012_140743_resized.jpg; 20191012_140747_resized.jpg; 20191012_140733.jpg; 20191012_140757_resized.jpg; 20191012_140805_resized.jpg; 20191012_140801_resized.jpg; WhatsApp Image 2019-10-12 at 9.35.37 AM.jpeg; WhatsApp Image 2019-10-12 at 9.36.30 AM.jpeg; WhatsApp Image 2019-10-12 at 9.36.35 AM.jpeg; 20191015_174651_resized.jpg; 20191015_174705_resized.jpg; 20191015_174635_resized.jpg; 20191015_174709_resized.jpg; 20191015_174637_resized.jpg; 20191015_174656_resized.jpg; 20191015_174710_resized.jpg; 20191015_174717_resized.jpg; 20191015_174725_resized.jpg; 20191015_174722_resized.jpg

Dear Mr Lim,

Without Prejudice

Thank You for assisting as the SJE for all the subject vehicle.

We are pleased to confirm our acceptance to your proposed of COR for

Vehicle Number	Finalised Amount	Repair Days
1 GBJ 5820R	\$10,000.00	10
2 GBB 5113R	\$3050.00	7
3 SJR 1046G	\$2050.00	5

Kindly advise OIC and reference number (if any) for our submission of LOD.

Enclosed herewith after-repair photos fyn.

Thank you.

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	02 Oct 2019		03 Oct 2019 11:07 Edit Adj Rpt	\$3,050.00 Edit Estimates	\$3,050.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	----------












































CLAIM SUBFOLDER DETAILS		[Created by insurer]
Insured:	-, Co. Reg. No.: -	
Main Claimant:	BUDGET AIRCONDITIONING PTE LTD, Co. Reg. No.: 201624123Z	
Vehicle Reg. No.:	GBB5113R	Date of Loss: 01/10/2019 08:00 - :59 [124 Months and 18 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / SNM19D204611-GBG9066R-TKL	Policy/Cover Note No.: DMCVSN3065221800 (Comprehensive)
Vehicle Reg. No. (Insured):	GBG9066R	Policy No. (Claimant): Z19VC05003528
	Excess:	\$350.00
Repairer:	Team Autopro Pte Ltd (Sin Ming) 385 Sin Ming Drive, #01-02 Vicom Inspection Centre, 575718 Sin Ming - Tel: 62581955	
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Tan Kah Leong - 63896193]	
Claimant's Insurer:	Lonpac Insurance Bhd (HQ) - Tel: +65 62507388	
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by Lim Teow Guan] ... [Final Rpt due 14/10/2019]	

ASSOCIATED MAIL RECEIVED	View All	Compose Case Mail
There are no mail for this case.		

ALL ASSOCIATED TASKS										View All	Search Tasks	Create New Task	Complete
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?				
No results.													

Claim Documents

*GBB5113R (SNM19D204611-GBG9066R-TKL)
[GBG9066R]
TP
BUDGET AIRCONDITIONING PTE LTD
Oct 1 2019 8:00AM
[-]
Team Autopro Pte Ltd

Upload Documents		Upload Photos	Compose New Letter	View View in Browser	
Photos/Images				3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print	
1	09/10/19 11:39	General View	 Load JPG	<input checked="" type="checkbox"/>	
2	09/10/19 11:39	General View	 Load JPG	<input checked="" type="checkbox"/>	
3	09/10/19 11:39	General View	 Load JPG	<input checked="" type="checkbox"/>	
4	09/10/19 11:39	General View	 Load JPG	<input checked="" type="checkbox"/>	
5	09/10/19 11:39	General View	 Load JPG	<input checked="" type="checkbox"/>	
6	09/10/19 11:39	General View	 Load JPG	<input checked="" type="checkbox"/>	
7	09/10/19 11:39	General View	 Load JPG	<input checked="" type="checkbox"/>	
8	09/10/19 11:39	General View	 Load JPG	<input checked="" type="checkbox"/>	
9	09/10/19 11:39	General View	 Load JPG	<input checked="" type="checkbox"/>	
10	09/10/19 11:39	General View	 Load JPG	<input checked="" type="checkbox"/>	
11	09/10/19 11:39	General View	 Load JPG	<input checked="" type="checkbox"/>	
12	09/10/19 11:39	General View	 Load JPG	<input checked="" type="checkbox"/>	
13	09/10/19 11:39	General View	 Load JPG	<input checked="" type="checkbox"/>	
14	09/10/19 11:39	General View	 Load JPG	<input checked="" type="checkbox"/>	
15	09/10/19 11:39	General View	 Load JPG	<input checked="" type="checkbox"/>	
16	09/10/19 11:39	General View	 Load JPG	<input checked="" type="checkbox"/>	
17	09/10/19 11:39	General View	 Load JPG	<input checked="" type="checkbox"/>	
18	09/10/19 11:39	General View	 Load JPG	<input checked="" type="checkbox"/>	
19	09/10/19 11:39	General View	 Load JPG	<input checked="" type="checkbox"/>	
20	09/10/19 11:39	General View	 Load JPG	<input checked="" type="checkbox"/>	
21	09/10/19 11:39	General View	 Load JPG	<input checked="" type="checkbox"/>	
22	09/10/19 11:39	General View	 Load JPG	<input checked="" type="checkbox"/>	
23	09/10/19 11:39	General View	 Load JPG	<input checked="" type="checkbox"/>	
24	09/10/19 11:39	General View	 Load JPG	<input checked="" type="checkbox"/>	
25	09/10/19 11:39	General View	 Load JPG	<input checked="" type="checkbox"/>	
26	09/10/19 11:39	General View	 Load JPG	<input checked="" type="checkbox"/>	
27	09/10/19 11:39	General View	 Load JPG	<input checked="" type="checkbox"/>	
28	09/10/19 11:39	General View	 Load JPG	<input checked="" type="checkbox"/>	
29	09/10/19 11:39	General View	 Load JPG	<input checked="" type="checkbox"/>	
30	09/10/19 11:39	General View	 Load JPG	<input checked="" type="checkbox"/>	
31	09/10/19 11:39	General View	 Load JPG	<input checked="" type="checkbox"/>	
32	09/10/19 11:39	General View	 Load JPG	<input checked="" type="checkbox"/>	
33	09/10/19 11:39	General View	 Load JPG	<input checked="" type="checkbox"/>	
34	09/10/19 11:39	General View	 Load JPG	<input checked="" type="checkbox"/>	
35	09/10/19 11:39	General View	 Load JPG	<input checked="" type="checkbox"/>	
36	09/10/19 11:39	General View	 Load JPG	<input checked="" type="checkbox"/>	
37	09/10/19 11:39	General View	 Load JPG	<input checked="" type="checkbox"/>	
38	09/10/19 11:39	General View	 Load JPG	<input checked="" type="checkbox"/>	
39	09/10/19 11:39	General View	 Load JPG	<input checked="" type="checkbox"/>	
40	09/10/19 11:39	General View	 Load JPG	<input checked="" type="checkbox"/>	
41	09/10/19 11:39	General View	 Load JPG	<input checked="" type="checkbox"/>	
42	09/10/19 11:39	General View	 Load JPG	<input checked="" type="checkbox"/>	
43	09/10/19 11:39	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>	

Photos/Images				3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
44	09/10/19 11:39	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
45	09/10/19 11:39	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
46	09/10/19 11:39	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
47	09/10/19 11:39	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
48	09/10/19 11:39	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>

Linked Accident Report Documents

Assessment Reports				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	National Assessment Centre Services (Bukit Merah)		Thumbnail	Print
1	02/10/19 15:54	Accident Statement		Load HTM	

Photos/Images				3 per page	<input checked="" type="checkbox"/>
No	Finalized On	National Assessment Centre Services (Bukit Merah)		Thumbnail	Print
1	02/10/19 15:49	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
2	02/10/19 15:49	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
3	02/10/19 15:49	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
4	02/10/19 15:49	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
5	02/10/19 15:49	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
6	02/10/19 15:49	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
7	02/10/19 15:49	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
8	02/10/19 15:49	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
9	02/10/19 15:49	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
10	02/10/19 15:49	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
11	02/10/19 15:49	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
12	02/10/19 15:49	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
13	02/10/19 15:49	Accident Photo		Load JPG	<input checked="" type="checkbox"/>

Documentation				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	National Assessment Centre Services (Bukit Merah)		Thumbnail	Print
1	02/10/19 15:53	Sketch Plan		Load JPG	<input checked="" type="checkbox"/>
2	02/10/19 15:53	Sketch Plan #2		Load JPG	<input checked="" type="checkbox"/>

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin: 5px 0;"></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI19017372/BSD3E2

Date: 25/10/2019

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSN3065221800
Claimant Vehicle No :	GBB5113R	Insured Vehicle No :	GBG9066R
Date of Loss:	01/10/2019	Nature of Claim:	TP
		Claim No:	SNM19D204611-GBG9066R-TKL

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBB5113R		
Make & Model:	TOYOTA DYNA 150 MANUAL 3SEATER, 3.0 D (M)	Engine No:	1KD1924892
Reg. Date:	13/05/2009 (Man. Year: 2009)	Chassis No:	JTFAT35Y70K200560
Colour:	Silver	Odometer:	170149 km
Engine Capacity:	2982 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195 R15	Rear Tyre Size:	195 R15
Front Left Side:	Austone 5 mm	Rear Left Side:	Austone 5 mm
Front Right Side:	Austone 5 mm	Rear Right Side:	Austone 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	16,667.16	2,187.09	14,480.07	86.88
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,360.00	1,670.00	3,690.00	68.84
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	22,027.16	3,857.09	18,170.07	82.49
Approved Total (Overridden) (S\$)		3,050.00		
Nett Amount (S\$)	22,027.16	3,050.00	18,977.16	86.15

INSPECTION

Date of Assignment:	03/10/2019	
Date Inspected:	03/10/2019 Inspected At:	160 Sin Ming Drive #01-14 Repairer : Team Autopro Pte Ltd (Sin Ming)
Estimated Period of Repair:	7.0 days	

Adjuster: Lim Teow Guan

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 25 Oct 2019)	
Parts:	N/A	TOYOTA DYNA 150 MANUAL 3SEATER 3.0 D (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBB5113R)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*FRONT DOOR RH	Dented	1,208.10 FL	*1,208.10 FL
2	2	*FRONT DOOR HINGE RH	No Damaged	148.00 FL	*- FL
3	1	*FRONT DOOR CHECK PIN RH	No Damaged	184.50 FL	*- FL
4	1	*FRONT DOOR WEATHERSTRIP RH	No Damaged	325.00 FL	*- FL
5	1	*FRONT DOOR OUTER MOULDING RH	No Damaged	168.00 FL	*- FL
6	1	*FRONT DOOR REGULATOR MOTOR RH	Jammed	157.00 FL	*157.00 FL
7	1	*FRONT DOOR REGULATOR GEAR RH	Bent	89.00 FL	*89.00 FL
8	1	*FRONT DOOR CHANNEL RH	No Application	106.00 FL	*- FL
9	1	*FRONT DOOR INNER LOCK RH	No Damaged	236.80 FL	*- FL
10	1	*FRONT DOOR INNER LOCK MOTOR RH	No Application	189.00 FL	*- FL
11	1	*FRONT DOOR OUTER HANDLE RH	Broken	89.00 FL	*89.00 FL
12	1	*FRONT FLOOR PANEL	Serviceable	480.10 FL	*- FL
13	1	*FRONT DOOR GLASS RH	No Damaged	254.00 FL	*- FL
14	1	*FRONT DOOR GLASS RUN RUBBER RH	No Damaged	165.00 FL	*- FL
15	1	*FRONT DOOR PILLAR RH	No Damaged	435.10 FL	*- FL
16	1	*FRONT WHEEL ARCH GARNISH RH	Repair	95.00 FL	*- FL
17	1	*FRONT CABIN COLUMN	Serviceable	1,021.00 FL	*- FL
18	1	*FRONT CABIN COLUMN BUSH	Serviceable	328.10 FL	*- FL
19	2	*FRONT CABIN MOUNTING	Serviceable	218.20 FL	*- FL
20	1	*FRONT CABIN PILLAR	Dented	678.00 FL	*678.00 FL
21	1	*FRONT CABIN LOCK	No Damaged	260.00 FL	*- FL
22	1	*FRONT CABIN AIR VENT	No Damaged	85.30 FL	*- FL
23	1	*REAR MUDGUARD RH	Repair	283.40 FL	*- FL
24	2	*SIDE GATE	Serviceable	5,105.80 FL	*- FL
25	2	*SIDE GATE LOCK FRONT	Serviceable	311.80 FL	*- FL
26	2	*SIDE GATE LOCK REAR	Dented	311.80 FL	*210.00 FL
27	1	*SIDE GATE RAIL	Repair	815.00 FL	*- FL
28	1	*REAR GATE	No Damaged	1,816.70 FL	*- FL
29	1	*RIGHT SIDE GATE HINGES (5PCS)	Bent (2Pcs Only)	437.50 FL	*90.00 FL
30	1	*REAR GATE LATCH LOCK	Dented	106.50 FL	*106.50 FL
31	2	*REAR GATE SIDE LOCK LEVER	Serviceable	111.20 FL	*- FL
32	1	*REAR GATE STOPPER BRACKET	Bent	186.70 FL	*109.70 FL
33	1	*REAR GATE REFLECTOR (2PCS)	Broken (1Pcs Only)	57.00 FL	*28.50 FL
34	1	*COOLANT TANK	Serviceable	156.00 FL	*- FL
35	1	*FUEL TANK	Serviceable	345.00 FL	*- FL
36	1	*EMBLEM TOYOTA D4D	Necessary	105.60 FL	*55.66 FL
37	1	*FRONT DOOR INNER BOARD CLIPS RH	Necessary	50.00 FS	*30.00 FS
38	3	*FRONT DOOR INNER PILLAR COVER CLIPS RH	Necessary	21.00 FS	*21.00 FS
39	1	*FRONT DOOR LTA STICKER	Necessary	40.00 FS	*20.00 FS
40	1	*REAR CANOPY	Serviceable	2,800.00 FS	*- FS
41	1	*CABIN REAR PANEL GLASS MOULDING	Serviceable	100.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
Sub Total (\$)					20,081.20	2,892.46
- List Item Discount on L Items 20.00/25.00% (\$)					3,414.04	705.37
Total Parts (\$)					16,667.16	2,187.09

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING	New	2,000.00	800.00
2	SPRAY PAINTING	New	2,000.00	700.00
3	APPLY PUTTY AND ANTI-CORROSION TO AFFECTED AREAS	New	250.00	60.00
4	CHECK WIRING	New	100.00	30.00
5	R&R UPHOLSTERY TO FACILITATE REPAIR	New	150.00	0.00
6	R&R DOOR MECHANISM TO NEW DOOR	New	150.00	80.00
7	R&R CABIN ASSY	New	100.00	0.00
8	R&R DOOR COMPONENT	New	80.00	0.00
9	R&R REAR FLAT BED	New	250.00	0.00
10	R&R REAR GATE COMPONENT	New	80.00	0.00
11	R&R REAR CANOPY	New	200.00	0.00
Gross Labour Cost (S\$)			5,360.00	1,670.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >