



Your Ref: AEMD/105/009/2018/041

Date: 15th October 2019

Our Ref: CS1/SPF19017392/Dyf3s2

M/s Automotive Engineering & MGT Division
Accident Claim Section (Singapore Police Force)
1 Mount Pleasant Road
Blk 8 Old Police Academy
Singapore 298333

Attn: Hafizul Farhan

Dear Sir / Madam,

EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT VEHICLE NO: SGG 7494S
INSURED VEHICLE: QX 305T ACCIDENT DATE: 04/02/2018

We thank you for your instruction on 01/10/2019.

We acknowledge receipt of the following documents:-

- a) Automobile Inspection Report of SGG 7494S from M/s JP Knights Adjusters & Surveyors.
- b) Final Repair Bill of SGG 7494S from M/s Success United Pte Ltd.
- c) Damaged vehicle photographs of SGG 7494S.

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments:-

1. Information Recorded: -

Registration Number	: SGG 7494S
Make & Model	: Hyundai Verna 1.4 (A)
Year of Registration	: 2006
Chassis Number	: KMHCM41AR6U065047
Engine Capacity	: 1399 cc
2. We recommend that the repairs of the entire damage require about 4 (Four) working days to complete.
3. We hereby provide our recommendations on the cost of repair to the damaged vehicle as stated in the following page.